



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0907E 12371-63030 ST150 Front Engine Bushing (RE)  B : 6 / C : 72 pcs.	T0907EZ 12371-63031-IN ST150 Insulator Engine (RE)  B : 2 / C : 24 pcs.
T0907F 12361-74010 ST150 Front Engine Bushing (FR)  B : 4 / C : 48 pcs.	T0907FZ 12361-74150-IN ST150 Insulator Engine (FR)  B : 2 / C : 24 pcs.
T0907L 12372-63011 ST150 Front Engine Bushing (LH)  B : 6 / C : 72 pcs.	T0907LZ 12372-63011-IN ST150 Insulator Engine (LH)  B : 2 / C : 24 pcs.
T0907R 12362-63031 ST150 Front Engine Bushing (RH)  B : 4 / C : 48 pcs.	T0907RZ 12362-63031-IN ST150 Insulator Engine (RH)  B : 2 / C : 24 pcs.
T0908E 12371-15170 AT171, ST171 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T0908EAZ 12371-15220-IN AT171, ST171 Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
T0908E 12371-15170 AT171, ST171 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T0908EMZ 12371-15170-IN AT171, ST171 Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T0908F 12361-16040 AT171 Front Engine Bushing (FR)  B : 4 / C : 48 pcs.	T0908FMZ 12361-15150-IN AT171 Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
T0908L 12372-16100 AT171 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	



is the registered trademark



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0927EA 12371-64141, 16090, 64130 AE92 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0909EAZ 12371-74260-IN, 64160-IN ST171 Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
T0908E 12371-15170 AT171, ST171 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T0909EMZ 12371-74250-IN ST171 Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T0909F 12361-64120 ST171 Front Engine Bushing (FR, A/T)  B : 4 / C : 48 pcs.	T0909FAZ 12361-74080-IN ST171 Insulator Engine (FR, A/T)  B : 2 / C : 24 pcs.
T0909FM 12361-74100 ST171 Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	T0909FMZ 12361-74070-IN ST171 Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
T0909L 12372-74120 ST171 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	T0909LAZ 12372-74130-IN ST171 Insulator Engine (LH, A/T)  B : 1 / C : 8 pcs.
T0909L 12372-74120 ST171 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	T0909LZ 12372-74120-IN ST171 Insulator Engine (LH, M/T)  B : 1 / C : 12 pcs.
T0909R 12362-74080 ST171 Front Engine Bushing (RH)  B : 4 / C : 48 pcs.	T0909RZ 12362-74080-IN ST171 Insulator Engine (RH)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0910E 12371-16270, 16290 AT190 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T0910AEMZ 12371-16270-IN AT190 Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T0910E 12371-16270, 16290 AT190 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T0910AEAZ 12371-16290-IN AT190 Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
T0910F 12361-16210 AT190 Front Engine Bushing (FR, A/T, M/T)  B : 4 / C : 48 pcs.	T0910FZ 12361-16210-IN AT190 Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
T0910FA 12361-74300 ST190 Front Engine Bushing (FR, A/T)  B : 4 / C : 48 pcs.	T0910FAZ 12361-74300-IN ST190 Insulator Engine (FR, A/T)  B : 1 / C : 12 pcs.
T0909FM 12361-74100 ST171 Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	T0910FMZ 12361-74260-IN ST190 Insulator Engine (FR, M/T)  B : 1 / C : 12 pcs.
T0930L 12362-15120 AE101, AT190 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	T0910LMZ 12372-16270-IN AT190 Insulator Engine (LH, M/T)  B : 1 / C : 9 pcs.
T0910R 12362-16190 AT190 EXSIOR (1.6 cc) Front Engine Bushing (RH)  B : 2 / C : 24 pcs.	T0910RZ 12305-16120-IN AT190 Insulator Engine (RH)  B : 1 / C : 9 pcs.
T0911EA 12371-74330,74500,74320 ST190 EXSIOR Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0910SEAZ 12371-74330-IN ST190 Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0911EA 12371-74330, 74500, 74320 ST190, EXSIOR Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0910SEMZ 12371-74320-IN ST190 (2.0 cc) Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T0911FA 12361-16290 ST191, EXSIOR (2.0 cc) Front Engine Bushing (FR, A/T)  B : 4 / C : 48 pcs.	T0911FAZ 12361-16290-IN ST191 EXSIOR Insulator Engine (FR, A/T)  B : 2 / C : 24 pcs.
T0911FM 12361-16280 ST191 EXSIOR Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	T0911FMZ 12361-16280-IN ST191 EXSIOR Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
T0911L 12372-16351 ST191 EXSIOR Front Engine Bushing (LH, A/T, M/T)  B : 4 / C : 48 pcs.	T0911LZ 12372-16351-IN ST191 EXSIOR Insulator Engine (LH, A/T, M/T)  B : 1 / C : 12 pcs.
T0910LM 12372-74351 ST191 Front Engine Bushing (LH, M/T)  B : 4 / C : 48 pcs.	T0911LMZ 12372-74351-IN ST190 Insulator Engine (LH, M/T)  B : 1 / C : 9 pcs.
T0911EA 12371-74330, 74500, 74320 ST190 EXSIOR Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0911SEAZ 12371-74500-IN ST190 EXSIOR Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
T0911EA 12371-74330, 74500, 74320 ST190 EXSIOR Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0911SEMZ 12371-74510-IN ST191 EXSIOR Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T0912FM 12361-16310 AT190 EXSIOR Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	T0912FMZ 12361-16310-IN AT191 EXSIOR (1.6 cc) Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0925E 12371-11080 AE80 Front Engine Bushing (RE)  B : 6 / C : 72 pcs.	
T0925F 12361-11020 AE80 Front Engine Bushing (FR)  B : 6 / C : 72 pcs.	T0925FZ 12361-11020-IN AE80 Insulator Engine (FR)  B : 2 / C : 24 pcs.
T0925L 12372-15051 AE80 Front Engine Bushing (LH)  B : 6 / C : 72 pcs.	
T0925R 12362-11010 AE80 Front Engine Bushing (RH)  B : 6 / C : 72 pcs.	
T0927EA 12371-64141, 16090, 64130 AE92 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0927EAZ 12371-64141-IN AE92 Insulator Engine (RE, A/T)  B : 2 / C : 24 pcs.
T0927E 12371-15200 AE92 Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	T0927EMZ 12371-15200-IN AE92 Insulator Engine (RE, M/T)  B : 1 / C : 12 pcs.
T0927EA 12371-64141, 16090, 64130 AE92 Front Engine Bushing (RE, A/T)  B : 6 / C : 72 pcs.	T0927FAZ 12361-16090-IN AE92 Insulator Engine (FR, A/T)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0908F 12361-16040 AT171 Front Engine Bushing (FR, A/T) B : 4 / C : 48 pcs. 	T0927FMZ 12361-16040-IN EE90, AE92 Insulator Engine (FR, M/T) B : 2 / C : 24 pcs. 
T0927R 12362-15160 AE92 Front Engine Bushing (RH) B : 4 / C : 48 pcs. 	T0927RZ 12362-15160-IN AE92 Insulator Engine (RH) B : 1 / C : 12 pcs. 
T0928F 12371-64120 EE90 Front Engine Bushing (FR, RE) B : 4 / C : 48 pcs. 	T0928EZ 12371-11210-IN EE90 Insulator Engine (RE) B : 2 / C : 24 pcs. 
T0928L 12372-15120 EE90 Front Engine Bushing (LH) B : 4 / C : 48 pcs. 	T0928LMZ 12372-15110-IN AE92 Insulator Engine (LH, M/T) B : 1 / C : 9 pcs. 
T0928R 12362-15130 EE90 Front Engine Bushing (RH) B : 4 / C : 48 pcs. 	T0928RZ 12362-11070-IN EE90 Insulator Engine (RH) B : 1 / C : 12 pcs. 
	T09281RZ 12362-11100-IN EE92 Insulator Engine (RH) B : 1 / C : 12 pcs. 
T0929E 12371-16280 AE101 Front Engine Bushing (RE) B : 4 / C : 48 pcs. 	T0929EZ 12371-16280-IN AE101 Insulator Engine (RE) B : 1 / C : 12 pcs. 
T0930E 12371-11430 EE100 Front Engine Bushing (RE) B : 4 / C : 48 pcs. 	T0930EZ 12371-15240 EE100 Insulator Engine (RE) B : 1 / C : 12 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0930F 12361-11160, 64210 EE100, AE101 Front Engine Bushing (FR)  B : 4 / C : 48 pcs.	T0930FZ 12361-11160-IN EE100, AE101 Insulator Engine (FR)  B : 2 / C : 24 pcs.
T0930L 12362-15120 AE101, AT190 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	
T0930R 12305-11010, 15020 EE100, AE101 Front Engine Bushing (RH)  B : 2 / C : 24 pcs.	
T0931EA 12371-64210 AE111 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T0931EAZ 12371-64210-IN AE110, AE111 Insulator Engine (RE, A/T)  B : 1 / C : 12 pcs.
T0931EM 12371-15240, 15241 AE110, AE111, AE102 Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	T0931EMZ 12371-15241-IN AE111 Insulator Engine (RE, M/T)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T0932LA 12372-15200 AE112, HI-TORQUE Front Engine Bushing (LH, A/T)  B : 4 / C : 48 pcs.	T0932LAZ 12372-15200-IN AE112, HI-TORQUE Insulator Engine (LH, A/T)  B : 1 / C : 12 pcs.
T0932LA 12372-15200 AE112, HI-TORQUE Front Engine Bushing (LH, A/T)  B : 4 / C : 48 pcs.	T0932LMZ 12372-15220-IN AE112, HI-TORQUE Insulator Engine (LH, M/T)  B : 1 / C : 12 pcs.
T0931R 12305-15040 AE101, AE111 Front Engine Bushing (RH)  B : 2 / C : 24 pcs.	T0931RZ 12305-15040-IN AE110, AE111 Insulator Engine (RH, A/T, M/T)  B : 1 / C : 8 pcs.
T0909F 12361-64120 ST171 Front Engine Bushing (FR, A/T)  B : 4 / C : 48 pcs.	T09C01FZ 12361-64120-IN CAMRY SV20 Insulator Engine (FR)  B : 2 / C : 24 pcs.
T09C01RB 12362-74030 CAMRY SV20 Front Engine Bushing (RH, BIG)  B : 2 / C : 24 pcs.	
T09C01RS 12362-74100 CAMRY SV20 Front Engine Bushing (RH, SMALL)  B : 4 / C : 48 pcs.	
T09C05RB 12309-28160B CAMRY ACV40 Front Engine Bushing (RH, BIG)  B : 4 / C : 48 pcs.	T09C05RZ 12309-28160-IN CAMRY ACV40 Insulator Engine  B : 2 / C : 24 pcs.
	T09C06RZ 12309-0V090-IN CAMRY ASV50 Insulator Engine (RH)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09C02RB 12363-74120B CAMRY SXV10 Front Engine Bushing (RH, A/T)  B : 8 / C : 96 pcs.	T09C02RBZ 12363-74120-IN CAMRY SXV10 Insulator Engine (RH, A/T)  B : 2 / C : 24 pcs.
T09C03B 12363-74140B CAMRY SXV10, SXV20 Front Engine Bushing (BIG)  B : 8 / C : 96 pcs.	T09C02PZ 12363-74140-IN CAMRY SXV10 Insulator Engine  B : 2 / C : 24 pcs.
T09C03S 12363-74140S, 74130S CAMRY SXV10, SXV20 Front Engine Bushing (SMALL)  B : 8 / C : 96 pcs.	T09C02PZ 12363-74140-IN CAMRY SXV10 Insulator Engine  B : 2 / C : 20 pcs.
T09C03FB 12363-74130B CAMRY SXV20 Front Engine Bushing (BIG)  B : 6 / C : 72 pcs.	T09C03PZ 12363-74130-IN CAMRY SXV20 (2.2 cc) Insulator Engine  B : 2 / C : 24 pcs.
T09C03S 12363-74140S, 74130S CAMRY SXV10, SXV20 Front Engine Bushing (SMALL)  B : 8 / C : 96 pcs.	T09C03PZ 12363-74130-IN CAMRY SXV20 (2.2 cc) Insulator Engine  B : 2 / C : 24 pcs.
T09C04B 12363-0H030B CAMRY ACV30, ACV31 Front Engine Bushing (BIG)  B : 6 / C : 72 pcs.	T09C04RZ 12363-0H030-IN CAMRY ACV30, ACV31 Insulator Engine  B : 2 / C : 24 pcs.
T09C04S 12363-0H030S CAMRY ACV30, ACV31 Front Engine Bushing (SMALL)  B : 8 / C : 96 pcs.	T09C04RZ 12363-0H030-IN CAMRY ACV30, ACV31 Insulator Engine  B : 2 / C : 24 pcs.
T09C00E 12371-74130 CAMRY (1992-1994) Front Engine Bushing  B : 4 / C : 48 pcs.	



is the registered trademark



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09C03FB 12363-74130B CAMRY SXV20 Front Engine Bushing (BIG)  B : 6 / C : 72 pcs.	T09C03Z 12363-20020-IN CAMRY MCV20, SXV20 V6 (3.0 cc) Insulator Engine  B : 2 / C : 24 pcs.
T09C03S 12363-74140S, 74130S CAMRY SXV10, SXV20 Front Engine Bushing (SMALL)  B : 8 / C : 96 pcs.	
T09C03E 12371-20030 CAMRY MCV20, SXV20 V6 (3.0 cc) Front Engine Bushing  B : 4 / C : 48 pcs.	
T09NC42EA 12371-0M030 VIOS Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T09NC4EAZ 12371-0M030-IN VIOS Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
T09NC42EM 12371-0M020 VIOS Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	T09NC4EMZ 12371-0M020-IN VIOS Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T09NC42L 12372-0M030, 0M040 VIOS Front Engine Bushing (LH, A/T, M/T)  B : 4 / C : 48 pcs.	T09NC4LAZ 12372-0M030-IN VIOS Insulator Engine (LH, A/T)  B : 2 / C : 24 pcs.
T09NC42L 12372-0M030, 0M040 VIOS Front Engine Bushing (LH, A/T, M/T)  B : 4 / C : 48 pcs.	T09NC4LMZ 12372-0M040-IN VIOS Insulator Engine (LH, M/T)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09EP71E 12371-10040 EP71 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.	
T09EP71L 12372-10020 EP71 Front Engine Bushing (LH)  B : 6 / C : 72 pcs.	
T09EP71R 12362-10010 EP71 Front Engine Bushing (RH)  B : 6 / C : 72 pcs.	T09EP71RZ 12362-10010-IN EP71 Insulator Engine (RH)  B : 2 / C : 24 pcs.
T09EP82E 12371-11240 EP82 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.	T09EP82EZ 12371-11240-IN EP82 Insulator Engine (RE)  B : 1 / C : 12 pcs.
T09EP82L 12372-10040 EP82 Front Engine Bushing (LH)  B : 6 / C : 72 pcs.	T09EP82LZ 12372-10040-IN EP82 Insulator Engine (LH)  B : 2 / C : 24 pcs.
T09EY10L 12362-11110 EXY10, SERA Front Engine Bushing (LH)  B : 6 / C : 72 pcs.	T09EY10RZ 12362-11110-IN EXY10 Insulator Engine (RH)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09S01EA 12371-02120 SOLUNA Front Engine Bushing (RE, A/T) B : 4 / C : 48 pcs. 	T09S01EAZ 12371-02120-IN SOLUNA Insulator Engine (RE, A/T) B : 1 / C : 6 pcs. 
T09S01EM 12371-02110 SOLUNA Front Engine Bushing (RE, M/T) B : 4 / C : 48 pcs. 	T09S01EMZ 12371-02110-IN SOLUNA Insulator Engine (RE, M/T) B : 1 / C : 6 pcs. 
T09S01LA 12372-02120 SOLUNA Front Engine Bushing (LH, A/T) B : 4 / C : 48 pcs. 	T09S01LAZ 12372-02120-IN SOLUNA Insulator Engine (LH, A/T) B : 2 / C : 24 pcs. 
T09S01LM 12372-02110 SOLUNA Front Engine Bushing (LH, M/T) B : 4 / C : 48 pcs. 	T09S01LMZ 12372-02110-IN SOLUNA Insulator Engine (LH, M/T) B : 2 / C : 24 pcs. 
T09S01R 12362-02050 SOLUNA Front Engine Bushing (RH, A/T, M/T) B : 6 / C : 72 pcs. 	T09S01RZ 12362-02050-IN SOLUNA Insulator Engine (RH, A/T, M/T) B : 1 / C : 12 pcs. 
T09S01R 12362-02050 SOLUNA Front Engine Bushing (RH, A/T, M/T) B : 6 / C : 72 pcs. 	T09S02R0Z 12362-02060-IN SOLUNA (1999-2000) Insulator Engine (RH) B : 1 / C : 12 pcs. 
T09S01LA 12372-02120 SOLUNA Front Engine Bushing (LH, A/T) B : 4 / C : 48 pcs. 	T09S02LAZ 12372-02150-IN SOLUNA (1999-2000) Insulator Engine (LH, A/T) B : 2 / C : 24 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09TE94E 12371-74420 ST204 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.	T09TE94EZ 12371-74420-IN ST204 Insulator Engine (RE)  B : 1 / C : 12 pcs.
T09TE94L 12372-74450 ST204 Front Engine Bushing (LH)  B : 2 / C : 24 pcs.	T09TE94LZ 12372-74451-IN ST204 Insulator Engine (LH)  B : 1 / C : 9 pcs.
T09Z12EA 12371-0D060 ALTIS ZZE121, ZZE122 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T09Z121EZ 12371-0D060-IN ALTIS ZZE121, ZZE122 Insulator Engine (RE)  B : 1 / C : 8 pcs.
T09Z12EM 12371-0D050 ALTIS ZZE121, ZZE122 Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	T09Z12EMZ 12371-0D050-IN ALTIS ZZE121, ZZE122 Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T09ZE121L 12372-0D050 ALTIS ZZE121, ZZE122 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	T09Z121LZ 12372-0D050-IN ALTIS ZZE121, ZZE122 Insulator Engine (LH)  B : 1 / C : 12 pcs.
	T09Z12FAZ 12361-0D040-IN ALTIS ZZE121, ZZE122 Insulator Engine (FR, A/T)  B : 1 / C : 12 pcs.
T09Z12FM 12361-0D030 ALTIS ZZE121, ZZE122 Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	T09Z12FMZ 12361-0D030-IN ALTIS ZZE121, ZZE122 Insulator Engine (FR, M/T)  B : 1 / C : 12 pcs.
T09ZE121F 12305-0D061 ALTIS ZZE121, ZZE122 Front Engine Bushing (RH)  B : 4 / C : 48 pcs.	T09Z12RZZ 12305-0D061-IN, 22430-IN ALTIS ZZE121, ZZE122 Insulator Engine (RH, A/T, M/T)  B : 1 / C : 8 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09Z14EA 12371-0D220 ALTIS ZZE141 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	T09Z14E0Z 12371-0D220-IN, 0D210-IN, 0T160-IN ALTIS ZZE141, ZRE141 (2010) Insulator Engine (RE, M/T, A/T)  B : 1 / C : 8 pcs.
	T09Z14FMZ 12361-0D210-IN ALTIS ZZE141 Insulator Engine (FR, M/T)  B : 1 / C : 12 pcs.
	T09Z14LMZ 12372-0D170-IN ALTIS ZZE141 Insulator Engine (LH, M/T)  B : 1 / C : 8 pcs.
	T09Z14FAZ 12361-0D220-IN ALTIS ZZE141 Insulator Engine (FR, A/T)  B : 1 / C : 12 pcs.
	T09Z14LAZ 12372-0D190-IN ALTIS ZZE141 Insulator Engine (LH, A/T)  B : 1 / C : 8 pcs.
T09ZE121R 12305-0D061 ALTIS ZZE121, ZZE122 Front Engine Bushing (RH)  B : 4 / C : 48 pcs.	T09Z12RZH 12305-0D061-HY, 12305-22430-HY ALTIS ZZE121, ZZE122 Insulator Engine (RH, A/T, M/T)  B : 1 / C : 8 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09RV1FA 12361-74370 RAV4, SXA11 Front Engine Bushing (FR, A/T) B : 4 / C : 48 pcs.		T09RV1FAZ 12361-74370-IN RAV4, SXA11 Insulator Engine (FR, A/T) B : 2 / C : 24 pcs.	
T09RV1FM 12361-74340 RAV4, SXA11 Front Engine Bushing (FR, M/T) B : 4 / C : 48 pcs.		T09RV1FMZ 12361-74340-IN RAV4, SXA11 Insulator Engine (FR, M/T) B : 2 / C : 24 pcs.	
T09RV1LA 12372-74410 RAV4, SXA11 Front Engine Bushing (LH, A/T) B : 4 / C : 48 pcs.		T09RV1LAZ 12372-74520-IN RAV4, SXA11 Insulator Engine (LH, A/T) B : 1 / C : 9 pcs.	
T09RV1EM 12371-74460, 74351, 74461 RAV4, SXA11 Front Engine Bushing (RE, M/T) B : 6 / C : 72 pcs.		T09RV1EMZ 12371-74461-IN RAV4, SXA11 Insulator Engine (RE, M/T) B : 2 / C : 24 pcs.	
T09RV1EA 12371-74470, 74341 RAV4, SXA11 Front Engine Bushing (RE, A/T) B : 6 / C : 72 pcs.		T09RV1EAZ 12371-74471-IN RAV4, SXA11 Insulator Engine (RE, A/T) B : 2 / C : 24 pcs.	
T09W110E 12371-28060 WISH ANE11 Front Engine Bushing (RE) B : 4 / C : 48 pcs.		T09W110EZ 12371-28080-IN WISH ANE11 Insulator Engine (RE) B : 1 / C : 8 pcs.	
T09W110L 12372-28110 WISH ANE11 Front Engine Bushing (LH) B : 4 / C : 48 pcs.			





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T09ZE171E 12371-0T320, 12371-0T330 ALTIS ZRE171, ZRE172 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T09Z17EAZ 12371-0T330-IN ALTIS ZRE171, ZRE172 Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
T09ZE171E 12371-0T320 ALTIS ZRE171, ZRE172 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	T09Z17EMZ 12371-0T320-IN ALTIS ZRE171, ZRE172 Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
T09ZE171L 12372-0T201, 12372-0T211 ALTIS ZRE171, ZRE172 Front Engine Bushing (LH, A/T, M/T)  B : 4 / C : 48 pcs.	
09AH20L0 12372-28390 ALPHARD ANH20, ESTIMA ACR50 Engine Bushing (LH)  B : 4 / C : 48 pcs.	T09NE12FZ 12361-21020-IN ALTIS NZE121 (1.5 cc), (2001, 2006) Insulator Engine (FR)  B : 2 / C : 24 pcs.
	T09Z17FAZ 12361-0T130-IN ALTIS ZRE141, 171 Insulator Engine (FR, A/T)  B : 1 / C : 12 pcs.
T09AH20E0 12371-28240 ALPHARD ANH20 (2008), ESTIMA ACR50 (2006) Engine Bushing (RE)  B : 2 / C : 24 pcs.	T09AH20EZ 12371-28240-IN ALPHARD ANH20 (2008), ESTIMA ACR50 (2006) Insulator Engine (RE)  B : 1 / C : 8 pcs.
T09AH20LZ 12372-28390-IN ALPHARD ANH20, ESTIMA ACR50 Insulator Engine (LH)  B : 1 / C : 8 pcs.	T09AH20FZ 12361-28280-IN ALPHARD ANH20, ESTIMA ACR50 Insulator Engine (FR)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T10030 12361-39018 RT80, RN25 Front Engine Mounting  B : 2 / C : 24 pcs.	T10040 12361-39105 RT100 Front Engine Mounting  B : 2 / C : 24 pcs.
T10050 12361-26041 TT130 (2T) Front Engine Mounting  B : 2 / C : 24 pcs.	T10070 12371-63040 ST150 Front Engine Mounting (RE, A/T)  B : 4 / C : 48 pcs.
	T1022R 12301-22011 KE20 Front Engine Mounting (RH)  B : 2 / C : 24 pcs.
T1023L 12302-24010 KE30 Front Engine Mounting (LH)  B : 1 / C : 12 pcs.	T1023R 12301-24020 KE30 Front Engine Mounting (RH)  B : 1 / C : 12 pcs.
T1024L 12302-12013 KE70 Front Engine Mounting (LH)  B : 1 / C : 12 pcs.	T1024R 12301-13020 KE70 Front Engine Mounting (RH)  B : 1 / C : 12 pcs.
T1031F 12361-15170, 15171, 11181, 15180 AE101, AE111, AE102 Front Engine Mounting (FR)  B : 4 / C : 48 pcs.	
T10430 12361-54020 RN30 Front Engine Mounting  B : 2 / C : 24 pcs.	T10440 12361-54140 LN40 Front Engine Mounting  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T10450 12361-38060, 38130 LN50, LN56 Front Engine Mounting  B : 2 / C : 24 pcs.	T10460 12361-54110 LN85 Front Engine Mounting  B : 2 / C : 24 pcs.
T10640 12361-54030 YH, LH60 Front Engine Mounting  B : 4 / C : 48 pcs.	T10650 12361-54143 YH, LH112 Front Engine Mounting  B : 2 / C : 24 pcs.
T10840 12361-49026 MS110 Front Engine Mounting  B : 4 / C : 48 pcs.	
T10880 12361-43060 MS120 Front Engine Mounting  B : 1 / C : 12 pcs.	
T10900 12361-25010 2T Front Engine Mounting  B : 2 / C : 24 pcs.	T10910 12361-49036 JU Front Engine Mounting  B : 2 / C : 24 pcs.
T10920 12361-59035 BU10 Front Engine Mounting  B : 2 / C : 24 pcs.	
T10B61L 12362-56010 BU61 (13B) Front Engine Mounting (LH)  B : 1 / C : 12 pcs.	T10B61R 12361-56070 BU61 (13B) Front Engine Mounting (RH)  B : 1 / C : 12 pcs.
T10CR27 12361-64022 CR27 (1C) Front Engine Mounting  B : 2 / C : 24 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T10KF40L 12302-13012 KF40 Front Engine Mounting (LH) B : 1 / C : 12 pcs.	T10KI20L 12302-13161 KIJANG (2000) Front Engine Mounting (LH) B : 1 / C : 12 pcs.
T10L010 12361-60022 LAND CRUISER FJ40, FJ42 Front Engine Mounting B : 2 / C : 24 pcs.	T10L030 12361-61020, 61030 LAND CRUISER FJ60V Front Engine Mounting B : 2 / C : 24 pcs.
T10J740 12361-58030, 58031 LAND CRUISER BJ74, HJ75 Front Engine Mounting B : 2 / C : 24 pcs.	T10L040 12361-61031 LAND CRUISER FJ70 Front Engine Mounting B : 2 / C : 24 pcs.
T10LHJ40 12361-68020 LAND CRUISER HJ40 Front Engine Mounting B : 1 / C : 12 pcs.	T10LHJ70 12361-68051 LAND CRUISER HJ70, FJ70 Front Engine Mounting B : 1 / C : 12 pcs.
T10RYN0F 12361-78110 RYNO Front Engine Mounting B : 2 / C : 24 pcs.	T10ST162 12361-63071 ST150, ST162 Front Engine Mounting (FR, A/T) B : 2 / C : 24 pcs.
T10Y510 12361-35050, 54121, 05010 TIGER Y51, Y56, Y60, LN106 Front Engine Mounting B : 2 / C : 24 pcs.	T10VG020 12361-0L030 HILUX VIGO (2WD), (4WD) Front Engine Mounting B : 2 / C : 24 pcs.
T10SX80F 12361-74090 SX80, SX81 Front Engine Mounting (FR) B : 2 / C : 24 pcs.	T10870L 12362-46020 MS133, JZS133 Front Engine Mounting (FR, LH) B : 1 / C : 12 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T10KD20B 12361-75080, 12361-75100 KDH200 (B) Front Engine Mounting (LH, RH)  B : 2 / C : 24 pcs.	T10KD20D 12361-30090 KDH200 (D) Front Engine Mounting (LH, RH)  B : 2 / C : 24 pcs.
T10VG02B 12305-0C011, 12306-0C011 FORTUNER VIGO (B) Front Engine Mounting (LH, RH)  B : 2 / C : 24 pcs.	T10VJ95R 12361-62110 PRADO VZJ (1995) Front Engine Mounting (RH)  B : 2 / C : 24 pcs.
T10G10L 12362-62050 5VXFE, VCH1#VCH2# Front Engine Mounting (LH)  B : 2 / C : 24 pcs.	T10G10R 12361-62120 5VXFE, VCH1#VCH2# Front Engine Mounting (RH)  B : 2 / C : 24 pcs.
T10G100 12361-62140, 12361-62160 PRADO 5VZFE, VZJ9# Front Engine Mounting  B : 2 / C : 24 pcs.	
T10KM361 12361-13030 5K, 7K, KM36, KR42 Front Engine Mounting  B : 2 / C : 24 pcs.	T10KM362 12362-13011 5K, 7K, KM36, KR42 Front Engine Mounting  B : 2 / C : 24 pcs.
T10W11R 12305-28120 WISH ANE11 Front Engine Mounting (RH)  B : 1 / C : 12 pcs.	



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T11030 12371-33010 RT80, RN25 Rear Engine Mounting  B : 2 / C : 24 pcs.	T11040 12371-34020 RT100 Rear Engine Mounting  B : 2 / C : 24 pcs.
T11230 12371-24010, 12371-13010 KE20, KE30 Rear Engine Mounting  B : 4 / C : 48 pcs.	
T11240 12371-13030 KE70 Rear Engine Mounting  B : 2 / C : 24 pcs.	T1125E 12371-15121 AE80 Rear Engine Mounting (RE)  B : 2 / C : 24 pcs.
T11270 12363-15020 AE92 Rear Engine Mounting  B : 2 / C : 24 pcs.	T11280 12363-11010 EE90 Rear Engine Mounting  B : 2 / C : 24 pcs.
	T11460 12371-34030 LN85, RT104 Rear Engine Mounting  B : 2 / C : 24 pcs.
	T1147XS 33183-34030 TIGER LN111 (4WD) Damper Transfer Rear Mounting (SMALL)  B : 4 / C : 48 pcs.
T114X0 12371-54050, 54060 LN56, LN106 Rear Engine Mounting  B : 1 / C : 15 pcs.	T11610 12371-40020 RH20 Rear Engine Mounting  B : 6 / C : 72 pcs.
T11630 12371-39025 RH30 Rear Engine Mounting  B : 6 / C : 72 pcs.	T11870 12371-46011 JZS133, 1J Rear Engine Mounting  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T11640 12303-72010-IN YH, LH60 Rear Engine Mounting  B : 2 / C : 24 pcs.	T11640E 12303-72010 YH, LH60 Rear Engine Bush  B : 4 / C : 48 pcs.
T11650 12303-54020-IN, 12303-67021-IN YH, LH112 Rear Engine Mounting (M/T)  B : 2 / C : 24 pcs.	T11650E 12371-67051 YH, LH112 Rear Engine Bush  B : 4 / C : 48 pcs.
T1165A 12303-67031-IN, 12371-67051-IN LH112 Rear Engine Mounting (A/T)  B : 2 / C : 24 pcs.	T11860 12371-70030 MS132 Rear Engine Mounting  B : 2 / C : 24 pcs.
T11920 12371-56010 BU10 Rear Engine Mounting  B : 4 / C : 48 pcs.	T11930 12371-59025, 87305 BU20 Rear Engine Mounting  B : 4 / C : 48 pcs.
T11B61Z 12371-56041 BU61 Rear Engine Mounting  B : 1 / C : 12 pcs.	T11C0200 12372-03090, 74570 CAMRY SXV10, SXV20 Rear Engine Mounting  B : 1 / C : 12 pcs.
T11GS151 12371-70050 GS151, G1 Rear Engine Mounting  B : 1 / C : 12 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T11VG030 12371-0L030 VIGO KUN15, KUN16 Rear Engine Mounting  B : 2 / C : 24 pcs.	T11VG020 12371-0C120 VIGO, FORTUNER (2005) (4WD) Rear Engine Mounting  B : 1 / C : 8 pcs.
T11VG050 12371-0L050 VIGO TGN26 Rear Engine Mounting  B : 2 / C : 24 pcs.	T11VG070 12371-0C070 VIGO KUN15 Rear Engine Mounting (M/T)  B : 2 / C : 24 pcs.
T11VG080 12371-0L080 VIGO (4WD), KUN25, 26 Rear Engine Mounting  B : 1 / C : 8 pcs.	T11RX60 12371-54040 CRESSIDA RX60, LX80, 2L# Rear Engine Mounting  B : 2 / C : 24 pcs.
T11KD20E 12360-75020 KDH 200 Rear Engine Bushing  B : 4 / C : 48 pcs.	T11KD200 12380-30010-IN KDH 200 Rear Engine Mounting  B : 2 / C : 24 pcs.
T11LS400 12371-50060 LEXUS, LS400 (1994-2000) Rear Engine Mounting  B : 1 / C : 12 pcs.	T11VZJ95 12371-67020 LAND CRUISER, PRADO KZJ95, RZJ95, VZJ95, LJ950 Rear Engine Mounting  B : 1 / C : 8 pcs.
T11UZ10 12371-50080, 12371-50081 LAND CRUISER (1988), UZJ100 Rear Engine Mounting  B : 1 / C : 12 pcs.	T11LJ90 12371-54160 PRADO (1996-2002) Rear Engine Mounting  B : 1 / C : 8 pcs.
T11GS400 12371-46160 GS400 (1998-2005), GS430 (2001-2005), LEXUS IS300 (2001-2005), GS300 (1998-2005) Rear Engine Mounting  B : 1 / C : 12 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

T1306F 48609-14040 TT141, TT132 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	
T1308F 48609-20220 ST171 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T1308E 48750-20050 ST171, AT190 Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 
T1310F 48609-20281 AT190, ST190 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T1311F 48609-20410 EXSIOR Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T1322F 48609-12030 KE20 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T1323F 48609-12050 KE30 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T1324F 48609-16010 KE70 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	
T1324L 48609-12100 KE70 Shock Absorber Mounting (FR, LH) B : 1 / C : 20 pcs. 	T1324R 48603-12010 KE70 Shock Absorber Mounting (FR, RH) B : 1 / C : 20 pcs. 
T1325E 48750-12020 AE80 Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 	T1325F 48609-20060 AE80 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T1326F 48609-12151 EE80, ST150 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T1328F 48609-12190, 12192 EE90, AE92 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 



is the registered trademark



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

T1330F 48609-12270 AE101, EE100 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T1331F 48609-12330, 48609-12350 AE110, AE111 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T1330EL 48072-12130, 12140 EE100, AE101, AE111, AE112 Shock Absorber Mounting (RE, LH) B : 1 / C : 20 pcs. 	T1330ER 48071-12130, 12140 EE100, AE101, AE111, AE112 Shock Absorber Mounting (RE, RH) B : 1 / C : 20 pcs. 
T1332F 48609-12370 AE112, HI-TORQUE Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	
T1395E 48750-10010 EP70 Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 	T1395F 48609-10060 EP70 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13EP80F 48609-10090 EP80 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	
T13RV1F 48609-42010 RAV4, SXA11 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13RX60F 48609-22010 CRESSIDA RX60 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13AH20F 48609-28040 ALPHARD AHR20, ESTIMA AHR20, ALPHARD ANH20 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	
T13F65F0 48609-BZ070 AVANZA F651 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

T13C02F 48609-33011 CAMRY SXV10 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	
T13C02EL 48760-06020 CAMRY SXV10 Shock Absorber Mounting (RE, LH)  B : 1 / C : 20 pcs.	T13C02ER 48750-06020 CAMRY SXV10 Shock Absorber Mounting (RE, RH)  B : 1 / C : 20 pcs.
T13C03L 48609-06070 CAMRY SXV20 Shock Absorber Mounting (LH)  B : 1 / C : 20 pcs.	T13C03R 48603-06020 CAMRY SXV20 Shock Absorber Mounting (RH)  B : 1 / C : 20 pcs.
T13C03EL 48760-06040 CAMRY SXV20 Shock Absorber Mounting (RE, LH)  B : 1 / C : 20 pcs.	T13C03ER 48750-06040 CAMRY SXV20 Shock Absorber Mounting (RE, RH)  B : 1 / C : 20 pcs.
T13C04F 48609-33170, 48609-48020 CAMRY (2002) ACV30, HARRIER MCU35 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	T13CR19F 48609-06410 CAMRY ASV71 (2019) Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.
T13C04EL 48760-33100 CAMRY ACV30 Shock Absorber Mounting (RE, LH)  B : 1 / C : 20 pcs.	T13C04ER 48750-33100 CAMRY ACV30 Shock Absorber Mounting (RE, RH)  B : 1 / C : 20 pcs.
T13C05EL 48760-06120 CAMRY (2007) ACV40, (2012) ACV50, ACV51, ASV50, AVV50 Shock Absorber Mounting (RE, LH)  B : 1 / C : 20 pcs.	T13C05ER 48750-06120 CAMRY (2007) ACV40, (2012) ACV50, ACV51, ASV50, AVV50 Shock Absorber Mounting (RE, RH)  B : 1 / C : 20 pcs.
T13S01F 48609-16220 SOLUNA (AL50) Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	T13S01E 48750-0A020 SOLUNA (AL50) Shock Absorber Mounting (RE)  B : 2 / C : 40 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

T13S01FR0 48609-16310 SOLUNA (2000) Shock Absorber Mounting (FR, RH) B : 1 / C : 20 pcs. 	T13S01FL0 48609-16280 SOLUNA (2000) Shock Absorber Mounting (FR, LH) B : 1 / C : 20 pcs. 
T13VG02 48609-0K010 HILUX VIGO (2WD), REVO Shock Absorber Mounting B : 1 / C : 20 pcs. 	T13VG04 48609-0K040, 0K070 HILUX VIGO, REVO (4WD), FORTUNER (2005, 2015) Shock Absorber Mounting B : 1 / C : 20 pcs. 
T13NC42F 48609-0D080 SOLUNA VIOS (2003) NCP42 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13NC42E 48755-0D090 NCP12, NCP13, NCP30, NCP42 Shock Absorber Mounting (RE) B : 10 / C : 200 pcs. 
T13GX81F 48609-22070 GX81 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	
T13Z121F 48609-12420 ALTIS ZZE121, ZZE122 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13SV30F 48609-32100 SV30 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13CV40EL 48760-32150 CV4, SV4 Shock Absorber Mounting (RE, LH) B : 1 / C : 20 pcs. 	T13CV40ER 48750-32150 CV4, SV4 Shock Absorber Mounting (RE, RH) B : 1 / C : 20 pcs. 
T13GS151F 48680-22020 GS151 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13GX90E 48755-30040, 22020 GX90, JZX90, LX90, SX90 Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 
T13CV40F 48609-32150 CV4, SV4 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13T11F 48609-28010 TCR11, LUCIDA, ASTIMA Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

T13LE01L 48609-33121 MCV15, MCV20, LEXUS Shock Absorber Mounting (LH) B : 1 / C : 20 pcs. 	T13LE01R 48603-33021 MCV15, MCV20, LEXUS Shock Absorber Mounting (RH) B : 1 / C : 20 pcs. 
T13GRJ12F 48609-60040 GRJ120 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13VZJ95F 48609-35030 VZJ95 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13W11F 48609-13010 WISH ANE11 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13Z141F 48609-02220, 02200, 12530 ALTIS ZZE141, ZRE171, ZRE172 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13C01EL 48760-33011 ES300 Shock Absorber Mounting (RE, LH) B : 1 / C : 20 pcs. 	T13C01ER 48750-33011 ES300 Shock Absorber Mounting (RE, RH) B : 1 / C : 20 pcs. 
T13NC91F 48609-0D050 YARIS NCP91, NCP93, VIOS Shock Absorber Mounting (FR) B : 2 / C : 40 pcs. 	T13CT190E 48750-21020, 20150 CT190, ST19#ST215 Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 
T13ST204F 48609-20401 ST204, ST205 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	T13AT15E 48750-32010 AT15# Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13NC50F 48609-0D150, 48609-0D180 VIOS NCP150, YARIS NSP152 SIENIA NSP170, ETIOS Shock Absorber Mounting (FR LH, RH) B : 1 / C : 20 pcs. 	T13ST184F 48609-20240 CELICA ST184 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
T13PZ30F 48609-47030, 48609-47040 PRIUS ZVW30, ZVW30R Shock Absorber Mounting B : 1 / C : 20 pcs. 	T13GR182F 48609-30060, 48609-30061 GRS 182 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 



is the registered trademark



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

T13Z121EB 48750-02020, 48750-0D180 ALTIS (2003) ZZE121-122, (2008) ZZE141-142, (2014) ZZE171-172, SIENTA (2007) NSP170 Shock Absorber Rubber (RE, LOWER, BIG)  B :10 / C : 200 pcs.	T13Z121ES 48755-02020, 48755-0D210 ALTIS (2003) ZZE121-122, (2008) ZZE141-142, (2014) ZZE171-172, SIENTA (2007) NSP170 Shock Absorber Rubber (RE, UPPER, SMALL)  B :20 / C : 400 pcs.
T13RV30F 48609-42020 RAV4, ACV30, ALA30 Shock Absorber Mounting (FR)  B :1 / C : 20 pcs.	T13C05F 48609-06230, 06210, 06340, 06360 CAMRY (2007) ACV40, (2012) ACV50, ACV51, ASV50, AVV50 Shock Absorber Mounting (FR)  B :1 / C : 20 pcs.
T13NCP91E 48755-0D060, 0D100 YARIS NCP 91, VIOS NCP42, NCP150, NCP152 Shock Absorber Rubber (RE)  B :12 / C : 240 pcs.	T13NC91E0 48752-0D020 YARIS NCP91, VIOS NCP150, NCP152, ETIOS Shock Absorber Rubber (RE)  B :12 / C : 240 pcs.
T13UZ10F 48609-60070 LAND CRUISER GRJ200, UZJ200, VDJ200 Shock Absorber Mounting (FR)  B :1 / C : 20 pcs.	T13UZ20F 48609-60080 LEXUS LX570, URJ201 Shock Absorber Mounting (FR)  B :1 / C : 20 pcs.
T13U0001 90303-22049 EE80, AE80, ST150, ST171, AT190, AE101, ALTIS, SOLUNA, VIOS, SOLUNA 1999-2000 Seal, Shock  B :12 / C : 660 pcs.	T13US40E0 48755-50121 LEXUS LS450 (2006) USF40 Shock Absorber Mounting (RE)  B :1 / C : 16 pcs.
T13ZE171F 48609-02310 ALTIS (2018), ZRE171 Shock Absorber Mounting (FR)  B :1 / C : 20 pcs.	
T13CH18F 48609-F4020 C-HR (2018), ALTIS (2019), COROLLA CROSS Shock Absorber Mounting (FR)  B :1 / C : 16 pcs.	
T13PW30EP 48755-12100 PRIUS ZVW30 Shock Absorber Rubber (RE, UP)  B :10 / C : 200 pcs.	T13PW30EW 48341-75010-3 PRIUS ZVW30 Shock Absorber Rubber (RE, LOW)  B :10 / C : 200 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T1407F 48331-20040 ST172, ST150, ST190 Shock Absorber Bumper (FR)  B : 10 / C : 120 pcs.	T1408E 48341-20120 ST171 Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.
T1411E 48341-32052 ST190, 191 CAMRY (1993) SXV10, (1998) SXV20, (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50 AVV50 Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.	T1422F 48331-12010 KE20 Shock Absorber Bumper (FR)  B : 12 / C : 144 pcs.
T1423F 48331-12030 KE30 Shock Absorber Bumper (FR)  B : 12 / C : 144 pcs.	
T1428E 48341-12130 EE90 Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.	T1428F 48331-12100 EE90 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T1429E 48341-12120 AE101 Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.	T1429F 48331-12120 AE101, AT171, AT190, AT191 Shock Absorber Bumper (FR)  B : 10 / C : 120 pcs.
T14C03F 48331-33020 CAMRY SXV10, SXV20 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14C04F0 48331-33031 CAMRY ACV30, ACV40 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T14NC42F 48331-0D040, 48341-10140 VIOS Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14ZE121F 48331-12210 ALTIS ZZE121, 122 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T14W11F0 48331-68020 WISH Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14W11E0 48341-32100 WISH Shock Absorber Bumper (RE)  B : 10 / C : 120 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T14JZ90E 48341-30060 JZX90 Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.	T14SV41F 48331-32090 SV41 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T14NC93F 48331-52080,48331-52100 VIOS NCP93, YARIS NCP91 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14C07F0 48331-33070 CAMRY (2011-2012), ACV51, ASV50, AVV50, GSV50 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T14AC21E 48306-42050 RAV4, ACA21 Shock Absorber Bumper (RE)  B : 2 / C : 24 pcs.	T14AV3E 48341-AA010 AVALON GSX30 (2005-2012) Shock Absorber Bumper (RE,LH,RH)  B : 6 / C : 72 pcs.
T14CH18F 48331-10120 C-HR (2018) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14CH18E2 48750-10100-2 C-HR (2018) Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.
T14AX54F 48331-42140 RAV4 AXAA54 (2019) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14GD30F 48331-26130 COMMUTER GDH300, HIACE GDH322 (2019) Shock Absorber Bumper (FR)  B : 4 / C : 48 pcs.
T14PW20F 48331-47020 PRIUS NHW20 Shock Absorber Bumper (FR,LH,RH)  B : 6 / C : 72 pcs.	T14CR19F0 48331-33090 CAMRY ASV71, AXVA70, AXVH71 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T14AS4F0 48331-42120 RAV4 (2012-2018) ZSA42, 44, AVA44, ALA49, ASA42, 44, HARRIER ZSU60 (2015) Shock Absorber Bumper (FR,LH,RH)  B : 6 / C : 72 pcs.	T14PW30F 48331-21030 PRIUS ZVW30 Shock Absorber Bumper (FR,LH,RH)  B : 6 / C : 72 pcs.
T14SU45E 48341-48050 HIGHLANDER GSU45 (2007-2013) Shock Absorber Bumper (RE,LH,RH)  B : 6 / C : 72 pcs.	T14AH20F1 48331-28050 ALPHARD ANH20, ATH20, GGH20 Shock Absorber Bumper (FR,LH,RH)  B : 6 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

T14AG30F1 48331-58010 ALPHARD AGH30 (2015) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	T14AN10F1 48331-28040 ALPHARD ANH10 (2002-2007), ESTIMA ACR30, ACR40 (2000-2006) Shock Absorber Bumper (LH,RH)  B : 6 / C : 72 pcs.
T14F60F 48331-BZ010 AVANZA F601, F602 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.	T14F65F1 48331-BZ110 AVANZA (2011) F651, F652, (2015) F653, F654 Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
T1431E 48341-12180 AE110, AE111 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	T1431F 48331-12140 AE110, AE111 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
T14S01EZ 48341-0A010-S SOLUNA, TERCEL (1995) Shock Dust Cover (RE, SET)  B : 2 / C : 40 pcs.	T14S01F 48331-0A010 SOLUNA Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
T14SV41E 48341-32090 SV41 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	T14NC15F 48304-0D150, 48331-0D120 VIOS NCP150, YARIS NSP152, ETIOS Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
T1430E 48550-12070 EE90, AE101, ST171, ST190 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	T14NC42E0 48341-0D040 VIOS Shock Dust Cover (RE)  B : 2 / C : 44 pcs.
T14Z121E0 48341-47010, 48341-12230 ALTIS (2003) ZZE121-122, (2008) ZZE141-142, (2014) ZZE171-172, SIENTA (2007) NSP170 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	T14YA91E 48750-0D060 YARIS NCP91, VIOS NCP150, NCP152, ETIOS Shock Dust Cover (RE)  B : 2 / C : 12 pcs.
T14Z12FP 48157-02020 ALTIS ZZE121, 122, 141, 142 Shock Dust Cover (FR, UP)  B : 2 / C : 12 pcs.	T14ST17F 48304-0D250 SIENTA NSP170 Shock Dust Cover (FR)  B : 2 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T1707IZ 43448-32010 ST150, AT171 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T1707UZ 43447-32021 ST150, AT171 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T1728IZ 43448-12040 EE90, AE101, ST171 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T1708UZ 43447-17041 EE90, AE92, AE101, ST171 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T1725IZ 43448-12020 AE80 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T1725UZ 43447-17020 AE80, EP70 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T174X3IZ 43448-35020, 75430-N5020 TIGER LN111 (4WD) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T174X3UZ 43447-35021 TIGER LN111 (4WD) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T1795IZ 43448-10020 EP70 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	
T17C02IZ 43448-20020 CAMRY SXV10, SXV20 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17C02UZ 43447-20030 CAMRY SXV10, SXV20 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17C04IZ 43448-06120 CAMRY ACV30, ACV31 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17C04UZ 43447-06120 CAMRY ACV30, ACV31 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17S01IZ 04438-0A020 SOLUNA Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17S01UZ 04437-0A020 SOLUNA Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T17NC42IZ 43448-52020 VIOS SOLUNA (2000) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17NC42UZ 43447-17011, 17021 VIOS SOLUNA (2000) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17ZE121I 43448-12120 ALTIS ZZE121, ZZE122 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17ZE121U 43447-28020 ALTIS ZZE121, 122, WISH ANE11, ALPHARD ANH20, CAMRY HYBRID AHV40, PRIUS ZVW30 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17Z14IZ 43448-12130 ALTIS ZZE141 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17Z14UZ 43447-12050 ALTIS ZZE141 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17VG04IZ 43448-0K020, 43448-0K060 HILUX VIGO, FORTUNER, REVO (4WD) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17VG04UZ 43447-0K020, 43447-0K060 HILUX VIGO, FORTUNER, REVO (4WD) Drive Shaft Boot (OUTER)  B : 1 / C : 44 pcs.
T17W11IZ 43448-28051, 04428-42110 WISH ANE11, ALPHARD ANH20, CAMRY AHV40, AVV50 HYBRID, PRIUS ZVW30, ESTIMA ACR50 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17AX30UZ 43447-07060 AVALON Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17YA91IZ 43448-0D140 YARIS NCP91 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17YA91UZ 43447-0D140 YARIS NCP91 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17C05IZ 43448-06350 CAMRY ACV40 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17C05UZ 43447-06350 CAMRY ACV40 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
T17C06IZ 43448-06441 CAMRY (2012) ACV50, ACV51, ASV50 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	T17C06UZ 43447-06441 CAMRY (2012) ACV50, ACV51, ASV50 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T17ZJ95IZ 43448-35030 PRADO VZJ95 Drive Shaft Boot (INNER)	 B : 1 / C : 44 pcs.	T17ZJ95UZ 43447-35040 PRADO VZJ95 Drive Shaft Boot (OUTER)	 B : 2 / C : 100 pcs.
T17XT10I 43448-16060 TERCEL Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.		
T17TA10IZ 04438-04011 TACOMA (2001-2002) Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	T17TA10UZ 04438-04021 TACOMA (2001-2002) Drive Shaft Boot (OUTER)	 B : 2 / C : 100 pcs.
T17UZ10IZ 75430-N0336 LAND CRUISER UZJ100 Drive Shaft Boot (INNER)	 B : 1 / C : 44 pcs.	T17UZ10UZ 43447-60030 LAND CRUISER UZJ100 Drive Shaft Boot (OUTER)	 B : 1 / C : 36 pcs.
T17KD12IZ 75430-N0574 LAND KDJ120, GRJ120 Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	T17KD12UZ 43447-60130, 43447-60140 KDJ120, KDJ150, GRJ120, GRJ150 Drive Shaft Boot (OUTER)	 B : 2 / C : 100 pcs.
T17KD15IZ 43448-60130 LAND CRUISER PRADO KDJ150, GRJ150 Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.		
T17NC50IZ 43448-0D350 VIOS NCP150, YARIS NSP152, ETIOS Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	T17NC50UZ 43447-0D350 VIOS NCP150, YARIS NSP152, ETIOS Drive Shaft Boot (OUTER)	 B : 2 / C : 100 pcs.
T17NC93IZ 43448-52030 VIOS NCP93 Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	T17NC93UZ 43447-52011 VIOS NCP93 Drive Shaft Boot (OUTER)	 B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER
 ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
 KLONGTOEI, BANGKOK 10110 THAILAND
 TEL: (66) 2 392 1148
 E-MAIL: rbiautoparts@gmail.com

TOYOTA

T17AV3IZ 43448-07060 AVALON Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	
		T17AS44UZ 43447-44020 CAMRY (2012) AVV50 HYBRID, RAV4 ZSA44, ASA44, ZGZ1# Drive Shaft Boot (OUTER)
T17ST17IZ 43448-0D420 SIENTA NSP170 Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	T17ST17UZ 43447-0D420 SIENTA NSP170 Drive Shaft Boot (OUTER)
T17UR2IZ 43448-60092 LAND CRUISER URJ20#, VDJ200 Drive Shaft Boot (INNER)	 B : 1 / C : 44 pcs.	T17UR2UZ 43447-60092 LAND CRUISER URJ20#, VDJ200 Drive Shaft Boot (OUTER)
T17CH18IZ 43448-F4080, 04438-F4030, 04437-F4030, F4040 C-HR (2018) Drive Shaft Boot (INNER)	 B : 2 / C : 100 pcs.	T17CH18UZ 43447-F4080 C-HR (2018) Drive Shaft Boot (OUTER)
T17NS52IZ 43448-0D320, 43448-0D340 YARIS NSP152 Drive Shaft Boot (LH, RH, INNER)	 B : 2 / C : 100 pcs.	T17NS52UZ 43447-0D320 YARIS NSP152 Drive Shaft Boot (OUTER, LH, RH)
T17AH30UZ 43447-58080 ALPHARD, VELLFIRE AGH30 (2015) Drive Shaft Boot (OUTER)	 B : 1 / C : 44 pcs.	T17AH30IZ 43448-58080 ALPHARD, VELLFIRE AGH30 (2015) Drive Shaft Boot (INNER)
T17ZE21UZ 43420-02F60, 43447-02F60, 0D411, 0D412, 0D561, 0D562, 0D541, 0D542 ALTIS (2019), ZRE210,211, ZWE211, COROLLA CROSS (2020) ZSG10, ZVG10 HYBRID Drive Shaft Boot (OUTER)	 B : 2 / C : 100 pcs.	T17ZE21IZ 43448-02F60, 0D411, 0D412, 0D561, 0D562, 0D541, 0D542, 0D027, 0D390 ALTIS (2019), ZRE210,211, ZWE211, COROLLA CROSS (2020) ZSG10, ZVG10 HYBRID Drive Shaft Boot (INNER)



is the registered trademark

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T1806LZ 45535-22011 TT141 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T1806PZ 45535-20010 TT141 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
T1806RZ 45536-14020 TT141 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.	T1807PZ 45535-20040 ST150, AT171 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
T18100Z 45535-33010 AT190 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	T1811PZ 45535-20080 ST191 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
T1824LBZ 45536-12010 KE70 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T1824RBZ 45535-12010 KE70 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
T1824LSZ 45536-12011 KE70 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T1824RSZ 45535-12011 KE70, AE80 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
T1825LZ 45536-12030 AE80, EE90, AT171 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T1827PZ 45535-12050 AE92 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
T1828PZ 45535-12040 EE90 Steering Gear Boot  B : 2 / C : 50 pcs.	T1829PZ 45535-12070 AE101 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
T18300Z 45535-12060 EE100 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

TOYOTA

T1865LZ 45536-26010 LH112 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T1865RZ 45535-26020 LH112 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
T1865PZ 45535-26030 LH112 Steering Gear Boot (LH, RH, POWER)  B : 2 / C : 50 pcs.	
T1895LZ 45536-10060 EP71, EP82 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T1895RZ 45535-10021 EP71, EP82 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
T1897Z 45535-06080 CAMRY (1994), SXV10, 20 (2.2 cc) Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	T18CV10Z 45535-14011 CV10 Steering Gear Boot  B : 2 / C : 50 pcs.
T18S01PZ 45535-10060 SOLUNA Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	T18L050 45535-35030 PRADO VZJ95 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
T18C040 45535-06040 CAMRY ACV30, ACV31 Steering Gear Boot  B : 2 / C : 50 pcs.	T18NC420 45535-02030 SOLUNA VIOS Steering Gear Boot  B : 2 / C : 50 pcs.
T18VG0L0 45536-0K010 HILUX VIGO Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	T18VG0R0 45535-0K010 HILUX VIGO Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
T18ZE1210 45535-52050 ALTIS ZZE121, ZZE122 Steering Gear Boot  B : 2 / C : 50 pcs.	T18W11LR 45535-13010 WISH ANE11 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T18ZE1410 45535-09110 ALTIS ZZE141, ZZE142 Steering Gear Boot B : 2 / C : 50 pcs. 	T18UZ20Z 45535-60020 LAND CRUISER UZJ200, UZJ202 Steering Gear Boot B : 2 / C : 50 pcs. 
T18NC500Z 45535-09300 VIOS NCP150, YARIS NSP152, ETIOS Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	T18C050Z 45535-33050 CAMRY ACV40 Steering Gear Boot B : 2 / C : 50 pcs. 
T18KD20LR 45535-26060 KDH 200 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	T18C07LR 45535-09250 CAMRY (2012) ACV50, ACV51, ASV50, AVV50 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 
T18NC93Z 45535-09100 VIOS NCP93 Steering Gear Boot B : 2 / C : 50 pcs. 	
T18RV02LR 45535-09380 REVO (2WD) Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	T18RV04LR 45535-09390 REVO (4WD), FORTUNER (2015) Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T19103 48257-30020 MS60 Coil Spring Rubber (THIN, BIG) B : 4 / C : 80 pcs.	T19104 48157-25010T MS60 Coil Spring Rubber (THICK, SMALL) B : 4 / C : 80 pcs.
T19105 48157-30020T MS60 Coil Spring Rubber (THICK, RE, BIG) B : 4 / C : 80 pcs.	T19Z12FW 48158-02030 ALTIS ZZE121, 122, 141, 142 Coil Spring Rubber (LOWER) B : 2 / C : 96 pcs.
T19ZE121 90919-02239 ALTIS ZZE121 Rubber Cover Coil Ignition B : 20 / C : 480 pcs.	T19ZE171 90919-02258 ALTIS ZRE143, ZRE171, BUAL Rubber Cover Coil Ignition B : 20 / C : 480 pcs.
T19912 XX1092 20 mm Water Pump Cap B : 32 / C : 768 pcs.	T19VG02P 90948-T1001 VIGO Shock Absorber Rubber (UPPER) B : 36 / C : 864 pcs.
T192900 11193-15010 AE101 Seal Rocker Cover B : 12 / C : 288 pcs.	T1944W 43345-26010 LN85 Cover Ball Joint (LOWER) B : 12 / C : 192 pcs.
T24P001 90389-19002 AT, ST190 EXSIOR Cover Bush B : 10 / C : 180 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2001E 90385-15039 RT40 Spring Shackle Rubber (RE)  B : 50 / C : 800 pcs.	T2001F 90385-13032 RT40 Spring Shackle Rubber (FR)  B : 16 / C : 384 pcs.
T2004E 90385-05001 RT100 Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.	T2004F 90385-17069 RT100 Spring Shackle Rubber (FR)  B : 12 / C : 192 pcs.
T2022E 90385-10015 KE20 Spring Shackle Rubber (RE)  B : 36 / C : 864 pcs.	T2022F 90385-10014 KE20 Spring Shackle Rubber (FR)  B : 20 / C : 480 pcs.
T2023E 90385-13071 KE30 Spring Shackle Rubber (RE)  B : 36 / C : 864 pcs.	T2023F 90385-13065 KE30 Spring Shackle Rubber (FR)  B : 12 / C : 192 pcs.
T20420 90385-18046 RN20, LN40 Spring Shackle Rubber  B : 20 / C : 480 pcs.	T2065E 90385-18008 LH112 Spring Shackle Rubber (RE)  B : 16 / C : 384 pcs.
T20460 90385-18013 LN85 Spring Shackle Rubber  B : 16 / C : 384 pcs.	T2047XE 90385-18020 TIGER LN111 Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.
T204X1E 90385-18007 LN56, TIGER LN111 Spring Shackle Rubber (RE)  B : 20 / C : 320 pcs.	T20620 90385-18058 RH20 Spring Shackle Rubber  B : 14 / C : 336 pcs.
T2092E 90385-18025 JU, BU Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.	T2092F 90385-23037 BU Spring Shackle Rubber (FR)  B : 10 / C : 160 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T20BJ40F 90385-15016 LAND CRUISER BJ40 Spring Shackle Rubber (FR, RE)  B : 30 / C : 720 pcs.	T20AT196 90385-15005 CALDINA AT196 Spring Shackle Rubber  B : 20 / C : 480 pcs.
T20L01B 90385-18009 LAND CRUISER Spring Shackle Rubber (BIG)  B : 10 / C : 160 pcs.	T20L01S 90389-18002 LAND CRUISER Spring Shackle Rubber (SMALL)  B : 12 / C : 192 pcs.
T20VG02F 90385-T0003 HILUX VIGO (2WD) Spring Shackle Rubber (FR)  B : 16 / C : 384 pcs.	
T20VG0EL 90385-T0001, 90385-T0009 VIGO, REVO (2WD, 4WD) Spring Shackle Rubber (RE, LONG)  B : 20 / C : 320 pcs.	T20VG0ES 90385-T0002, 90385-T0010 VIGO, REVO (2WD, 4WD) Spring Shackle Rubber (RE, SHORT)  B : 20 / C : 480 pcs.
T20HZ700 90385-18021 LAND CRUISER (1999-2004), HZJ7# Spring Shackle Rubber (RE)  B : 8 / C : 128 pcs.	T20HZ70E 90385-18022 LAND CRUISER (1993-2004), HZJ7#, PJZ70 Spring Shackle Rubber (RE)  B : 8 / C : 128 pcs.
T20BB4E0 90385-23002 COASTER N04C, XZB50 Spring Shackle Rubber (RE)  B : 10 / C : 160 pcs.	
T20GD30E 48457-26010 COMMUTER, HIACE (2019) GDH300 Spring Shackle Rubber (RE)  B : 8 / C : 128 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21010 48815-20020 RT40 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	T21040 48815-20090 RT100 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.
T21060 48815-14150 TT141 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	
T2108E 48818-20080 AT171, ST171 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T2108F 48815-30060 AT171, ST171 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T2109E 48818-20280 AT191, ST191 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T2109F 48815-30040 ST190, ST191 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21220 48815-12010 KE20 Stabilizer Shaft Rubber  B : 18 / C : 432 pcs.	T21231 48815-12050 KE30 (17 mm) Stabilizer Shaft Rubber  B : 14 / C : 336 pcs.
T21232 48815-12080 KE36 (19 mm) Stabilizer Shaft Rubber  B : 14 / C : 336 pcs.	T21240 48815-14020 KE70 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.
T21250 48815-24010 AE80 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	
T2128E 48818-12050 EE90, AE92 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T2128F 48815-12160 EE90, AE92 Stabilizer Shaft Rubber (FR)  B : 12 / C : 192 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2130E 48818-20070, 48818-12150 EE100, AE101, AE111 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T2130F 48815-12230, 48815-12220 EE100, AE101 Stabilizer Shaft Rubber (FR)  B : 20 / C : 320 pcs.
T21420 48815-20030 RN20, LN40 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	T21460 48815-14160 LN85 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.
T21640 48815-26020 YH, LH60 Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.	T21650 48815-26060 YH, LH112 Stabilizer Shaft Rubber  B : 10 / C : 240 pcs.
T2166E 48815-26140 RZH135 Stabilizer Shaft Rubber (LH, RE)  B : 10 / C : 240 pcs.	T2167E 48815-26160 RZH135 Stabilizer Shaft Rubber (RE)  B : 10 / C : 240 pcs.
T21820 48815-30050 MS60, LN56, NADIA 4 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	T21860 48815-30171 MS132 Stabilizer Shaft Rubber  B : 10 / C : 160 pcs.
T21920 48815-36012 BU Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.	T21C01E 48815-32110, 48815-32060 CAMRY Stabilizer Shaft Rubber (RE)  B : 6 / C : 96 pcs.
T21C02E 48818-06051 CAMRY SXV10 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	T21C02F 48815-06030 CAMRY SXV10 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.
T21C03E 48818-06100 CAMRY SXV20 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	T21C03F 48815-33040 CAMRY SXV20 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21C04F00 48815-33090 CAMRY ACV30, ACV31 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21C04E00 48818-06180,21030 CAMRY ACV30, ACV31, MCV30, MCV31, ST215 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.
T21GY04F 48815-38010 IPSUM, GAYA (4WD) Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21KF40F 48815-16010 KF40 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21L01E 48815-60010 LAND CRUISER Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	T21NC42F 48815-0D040 VIOS Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21S01F 48815-0A010 SOLUNA Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21SV30F 48815-32090 SV3, SV4 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21TCR11 48815-28030 LITE, ACE, TCR11 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	T21GX900 48815-22150 MARK II, GX90 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
T21VG02C 48815-0K070 HILUX VIGO (2WD) (CAP4), REVO, SCB, XTR Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	T21VG02F 48815-0K050 HILUX VIGO (2WD), REVO, DCB Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21VG04F 48815-0K010, 48815-0K020 HILUX VIGO (4WD), INNOVA KUN40 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	T21XT10F 48815-10060 TERCEL Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
T21ZE120F 48815-13040 ALTIS ZZE122 (1.8 cc) Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21ZE121F 48815-02060 ALTIS ZZE121, ZZE122 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER
 ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
 KLONGTOEI, BANGKOK 10110 THAILAND
 TEL: (66) 2 392 1148
 E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21AZT22F 48815-05050 AVENSIS, ATZZ#, AZT22# Stabilizer Shaft Rubber (FR)  B : 12 / C : 192 pcs.	T21AZT22E 48818-05041 AVENSIS, ATZZ#, AZT22# Stabilizer Shaft Rubber (RE)  B : 12 / C : 192 pcs.
T21C003F 48815-33050 SXV20 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	T26FJ95F 48815-35100 PRADO FJ95 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.
T21GY02F 48815-44010 IPSUM, GAYA Stabilizer Shaft Rubber (FR)  B : 12 / C : 192 pcs.	T21RV01F 48815-42010 RAV4, SXA10, SXA15 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21ND02F 48815-44020 NADIA, PLTC (2WD) Stabilizer Shaft Rubber (FR)  B : 12 / C : 192 pcs.	
T21VP02F 48815-52030 ECHO, YARIS, VITZ, P LATZ (2WD) Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21ST182F 48815-20200 HILUX, KZN13#, ST182 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T2131F 48815-12280 AE110 COROLLA Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21RX0F 48815-22040 RX70, RX81, GX81, SX80 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
T21CM30F 48815-30120 CM30 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21CM4F 48815-30100 LITEACE, CM60, YM60 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21AV3E 48818-12170 AVALON GSX30 (2005-2012) Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T21GU45E 48818-48030 GSU45 (2007-2013) Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21CR5F 48815-28070 LITEACE, TOWNACE NOAH CR5# Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21CV00E 48818-21020, 31020, 32080 CV43, SV43 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.
T21KD20F 48815-26370 HIACE, KDH2 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	T21CV40E 48818-32120, 48818-32100 CV40, SV40, SV41, SV42 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
T21670F 48815-26221 RZH135 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21BJ70F 48815-60040 LAND CRUISER BJ70 Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
T21RV1F 48815-42020 RAV4, SXA11 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	
T21C05E 48818-06220 CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T21C05F 48815-06200 CAMRY (2007) ACV40, (2012) ACV51, ASV50 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
T21YA91F 48815-0D110, 48815-0D190 YARIS NCP91, NCP152, VIOS NCP150, ETIOS Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	
T21AC21F 48815-42050 ACA21 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21CX10F 48815-28061 CXR10 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21FZ80F 48815-60070 FZJ80 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21GR21F 48815-14140 GRN21#, KZN215 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21LJ90F 48815-16170 LJ9# Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.	T21T11F 48815-28040 LUCIDA, TCR11 Stabilizer Shaft Rubber (FR) B : 8 / C : 128 pcs.
T21RV02E 48818-42010 RAV4, ACV30, ACV33, ALA30 Stabilizer Shaft Rubber (RE) B : 12 / C : 288 pcs.	T21RV02F 48815-42030 RAV4, ACV20, ACV22, CLA20, ZCA25 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.
T21AC30F 48815-28150 ACR30, ESTIMA, ALPHARD (MNH10) Stabilizer Shaft Rubber (FR) B : 10 / C : 160 pcs.	T21GRJ12F 48815-60160, 48815-60180 GRJ120 Stabilizer Shaft Rubber (FR) B : 6 / C : 96 pcs.
T21Z141F 48815-02240 ALTIS ZZE141 Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs.	T21Z141F0 48815-02230 ALTIS ZZE141 (24 mm) Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs.
T21AC20F 48815-42040 RAV4, ACA20, CLA21, ZCA26 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.	T21C003E 48818-33060, 48818-07010 SXV20, MCV20, MCX20 Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs.
T21C031E 48818-21050, 48818-20290 CAMRY SXV25, MCV25 (2004-2006) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs.	
T21C05F0 48815-33100, 48815-06170 CAMRY ACV41 Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs.	T21C06F 48815-33110 CAMRY ACV35, ACV45 Stabilizer Shaft Rubber (FR) B : 12 / C : 192 pcs.
T21GV40F 48815-06180 GSV40 Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs.	T21LE01F 48815-33011 LEXUS ES300, MCV10, VCV10 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.



is the registered trademark

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21UZ20F 48815-60250 UZJ200, GRJ200, VDJ200 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	T21UZ20E 48815-60241 LAND CRUISER (2007) GRJ200, URJ20#, UZJ200, VDJ200 Stabilizer Shaft Rubber (RE)  B : 6 / C : 96 pcs.
T21AC30L 48815-42090 ACA3#, ALA30, GSA3# (23.4) Stabilizer Shaft Rubber (LH)  B : 6 / C : 96 pcs.	T21AC30R 48815-42100 ACA3#, ALA30, GSA3# Stabilizer Shaft Rubber (RH)  B : 6 / C : 96 pcs.
T21AC38L 48815-42070,42020 RAV4 (2005-2007) ACA38, PRIUS ZVW30 (22.2 mm) Stabilizer Shaft Rubber (LH)  B : 6 / C : 96 pcs.	T21AC38R 48815-42080,47030 RAV4 (2005-2007) ACA38, PRIUS ZVW30 (22.2 mm) Stabilizer Shaft Rubber (RH)  B : 6 / C : 96 pcs.
T21AC50L 48815-28180 ACR50 Stabilizer Shaft Rubber (LH)  B : 6 / C : 96 pcs.	T21AC50R 48815-28190 ACR50 Stabilizer Shaft Rubber (RH)  B : 6 / C : 96 pcs.
T21AC55L 48815-28200 ACR55, AHR20, GSR50 Stabilizer Shaft Rubber (LH)  B : 6 / C : 96 pcs.	T21AC55R 48815-28210 ACR55, AHR20, GSR50 Stabilizer Shaft Rubber (RH)  B : 6 / C : 96 pcs.
T21880E 48818-30090 JZS155 Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.	T21CR50F 48815-28090 CR50, SR50 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21FZ76F 48815-60210 FZJ76, HZJ76 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21GS151 48815-30470 GS151 Stabilizer Shaft Rubber  B : 10 / C : 160 pcs.
T21HD100F 48815-26250, 48815-60140 HDJ100, UZJ100, KCH46, RCH47 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21KC100F 48815-26260, 48815-26330 KCH10, KLH22, KC1H1, LXH22 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21KC10F 48815-26200 KCH10, KLH12, LXH12, RCH11 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21KC16F 48815-26340 KCH16, VCH16 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
T21KC400F 48815-26270 KCH40, RCH41, RZU280, BU28# Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	T21KC40F 48815-26240 KCH40, RCH41 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.
T21LH12F 48815-26300 LH12#, RZH10, YH53, TRH10 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21UZ10F 48815-60150 HDJ100, HDJ101, UZJ100 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.
T21FZ70F 48815-60170 FZJ7#, HDJ7#, HZJ7#, VDJ Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21FJ80F 48815-60050 FJ80, HDJ80, HZJ80 Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
T213101F 48815-12200 AE101 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21310F 48815-12210 AE101, AE111 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21311F 48815-12300 AE111 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	
T21652F 48815-26230 KCH16, LXH18, LH56, YH56 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21880F 48815-30400 JZS155 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
T21GS10F 48815-30180 GS131, MS135, JZS131 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21SR50F 48815-28100 SR50, CM75, CM8#, CR52, KM75, KM8#, KR52 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21UZ12F 48815-60200 UZJ120 Stabilizer Shaft Rubber (FR)  B : 4 / C : 64 pcs.	T21UZ22F 48815-60220 UZJ200, VDJ200 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21090F 48815-20220 ST191 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	
T21280F 48815-12180 AE92, AE95, CE95, EE90 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	T21280E 48818-12070 AE92, EE90 (1987-1993) Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.
T21300E 48818-12180, 12250, 20120 AE101, AE11#, CDE110, ZZE11#, SV25 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	
T21340E 48818-12200, 12140 AE104, CE104 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	T213400E 48818-12190, 12130 AE104 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
T21AT200E 48818-20390 AT200, ST20# Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	T21AZ241E 48818-21080, 48818-21090 AZT241, AZT255, ZZT241, ANT10, ST246 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
T21AZ55E 48818-32130 AZV55, SV55, ZZT245, ZCT15 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	T21C03F 48815-33040 SXV20 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
T21CE90E 48818-12080 CE90 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	T21E124E 48818-12260, 63010 NZE14, NZE124, ZZE124, ZZE129 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21ST205F 48815-20260, 20270 ST202, ST205, ST206 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21ST205E 48818-20380 AT200, ST200, ST202, ST204, ST206, ST208 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.
T21ST215F 48815-21010 ST215, CT216 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	T21UZ2F 48815-60260 UZJ200, VDJ200 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21C002E 48818-33040 SXV20, MCV20, SXV20# Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	
T21F60F 48815-BZ010 AVANZA F601, F602 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	T21W110F 48815-20290 WISH ANE11 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
T21AC2F 48815-42060 ACA2# Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	T21RV04F 48815-0K090 REVO (4WD), FORTUNER (2015) (32 mm) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21KJ90E 48815-10090 KZJ90, LJ90, RZJ90, VZJ90, GRJ120 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	T21T231E 48818-20350 ZZT231, ANE11, WISH Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.
T21GR150E 48818-60040 GRJ15#, KDJ15#, LJ15#, TRJ15# Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.	T21GR150F 48815-60380 GRJ15#, KDJ15#, LJ15#, TRJ15# Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21GR151E 48818-60020 PRADO GRJ150, KDJ150 Stabilizer Shaft Rubber (RE)  B : 6 / C : 96 pcs.	T21GR151F 48815-60320 PRADO GRJ150, KDJ150 Stabilizer Shaft Rubber (FR)  B : 4 / C : 64 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21ZE151L 48815-12370 ADE150, NDE150, ZRE151, ZRE152, ZZE150 (21.2 mm) Stabilizer Shaft Rubber (LH)  B : 6 / C : 96 pcs.	T21ZE151R 48815-12390 ADE150, NDE150, ZRE151, ZRE152, ZZE150 (21.2 mm) Stabilizer Shaft Rubber (RH)  B : 6 / C : 96 pcs.
T21AC200F 48815-44030, 48815-44040 ACM21, ACM2#, ACM20, ACM26, CLM20 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	T21NC93F 48815-0D081 VIOS NCP93 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
T21BB4E0 48815-60020 COASTER N04C XZB50 Stabilizer Shaft Rubber (RE)  B : 10 / C : 240 pcs.	T21ST17F 48815-0D220 SIENTA NSP170 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
T21CH18F 48815-F4020 C-HR (2018) Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	T21CH18E 48818-F4030 C-HR (2018) Stabilizer Shaft Rubber (RE)  B : 6 / C : 96 pcs.
T21AS4E0 48818-42020 RAV4 (2012), ASA4#, ZSA4# Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	
T21AS4FL 48815-48090 RAV4 (2012), ASA4#, ZSA4# Stabilizer Shaft Rubber (FR, LH)  B : 6 / C : 96 pcs.	T21AS4FR 48815-48080 RAV4 (2012), ASA4#, ZSA4# Stabilizer Shaft Rubber (FR, RH)  B : 6 / C : 96 pcs.
T21GR18E 48818-30160 CROWN GRS182 Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.	T21GU45F 48815-48070 HIGHLANDER GSU45 (2007-2013) Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
T21CR19F 48815-06280 CAMRY ASV71, AXVA70, AXVH71 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	T21CR19E 48818-06370 CAMRY ASV71, AXVA70, AXVH71 Stabilizer Shaft Rubber (RE)  B : 8 / C : 128 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T21F65F0 48815-BZ150 AVANZA F653 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	T21GD30F 48815-26390 COMMUTER GDH300, HIACE GDH322 (2011) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
T21GG30FL 48815-58021 ALPHARD GGH30 (27.2 mm) Stabilizer Shaft Rubber (FR, LH)  B : 6 / C : 96 pcs.	T21GG30FR 48815-58031 ALPHARD GGH30 (27.2 mm) Stabilizer Shaft Rubber (FR, RH)  B : 6 / C : 96 pcs.
T21GR182F 48815-30551 CROWN GRS182 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	T21ZE21F 48815-02390 ALTIS (2019), ZRE210, ZWE211 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.
T21AG30E 48818-58010 ALPHARD, VELLFIRE AGH30, AYH30 Stabilizer Shaft Rubber (RE)  B : 6 / C : 144 pcs.	T21C05F1 48815-06230 CAMRY AVV50 HYBRID Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
T22010 48817-20010 RT40 Stabilizer Shaft Grommet  B : 30 / C : 1,500 pcs.	T22220 48817-12010 KE20, KE30 Stabilizer Shaft Grommet  B : 50 / C : 2,500 pcs.
T2225E 90385-11021 AE80, AE92, LN106 Stabilizer Shaft Grommet  B : 30 / C : 1,500 pcs.	T22670 90385-13008 RZH135 Stabilizer Shaft Grommet  B : 20 / C : 1,000 pcs.
T22810 48817-30010 MS60 Stabilizer Shaft Grommet  B : 50 / C : 1,200 pcs.	T22NC42 48817-52010 VIOS NCP42, NCP150, YARIS NCP152 Stabilizer Shaft Grommet  B : 32 / C : 2,080 pcs.
T22GR150F 48849-60040 PRADO GRJ150, KDJ150 Stabilizer Shaft Grommet (FR)  B : 8 / C : 128 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T23021 48675-22010 RT60 Strut Bar Rubber (Without Edge)  B : 16 / C : 256 pcs.	T23022 48674-22010 RT60 Strut Bar Rubber (Without Edge)  B : 16 / C : 256 pcs.
T2322Y 48674-12010 KE20 Strut Bar Rubber  B : 20 / C : 320 pcs.	T2323Y 48674-12080 KE30 Strut Bar Rubber  B : 20 / C : 320 pcs.
T2324Y 48674-14020 KE70 Strut Bar Rubber  B : 20 / C : 320 pcs.	T2344Y 48674-39045 LN40, RN30 Strut Bar Rubber  B : 20 / C : 320 pcs.
T2346Y 48674-22021 LN85, TIGER Strut Bar Rubber  B : 20 / C : 320 pcs.	T2365Y 48674-26010 LH112, LH60 Strut Bar Rubber  B : 12 / C : 192 pcs.
T2382Y 48674-30020 MS50, MS60 Strut Bar Rubber  B : 16 / C : 256 pcs.	T2384Y 48674-30040 MS110 Strut Bar Rubber  B : 20 / C : 320 pcs.
T2385Y 48674-30031 MS120, MS132 Strut Bar Rubber  B : 15 / C : 360 pcs.	T2367Y 48674-26021 RZH135 Strut Bar Rubber  B : 12 / C : 192 pcs.
T23XT10 48674-16030 TERCEL (1993) Strut Bar Rubber  B : 36 / C : 864 pcs.	T23XT11 48675-16040 TERCEL (1993) Strut Bar Rubber  B : 16 / C : 384 pcs.
T23GX81R 48667-22020 GX81 Repainer, Strut Bar  B : 10 / C : 160 pcs.	T23CR27 48674-28010 CR27 Strut Bar Bushing  B : 18 / C : 288 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T23LJ7Y 48674-60020 LJ7# Strut Bar Bushing  B : 6 / C : 144 pcs.	T23KD200 48674-26040 KDH200 Strut Bar Bushing  B : 8 / C : 128 pcs.
T2302Z 48674-29015-S RT60 Strut Bar Rubber (SET, Without Edge)  B : 1 / C : 65 pcs.	T2306Z 48674-17065-S TT141 Strut Bar Rubber (SET, Without Edge)  B : 1 / C : 65 pcs.
T2322Z 48674-12010-S KE20 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	T2323Z 48674-12080-S KE30 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
T2324Z 48674-19095-S KE70 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	T2344Z 48674-39045-S LN40 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
T2346Z 48674-22021-S LN85 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	T2365Z 48674-26010-S LH60, LH112 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
T2382Z 48674-39025-S MS50, MS60 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	T2384Z 48674-30040-S MS110 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
T2385Z 48674-30031-S MS120, MS132 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	T2367Z 48674-26021-S RZH135 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
T23KD20Z 48674-26040-S KDH200 Strut Bar Rubber (SET)  B : 1 / C : 50 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2402P 48632-22010 RT60 Upper Arm Bushing  B : 10 / C : 180 pcs.	T2402W 48654-22010 RT60, MX12 Lower Arm Bushing  B : 8 / C : 144 pcs.
T2404P 48091-12010 RT100 Upper Arm Bushing  B : 8 / C : 144 pcs.	
T2408WB 48655-20060 AT171, ST171 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	T2408WS 48068-20200 AT171, ST171 Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T2408WLB 48076-20010-IN AT171, ST171 Lower Arm Bushing (BIG, LH Bracket)  B : 2 / C : 36 pcs.	T2408WRB 48075-20010-IN AT171, ST171 Lower Arm Bushing (BIG, RH Bracket)  B : 2 / C : 36 pcs.
T2409WB 48655-20140 AT190, ST190 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T2409WS 48654-20150, 20160 AT190, ST190 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T2411WB 48655-20221 ST191 (EXSIOR) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T2411WS 48654-20190 ST191 (EXSIOR) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T2411WT 48655-20221T ST191 (EXSIOR) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T2411XB 48655-20260 CORONA AT195 Lower Arm Bushing  B : 4 / C : 72 pcs.
T2421W 48061-12010 KE10 Lower Arm Bushing  B : 10 / C : 180 pcs.	T2422W 48654-12010 KE20, KE30, KE70 Lower Arm Bushing  B : 10 / C : 180 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2425WB 48655-20030 AE80, ST150 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	T2425WS 35654-20060 AE80, ST150 Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T2428WB 48655-12010, 12060 EE90, AE92 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	T2428WS 48654-12050 EE90, AE92 Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T2430WB 48655-12050 EE100, AE101 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	T2430WS 48654-12070 EE100, AE101 Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T2429WL 48076-12010-IN EE100, AE101 Lower Arm Bushing (BIG, LH Bracket)  B : 2 / C : 24 pcs.	T2429WR 48075-12010-IN EE100, AE101 Lower Arm Bushing (BIG, RH Bracket)  B : 2 / C : 24 pcs.
T2431WB 48655-12120, 48655-12H30 AE110, AE111, AE102 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	T2431WS 48654-12090 AE110, AE111, AE102 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T2444W 48654-35010 LN40, LN85 Lower Arm Bushing  B : 6 / C : 108 pcs.	T2446P 48632-35020 LN85 Upper Arm Bushing  B : 8 / C : 144 pcs.
T2464PB 48635-26010, 48635-26080 LH60, LH112, TIGER (4WD) Upper Arm Bushing  B : 5 / C : 80 pcs.	T2464PS 48632-26010, 35050, 26090 LH60, LH112, KDH200, TIGER, VZN13 (4WD) Upper Arm Bushing  B : 6 / C : 108 pcs.
T2464W 48061-26010, 26050 LH60, LH112, KDH200, TIGER (4WD), LN167 Lower Arm Bushing  B : 4 / C : 72 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2482P 48632-30020, 48632-39025 MS60, CR27 Upper Arm Bushing (SMALL) B : 8 / C : 144 pcs. 	T2482W 48654-30020 MS60 Lower Arm Bushing B : 6 / C : 108 pcs. 
T2486P 48632-30070 MS132 Upper Arm Bushing B : 8 / C : 144 pcs. 	T2486W 48654-30030 MS132 Lower Arm Bushing B : 4 / C : 72 pcs. 
T2494P 48632-22020 MX12 Upper Arm Bushing B : 8 / C : 144 pcs. 	
T2495WB 48655-16010 EP70 Lower Arm Bushing (BIG) B : 8 / C : 144 pcs. 	T2495WS 48654-16060 EP70 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs. 
T2496B 48674-32090 CAMRY Lower Arm Bushing (BIG) B : 10 / C : 180 pcs. 	T2496S 48674-32030 CAMRY Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs. 
T24C00W 48654-32040 CAMRY Lower Arm Bushing B : 8 / C : 144 pcs. 	
T24C02WB 48655-33040 CAMRY SXV10 (2.2 cc) (1994) Lower Arm Bushing (BIG) B : 6 / C : 108 pcs. 	T24C02WS 48654-33040 CAMRY SXV10 (2.2 cc) (1994), SXV20 (2.2 cc) (1997) Lower Arm Bushing (SMALL) B : 6 / C : 96 pcs. 
T24C010 48654-32020 CAMRY Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs. 	T24C03 48655-06030 CAMRY SXV20 (2.2 cc) (1997) Lower Arm Bushing B : 6 / C : 108 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24C04WB 48655-28020, 58011 CAMRY (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50, AVV50, ALPHARD (2002) ANH10 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24C04WS 48654-28060, 33050, 28020 CAMRY (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50, AVV50, ALPHARD (2002) ANH10 Lower Arm Bushing (SMALL)  B : 6 / C : 96 pcs.
T24CR27P 48635-28010 CR27, KM36 Upper Arm Bushing  B : 4 / C : 72 pcs.	T24CR27W 48061-27011 CR27, KM36 Lower Arm Bushing  B : 4 / C : 72 pcs.
T24CR304W 48061-28030 LITEACE, TOWNACE CR3# (4WD) Lower Arm Bushing  B : 6 / C : 108 pcs.	T24FJ80W 48061-60010 LAND CRUISER FJ80 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.
T24GX81W 48654-22030 CRESSIDA, GX81 Lower Arm Bushing  B : 8 / C : 144 pcs.	
T24GX901P 48632-30100 CHASER GX90 Upper Arm Bushing  B : 6 / C : 108 pcs.	T24GX901W 48654-30070 CHASER GX90 Lower Arm Bushing  B : 6 / C : 108 pcs.
T24GX90WB 48655-22010 MARK II, GX90 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24JZX93W 48655-22041 MARK II, JZX93 (4WD) Lower Arm Bushing  B : 4 / C : 64 pcs.
T24KM20PB 48635-27010 KM20 Upper Arm Bushing  B : 4 / C : 72 pcs.	
T24NC42WB 48655-0D060, 48655-52010 VIOS, ECHO, YARIS, VITZ Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24NC42WS 48654-0D040 VIOS, ECHO, YARIS Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24ND04W 48655-44020 IPSUM, GAYA, NADIA (4WD) Lower Arm Bushing  B : 4 / C : 72 pcs.	T24R01W0 42304-12110 CALRINA ED Lower Arm Bushing  B : 8 / C : 144 pcs.
T24RV1WB 48075-42050 RAV4, SXA11 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	T24RV1WS 48654-42020 RAV4, SXA11 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T24S01WB 48655-10030 SOLUNA Lower Arm Bushing (BIG)  B : 8 / C : 144 pcs.	T24S01WS 48654-16110 SOLUNA Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T24S02WB 48655-10050B SOLUNA (2000) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24S02WS 48654, 48655-10050S SOLUNA (2000) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T24S0AR91 48632-14040 SOARER (1991) Lower Arm Bushing  B : 8 / C : 144 pcs.	T24T11WB 48655-28010 LUSIDA, TCR11 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.
T24TE94W 48654-20100 CELIGA, ST184 Lower Arm Bushing  B : 8 / C : 144 pcs.	
T24TE94WB 48655-20210 CELIGA, ST204 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24TE94WS 48654-20180 CELIGA, ST204 Lower Arm Bushing  B : 10 / C : 180 pcs.
T24AH20WB 48655-28030, 48609-28140-1 ALPHARD ANH20, ALPHARD (2015) AGH30, AYH30, GGH30 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA


T24VG02P 48632-0K010, 48632-0K020 HILUX VIGO (2WD), INNOVA, REVO Upper Arm Bushing  B : 8 / C : 144 pcs.	T24VG04P 48632-0K040 HILUX VIGO (4WD), FORTUNER Upper Arm Bushing  B : 6 / C : 108 pcs.
T24VG2WB 48655-0K010, 0K020 HILUX VIGO (2WD), INNOVA, REVO Lower Arm Bushing (BIG)  B : 4 / C : 64 pcs.	T24VG2WS 48654-0K010, 0K020 HILUX VIGO (2WD), INNOVA, REVO Lower Arm Bushing (SMALL)  B : 4 / C : 72 pcs.
T24VG4WB 48655-0K040 HILUX VIGO (4WD), FORTUNER Lower Arm Bushing (BIG)  B : 4 / C : 64 pcs.	T24VG4WS 48654-0K040 HILUX VIGO (4WD), FORTUNER Lower Arm Bushing (SMALL)  B : 4 / C : 72 pcs.
T24W11WB 48655-21010 WISH Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24W11WS 48654-21010 WISH Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T24Y5102W 48654-04020 TIGER (2WD) Lower Arm Bushing  B : 6 / C : 108 pcs.	
T24ZE121B 48655-12170 ALTIS ZZE121, ZZE122, ZZE141 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24ZE121S 48654-12120 ALTIS ZZE121, ZZE122, ZZE141 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T24ZE121T 48655-12170T, 48655-21010T ALTIS ZZE121, ZZE122, WISH Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	
T24ZJ95P 48632-35080 PRADO Upper Arm Bushing  B : 8 / C : 144 pcs.	T24ZJ95WB 48061-35040 PRADO VZJ (1995) Lower Arm Bushing  B : 4 / C : 72 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24VP02WB 48654-59035 ECOHO, YARIS VITZ, PLATZ (2WD) Lower Arm Bushing B : 10 / C : 180 pcs.		T24X10W0 48655-44010 IPSUM, NADIA, GATA Lower Arm Bushing B : 4 / C : 72 pcs.	
T24G10PB 48635-26040 GRANVIA VCH10 Upper Arm Bushing (BIG) B : 2 / C : 36 pcs.		T24G10PS 48632-26050 GRANVIA VCH10 Upper Arm Bushing (SMALL) B : 4 / C : 72 pcs.	
T24GR18WB 48075-30020-0, 48076-30020-0 GRS 182 Lower Arm Bushing (BIG) B : 2 / C : 24 pcs.		T24GR18WS 48640-30290 GRS 182 Lower Arm Bushing (SMALL) B : 6 / C : 108 pcs.	
T24F60WB 48655-BZ010 AVANZA F601, F602 Lower Arm Bushing (BIG) B : 4 / C : 72 pcs.		T24F60WS 48654-BZ010 AVANZA F601, F602 Lower Arm Bushing (SMALL) B : 6 / C : 108 pcs.	
T24GR21P 48632-60020 GRN21#, GRN215, GSJ1#, GRJ12# Upper Arm Bushing B : 6 / C : 108 pcs.		T24GR21W 48654-60030 GRN21#, GRN215, GSJ1#, GRJ12# Lower Arm Bushing B : 4 / C : 72 pcs.	
T24NC93WB 48655-0D051 VIOS NCP93, YARIS NCP91 Lower Arm Bushing B : 4 / C : 72 pcs.		T24NC93WS 48654-0D060 VIOS NCP93, YARIS NCP91 Lower Arm Bushing B : 10 / C : 180 pcs.	
T24LS43W 48655-50012, 50010 LS430, UCF3# Lower Arm Bushing B : 2 / C : 36 pcs.		T24GX900P 48632-22030 GX90 Upper Arm Bushing B : 6 / C : 108 pcs.	
T24UZ10P 48632-60010 UZJ100, FZJ100, LX470 Upper Arm Bushing B : 4 / C : 72 pcs.			



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24UZ10WB 48655-60010, 48655-60020 UZJ100, FZJ100, LX470 Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	T24UZ10W 48654-60010, 48654-60020 UZJ100, FZJ100, LX470 Lower Arm Bushing  B : 4 / C : 72 pcs.
T24UZ20P 48632-60030 UZJ200, URJ201, GRJ200 Upper Arm Bushing  B : 4 / C : 72 pcs.	
T24UZ20W 48654-60040 GRJ200, UZJ200, URJ201 Lower Arm Bushing  B : 2 / C : 36 pcs.	T24UZ20WB 48655-60040 GRJ200, URJ200, VDJ200, LX570 Lower Arm Bushing (BIG)  B : 1 / C : 24 pcs.
T24RV30WB 48655-42060 RAV4, ACA30 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24RV30WS 48654-42040, 48609-28140-2 RAV4 ACA30, PRIUS VZW30, ALPHARD ANH20, ALPHARD (2015) AGH30, AYH30, GGH30 Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
T24RV20WB 48655-42040 RAV4, ACA20 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24RV20WS 48654-42030 RAV4, ACA20 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T2409WBS 48655-20140S AT190, ST190 (ID.14.30) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	
T24CR5WB 48061-28050 CR5#, KR5#, SR5# Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24CR5WS 48061-28040 CR5#, KR5#, SR5# Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
T24US40WL 48620-50070-1 LS460 USF40 Lower Arm Bushing (LONG)  B : 4 / C : 72 pcs.	T24LS46WS 48536-50010, 48620-50070-2 LS460 USF40 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24KD22W 48061-25010 KDH225, TRH219, KDY270 Lower Arm Bushing  B : 6 / C : 108 pcs.	T24UZ01W 48655-30090 UZS173, JZS147 Lower Arm Bushing  B : 6 / C : 108 pcs.
T24BB2WB 48061-36011 RB2#, BB2#, FB30, HDB20 Lower Arm Bushing  B : 4 / C : 72 pcs.	
T24BB4WB 48061-36020 BB4#, BZB4#, HDB4# Lower Arm Bushing  B : 4 / C : 72 pcs.	T24BB4W0 48655-36010 BB4#, BZB5#, HZB5#, TRB40 Lower Arm Bushing  B : 4 / C : 72 pcs.
T24F601WB 48655-B1020, 48655-B1040 BB QNC20 (1.3 cc) (2WD), QNC21 (1.5 cc) (2WD), QNC25 (1.3 cc) (4WD) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24F601W 48654-B2010 BB QNC20 (1.3 cc) (2WD), QNC21 (1.5 cc) (2WD), QNC25 (1.3 cc) (4WD) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T24KD25W 48061-25020, 26060 KDH205, KDH225, TRH219, TRH226, KDY22#, KDY24#, KDY26#, KDY280, RZY220, RZY23#, TRY220, TRY230 Lower Arm Bushing  B : 2 / C : 36 pcs.	T24GR20W 48655-60030 GRN#, GRN215, GSJ1#, GRJ12# Lower Arm Bushing  B : 2 / C : 36 pcs.
T24UC10W 48654-50010 UCF10 Lower Arm Bushing  B : 4 / C : 72 pcs.	T24UZ15W 48654-30050 JZS147, JZS155, UZS15#, UZS173 Lower Arm Bushing  B : 6 / C : 108 pcs.
T24UC3WB 48655-34010 UCK35, UCK45, UCK3#, UCK4#, VCK30, VCK40, GSK30 Lower Arm Bushing  B : 2 / C : 36 pcs.	T24UC3WS 48654-34010, 48654-34020 UCK35, UCK45, UCK3#, UCK4#, VCK30, VCK40, GSK30 Lower Arm Bushing  B : 2 / C : 36 pcs.
T24RV04WI 48655-0K080 REVO (4WD), FORTUNER (2015) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	T24RV04WS 48654-0K080 REVO (4WD), FORTUNER (2015) Lower Arm Bushing (SMALL)  B : 4 / C : 72 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24JZ160W 48655-30181 JZS160 Lower Arm Bushing  B : 2 / C : 36 pcs.	T24MA0W 48655-22030 MARK II (1994) Lower Arm Bushing  B : 4 / C : 72 pcs.
T24CR4PB 48635-28040 LITEACE, TOWNACE, MASTERACE (1988-1992) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24CR4PS 48632-28030 LITEACE, TOWNACE, MASTERACE (1988-1992) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
T24GR182P 48632-30150 GRS 182 Upper Arm Bushing  B : 6 / C : 108 pcs.	T24C036B 48655-06060 CAMRY ACV36 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.
T24F65WB 48655-BZ120 AVANZA F651, F652 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24F65WS 48654-BZ070 AVANZA F651, F652 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T24F70WB 48655-BZ020 RUSH F700 Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	
T24NC50WB 48655-0D140, 0D240, 48069-09270-1 VIOS NCP150, YARIS NSP152 SIENTA NSP170, ETIOS Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24NC50WS 48654-0D120, 0D160, 48069-09270-2 VIOS NCP150, YARIS NSP152 SIENTA NSP170, ETIOS Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
T24PW1WE 48655-47021 PRIUS NHW10, NHW11 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24PW1WS 48654-47010 PRIUS NHW10, NHW11 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
T24PW30WB 48655-12210 PRIUS, ZVW30 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	T24ZE171WB 48655-02130, 48655-21020 ALTIS ZRE171, ZRE172, PRIUS NHW20 Lower Arm Bushing  B : 4 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T24GR15WB 48655-60050 PRADO KDJ 150 Lower Arm Bushing  B : 2 / C : 36 pcs.	T24GR15WS 48654-60050 PRADO KDJ 150 Lower Arm Bushing  B : 4 / C : 72 pcs.
T24GR15P 48632-60040 PRADO GRJ150, KDJ150 Upper Arm Bushing  B : 4 / C : 72 pcs.	
T24BJ70W 48061-60020 BJ70 Lower Arm Bushing  B : 6 / C : 108 pcs.	T24HJ79W 48061-60050 HZJ78, LX, HZJ79, ARL, FZJ78, GCC, FZJ79, GRJ71, GRJ76, HZJ71, HZJ76, VDJ76 (2012) Lower Arm Bushing  B : 4 / C : 72 pcs.
T24RV04P 48632-0K070 REVO (4WD), FORTUNER (2015) Upper Arm Bushing  B : 4 / C : 72 pcs.	
T24GR18WL 48076-30020-IN GRS 182 Lower Arm Bushing (LH Bracket)  B : 1 / C : 12 pcs.	T24GR18WR 48075-30020-IN GRS 182 Lower Arm Bushing (RH Bracket)  B : 1 / C : 12 pcs.
T24CH18WS 48069-F4020-2 C-HR (2018) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.	T24CH18WB 48069-F4020-1 C-HR (2018), ALTIS (2020) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.
T24CR19WS 48069-33090-2, 48654-33060 CAMRY ASV71 Lower Arm Bushing (SMALL)  B : 6 / C : 96 pcs.	T24CR19WB 48069-33090-1, 48655-33090 CAMRY ASV71 Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.
T24GD30WB 48068-26180-1, 48069-26180-1, 48655-26010 GDH 300 Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	T24GD30WS 48069-26180-2, 48654-26030 COMMUTER, MAJESTY (2019) GDH300, HIACE (2019) GDH322 Lower Arm Bushing (SMALL)  B : 4 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25050 48702-22060 RT130 Suspension Bush (RE) B : 8 / C : 144 pcs.	T25081 48725-20070 AT171, ST171 Suspension Bush B : 10 / C : 180 pcs.
T25082 48725-32110 AT171, ST171 Suspension Bush B : 10 / C : 180 pcs.	T25083 48725-20050 AT171, ST171 Suspension Bush B : 10 / C : 180 pcs.
T25084 48725-20340 AT171, ST171 Suspension Bush B : 10 / C : 180 pcs.	T25241 48706-14010 KE70, TT141 Suspension Bush B : 10 / C : 180 pcs.
T25242 90385-20001 KE70 Suspension Rubber B : 50 / C : 1200 pcs.	T25243 12375-12072 KE70 Suspension Bush B : 8 / C : 144 pcs.
T25244 12375-12070 KE70 Suspension Bush B : 10 / C : 180 pcs.	
T2524GZ 48702-12040 KE70 Suspension Bush (LONG) B : 1 / C : 18 pcs.	T2524TZ 48702-12020 KE70 Suspension Bush (SHORT) B : 1 / C : 10 pcs.
T2525E 48725-32070 ST150, AE80 Suspension Bush B : 10 / C : 180 pcs.	
T25CH1880 48780-F4030-0 C-HR (2018) Suspension Bush (BIG) B : 4 / C : 64 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25281 48725-12150 EE90 Suspension Bush B : 8 / C : 144 pcs.		T25282 48725-20380 AE92, AE101, ST171 Suspension Bush B : 8 / C : 144 pcs.	
T25283 48725-12290 EE90, AE92 Suspension Bush B : 10 / C : 180 pcs.		T25284 48725-12110 EE90, AE90 Suspension Bush B : 10 / C : 180 pcs.	
T25301 48725-12200 EE100, AE101 Suspension Bush B : 8 / C : 144 pcs.		T25302 48725-12240 EE100, AE101 Suspension Bush B : 8 / C : 144 pcs.	
T2531S 48725-12370, 48725-12400 AE111 Suspension Bush (SMALL) B : 10 / C : 180 pcs.			
T25670 48706-30020 RZH 135 Suspension Bush (RE) B : 10 / C : 180 pcs.		T256701 48702-26051 RZH 135 Suspension Bush B : 4 / C : 72 pcs.	
T25671 48702-28080 RZH 135 Suspension Bush B : 6 / C : 108 pcs.		T25672 48702-26041 RZH 135 Suspension Bush B : 4 / C : 72 pcs.	
T25820 48702-30031 MS60 Suspension Bush B : 8 / C : 144 pcs.		T25860 48702-30140 MS132 Suspension Bush B : 8 / C : 144 pcs.	
T25870 48725-30050 MS133, JZS133 Suspension Bush (SMALL Diameter) B : 4 / C : 72 pcs.		T25870B 48725-30060 MS133, JZS133 Suspension Bush (BIG Diameter) B : 4 / C : 72 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25900 48702-14010, 14020 2T, TT141, TT133 Suspension Bush  B : 8 / C : 144 pcs.	T25GX810 48702-22090 CRESSIDA GX81 Suspension Bush  B : 8 / C : 144 pcs.
T25920 48702-60050, 60060 LAND CRUISER Suspension Bush  B : 4 / C : 72 pcs.	T25950 48725-10010 EP70 Suspension Bush  B : 8 / C : 144 pcs.
T25C010 T25C010 SV30 Suspension Bush  B : 8 / C : 144 pcs.	T25C020 48725-03010, 06020, YC010 SXV10, SXV20 Suspension Bush  B : 8 / C : 144 pcs.
T25C02S 48716-12040, 48730-33020 CAMRY SXV10, AE92 Suspension Bush  B : 8 / C : 144 pcs.	
T25DJ2150 48706-60060 PRADO, KDJ215 Suspension Bush  B : 10 / C : 180 pcs.	T25DJ2152 48725-35020 PRADO, KDJ215 Suspension Bush  B : 6 / C : 108 pcs.
T25FJ801 48702-60040 LAND CRUISER Suspension Bush  B : 4 / C : 72 pcs.	T25FJ802 48702-60031 LAND CRUISER Suspension Bush  B : 6 / C : 108 pcs.
T25FJ803 48706-60030 LAND CRUISER Suspension Bush (RE)  B : 10 / C : 180 pcs.	T25FJ804 48706-60040 LAND CRUISER Suspension Bush  B : 10 / C : 180 pcs.
T25UZ2040 48740-60150-0, 48740-60170-0 LAND CRUISER UZJ200, URJ200, VDJ200, FJA300, GRJ300, VJA300 Suspension Bush  B : 10 / C : 180 pcs.	

NEW



is the registered trademark

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25GX901 48725-22180 CHAISER GX90 Suspension Bush  B : 10 / C : 180 pcs.	T25GX90E 48725-22150 MARK II, GX90 Suspension Bush  B : 10 / C : 180 pcs.
T25GX90B 14.2 MARK II, GX90 Suspension Bush (BIG)  B : 8 / C : 144 pcs.	T25GX90S 12.3 MARK II, GX90 Suspension Bush (SMALL)  B : 8 / C : 144 pcs.
T25KJ215 48714-35010 PRADO KDJ 215 Suspension Bush  B : 6 / C : 108 pcs.	T25LS401 48725-22110 UCF10, LS400 Suspension Bush  B : 8 / C : 144 pcs.
T25RV10 48725-42011 RAV4 Suspension Bush (RE)  B : 4 / C : 72 pcs.	T25S011 48725-0A010 SOLUNA Suspension Bush  B : 4 / C : 72 pcs.
T25TG1020 48725-26020 GRANVIA RCH10, RCH11, RCH16 Suspension Bush  B : 4 / C : 72 pcs.	T25TG1030 48725-26030 GRANVIA RCH10, RCH11, RCH16 Suspension Bush  B : 4 / C : 72 pcs.
T25ZJ95E1 48702-35070 PRADO VZJ (1995) Suspension Bush  B : 8 / C : 144 pcs.	T25CR30E 48704-28010 LITEACE, TOWNACE, CR3 Suspension Bush  B : 6 / C : 108 pcs.
T25ZE171E 48725-02360 ALTIS ZRE171, ZRE172 Suspension Bush  B : 2 / C : 24 pcs.	
T25ZE121E 48725-02240, 48725-12560 ALTIS ZZE121, ZZE122 Suspension Bush (RE)  B : 2 / C : 32 pcs.	T25ZE141E 48725-02310 ALTIS ZZE141 Suspension Bush  B : 2 / C : 32 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25NC42E 48725-0D040 VIOS Suspension Bush  B : 2 / C : 36 pcs.	T25ST93E 48702-10020 STARLET (1993) Suspension Bush  B : 8 / C : 144 pcs.
T254X0E 48725-35010 LN106 Suspension Bush  B : 6 / C : 108 pcs.	T25BJ7E 48706-60011 BJ7# Suspension Bush  B : 10 / C : 180 pcs.
T25C040 48725-12460 CAMRY ACV30 Suspension Bush  B : 6 / C : 108 pcs.	T25C04E 48710-33070, 48710-06100 CAMRY (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE)  B : 10 / C : 180 pcs.
T25C04B 48725-48020B Suspension Bush (BIG)  B : 6 / C : 108 pcs.	T25C04S 48725-48020S CAMRY (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (SMALL)  B : 8 / C : 144 pcs.
T25C04L00 48740-33080, 48740-33100 CAMRY (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE, LH)  B : 2 / C : 24 pcs.	T25C04R00 48730-33080, 48730-33150 CAMRY (2002) ACV30, (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE, RH)  B : 2 / C : 24 pcs.
T25C05E0 48780-06040 CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE)  B : 8 / C : 144 pcs.	T25CM30E 48702-27040 CM30, CM31, KM30, KM31, YM4 Suspension Bush  B : 6 / C : 108 pcs.
T25ND024 48725-44030 NADIA (2WD), (4WD) Suspension Bush  B : 2 / C : 32 pcs.	T25RM3E 48706-22030 RM3# Suspension Bush  B : 10 / C : 180 pcs.
T251140 48740-20080 ST191 EXSIOR Suspension Bush  B : 10 / C : 180 pcs.	T251125 48725-20560 ST191 EXSIOR Suspension Bush  B : 10 / C : 180 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25VG041 48740-0K070-0, 48706-0K030 FORTUNER (2005, 2015, 2016), INNOVA KUN40 Suspension Bush (RE)  B : 10 / C : 180 pcs.	T25VG042 48702-0K010, 0K070, 0K160, 0K200, 48710-0K120-0, 0K070-0, 0K080-0 FORTUNER (2005, 2015), INNOVA (2004) KUN40, INNOVA CRYSTA (2016) GUN143 Suspension Bush (RE)  B : 6 / C : 108 pcs.
T25VG043 48720-0K050-2, 48702-0K020, 0K080 FORTUNER (2005, 2015, 2016), INNOVA KUN40 Suspension Bush  B : 4 / C : 72 pcs.	T25VG044 48720-0K050-1, 48702-0K030, 0K090 FORTUNER, INNOVA KUN40 Suspension Bush  B : 4 / C : 72 pcs.
T25NC12E 48725-52010 ECHO, WILL NCP12, NCP91 Suspension Bush  B : 2 / C : 36 pcs.	T25YA91E 48725-0D070 YARIS NCP91 Suspension Bush  B : 2 / C : 36 pcs.
T25GX900 48702-22410 GX90 Suspension Bush  B : 10 / C : 180 pcs.	T25AC50E 48725-28080 ACR5#, GSR5#, AHR20 Suspension Bush  B : 2 / C : 24 pcs.
T25UZ201 48702-60100 GRJ200, UZJ200, URJ201, LAND CRUISER Suspension Bush  B : 6 / C : 108 pcs.	T25UZ202 48702-60110 GRJ200, UZJ200, URJ201, LAND CRUISER Suspension Bush (RE)  B : 6 / C : 108 pcs.
T25UZ20E 48849-60110 GRJ200, UZJ200, URJ201, LAND CRUISER Suspension Bush  B : 8 / C : 144 pcs.	T25W11E 48070-68020 WISH ANE11 Suspension Bush  B : 4 / C : 72 pcs.
T25W110E 48725-32250 WISH ANE11 Suspension Bush  B : 6 / C : 108 pcs.	T25W111E 48770-20020 WISH ANE11 Suspension Bush  B : 10 / C : 180 pcs.
T25AZ250 48725-05071 AVENIS (2003-2008), AZT25# Suspension Bush  B : 8 / C : 144 pcs.	T25AN10E 48725-58010, 44051, 58030 ALPHARD ANH10, ANH15, ANH20, ACR30 Suspension Bush  B : 2 / C : 24 pcs.



is the registered trademark

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25F600E 48704-BZ010 AVANZA F601, F602, F700 Suspension Bush  B : 4 / C : 72 pcs.	T25F601E 48706-BZ010 AVANZA F601, F602 Suspension Bush  B : 10 / C : 180 pcs.
T25AZ251 48725-05141 AVENIS (2003-2008) AZY25# Suspension Bush  B : 8 / C : 144 pcs.	T25CR4E 48704-28040 LITEACE, TOWNACE, MASTERACE (1996-2001) Suspension Bush (RE)  B : 6 / C : 108 pcs.
T25AH10E 48725-28050, 42100-SZW-020-0 ACR30, ACR40, CLR30, MCR30, MCR40, AHR10, ACM2#, ACM20, CLM20, STEPWAGON SPADA (2010) Suspension Bush (RE)  B : 2 / C : 24 pcs.	T25AZ240 48725-32280 AZT240, NZT240, ZYT240, AZV50, SV50, ZZV50, ACT10, ZCT10, NHW20 Suspension Bush  B : 2 / C : 32 pcs.
T25AZ25E 48704-05030, 48725-05080 AZT25#, ADT25#, CDT25#, ZYT25# Suspension Bush  B : 10 / C : 180 pcs.	T25ZE151E 48725-12590, 48725-47030 ADE150, NDE150, ZRE151, ZRE152, ZZE150, PRIUS ZVW30 Suspension Bush  B : 2 / C : 36 pcs.
T25ZJ95E 48702-35050 PRADO VZJ95 Suspension Bush  B : 6 / C : 108 pcs.	T25ZJ95E0 48740-35030-0, 48706-35020 PRADO VZJ95 Suspension Bush (RE)  B : 10 / C : 180 pcs.
T25AH00E 48725-28070 ACR30, ACR40, MCR30, MCR40, ACM2#, CLM20 Suspension Bush  B : 2 / C : 24 pcs.	T25AC20E 48725-42080 RAV4, ACA2#, CLA2#, ZCA2# Suspension Bush  B : 4 / C : 72 pcs.
T25UZ200 48849-60050 UZJ200, VDJ200 Suspension Bush  B : 6 / C : 108 pcs.	T25HD100E 48702-60090 HDJ100 Suspension Bush  B : 6 / C : 108 pcs.
T25UZ203 48702-60130 GRJ200, UZJ20, VDJ200 Suspension Bush  B : 4 / C : 72 pcs.	T25UZ201E 48849-60090 UZJ200, VDL200 Suspension Bush  B : 6 / C : 108 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25F602E 48702-BZ050, BZ010 AVANZA F601, F602 Suspension Bush  B : 6 / C : 108 pcs.	T25HJ79 48702-60120 HZJ78, LX, HZJ79, ARL, FZJ78, GCC, FZJ79, GRJ71, GRJ76, HZJ71, HZJ76, VDJ76 (2012) Suspension Bush  B : 2 / C : 24 pcs.
T25VZJ95E 48702-35040 VZJ95 Suspension Bush  B : 6 / C : 108 pcs.	T25W112E 42304-0M010, 42305-0M010 WISH Suspension Bush  B : 8 / C : 144 pcs.
T25GR12E 48725-35061 LANCRUISER PRADO GRJ120, LJ120 Suspension Bush  B : 6 / C : 108 pcs.	T25VG40E 90385-T0005, 20006 FORTUNER, INNOVA CRYSTA (2016) (GUN143) Suspension Rubber (RE)  B : 40 / C : 960 pcs.
T25NC15E 48725-0D120, 42110-0D550-0 VIOS NCP150, YARIS NSP152, ETIOS, SIENIA NSP170 Suspension Bush (RE)  B : 2 / C : 36 pcs.	T25UZ204 48702-60140 LAND CRUISER UZJ200, DJ200, GRJ200 Suspension Bush  B : 4 / C : 72 pcs.
T25CR1971F 52271-06160 CAMRY ASV71 Suspension bush (FR,LH,RH)  B : 2 / C : 24 pcs.	T25CR1976E 52276-06040 CAMRY ASV71 Suspension bush (RE,LH)  B : 2 / C : 24 pcs.
T25VG04F 41651-60040, 52380-71010-0 VIGO (4WD) Cushion Differential Mount (FR)  B : 6 / C : 108 pcs.	T25AH30800 48780-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)  B : 2 / C : 24 pcs.
T25AH3005B 42305-58010-1 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)  B : 6 / C : 108 pcs.	T25AH3005S 42305-58010-2 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)  B : 6 / C : 108 pcs.
T25AH30200 48720-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)  B : 6 / C : 108 pcs.	T25AH30400 48740-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)  B : 6 / C : 108 pcs.



is the registered trademark

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25AC10EZ 48720-42010-IN  SXA1#, ACA2#, CLA2#, ZCA2# Suspension Bush B : 1 / C : 8 pcs.	
T25AC20EZ 48720-42020-IN  ACA2#, CLA2#, ZCA2# Suspension Bush B : 1 / C : 8 pcs.	T25AC21EZ 48770-42020-IN  ACA2#, CLA2#, ZCA2# Suspension Bush B : 1 / C : 8 pcs.
T25C03EZ 48780-YC010-IN  CAMRY SXV20 Suspension Bush (LH, RH) B : 1 / C : 8 pcs.	T25C03E 48710-33050, 33051  CAMRY SXV20 Suspension Bush (LH, RH) B : 1 / C : 12 pcs.
T25C04E0Z 48780-12020-IN, 48780-32060-IN  CAMRY ACV30, SXV10 Suspension Bush (LH, RH) B : 1 / C : 8 pcs.	T25C04E1Z 48710-33070-IN  CAMRY ACV30 Suspension Bush B : 1 / C : 12 pcs.
T25C04ELZ 48740-33080-IN  CAMRY ACV30 Suspension Bush B : 1 / C : 12 pcs.	T25C04ERZ 48730-33080-IN  CAMRY ACV30 Suspension Bush B : 1 / C : 12 pcs.
T25C05E0Z 48710-06100-IN  CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE) B : 1 / C : 12 pcs.	T25C05EZ 48780-06040-IN  CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE) B : 1 / C : 8 pcs.
T25C05ELZ 48740-33100-IN  CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE, LH) B : 1 / C : 12 pcs.	T25C05ERZ 48730-33150-IN  CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Suspension Bush (RE, RH) B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T25C03R 48730-33050 CAMRY SXV20 Suspension Bush (RH) B : 1 / C : 12 pcs. 	T25C03L 48740-33060 CAMRY SXV20 Suspension Bush (LH) B : 1 / C : 12 pcs. 
T25RV20LZ 48790-42010-IN RAV4 (1994-2000), SXA1# Suspension Bush B : 1 / C : 8 pcs. 	T25RV20Z 48770-42010-IN RAV4 (1994-2000), SXA1# Suspension Bush B : 1 / C : 8 pcs. 
T25C02EZ 48710-33030-IN CAMRY SXV10 Suspension Bush (LH, RH) B : 1 / C : 8 pcs. 	
T25C02RZ 48740-33020-IN CAMRY SXV10 Suspension Bush (RH) B : 1 / C : 8 pcs. 	T25C02LZ 48730-33020-IN CAMRY SXV10 Suspension Bush (LH) B : 1 / C : 8 pcs. 
T25AZ22F0 48650-20020, 48650-20021 AVENSIS AZT220, AT221, ST220 Suspension Bush (FR) B : 2 / C : 24 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2628E 48725-12050 EE90, AE92 Suspension Bush B : 8 / C : 144 pcs.		T26280 48725-12300 EE90 Suspension Bush B : 8 / C : 144 pcs.	
T2628B 48725-12040 EE90, AE90 Suspension Bush B : 8 / C : 144 pcs.		T2628S 48725-16080, 48725-32030 EE90, AE92 Suspension Bush B : 8 / C : 144 pcs.	
T2645001 48500-35030 LN85, L200 Shock Absorber Bush B : 16 / C : 256 pcs.			
T26ZE121 48537-02010 ALTIS, ZZE121, ZZE122 Shock Absorber Bush B : 8 / C : 144 pcs.		T26GR18E 48520-80161, 48536-30030 CROWN (GRS182) Shock Absorber Bush B : 8 / C : 144 pcs.	
T26GS00 90389-14044 GS151, JZS155, GX90, JZX90, LX90 Shock Absorber Bush B : 8 / C : 144 pcs.		T26GS01 90389-12016 GS151, JZS155, GX90, JZX90, JZX91 Shock Absorber Bush B : 10 / C : 180 pcs.	
T26ZJ950 90389-14048 VZJ95 Shock Absorber Bush B : 8 / C : 144 pcs.		T26GR150 48536-60010 GRJ15#, KDJ15#, LJ15#, TRJ15# Shock Absorber Bush B : 8 / C : 144 pcs.	
T26VG02 90389-T0001 VIGO, REVO (2WD, 4WD), FORTUNER (2005, 2015), INNOVA 2004 KUN40, CRYSTA 2016 GUN142, 143 Shock Absorber Bush B : 8 / C : 144 pcs.		T26KD20FW 48511-80174 KDH200 Shock Absorber Bush (FR) B : 10 / C : 180 pcs.	
T26CR19E 48530-8Z116-0 CAMRY ASV71 Shock Absorber Bush (RE) B : 8 / C : 144 pcs.		T26FT15E 48530-8Z002-0, 48530-8Z036-0 FORTUNER (2016), INNOVA GUN143 Shock Absorber Bush (RE) B : 6 / C : 108 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T26NC50E 48537-0D150 VIOS NCP150, YARIS NSP152, ETIOS Shock Absorber Bush (RE) B : 8 / C : 144 pcs. 	T26VG02F 90389-T0009 VIGO (2WD) (4 Doors) Shock Absorber Bush B : 6 / C : 108 pcs. 
T26ZE141E 48537-02080 ALTIS ZZ141 Shock Absorber Bush B : 8 / C : 144 pcs. 	T26GD30E0 48530-80A06-0, 48537-26010 GDH300 Shock Absorber Bush (RE) B : 8 / C : 144 pcs. 
T26CC20E0 48530-0A050-0 COROLLA CROSS (2020) Shock Absorber Bush (RE) B : 8 / C : 144 pcs. 	
T26UZ20EW 90385-19010 LX450, 460, 570, LAND CRUISER URJ200, GRJ200 Shock Absorber Bush (RE) B : 8 / C : 144 pcs. 	NEW
T26ZE141 43474-12130 ALTIS ZZE141 Damper Drive Shaft B : 4 / C : 64 pcs. 	T26ZJ95F 48815-60100 PARDO VZJ95 Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 
T26RV1F 52380-42071 RAV4, SAX11 Suspension Bush (FR) B : 6 / C : 108 pcs. 	T2685Z 52201-30040-S MS120 Suspension Bush (SET) B : 1 / C : 65 pcs. 
T26FZ80F 41651-60010 FZJ80 Cushion Differential Mount B : 6 / C : 108 pcs. 	T26AN15E 41651-58010 ALPHARD MNH10, ANH15, MNH15 Cushion Differential Mount (RE) B : 4 / C : 64 pcs. 
T26G100F 41651-26070 GRANVIA VCH10, VCH16 Cushion Differential Mount (FR) B : 4 / C : 72 pcs. 	T26G100E 41651-12010 GRANVIA VCH10, VCH16 Cushion Differential Mount (RE) B : 6 / C : 108 pcs. 







PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T26Z1410 45516-02040 ALTIS ZZE141 Grommet Steering Bush  B : 10 / C : 180 pcs.	T26ST17LR 45510-0D440-0 SIENTA NSP170 Grommet Steering Bush (LH, RH)  B : 10 / C : 180 pcs.
T26Z121B 45516-02090 ALTIS Grommet Steering Bush (BIG)  B : 10 / C : 180 pcs.	T26Z121S 45516-02100 ALTIS Grommet Steering Bush (SMALL)  B : 10 / C : 180 pcs.
T26ZJ95B 45522-35040 PRADO VZJ95 Grommet Steering Bush (LH)  B : 6 / C : 108 pcs.	T26ZJ95S 45516-35040 PRADO VZJ95 Grommet Steering Bush (SMALL)  B : 10 / C : 180 pcs.
T26RV21 45516-42020 RAV4, ACA21 Grommet Steering Bush (SMALL)  B : 10 / C : 180 pcs.	T26AC20 45516-44041 ACM2# Grommet Steering Bush  B : 10 / C : 180 pcs.
T2611RM 45516-20080 AT190, ST190 Grommet Steering Bush (RH, M/T)  B : 10 / C : 180 pcs.	T2611RP 44250-20392 AT190, ST190, EXSIOR Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
T26C02R 45516-06080 CAMRY Grommet Steering Bush (RH)  B : 10 / C : 240 pcs.	T26KD20R 45516-26060 KDH 200 Grommet Steering Bush  B : 10 / C : 180 pcs.
T26AC20 45516-44041 ACM2# Grommet Steering Bush  B : 10 / C : 180 pcs.	T26F60R 45516-BZ140 AVANZA F601 Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
T26F65R0 45516-BZ110 AVANZA F651, F652 Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.	T2625E 90385-11021-S AE80, AE92, LN106 Stabilizer Shaft Grommet  B : 30 / C : 1,500 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T266500 90389-14007, 90389-14004, 14037 LH60, LH112, KDH200, TIGER Spring Shackle Bush (FR)  B : 10 / C : 160 pcs.	T26VG04F 90389-T0005 HILUX VIGO (4WD), REVO Spring Shackle Bush (FR)  B : 8 / C : 128 pcs.
T26AE71 90389-14034 AE71 Spring Shackle Bush  B : 8 / C : 128 pcs.	T26B61F 90389-16002 BU20, BU61 Spring Shackle Bush (FR)  B : 8 / C : 128 pcs.
T26BB4E0 90389-16015 COASTER N04C, XZB50 Spring Shackle Bush (RE)  B : 4 / C : 72 pcs.	T26BB4F0 90389-16018 COASTER N04C, XZB50 Spring Shackle Bush (FR)  B : 2 / C : 36 pcs.
T26090 90389-14035 ST171 VAN Spring Shackle Bush  B : 6 / C : 96 pcs.	T262500 90389-12001 KE76, AE72 Spring Shackle Bush  B : 10 / C : 180 pcs.
T26C01000 48674-32110, 48674-32120 SV41 Strut Bar Bush  B : 8 / C : 144 pcs.	T26GX810 48674-22141 GX81, CRESSIDA Strut Bar Bushing  B : 4 / C : 72 pcs.
T26CV40 48667-32020 CV40, SV40, SV41, SV42 Strut Bar Bushing  B : 6 / C : 390 pcs.	T26GD30E 48288-26010 HIACE GDH300 Spring Shackle Bush (RE)  B : 2 / C : 36 pcs.
T26CH18L 43474-F4080, F4060 C-HR (2018) ZGX11, ZYX10 Damper Drive Shaft (LH)  B : 4 / C : 72 pcs.	T26ZE21L 43420-02F60-0, 43474-02660 ALTIS (2019), ZRE210, ZWE211 Damper Drive Shaft (LH)  B : 4 / C : 72 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27040 90101-08458K RT100 Stabilizer Link B : 10 / C : 120 pcs. 	T27060 48819-20010K TT133, TT141 Stabilizer Link B : 10 / C : 120 pcs. 
T27230 90101-08274K KE30 Stabilizer Link B : 10 / C : 120 pcs. 	T27240 48819-12010K KE70 Stabilizer Link B : 10 / C : 120 pcs. 
T27250 48819-20030K AE80, AE92 Stabilizer Link B : 10 / C : 120 pcs. 	T27410 91111-70856K RN25, RT80 Stabilizer Link B : 20 / C : 240 pcs. 
T27440 90101-08038K LN40, LN50 Stabilizer Link B : 10 / C : 120 pcs. 	T27460 48819-35020K LN85, TIGER Stabilizer Link B : 10 / C : 120 pcs. 
T274X3 90101-10140 LN106, LN145, TIGER LN111 (4WD) Stabilizer Link B : 10 / C : 120 pcs. 	T27620 90101-10259K RH20 Stabilizer Link B : 10 / C : 120 pcs. 
T27650 48819-26050K LH112 Stabilizer Link B : 10 / C : 120 pcs. 	T27820 90101-80206K MS60 Stabilizer Link B : 10 / C : 120 pcs. 
T27910 90101-10323K JU, BU Stabilizer Link B : 10 / C : 120 pcs. 	T27S010 48819-10010K SOLUNA Stabilizer Link B : 10 / C : 120 pcs. 
T27NC42 48819-52010K VIOS Stabilizer Link B : 10 / C : 120 pcs. 	T27NC50 48821-52040 VIOS NCP150, YARIS NSP152, ETIOS Stabilizer Link B : 10 / C : 120 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2709FL 48810-20010 AT171, ST171 Link Assy (FR, LH) B : 2 / C : 90 pcs.	T2709FR 48820-20030 AT171, ST171 Link Assy (FR, RH) B : 2 / C : 90 pcs.
T2710FL 48810-20020 AT191, ST191 Link Assy (FR, LH) B : 2 / C : 90 pcs.	T2710FR 48820-20040 AT191, ST191 Link Assy (FR, RH) B : 2 / C : 90 pcs.
T2730E 48830-20010 AE101, AT171-190 Link Assy (RE) B : 2 / C : 90 pcs.	T2730F 48820-33010 AE101, CAMRY Link Assy (FR) B : 2 / C : 108 pcs.
T274N130F 48820-35010 LN, YZN130 Link Assy (FR) B : 2 / C : 54 pcs.	T274N130E 48830-35010 LN, YZN130 Link Assy (RE) B : 2 / C : 40 pcs.
T2766FL 48810-26010 RZH 135 Link Assy (FR, LH) B : 2 / C : 54 pcs.	T2766FR 48820-26010 RZH 135 Link Assy (FR, RH) B : 2 / C : 54 pcs.
T2786FL 48820-30020 MS132 Link Assy (FR, LH) B : 2 / C : 54 pcs.	T2786FR 48820-30010 MS132 Link Assy (FR, RH) B : 2 / C : 54 pcs.
T27870E 48830-30020 MS133 Link Assy (RE) B : 2 / C : 90 pcs.	
T27880F0 48820-22041 JZS 155, CROWN Link Assy (FR) B : 2 / C : 54 pcs.	T27880E0 48830-22041 JZS 155, CROWN Link Assy (RE) B : 2 / C : 54 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27C0091F 48820-33000 CAMRY (1991) Link Assy (FR)  B : 2 / C : 40 pcs.	T2796E 48830-33010 CAMRY SXV10, SXV20 Link Assy (RE)  B : 2 / C : 40 pcs.
T27C03FL 48810-33010 CAMRY SXV20 Link Assy (FR, LH)  B : 2 / C : 32 pcs.	T27C03FR 48820-33020 CAMRY SXV20 Link Assy (FR, RH)  B : 2 / C : 32 pcs.
T27C04E00 48830-48010 CAMRY ACV30, ACV31 Link Assy (RE)  B : 2 / C : 40 pcs.	T27C04F00 48820-28050 CAMRY ACV30, ACV31, ACR30 Link Assy (FR)  B : 2 / C : 32 pcs.
T27G10E 48830-26030 GRANVIA, VCH10 Link Assy (RE)  B : 2 / C : 90 pcs.	
T27G10FL 48810-26020 GRANVIA, VCH10 Link Assy (FR, LH)  B : 2 / C : 54 pcs.	T27G10FR 48820-26020 GRANVIA, VCH10 Link Assy (FR, RH)  B : 2 / C : 54 pcs.
T27GX81FL 48810-22011 CRESSIDA GX81 Link Assy (FR, LH)  B : 2 / C : 40 pcs.	T27GX81FR 48820-22011 CRESSIDA GX81 Link Assy (FR, RH)  B : 2 / C : 40 pcs.
T27L05F00 48820-35030 LAND CRUISER, PRADO RZJ95 Link Assy (FR)  B : 2 / C : 54 pcs.	T27RV1F 48820-42010 RAV4, SXA11 Link Assy (FR)  B : 2 / C : 90 pcs.
T27RV21F 48820-42020 RAV4, ACA21 Link Assy (FR)  B : 2 / C : 32 pcs.	T27AS42ELR 48830-42022 RAV4 (2012), ASA42, ZSA42 Link Assy (RE, LH,RH)  B : 2 / C : 54 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27SV32E 48830-32030 SV30, SV32, SV33 Link Assy (RE)  B : 2 / C : 40 pcs.	T27SV43E 48830-32040 SV43, CV43 Link Assy (RE)  B : 2 / C : 40 pcs.
T27T11FL 48810-28020 LUCIDA, TCR11 Link Assy (FR, LH)  B : 2 / C : 32 pcs.	T27T11FR 48820-28030 LUCIDA, TCR11 Link Assy (FR, RH)  B : 2 / C : 32 pcs.
T27VG02F 48820-0K010 HILUX VIGO (2WD), REVO Link Assy (FR)  B : 2 / C : 54 pcs.	
T27VG04FL 48810-0K010 HILUX VIGO (4WD), REVO Link Assy (FR, LH)  B : 2 / C : 54 pcs.	T27VG04FR 48820-0K030 HILUX VIGO (4WD), REVO Link Assy (FR, RH)  B : 2 / C : 54 pcs.
T27W110F 48820-02050 WISH Link Assy (FR)  B : 2 / C : 32 pcs.	T27W110E 48820-24010 WISH Link Assy (RE)  B : 2 / C : 90 pcs.
T27ZE121F 48820-47010 ALTIS ZZE121, ZZE122 Link Assy (FR)  B : 2 / C : 32 pcs.	T27KD20F 48820-26050 HIACE, KDH 200 Link Assy (FR)  B : 2 / C : 54 pcs.
T27180F 48820-20010 AT180, AE92 Link Assy (FR)  B : 2 / C : 108 pcs.	T27ST205F 48820-20060 CELICA, ST205 Link Assy (FR)  B : 2 / C : 54 pcs.
T27ST185F 48820-20021 CELICA, ST185 Link Assy (FR)  B : 2 / C : 108 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27C05E00 48830-06070  CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Link Assy (RE) B : 2 / C : 40 pcs.	T27C05F00 48820-06070  CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Link Assy (FR) B : 2 / C : 32 pcs.
T27C06E00 48830-33040  CAMRY ACV41 Link Assy (RE) B : 2 / C : 40 pcs.	
T27KZ7FL 48810-60010 KZJ7#, LJ7#, BJ7#  Link Assy (FR, LH) B : 2 / C : 54 pcs.	T27KZ7FR 48820-60010 KZJ7#, LJ7#, BJ7#  Link Assy (FR, RH) B : 2 / C : 54 pcs.
T27RC11FL 48810-26030 GRANVIA, RCH11  Link Assy (FR, LH) B : 2 / C : 108 pcs.	T27RC11FR 48820-26030 GRANVIA, RCH11  Link Assy (FR, RH) B : 2 / C : 108 pcs.
T27RC135E 48830-26011 GRANVIA, RCH135  Link Assy (RE) B : 2 / C : 90 pcs.	T2730CF 48820-12010 COUPE SUPER STRUT, AE101  Link Assy (FR) B : 2 / C : 40 pcs.
T27LS40E 48830-50020 UCF10, LS400  Link Assy (RE) B : 2 / C : 90 pcs.	
T27RV10E 48830-42020 RAV4 (2000-2006)  Link Assy (RE) B : 2 / C : 54 pcs.	T27RV10F 48820-42030, 02080, 47020 RAV4 ACA30, ASA44, ALPHARD, ANH20, AGH30, AYH30, HYBRID, PRIUS, ZVW30, ESTIMA ACR50  Link Assy (FR) B : 1 / C : 18 pcs.
T27UC10FL 48810-50011 UCF10  Link Assy (FR, LH) B : 2 / C : 54 pcs.	T27UC10FR 48820-50011 UCF10  Link Assy (FR, RH) B : 2 / C : 54 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27CR27F 48820-28021 CR27 Link Assy (FR)  B : 2 / C : 108 pcs.	T27JZ160E 48830-30080 JZH160 Link Assy (RE)  B : 2 / C : 54 pcs.
T27JZ175E 48830-51010 JZH175 Link Assy (RE)  B : 2 / C : 54 pcs.	
T27LE00E 48802-60090 LEXUS LX470 (1998-2002) Link Assy (RE)  B : 2 / C : 54 pcs.	T27LE00F 48820-60032 LEXUS LX470 (1998-2002) Link Assy (FR)  B : 2 / C : 108 pcs.
T27NCP91 48820-0D020 YARIS NCP91, VIOS NCP93 Link Assy (FR)  B : 2 / C : 36 pcs.	T27ZJ95E 48830-35020 PRADO VZJ95 Link Assy (RE)  B : 2 / C : 54 pcs.
T27RV21EL 48840-42010 RAV4, ACA21 Link Assy (RE, LH)  B : 2 / C : 108 pcs.	T27RV21ER 48830-42010 RAV4, ACA21 Link Assy (RE, RH)  B : 2 / C : 108 pcs.
T27ZE141F 48820-02100 ALTIS ZZE141 Link Assy (FR)  B : 2 / C : 32 pcs.	
T27F60F 48820-B0010, 48820-BZ080 AVANZA F601, F602, F653 Link Assy (FR)  B : 2 / C : 40 pcs.	T27ZT231F 48820-32010 CELICA, ZTZ231 Link Assy (FR)  B : 2 / C : 32 pcs.
T27CT190E 48830-12050 CT190#, AT17#, ST17#, SV2# Link Assy (RE, LH, RH)  B : 2 / C : 54 pcs.	T27UZ20F 48802-60110 GRJ200, UZJ200, VDJ200 Link Assy (FR, LH, RH)  B : 2 / C : 54 pcs.



is the registered trademark

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27100FL 48810-20030 AT19#, CT190, ST191 Link Assy (FR, LH)  B : 2 / C : 54 pcs.	T27100FR 48820-20050 AT19#, CT190, ST191 Link Assy (FR, RH)  B : 2 / C : 54 pcs.
T27A25EL 48840-21010 AZT250, AZT255, ST246 Link Assy (RE, LH)  B : 2 / C : 90 pcs.	T27A25ER 48830-21020 AZT250, AZT255, ST246 Link Assy (RE, RH)  B : 2 / C : 90 pcs.
T27AC30F 48820-28060 ACR30, ACR40, MCR30, MCR40, CLR30 Link Assy (FR)  B : 2 / C : 32 pcs.	T27AZ60F 48820-44020 ZRR70, AZR60, ACM20, AM10, ANM15 Link Assy (FR)  B : 2 / C : 32 pcs.
T27BZ40E 48830-36020 BZB40, BZB50, HDB40, HDB50, XZB4, XZB5 Link Assy (RE)  B : 2 / C : 40 pcs.	T27C05F01 48820-33060 AVC4#, GSV40 Link Assy (FR)  B : 2 / C : 40 pcs.
T27GR15E 48830-60030 GRJ15#, TRJ15# Link Assy (RE)  B : 2 / C : 54 pcs.	
T27GR18F0 48820-30100 GRS181, GRS183, GRS195, GRS196, UZS187, GSE25, GRX125 Link Assy (FR)  B : 2 / C : 90 pcs.	T27GR18E 48830-30090 GRS180, GRS190, GRS20#, GWS204, URS206, UZS207, USE20, GSE2# Link Assy (RE)  B : 2 / C : 54 pcs.
T27GR18FL 48810-30080 GRS181, GRS183, GRS195, GRS196, GSE25, GRX125 Link Assy (FR, LH)  B : 2 / C : 90 pcs.	T27GR18FR 48820-30090 GRS180, GRS190, GRS20#, GWS204, URS206, UZS207, USE20, GSE2# (2WD, 4WD) Link Assy (FR, RH)  B : 2 / C : 54 pcs.
T27GR80FL 48810-30070 GRS180, GRS190, GRS20#, GWS204, URS206, UZS207, USE20, GSE2# (2WD, 4WD) Link Assy (FR, LH)  B : 2 / C : 54 pcs.	T27GS3F 48820-34010 GSK3#, UCK3# VCK30, VCK40 Link Assy (FR)  B : 2 / C : 40 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27HD51F 48820-36010, 48820-36020, 48820-36021 HDB51, HZB41, XZB51  Link Assy (FR) B : 2 / C : 36 pcs.	T27J200F 48822-97503 J200E, S221E, S231E  Link Assy (FR) B : 2 / C : 108 pcs.
T27MH38E 48830-48030 MHU38  Link Assy (RE, LH, RH) B : 2 / C : 40 pcs.	
T27UC3EL 48840-50010 UCF3#  Link Assy (RE, LH) B : 2 / C : 90 pcs.	T27UC3ER 48830-50030 UCF3#  Link Assy (RE, RH) B : 2 / C : 90 pcs.
T27US40FL 48810-50020 LEXUS LS450 (2006) USF40  Link Assy (FR, LH) B : 2 / C : 90 pcs.	T27US40FR 48820-50030 LEXUS LS450 (2006) USF40  Link Assy (FR, RH) B : 2 / C : 90 pcs.
T27UZ21F 48802-60100 UZJ200, VDJ200  Link Assy (FR) B : 2 / C : 90 pcs.	T27ZE124E 48830-32050 ZZE124, ZZE129, NZE124 WISH (4WD)  Link Assy (RE) B : 2 / C : 108 pcs.
T27C06FL 48810-33020 ACV35  Link Assy (FR, LH) B : 2 / C : 40 pcs.	T27C06FR 48820-33030 ACV35  Link Assy (FR, RH) B : 2 / C : 40 pcs.
T27E91F 48820-10010 E91  Link Assy (FR, LH, RH) B : 2 / C : 108 pcs.	
T27GS20FL 48810-53010 ALE20, GSE2#  Link Assy (FR, LH) B : 2 / C : 54 pcs.	T27GS20FR 48820-53010 ALE20, GSE2#  Link Assy (FR, RH) B : 2 / C : 54 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27GX10FL 48810-22041 GX93, GX105, GX115, JZX115 (4WD), UZS155 (4WD), GXE15, JCE15 (4WD) Link Assy (FR, LH) B : 2 / C : 40 pcs.	T27GX10FR 48820-22051 GX93, GX105, GX115, JZX115 (4WD), UZS155 (4WD), GXE15, JCE15 (4WD) Link Assy (FR, LH) B : 2 / C : 40 pcs.
T27JZ140 48830-24010 JZS147 (1993-1995), JZS147 (1993-1995), JZZ3#, UZZ30 (1991-2000), JZS147, UZS143 Link Assy (RE, LH, RH) B : 2 / C : 108 pcs.	T27JZ14E 48830-30060 JZS147 (1995-1997), UZS143 (1995-1997), JZS155, UZS151 (1995-1999) Link Assy (RE, LH, RH) B : 2 / C : 108 pcs.
T27SR40E 48830-28010 SR40, SR50, CR40, CR50 Link Assy (RE, LH, RH) B : 2 / C : 90 pcs.	
T27SR40FL 48810-28030 SR40, SR50, CR40, CR50 Link Assy (FR, LH) B : 2 / C : 54 pcs.	T27SR40FR 48820-28040 SR40, SR50, CR40, CR50 Link Assy (FR, RH) B : 2 / C : 54 pcs.
T27UZ15EL 48840-14030 UZS155, JZA80 Link Assy (RE, LH) B : 2 / C : 90 pcs.	T27UZ15ER 48830-14050 UZS155, JZA80 Link Assy (RE, RH) B : 2 / C : 90 pcs.
T27AN10F 48820-58010 ANH10, ATH10, MNH10 Link Assy (FR) B : 2 / C : 32 pcs.	
T27US40EL 48840-50020 LEXUS LS450 (2006) USF40 Link Assy (RE, LH) B : 2 / C : 32 pcs.	T27US40ER 48830-50040 LEXUS LS450 (2006) USF40 Link Assy (RE, RH) B : 2 / C : 32 pcs.
T27ZT230F 48820-20070 ZZT231 Link Assy (FR, LH, RH) B : 2 / C : 54 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T27J214FL 48810-30010 JZS147, 160M, UZS151, UZS171, UZS175 Link Assy (FR, LH) B : 2 / C : 24 pcs.	T27J214FR 48820-30030 JZS147, 160M, UZS151, UZS171, UZS175 Link Assy (FR, RH) B : 2 / C : 24 pcs.
T27UZ14FL 48810-30050 UZS143, UZS155, UZS173 Link Assy (FR, LH) B : 2 / C : 24 pcs.	T27UZ14FR 48820-30070 UZS143, UZS155, UZS173 Link Assy (FR, RH) B : 2 / C : 24 pcs.
T27CH18F 48820-F4010 C-HR (2018), ALTIS (2020) Link Assy (FR, LH, RH) B : 2 / C : 36 pcs.	T27GD30E 48830-26040 GDH300 Link Assy (RE, LH, RH) B : 2 / C : 54 pcs.
T27CR19F 48820-06110 CAMRY ASV71 Link Assy (FR, LH, RH) B : 2 / C : 32 pcs.	T27CR19E 48830-06100 CAMRY ASV71, C-HR (2018), ALTIS (2019) ZRE210, 211, ZWE211 Link Assy (RE, LH, RH) B : 2 / C : 54 pcs.
T27GD30FL 48810-26050 GDH300 Link Assy (FR, LH) B : 1 / C : 16 pcs.	T27GD30FR 48820-26060 GDH300 Link Assy (FR, RH) B : 1 / C : 16 pcs.
T27FT15E 48830-0K010 FORTUNER (2015) Link Assy (RE) B : 2 / C : 54 pcs.	T27YR19F0 48820-WB002 YARIS DADW1, DAEA1 (2016-2019), YARIS R (2016), YARIS IA (2017), SCION IA (2016) Link Assy (FR, LH, RH) B : 2 / C : 40 pcs.
T27KD12FL 48810-60040 PRADO (2009) GRJ121, KDJ121, TRJ150 Link Assy (FR, LH) B : 2 / C : 54 pcs.	T27KD12FR 48820-60050 PRADO (2009) GRJ121, KDJ121, TRJ150 Link Assy (FR, RH) B : 2 / C : 54 pcs.
T27ST17F 48820-0D040 SIENTA NSP170 Link Assy (FR) B : 2 / C : 36 pcs.	




is the registered trademark



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2841W 48304-39035 RN25 Lower Bumper Bound B : 6 / c : 72 pcs. 	
T2844E 48341-35020 LN40, RN30 Bumper Bound (RE) B : 4 / c : 48 pcs. 	T2844P 48332-35010 RN30, LN40 Upper Bumper Bound B : 20 / c : 480 pcs. 
T2844W 48304-35030 RN30, LN40 Lower Bumper Bound B : 6 / c : 72 pcs. 	T2845E 48341-35041 LN50 Bumper Bound (RE) B : 2 / c : 24 pcs. 
T2845P 48332-35020 LN50, LN85, LH112 Upper Bumper Bound B : 16 / c : 384 pcs. 	T2845W 48304-35080 LN50, LN56 Lower Bumper Bound B : 4 / c : 48 pcs. 
T2846E 48341-35050 LN85 Bumper Bound (RE) B : 4 / c : 48 pcs. 	T2846W 48304-35130 LN85 Lower Bumper Bound B : 6 / c : 72 pcs. 
T284X3WB 48304-04060 TIGER LN111 (4WD) Low Bumper Bound (BIG) B : 8 / c : 96 pcs. 	T284X3PS 48305-04020 TIGER LN111 (4WD) Upper Bumper Bound (SMALL) B : 10 / c : 120 pcs. 
T284X3W 48304-04050 LN145, LN156, TIGER (2WD) Lower Bumper Bound B : 6 / c : 72 pcs. 	T2847XE 48306-35190, 48306-04020 VIGO, TIGER LN111, LN145 (4WD) Upper Bumper Bound (RE) B : 4 / c : 48 pcs. 
T2862P 48305-26011 RH20, RH30 Upper Bumper Bound B : 10 / c : 120 pcs. 	T2862W 48304-26010 RH20, RH30 Lower Bumper Bound B : 6 / c : 72 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2865E 48341-26150 LH112 Bumper Bound (RE)	 B : 2 / C : 24 pcs.	T2865W 48331-26090, 26100 LH112 Lower Bumper Bound	 B : 6 / C : 72 pcs.
T28VG02W 48304-0K010, 0K020 HILUX VIGO (2WD), INNOVA, REVO Lower Bumper Bound	 B : 6 / C : 72 pcs.	T28VG02E 48341-0K010 HILUX VIGO (2WD) Bumper Bound (RE)	 B : 4 / C : 48 pcs.
T28VG04W 48304-0K040 HILUX VIGO (4WD), REVO Lower Bumper Bound	 B : 4 / C : 48 pcs.	T284X4W 48304-35100 LN, RN, YN106 (4WD) Lower Bumper Bound	 B : 2 / C : 24 pcs.
T284X20E 48306-35110 LN106 Bumper Bound (RE)	 B : 2 / C : 24 pcs.		
T28KD20E 48341-26240 HIACE, KDH200 Bumper Bound (RE)	 B : 2 / C : 24 pcs.	T28KD20W 48331-26140 HIACE, KDH200 Lower Bumper Bound	 B : 6 / C : 72 pcs.
T28DJ21EL 48036-60010 PRADO KDJ215 Bumper Bound (RE,LH)	 B : 2 / C : 24 pcs.	T28DJ21ER 48306-60200 PRADO KDJ215 Bumper Bound (RE,RH)	 B : 2 / C : 24 pcs.
T28FJ01WL 48305-60020 FJ75, BJ, HJ Lower Bumper Bound (LH)	 B : 2 / C : 24 pcs.	T28FJ01WR 48304-60050 FJ75, BJ, HJ Lower Bumper Bound (RH)	 B : 2 / C : 24 pcs.



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T2847X2C 48341-04040 TIGER (2WD) (CAP4) Bumper Bound (RE) B : 2 / C : 24 pcs.		T2847X2E 48341-04030 TIGER (2WD) Bumper Bound (RE) B : 2 / C : 24 pcs.	
T28IN40E 48341-0K030, 48341-0K050 INNOVA KUN40 Bumper Bound (RE) B : 4 / C : 48 pcs.		T28RN67W 48304-36040 RN67, YN67 Lower Bumper Bound B : 2 / C : 24 pcs.	
T28KD20S 48252-28170 KDH 200 Bumper Bound (SMALL) B : 10 / C : 120 pcs.			
T28JZ95E 48306-35180 VZJ95 Bumper Bound (RE) B : 2 / C : 24 pcs.		T28FT16E0 48341-0K110 FORTUNER (2016) Bumper bound (RE) B : 2 / C : 24 pcs.	
T28RV02E 48341-0K090 REVO (2WD) Bumper Bound (RE) B : 4 / C : 48 pcs.		T28RV04E 48306-0K040 REVO (4WD) Bumper Bound (RE) B : 4 / C : 48 pcs.	
T28RV15E 48306-0K050 REVO PRERUNNER Bumper Bound (RE) B : 2 / C : 24 pcs.		T28IN15E 48341-0K150 INNOVA GUN143 Bumper Bound (RE) B : 2 / C : 24 pcs.	
T28GD30E0 48341-26290 COMMUTER, MAJESTY (2019) GDH300, HIACE (2019) GDH322 Bumper Bound (RE) B : 2 / C : 24 pcs.			





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Center Bearings assembled with Japanese Bearing

T29050 37230-14031 TT132 Center Bearing  B : 1 / C : 24 pcs.	T29060 37230-24010, 37230-22140 TT141 Center Bearing  B : 1 / C : 24 pcs.
T29411 37230-35013 RN20 Center Bearing  B : 1 / C : 24 pcs.	T29412 37230-40031 RN25 Center Bearing  B : 1 / C : 20 pcs.
T29440 37230-35030 LN40, RN30 Center Bearing  B : 1 / C : 24 pcs.	T29450 37230-35050, 37230-35070 LN50, LN85 Center Bearing  B : 1 / C : 24 pcs.
T2947X4 37230-35130 TIGER (4WD) Center Bearing  B : 1 / C : 24 pcs.	T2947X2 37230-35120 TIGER (2WD) Center Bearing  B : 1 / C : 24 pcs.
T294X10 37230-35061 LN65 (4WD) Center Bearing (THIN)  B : 1 / C : 10 pcs.	T294X20 37230-35080, 37230-35100 LN106 (4WD) Center Bearing (THICK)  B : 1 / C : 10 pcs.
T29650 37230-26010 LH112 Center Bearing  B : 1 / C : 24 pcs.	T29830 37230-30022 MS80 Center Bearing  B : 1 / C : 24 pcs.
T29840 37230-30030 MS110 Center Bearing  B : 1 / C : 24 pcs.	T29850 37230-30040 MS122, MS132 Center Bearing  B : 1 / C : 20 pcs.
T29T11BS 48725-28010 LUCIDA (B) Coupling Bush  B : 12 / C : 216 pcs.	T29T11DB 48725-28020 LUCIDA (D) Coupling Bush  B : 12 / C : 216 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

* RBI Center Bearings assembled with Japanese Bearing

T29VG02 37230-0K021 HILUX VIGO (2WD) Center Bearing B : 1 / C : 24 pcs. 	T29VG04 37230-0K011 HILUX VIGO (4WD) Center Bearing B : 1 / C : 24 pcs. 
T29KD200 37230-26030 KDH200 Center Bearing B : 1 / C : 24 pcs. 	
T29GX10 37230-22110, 37230-30152 MARK II, GX100, GX105, JZS151 Center Bearing B : 1 / C : 24 pcs. 	T29RV21 37230-20130, 29025 RAV4 ACA21 Center Bearing B : 1 / C : 20 pcs. 
T29F600 37230-BZ010 AVANZA F601, F602 Center Bearing B : 1 / C : 20 pcs. 	
T29MC15 37230-29015 HARRIER MCU15, MCU35, MCU36 Center Bearing (RE) B : 1 / C : 20 pcs. 	T29MC15E 37230-49015 HARRIER MCU15, MCU35, MCU36 Center Bearing (FR) B : 1 / C : 20 pcs. 
T29RV020 37230-09010 REVO (2WD), GUN122 Center Bearing B : 1 / C : 20 pcs. 	T29RV021 37230-09020 REVO PRERUNNER Center Bearing B : 1 / C : 20 pcs. 
T29RV040 37230-09030 REVO (4WD), GUN126 Center Bearing B : 1 / C : 20 pcs. 	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

TOYOTA

T30060 47731-14070 TT141 Cylinder Piston  B : 1 / C : 60 pcs.	T30081 47731-32020 AT171 (1600) Cylinder Piston  B : 1 / C : 60 pcs.
T30082 47731-32040 AT171 (2000) Cylinder Piston  B : 1 / C : 60 pcs.	T30090 47731-20190 CAMRY AT, ST190, ST191 Cylinder Piston  B : 1 / C : 60 pcs.
T30280 47731-12150 AE92, AE101 Cylinder Piston  B : 1 / C : 60 pcs.	T30430 47731-26010 RN30, RH30 Cylinder Piston  B : 1 / C : 60 pcs.
T30440 47731-26020 LN40 Cylinder Piston  B : 1 / C : 60 pcs.	T30450 47731-40010 LN50-85 Cylinder Piston  B : 1 / C : 60 pcs.
T3047X 47731-35010 LN106, LN111, TIGER (4WD) Cylinder Piston  B : 1 / C : 120 pcs.	T30650 47731-25010 LH112 Cylinder Piston  B : 1 / C : 75 pcs.
T30810 47731-20040 MS50, MS60 Cylinder Piston  B : 1 / C : 120 pcs.	T30820 47731-30040 MS80, MS110 Cylinder Piston  B : 1 / C : 60 pcs.
T30860 47731-35020 MS132 Cylinder Piston (FR)  B : 1 / C : 60 pcs.	T30S01 47731-16020 SOLUNA AL50 Cylinder Piston  B : 1 / C : 60 pcs.
T3047X2 47731-04050 TIGER (2WD) Cylinder Piston  B : 1 / C : 60 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T30Z121F 47731-02160 ALTIS ZZ121, ZZ122 Cylinder Piston (FR)  B : 1 / C : 60 pcs.	T30Z121E 47731-42020 ALTIS ZZ121, ZZ122 Cylinder Piston (RE)  B : 1 / C : 120 pcs.
T30NC42F 47731-0D040 VIOS Cylinder Piston (FR)  B : 1 / C : 60 pcs.	T30NC42E 47731-52020 VIOS Cylinder Piston (RE)  B : 1 / C : 120 pcs.
T30W1100 47731-33090 WISH, ANE11 Cylinder Piston (FR)  B : 1 / C : 75 pcs.	T30W110E 47731-48020 WISH, ANE11 Cylinder Piston (RE)  B : 1 / C : 120 pcs.
T30Z121FS 47731-12170 ALTIS (1600) Cylinder Piston (FR, SMALL)  B : 1 / C : 60 pcs.	T30VG04 47731-0K060 HILUX VIGO (4WD) Cylinder Piston  B : 1 / C : 120 pcs.
T30FJ80E 47731-60020 FJ80 Cylinder Piston (RE)  B : 1 / C : 120 pcs.	T30YZ130 47731-60010 SURF, YZN130 Cylinder Piston  B : 1 / C : 60 pcs.
T30C05F 47731-06260 CAMRY (2007) ACV40, (2012) ACV51, ASV50, AVV50 Cylinder Piston (FR)  B : 1 / C : 75 pcs.	
T30YA91FE 47731-52190 YARIS NCP91 (E, G) Cylinder Piston (FR)  B : 1 / C : 60 pcs.	T30YA91FS 47731-52210 YARIS NCP91 (S) Cylinder Piston (FR)  B : 1 / C : 60 pcs.
T30Z141F 47731-02450 ALTIS ZZE141 Cylinder Piston (FR)  B : 1 / C : 60 pcs.	



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T30UZ10E 47731-60070 UZJ100, VX100, HDJ101 Cylinder Piston (RE)  B : 1 / C : 60 pcs.	T30UZ10F 47732-60010 HZJ105 Cylinder Piston (FR)  B : 1 / C : 120 pcs.
T30UZ30F 47731-60030 UZJ100 Cylinder Piston (FR)  B : 1 / C : 120 pcs.	T30UZ40F 47731-60040 FZJ105 Cylinder Piston (FR)  B : 1 / C : 120 pcs.
T30F60F 47731-BZ010 AVANZA F601, F602 Cylinder Piston (FR)  B : 1 / C : 60 pcs.	
T3047X4 47731-35050 TIGER (4WD) LN167, KZN165 Cylinder Piston  B : 1 / C : 120 pcs.	T30C07E 47831-06090 CAMRY (2012) ACV50, ACV51, ASV50, AVV50 Cylinder Piston (RE)  B : 1 / C : 120 pcs.
T30NC500F 47731-0D220 VIOS NCP150, YARIS NSP152 D, R, ETIOS Cylinder Piston (FR)  B : 1 / C : 60 pcs.	T30NC50F 47731-0D110 VIOS NCP150, YARIS NSP152 G, V, ETIOS Cylinder Piston (FR)  B : 1 / C : 60 pcs.
T30ZJ95 47731-35040 PRADO VZJ95, VIGO CHAMP (4WD) Cylinder Piston  B : 1 / C : 120 pcs.	
T30AH20F 47731-48030 ALPHARD ANH20, AGH30, AYH30 Cylinder Piston (FR)  B : 1 / C : 75 pcs.	T30AH21F 47731-48150 ALPHARD ANH20 (CVT) Cylinder Piston (FR)  B : 1 / C : 60 pcs.
T30RV02F 47731-0K220 REVO (2WD) Cylinder Piston (FR)  B : 1 / C : 60 pcs.	T30Z141E 47831-52050 ALTIS ZZE141 Cylinder Piston (RE)  B : 1 / C : 60 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T31070 17573-74020 AT, ST171 Exhaust Pipe Support B : 6 / C : 96 pcs. 	T31090 17571-74333 AT, ST190 Exhaust Pipe Support B : 6 / C : 96 pcs. 
	T31310 17506-15070 AE101, AE111 Exhaust Pipe Support B : 6 / C : 96 pcs. 
T31310Z 17506-15070-IN AE101 Exhaust Pipe Support (Bracket) B : 2 / C : 32 pcs. 	T31311Z 17506-15080-IN AE101 Exhaust Pipe Support (Bracket) B : 2 / C : 32 pcs. 
T31460 17572-54080-IN, 54081-IN LN85 Exhaust Pipe Support (Bracket) B : 4 / C : 64 pcs. 	T31RV10 17565-74420 RAV4, SXA1#, 3SFE, 1FZFE, 1HZ, FZJ105, HZJ105 Exhaust Pipe Support B : 6 / C : 96 pcs. 
T31462 17563-35020 LN85 (2 HOLE) Exhaust Pipe Support B : 12 / C : 192 pcs. 	T31463 17566-35010 LN85 (3 HOLE) Exhaust Pipe Support B : 12 / C : 192 pcs. 
T31650 17563-63020 LH112 Exhaust Pipe Support B : 12 / C : 192 pcs. 	T31BU610 17567-61030 BU61, LAND CRUISER Exhaust Pipe Support B : 12 / C : 192 pcs. 
T31C0203 17572-07040 CAMRY SXV10, SXV20 Exhaust Pipe Support B : 6 / C : 96 pcs. 	T31KD200 17565-28010 KDH200 Exhaust Pipe Support B : 10 / C : 160 pcs. 
T31C040 17572-0H040 CAMRY ACV30 Exhaust Pipe Support B : 6 / C : 96 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T3809LA 45517-20050 AT, ST171 Grommet Steering Rack (LH, A/T) B : 8 / c : 128 pcs. 	T3809LM 45517-20060 AT, ST171 Grommet Steering Rack (LH, M/T) B : 8 / c : 128 pcs. 
T3809R 45516-20020, 20050 AT, ST171 Grommet Steering Rack (RH, A/T, M/T) B : 8 / c : 128 pcs. 	T3811LM 45517-20150 AT190, ST190 Grommet Steering Rack (LH) B : 8 / c : 128 pcs. 
T3824L 45517-12020 KE70 Grommet Steering Rack (LH) B : 10 / c : 160 pcs. 	T3824R 45516-12020 KE70 Grommet Steering Rack (RH) B : 10 / c : 160 pcs. 
T3825L 45517-12120 AE80, EE90 Grommet Steering Rack (LH) B : 6 / c : 96 pcs. 	T3825R 45516-20010 AE80, EE90 Grommet Steering Rack (RH) B : 6 / c : 96 pcs. 
T3829L 45517-12111 AE101, AE111 Grommet Steering Rack (LH) B : 6 / c : 96 pcs. 	T3829R 45516-12060 AE101 Grommet Steering Rack (RH) B : 6 / c : 96 pcs. 
T3865L 45517-26030 LH112 Grommet Steering Rack (LH) B : 6 / c : 96 pcs. 	T3865LP 45517-26020 LH112 Grommet Steering Rack (LH, POWER) B : 6 / c : 96 pcs. 
T3865R 45516-26010 LH112 Grommet Steering Rack (RH) B : 6 / c : 96 pcs. 	T38ST195 45517-20130 ST195, ST198, ST215, CT195, ST198, CT199, CT215, CT216, SXM15, SXN15 Grommet Steering Rack B : 8 / c : 128 pcs. 
T38AC10L 45517-44010 ACM10, CXM10, SXM10 Grommet Steering Rack (LH) B : 6 / c : 96 pcs. 	T38AC20L 45517-42020 ACA2#, CLA2#, ZCA2#, AT19#, AT191, AT210, AT211, AT212, ST190, ST191, ST210, ET196 Grommet Steering Rack (LH) B : 6 / c : 96 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

TOYOTA

T38C02L 45517-786RB CAMRY Grommet Steering Rack (LH) B : 8 / C : 128 pcs. 	T38KD20L 45517-26060 KDH200 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 
T38S01ML 45517-0A010 SOLUNA AL50 Grommet Steering Rack (LH, M/T) B : 8 / C : 128 pcs. 	T38S01MR 45516-0A010 SOLUNA AL50 Grommet Steering Rack (RH, M/T) B : 8 / C : 128 pcs. 
T38S01PL 45517-10070 SOLUNA AL50 Grommet Steering Rack (LH, POWER) B : 8 / C : 128 pcs. 	T38S01PR 45516-16060 SOLUNA AL50 Grommet Steering Rack (RH, POWER) B : 8 / C : 128 pcs. 
T38NC42L 45517-0D040 VIOS Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 	T38ZJ95L 45517-35010 PRADO VZJ95 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 
T38F60L 45516-BZ010, 45516-BZ120 AVANZA F601 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 