



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

List of New Products

MAZDA

D21MZ02F1	NEW	CN155484AA, CN1Z5484B, DN21 34 156A MAZDA2 (2012) DE, (4D, 5D SPORT), ECOSPORT Stabilizer Shaft Rubber (FR)		B : 8 / C : 192 pcs.
-----------	------------	--	--	----------------------

TOYOTA

T09AH20LZ	NEW	12372-28390-IN ALPHARD ANH20, ESTIMA ACR50 Insulator Engine (LH)		B : 1 / C : 8 pcs.	T13CR19F	NEW	48609-06410 CAMRY ASV71 (2019) Shock Absorber Mounting (FR)		B : 1 / C : 20 pcs.
T14AG30F1	NEW	48331-58010 ALPHARD AGH30 (2015) Shock Absorber Bumper (FR)		B : 6 / C : 72 pcs.	T14AN10F1	NEW	48331-28040 ALPHARD ANH10 (2002-2007), ESTIMA ACR30, ACR40 (2000-2006) Shock Absorber Bumper (LH,RH)		B : 6 / C : 72 pcs.
T14F65F1	NEW	48331-BZ110 AVANZA F651 Shock Absorber Bumper (FR)		B : 6 / C : 72 pcs.	T25AH30800	NEW	48780-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)		B : 2 / C : 24 pcs.
T25AH30200	NEW	48720-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)		B : 6 / C : 108 pcs.	T25AH30400	NEW	48740-58010-0 ALPHARD, VELLFIRE AGH30, AYH30 (2015) Suspension Bush (RE)		B : 6 / C : 108 pcs.
T26F60R	NEW	45516-BZ140 AVANZA F601 Grommet Steering Bush (RH)		B : 10 / C : 180 pcs.	T26GD30E0	NEW	48530-80A06-0, 48537-26010 GDH300 Shock Absorber Bush (RE)		B : 8 / C : 144 pcs.
T27FT15E	NEW	48830-0K010 FORTUNER (2015) Link Assy (RE)		B : 2 / C : 54 pcs.	T27YR19F0	NEW	48820-WB002 YARIS DADW1, DAEA1 (2016-2019), YARIS R (2016), YARIS IA (2017), SCION IA (2016) Link Assy (FR, LH, RH)		B : 2 / C : 40 pcs.



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

TOYOTA

<p>T27KD12FL NEW</p> <p>48810-60040 PRADO (2009) GRJ121, KDJ121, TRJ150 Link Assy (FR, LH)</p>  <p>B : 2 / C : 54 pcs.</p>	<p>T27KD12FR NEW</p> <p>48820-60050 PRADO (2009) GRJ121, KDJ121, TRJ150 Link Assy (FR, RH)</p>  <p>B : 2 / C : 54 pcs.</p>
<p>T28IN15E NEW</p> <p>48341-0K150 INNOVA GUN143 Bumper Bound (RE)</p>  <p>B : 2 / C : 24 pcs.</p>	



MITSUBISHI

<p>M26XP18EW NEW</p> <p>4162A409-0 XPANDER (2018) NC1W Shock Absorber Bush (RE)</p>  <p>B : 6 / C : 108 pcs.</p>	
--	--

NISSAN

<p>N19T32EP NEW</p> <p>55034-EN101 X-TRAIL T31, T32 (2013) Coil Spring Rubber (RE, UPPER)</p>  <p>B : 4 / C : 64 pcs.</p>	<p>N27Y61E0 NEW</p> <p>56260-VC300 PATROL Y61 (1997-2013) Link Assy (RE)</p>  <p>B : 2 / C : 54 pcs.</p>
<p>N25Y62EP NEW</p> <p>55045-1LB0A, 55501-1LB0A-0 PATROL Y62 Suspension Bush (UP RE LH,RH)</p>  <p>B : 4 / C : 72 pcs.</p>	<p>N25Y62EW NEW</p> <p>551A0-1LB0B-0 PATROL Y62 Suspension Bush (LOW RE LH,RH)</p>  <p>B : 4 / C : 72 pcs.</p>

HONDA

<p>O14305E0 NEW</p> <p>52610-SEL-T22-3 CITY (03) G2, (06) ZX, (08) G3, JAZZ (04) GD, (09) GE, BRIO, AMAZE (11), BR-V (16) Shock Dust Cover (RE)</p>  <p>B : 2 / C : 40 pcs.</p>	<p>O14515E1 NEW</p> <p>52722-T8N-T01 HR-V (2015) Shock Dust Cover (RE, INNER)</p>  <p>B : 2 / C : 12 pcs.</p>
--	--



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

List of New Products

PP+EPDM

<p>A18PM5LR NEW</p> <p>10045281-P</p> <p>MG5</p> <p>Steering Gear Boot LH, RH (PP+EPDM) B : 2 / C : 50 pcs.</p>		<p>A18PM617LR NEW</p> <p>QFWS0011A-P</p> <p>MG6 (2014)</p> <p>Steering Gear Boot LH, RH (PP+EPDM) B : 2 / C : 50 pcs.</p>	
<p>T18PC07LR NEW</p> <p>45535-09250-P</p> <p>CAMRY (2012) ACV51, ASV50, AVV50</p> <p>Steering Gear Boot LH, RH (PP+EPDM) B : 2 / C : 50 pcs.</p>		<p>T18PZE1410 NEW</p> <p>45535-09110-P</p> <p>ALTIS ZZE141,142, ZRE171</p> <p>Steering Gear Boot LH, RH (PP+EPDM) B : 2 / C : 50 pcs.</p>	

TPEE

<p>N17PNR40UZ NEW</p> <p>39241-EA027-P</p> <p>NAVARA D40T (4WD)</p> <p>Drive Shaft Boot (OUTER, TPEE) B : 1 / C : 44 pcs.</p>		<p>D17PMZ2UA NEW</p> <p>FA81 22 530A-P</p> <p>MAZDA2, FIESTA</p> <p>Drive Shaft Boot (A/T, OUTER, TPEE) B : 1 / C : 44 pcs.</p>	
<p>D17PCX12DFU NEW</p> <p>FTB4 22 530-P</p> <p>CX5 (2012) (D)</p> <p>Drive Shaft Boot (FR, OUTER, TPEE) B : 1 / C : 44 pcs.</p>		<p>D17PCX12EU NEW</p> <p>RTA1 22 530-P</p> <p>CX5 (2012) (4WD)</p> <p>Drive Shaft Boot (RE, OUTER, TPEE) B : 1 / C : 44 pcs.</p>	
<p>D17PT20IZ NEW</p> <p>GD29 22 540-P</p> <p>TRIBUTE, ESCAPE</p> <p>Drive Shaft Boot (RE, INNER, TPEE) B : 1 / C : 44 pcs.</p>		<p>D17PT20UE NEW</p> <p>GD29 22 530-P</p> <p>TRIBUTE, ESCAPE</p> <p>Drive Shaft Boot (RE, OUTER, TPEE) B : 1 / C : 44 pcs.</p>	

BEARING

<p>A13BHS19F NEW</p> <p>10401259</p> <p>MG HS (2019)</p> <p>Shock Absorber Bearing (FR) B : 2 / C : 32 pcs.</p>		<p>A13BZS17F NEW</p> <p>10244443</p> <p>MG ZS (2017)</p> <p>Shock Absorber Bearing (FR) B : 4 / C : 72 pcs.</p>	
--	--	--	--



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

FORD

124ES13WS	NEW	GN153063AA, GN1Z3079B-2 ECOSPORT (2013) Lower Arm Bushing (SMALL)		B : 6 / C : 108 pcs.
-----------	------------	---	--	----------------------

MG

A14HS19F	NEW	10486951 MG HS (2019) Shock Absorber Bumper (FR)		B : 6 / C : 72 pcs.	A14ZS17E1	NEW	10297341 MG ZS (2017) Shock Absorber Bumper (RE)		B : 6 / C : 72 pcs.
A14MG516F	NEW	10091669 MG5 (2016) Shock Absorber Bumper (FR)		B : 8 / C : 96 pcs.	A14M516E1	NEW	10091675 MG5 (2016) Shock Absorber Bumper (RE)		B : 6 / C : 72 pcs.
A14ZS17F1	NEW	10415595 MG ZS (2017) Shock Absorber Bumper (FR)		B : 6 / C : 72 pcs.					
A27MG516F	NEW	10091671 MG5 (2016) Link Assy (FR)		B : 2 / C : 40 pcs.	A27ZS17F	NEW	10227851 MG ZS (2017) Link Assy (FR)		B : 2 / C : 32 pcs.

DAIHATSU

324S40WB	NEW	48068-BZ080-1 DAIHATSU GRAN MAX Low Arm Bushing (BIG)		B : 4 / C : 72 pcs.	324S40WS	NEW	48068-BZ080-2 DAIHATSU GRAN MAX Low Arm Bushing (SMALL)		B : 6 / C : 108 pcs.
----------	------------	---	--	---------------------	----------	------------	---	--	----------------------



RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

HYUNDAI

H38H10L	NEW		B : 6 / C : 96 pcs.
57789-4H000			
HYUNDAI H1			
Grommet Steering Rack (LH)			

SUZUKI

413SW18E	NEW		B : 12 / C : 240 pcs.	419SW18F	NEW		B : 20 / C : 400 pcs.
41810-52R00-2				41724-65P00			
SWIFT (2018)				SWIFT (2018)			
Shock Absorber Rubber (RE,UP,LOW)				Shock ABS Mounting Cap (UPPER)			
417SW18IZ	NEW		B : 2 / C : 100 pcs.	417SW18UZ	NEW		B : 2 / C : 100 pcs.
44119-57R00				44118-57R00			
SWIFT (2018)				SWIFT (2018)			
Drive Shaft Boot (INNER)				Drive Shaft Boot (OUTER)			
421SW18F	NEW		B : 12 / C : 288 pcs.	424SW18WS	NEW		B : 6 / C : 108 pcs.
42431-52R00				45202-53R02-2			
SWIFT ZC63 (2018)				SWIFT (2018)			
Stabilizer Shaft Rubber (FR)				Lower Arm Bushing (SMALL)			
413SW18F	NEW		B : 2 / C : 48 pcs.	413SW18FP	NEW		B : 8 / C : 160 pcs.
41710-52R00				41720-52R00			
SWIFT (2018)				SWIFT (2018)			
Shock Absorber Mounting (FR)				Rebound Stop Comp Damper (FR)			
427SW18F	NEW		B : 2 / C : 36 pcs.				
42420-53R01							
SWIFT (2018)							
Link Assy (FR LH, RH)							

SUBARU

S27XV17EL	NEW		B : 2 / C : 54 pcs.	S27XV17ER	NEW		B : 2 / C : 54 pcs.
20470FL010				20470FL000			
SUBARU XV (2017)				SUBARU XV (2017)			
Link Assy (RE, LH)				Link Assy (RE, RH)			