



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O09088RB 50836-SA0-981 ACCORD (1988) Front Engine Bushing (RH, BIG) B : 6 / C : 72 pcs.	
O09088S 50834-SA0-010 ACCORD (1988) Front Engine Bushing (SMALL) B : 8 / C : 96 pcs.	
O09090FB 50830-SM4-020-B, 981-B, 982-B ACCORD (1990), LXI Front Engine Bushing (BIG, FR, A/T, M/T) B : 4 / C : 48 pcs.	O09090FZ 50830-SM4-020-IN, 981-IN, 982-IN ACCORD (1990) Insulator Engine (FR, A/T, M/T) B : 1 / C : 12 pcs.
O09090FS 50830-SM4-020-S, 981-S, 982-S ACCORD (1990), LXI Front Engine Bushing (SMALL, FR A/T, M/T) B : 6 / C : 144 pcs.	O09090FZ 50830-SM4-020-IN, 981-IN, 982-IN ACCORD (1990) Insulator Engine (FR, A/T, M/T) B : 1 / C : 12 pcs.
O09292L 50820-SR3-003, J03, J11 CIVIC (1992), CITY Front Engine Bushing (LH) B : 2 / C : 24 pcs.	O09098RMZ 50805-S84-A01-IN ACCORD (1998) Insulator Engine (RH, M/T) B : 1 / C : 12 pcs.
O09292L 50820-SR3-003, J03, J11 CIVIC (1992), CITY Front Engine Bushing (LH) B : 2 / C : 24 pcs.	O09292LAZ 50820-SR3-003-IN CIVIC (1992) (V-TEC) Insulator Engine (LH, A/T) B : 1 / C : 12 pcs.
O09292L 50820-SR3-003, J03, J11 CIVIC (1992), CITY Front Engine Bushing (LH) B : 2 / C : 24 pcs.	O09292LZ 50820-SR3-J03-IN, J11-IN CIVIC (1988, 1992), CITY Insulator Engine (LH, A/T, M/T) B : 1 / C : 12 pcs.
O09286EA 50810-SH3-985 CIVIC (1986) Front Engine Bushing (RE, A/T) B : 4 / C : 48 pcs.	O09286EAZ 50810-SH3-985-IN CIVIC (1986) Insulator Engine (RE, A/T) B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O09286EM 50810-SH3-040 CIVIC (1986) Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	O09286EMZ 50810-SH3-040-IN CIVIC (1986) Insulator Engine (RE, M/T)  B : 2 / C : 24 pcs.
O09301EA 50810-SX8-T50 CITY Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	O09301EAZ 50810-SX8-T50-IN CITY Insulator Engine (RE, A/T)  B : 1 / C : 9 pcs.
O09303FM 50840-SAA-003 CITY (2003) Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	O09303FMZ 50840-SAA-003-IN CITY (2003) Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
	O09303LAZ 50805-SAA-982-IN CITY (2003) Insulator Engine (LH, A/T)  B : 1 / C : 9 pcs.
	O09303LMZ 50805-SAA-013-IN CITY (2003) Insulator Engine (LH, M/T)  B : 1 / C : 12 pcs.
	O09201RZ 50805-S5A-033-IN CIVIC (2001) Insulator Engine (RH M/T, A/T)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O100880 50811-SA5-000 ACCORD (1980-1983) Front Engine Mounting  B : 4 / C : 48 pcs.	
O10088F 50811-SE0-000, 980 ACCORD (1988) Front Engine Mounting (FR, RE)  B : 2 / C : 24 pcs.	O10088L 50821-SE0-931 ACCORD (1988) Front Engine Mounting (LH)  B : 4 / C : 48 pcs.
O10090L 50820-SM4-020, 981, 010 ACCORD (1990) Front Engine Mounting (LH, A/T, M/T)  B : 2 / C : 24 pcs.	O10090R 50805-SM4-020 ACCORD (1990) Front Engine Mounting (RH, A/T, M/T)  B : 1 / C : 12 pcs.
O10094FA 50840-SV4-980 ACCORD (1994-1996) Front Engine Mounting (FR, A/T)  B : 2 / C : 24 pcs.	O10094FM 50840-SV4-000 ACCORD (1994-1996) Front Engine Mounting (FR, M/T)  B : 2 / C : 24 pcs.
O10094RA 50806-SV4-980, 981 ACCORD (1994-1996) Front Engine Mounting (RH, A/T)  B : 2 / C : 24 pcs.	O10094RM 50806-SV4-000 ACCORD (1994-1996) Front Engine Mounting (RH, M/T)  B : 1 / C : 12 pcs.
O10098EM 50810-S84-A00 ACCORD (1998) Front Engine Mounting (RE, M/T)  B : 1 / C : 12 pcs.	O10098RA 50806-S0A-980 ACCORD (1998) Front Engine Mounting (RH, A/T)  B : 1 / C : 12 pcs.
O10008L0 50850-TA2-H02 ACCORD (2008) (2.0 cc) Front Engine Mounting (LH)  B : 2 / C : 24 pcs.	O10008E 50810-TA2-H01 ACCORD (2008) (2.0 cc) Front Engine Mounting (RE)  B : 1 / C : 8 pcs.
O10008L 50851-TA1-A01 ACCORD (2008) (3.5 cc) Front Engine Mounting (LH)  B : 2 / C : 24 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O10008E0 50810-TA0-A01 ACCORD (2008) (2.4 cc) Front Engine Mounting (RE)  B : 1 / C : 8 pcs.	O10008L1 50850-TA0-A01 ACCORD (2008) (2.4) Front Engine Mounting (LH)  B : 2 / C : 24 pcs.
O1003FL 50850-SDA-A00 ACCORD (2003) Front Engine Mounting (FR, LH)  B : 2 / C : 24 pcs.	
O10013FL4 50850-T2A-A02 ACCORD (2013) (2.4 cc) Front Engine Mounting (FR, LH)  B : 2 / C : 24 pcs.	O10013LW0 50850-T2C-W01 ACCORD (2013-2015) (2.0 cc) Front Engine Mounting (LOW, LH)  B : 2 / C : 24 pcs.
O1003E0 50860-SDA-A02 ACCORD (2003) Front Engine Mounting (RE, LH)  B : 2 / C : 24 pcs.	
O10013E4 50810-T2A-Y01 ACCORD (2013) (2.4 cc) Front Engine Mounting (RE)  B : 1 / C : 6 pcs.	
O10201FA 50840-S5A-990 CIVIC (2001) Front Engine Mounting (FR, A/T)  B : 2 / C : 24 pcs.	O10201FM 50840-S5A-010 CIVIC (2001) Front Engine Mounting (FR, M/T)  B : 1 / C : 12 pcs.
O10201EA 50810-S5A-992 CIVIC (2001) Front Engine Mounting (RE, A/T)  B : 2 / C : 24 pcs.	O10201EM 50810-S5A-013 CIVIC (2001) Front Engine Mounting (RE, M/T)  B : 2 / C : 24 pcs.
O10286FA 50841-SH3-984, 983 CIVIC (1986) Front Engine Mounting (FR, A/T)  B : 2 / C : 24 pcs.	O10286FM 50840-SH3-000 CIVIC (1986) Front Engine Mounting (FR, M/T)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O10286RA 50805-SH3-983 CIVIC (1986) Front Engine Mounting (RH, A/T) B : 2 / C : 24 pcs. 	O10288L0 50821-SH3-040 CIVIC (1988) Front Engine Mounting (LH, A/T, M/T) B : 1 / C : 12 pcs. 
O10292FL 50842-SR3-020, 030, 982, 983, 984 CIVIC (1992-1996) Front Engine Mounting (FR, LH, A/T, M/T) B : 2 / C : 24 pcs. 	O10292FR 50841-SR3-020, 030, 982, 983, 984 CIVIC (1992-1996) Front Engine Mounting (FR, RH, A/T, M/T) B : 2 / C : 24 pcs. 
O10292RA 50805-SR3-951 CIVIC (1992) Front Engine Mounting (RH, A/T) B : 1 / C : 12 pcs. 	O10292RAV 50805-SR3-981 CIVIC (1992) (V-TEC) Front Engine Mounting (RH, A/T) B : 1 / C : 12 pcs. 
O10292RM 50805-SR3-010, 900 CIVIC (1992) Front Engine Mounting (RH, M/T) B : 1 / C : 12 pcs. 	
O10296L0 50820-S04-013 CIVIC (1996) Front Engine Mounting (LH, A/T, M/T) B : 1 / C : 12 pcs. 	O10296R 50805-S04-000, 50805-SX8-T00 CIVIC (1996), CITY Front Engine Mounting (RH, A/T, M/T) B : 2 / C : 24 pcs. 
O102060 50890-SNL-Z81 CIVIC (2006) (1.8 cc) Front Engine Mounting (RE) B : 2 / C : 24 pcs. 	O10206R0 50880-SNA-A82 CIVIC (2006) (1.8 cc) Front Engine Mounting (RH) B : 1 / C : 12 pcs. 
O10206R 50880-SNG-981 CIVIC (2006) (2.0 cc) Front Engine Mounting (RH) B : 1 / C : 12 pcs. 	O10206E 50890-SNG-982 CIVIC (2006) (2.0 cc) Front Engine Mounting (RE) B : 2 / C : 24 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O10206L 50850-SNG-981 CIVIC (2006) (2.0 cc) Front Engine Mounting (LH)  B : 1 / C : 8 pcs.	O10206L0 50850-SNA-A82 CIVIC (2006) (1.8 cc) Front Engine Mounting (LH)  B : 1 / C : 8 pcs.
O10212EA 50890-TS6-H81 CIVIC (2012) (1.8 cc, 2.0 cc) Front Engine Mounting (RE, A/T)  B : 1 / C : 12 pcs.	O10212EM 50890-TS6-H02 CIVIC (2012) (1.8 cc) Front Engine Mounting (RE, M/T)  B : 1 / C : 12 pcs.
O10212LA 50850-TS6-H91 CIVIC (2012) (2.0 cc) Front Engine Mounting (LH, A/T)  B : 1 / C : 12 pcs.	O10212L0 50850-TR0-A01, A81 CIVIC (2012) (1.8 cc) Front Engine Mounting (LH A/T, M/T)  B : 1 / C : 12 pcs.
O10217E0 50890-TBA-A82 CIVIC (2017) Front Engine Mounting (RE)  B : 1 / C : 12 pcs.	
O10314EA 50890-T5A-003 CITY (2014), JAZZ (2015) Front Engine Mounting (RE, A/T)  B : 1 / C : 12 pcs.	O10314EM 50890-T5A-911 CITY (2014), JAZZ (2015) Front Engine Mounting (RE, M/T)  B : 1 / C : 12 pcs.
O10301FA 50840-SX8-T51, 50841-SX8-T500 CITY Front Engine Mounting (FR, A/T)  B : 2 / C : 24 pcs.	O10301F0 50840-SX8-T01 CITY Front Engine Mounting (FR, M/T)  B : 2 / C : 24 pcs.
O103040A 50890-TF0-981 JAZZ (2008, 2009) Front Engine Mounting (A/T)  B : 1 / C : 15 pcs.	O103040M 50890-TF0-911 JAZZ (2008, 2009) Front Engine Mounting (M/T)  B : 1 / C : 12 pcs.
O10303RA 50821-SAA-013 CITY (2003) Front Engine Mounting (RH, A/T)  B : 2 / C : 24 pcs.	O10303RM 50826-SEL-E01 CITY (2003) Front Engine Mounting (RH, M/T)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O10311E 50890-TF0-901 BRIO AMAZE (2011) Front Engine Mounting (RE, A/T, M/T) B : 1 / C : 12 pcs. 	
O10496FL 50842-ST0-N10 CRV (1996) Front Engine Mounting (LH, M/T) B : 2 / C : 24 pcs. 	O10496FR 50841-ST0-N10 CRV (1996) Front Engine Mounting (FR, RH, M/T) B : 2 / C : 24 pcs. 
O10414E0 50890-T0A-A81 CRV (2014) (2.0, 2.4 cc) Front Engine Mounting (RE) B : 2 / C : 24 pcs. 	
O10402FA 50840-S7C-980 CRV (2002-2006) Front Engine Mounting (FR, A/T) B : 2 / C : 24 pcs. 	O10402EA 50810-S7D-003 CRV (2002-2006) Front Engine Mounting (RE, A/T) B : 2 / C : 24 pcs. 
O10407E0 50810-S7C-981 STREM (2002-2004) (2.0 cc) Front Engine Mounting (RE) B : 2 / C : 24 pcs. 	O10407E1 50890-SWA-A81 CRV (2007) Front Engine Mounting (RE) B : 1 / C : 12 pcs. 
O104070R 50880-SWC-E81B, 50880-SWA-A81 CRV (2007) Front Engine Mounting (UPPER, RH) B : 1 / C : 12 pcs. 	
	O10414RP 50880-T0A-A81 CRV (2014) (2.0 cc, 2.4 cc) Front Engine Mounting (UPPER, RH) B : 1 / C : 12 pcs. 
O10417F0 50890-THB-H01 CRV (2017) (B) (2.4 cc) Engine Mounting (FR) B : 2 / C : 24 pcs. 	O10417RP 50880-TME-T11 CRV (2017) (B) (2.4 cc) Engine Mounting (UPPER, RH) B : 1 / C : 12 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

O13301E 52678-SX8-T01 CITY Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 	O13301F 51920-SX8-T01 CITY Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
O13201FLR 51920-S5H-T02 CIVIC (2001), CRV (2002) Shock Absorber Mounting (FR, LH, RH) B : 1 / C : 20 pcs. 	<u>Substitute Number</u> 2) 51925-S5H-T02 3) 51920-S9E-T02 4) 51925-S9E-T02
O13303F0 51920-SAA-015, TG0-T01, SCC-015 CITY 03,06,08,14, JAZZ 04,09,15, FREED 10, BRIO AMAZE 11, BR-V 16, HR-V 15,21, MOBILIO 14 Shock Absorber Mounting (FR) B : 2 / C : 40 pcs. 	O13206F 51920-SNA-013, 51920-TR0-A01 CIVIC (2006, 2012) Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 
O13088E 52725-SB2-013 ACCORD (1988-1990), CIVIC (1988-1990) Shock Absorber Rubber (RE) B : 20 / C : 400 pcs. 	O13088F 51631-SB0-003, 51631-SS0-004 ACCORD (1988-1990), CIVIC (1988-1990), CRV (1996) Shock Absorber Rubber (FR) B : 20 / C : 400 pcs. 
O130980 51631-SV7-004 ACCORD (1998) Shock Absorber Rubber (FR, RE) B : 20 / C : 400 pcs. 	O13201E 52631-S5A-004 CIVIC (2001) ES, G7, CRV (2002) G2, (2007) G3, (2013) G4, STREAM (2000) Shock Absorber Rubber (RE) B : 20 / C : 400 pcs. 
O13304E 52725-TG0-T01, 52610-SEL-T22-2, TG1-T02-2, SZY-003-2, TRD-K01-2, T4T-T01-2, TSE-T02-2 CITY 06, JAZZ 09, FREED 10, BRIO 11, AMAZE12, MOBILIO 14, BR-V 16 Shock Absorber Rubber (RE) B : 16 / C : 320 pcs. 	O13407F0 51920-SWA-A01 CRV (2007) Shock Absorber Mounting (FR LH, RH) B : 1 / C : 20 pcs. 
O132120E 52631-TR0-A01 CIVIC (2012) Shock Absorber Rubber (RE) B : 12 / C : 240 pcs. 	
O13013FLR 51670-T3V-A01 ACCORD (2013) Shock Absorber Mounting (FR LH, RH) B : 1 / C : 20 pcs. 	O13SW10F 51920-SMA-014 STEP WAGON, SPADA (2010-2015) Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 



is the registered trademark



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

O13309F0 51925-SAA-005 CITY (2020), JAZZ (2003, 2009, 2014) Rebound Stop Comp, Damper (FR)  B : 10 / C : 200 pcs.	O13BR12F 51925-TG1-T01 BRIO AMAZE Rebound Stop Comp, Damper (FR)  B : 8 / C : 160 pcs.
O13306EP 52633-T5A-J01 CITY (2014, 2020), JAZZ (2015), HR-V (2015), (2021) G2 Shock Absorber Rubber (RE, UP)  B : 20 / C : 400 pcs.	O13306EW 52670-T5A-J02 CITY (2014), JAZZ (2015), HR-V (2015), (2021) G2 Shock Absorber Rubber (RE, LOW)  B : 4 / C : 80 pcs.
O13216F0 51670-TEA-T01 CIVIC (2016) Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	O13417F0 51670-TMJ-T01 CRV (2017) Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O14098F 51722-S84-A01 ACCORD (1998) Shock Dust Cover (FR) B : 2 / C : 32 pcs. 	O14003E 52688-S0A-004 ACCORD (2003) Shock Dust Cover (RE) B : 2 / C : 44 pcs. 
O14201F0 51722-S5A-014 CIVIC (2001), CITY Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	O14303F 51722-SEL-T01 CITY (2003) Shock Dust Cover (FR) B : 2 / C : 40 pcs. 
O14402F 51722-S7A-014 CRV (2002) Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	O14414E0 52687-T0A-A01 CRV (2014) Shock Dust Cover (RE) B : 2 / C : 40 pcs. 
O14003F 51688-SDA-A01 ACCORD (2003) Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	O14301F 51722-SX8-T01 CITY (1996) Shock Dust Cover (FR) B : 2 / C : 40 pcs. 
O14305F 51686-TG0-T01 CITY (2006) ZX (2008-2020), JAZZ (2004-2020), BR-V (2016), FREED (2010) Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	O1421201E 52688-TS4-T01, 52610-TRD-K01-4, T4T-T01-4, TSE-T02-4, TG1-T02-4, SZY-003-4 CIVIC (12) FB, G9, BR-V (16), MOBILIO (14), BRIO, AMAZE (11), FREED (10) Shock Dust Cover (RE) B : 2 / C : 44 pcs. 
O14013FL 51403-T2A-A01 ACCORD (2013) Shock Dust Cover (FR, LH) B : 2 / C : 12 pcs. 	O14013FR 51402-T2A-A01 ACCORD (2013) Shock Dust Cover (FR, RH) B : 2 / C : 12 pcs. 
O14306E 52686-T5A-J01 CITY (2014, 2020), JAZZ (2015), HR-V (2021) G2 Shock Dust Cover (RE, OUTER) B : 2 / C : 40 pcs. 	O14314E 52722-T5A-J02 CITY (2014, 2020), JAZZ (2015) Shock Dust Cover (RE, INNER) B : 2 / C : 12 pcs. 
O14608F0 51686-SAA-E02, 51686-SZY-003 FREED (2010) GB Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O14013E 52687-T2A-A01 ACCORD (2013) Shock Dust Cover (RE) B : 2 / C : 12 pcs. 	O14SW10F 51722-S7S-J01 STEP WAGON, SPADA (2010) Shock Dust Cover (FR) B : 2 / C : 40 pcs. 
O14212FL 51403-TR7-A01 CIVIC (2012) Shock Dust Cover (FR, LH) B : 2 / C : 12 pcs. 	O14212FR 51402-TR7-A01 CIVIC (2012) Shock Dust Cover (FR, RH) B : 2 / C : 12 pcs. 
O14216F0 51722-TBA-A03 CIVIC (2016) Shock Absorber Bumper (FR) B : 4 / C : 48 pcs. 	
O14013E0 52722-T2A-A01, T2M-T01 ACCORD (2013) Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 	O14417F0 51722-TMJ-T01 CRV (2017) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 
O14014E0 52722-T3V-A01 ACCORD HYBRID (2014) Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 	O14014F0 51722-T3V-A01 ACCORD HYBRID (2014) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 
O14008E 52722-SJA-003 ACCORD (2008) Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 	O14019F1 51722-TVA-A01 ACCORD (2019) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 
O14090E 52722-SM4-961 ACCORD (1990-1993) Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 	O14090F 51722-SM4-003 ACCORD (1990) Shock Absorber Bumper (FR) B : 10 / C : 120 pcs. 
O14094E 52722-SM4-013, SV1-A02 ACCORD (1994) G5 (1998) G6 Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 	O14094F 51722-SV4-004 ACCORD (1994) Shock Absorber Bumper (FR) B : 10 / C : 120 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O14292E 52722-SR3-003 CIVIC (1992, 1996) Shock Absorber Bumper (RE)  B : 10 / C : 120 pcs.	O14292F 51722-SS0-004 CIVIC (1992), PRELUDE, ACCORD (2003, 2008) Shock Absorber Bumper (FR)  B : 10 / C : 120 pcs.
O14296E 52722-SN4-003 CIVIC (1992-1996) Shock Absorber Bumper (RE)  B : 10 / C : 120 pcs.	O14201 52722-S5A-004 CIVIC (2001) Shock Absorber Bumper  B : 10 / C : 120 pcs.
O14003E1 52722-SDA-A01 ACCORD (2003) Shock Absorber Bumper (RE)  B : 10 / C : 120 pcs.	O14402E 52722-S9A-014 CRV (2002) Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.
O14496E 52722-SS0-003 CITY (1996) Shock Absorber Bumper (RE)  B : 10 / C : 120 pcs.	O14206F 51722-SNA-904 CIVIC (2006) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
O14304F 51722-TF0-014 CITY, JAZZ (2009) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	O14407E 52722-SWA-A01 CRV (2007-2011) Shock Absorber Bumper (RE)  B : 12 / C : 144 pcs.
O144070F 51722-SWE-T01 CRV (2007-2011) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	O142120E 52722-TS0-T01 CIVIC (2012) Shock Absorber Bumper Cover (RE)  B : 10 / C : 120 pcs.
O14212F0 51722-TS6-H01 CIVIC (2012) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	O14311F 51722-TG1-T01 BRIO, AMAZE (2011), MOBILIO (2014) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.
O14314F 51722-T5A-J02 CITY (2014), JAZZ (2015) Shock Absorber Bumper (FR)  B : 6 / C : 72 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O14608F 51722-SAA-E02 FREED Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 	O14414E1 52722-T0A-A01 CRV (2014) Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 
O14013F0 51722-T2A-A01, 51722-T2M-T01 ACCORD (2013) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 	
O14216E0 52722-TEA-T02 CIVIC (2016) Shock Absorber Bumper (RE) B : 4 / C : 48 pcs. 	O14417E0 52722-THA-H01 CRV (2017) Shock Absorber Bumper (RE) B : 4 / C : 48 pcs. 
O14515F 51722-T8N-T01 HR-V (2015) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 	O14515E1 52722-T8N-T01 HR-V (2015) Shock Dust Cover (RE, INNER) B : 2 / C : 12 pcs. 
O14305E0 52610-SEL-T22-3 CITY (03) G2, (06) ZX, (08) G3, JAZZ (04) GD, (09) GE, BRIO, AMAZE (11), BR-V (16) Shock Dust Cover (RE) B : 2 / C : 40 pcs. 	
O14019E1 52722-TVA-A01 ACCORD (2019) Shock Absorber Bumper (RE LH, RH) B : 6 / C : 72 pcs. 	O14320F1 51722-T00-T01 CITY (2020) Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 
O14311E1 52610-T4T-T01-3, 52610-TG1-T02-3 BRIO AMAZE (2012), BRIO (2011) Shock Absorber Bumper (RE) B : 10 / C : 120 pcs. 	O14608E1 52610-SZY-003-3 FREED (2010) Shock Absorber Bumper (RE) B : 8 / C : 96 pcs. 
O14M014E1 52610-TRD-K01-3, 52610-TSE-T02-3 MOBILIO (2014), BR-V (2016) Shock Absorber Bumper (RE) B : 8 / C : 96 pcs. 	

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O17084IL 44326-SB0-300 ACCORD (1984) Drive Shaft Boot (INNER, LH)  B : 2 / C : 100 pcs.	O17084UL 44324-SB0-310 ACCORD (1984) Drive Shaft Boot (OUTER, LH)  B : 2 / C : 100 pcs.
O17084IR 44325-SB0-300 ACCORD (1984) Drive Shaft Boot (INNER, RH)  B : 2 / C : 100 pcs.	O17084UR 44323-SB0-310 ACCORD (1984) Drive Shaft Boot (OUTER, RH)  B : 2 / C : 100 pcs.
O17086IL 44315-SD2-003 ACCORD (1986-1989) Drive Shaft Boot (INNER, LH)  B : 2 / C : 100 pcs.	O17086UL 44333-SD2-003 ACCORD (1986-1989) Drive Shaft Boot (OUTER, LH)  B : 2 / C : 100 pcs.
O17086IR 44315-SB2-980 ACCORD (1986-1989) Drive Shaft Boot (INNER, RH)  B : 2 / C : 100 pcs.	O17086UR 44333-SB2-980 ACCORD (1986-1989) Drive Shaft Boot (OUTER, RH)  B : 2 / C : 100 pcs.
O17090IZ 44315-SM4-003 ACCORD (1990) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17090UZ 44333-SM4-003 ACCORD (1990) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17098IZ 44315-SM1-A000 ACCORD (1996-1998) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17098UZ 44333-S84-A01 ACCORD (1996-1998) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17286IZ 44315-SA2-300 CIVIC (1986-1989) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17286UZ 44333-SA2-310 CIVIC (1986-1989) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17292IZ 44315-SR3-003 CIVIC (1992) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17292UZ 44333-SR3-013 CIVIC (1992) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O17296IZ 44315-S04-0030 CIVIC (1996) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17296UZ 44333-S04-0130 CIVIC (1996) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17201IZ 44017-S5D-A01 CIVIC (2001) Drive Shaft Boot (INNER, LH)  B : 2 / C : 100 pcs.	O17201IR 44017-S5D-A11 CIVIC (2001) Drive Shaft Boot (INNER, RH)  B : 2 / C : 100 pcs.
	O17201UZ 44018-S5D-A010 CIVIC (2001) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17003IZ 44315-SDE-T01, 44017-SDE-T00 ACCORD (2003,2013), CIVIC (2006) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17003UZ 44333-SDE-T01, 44018-SDE-T00 ACCORD (2003,2013), CIVIC (2006) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17303IZ 44315-SEL-T01, S5A-003, 44017-SEL-T01 CITY (2003), CIVIC (2006), CIVIC (2012) (1.8 cc) (2.0 cc) Drive Shaft Boot (INNER, A/T)  B : 2 / C : 100 pcs.	O17303UZ 44333-S04-N01, 44018-SEL-T02 CITY (2003) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17402E 42315-S71-003, 42017-S0E-000 CRV (2002) Drive Shaft Boot (RE)  B : 2 / C : 100 pcs.	
O17402FI 44315-S0K-J02 CRV (1996, 2002) Drive Shaft Boot (FR, INNER)  B : 2 / C : 100 pcs.	O17402FU 44333-SX0-C02, 44018-T3V-A01, 44018-3N0-306, 305 CRV (2002), HR-V (2021) G2 Drive Shaft Boot (FR, OUTER)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O17496EI 42315-S10-000 CRV (1996) Drive Shaft Boot (RE, INNER)  B : 2 / C : 100 pcs.	O17496EU 42333-SR7-J21 CRV (1996) Drive Shaft Boot (RE, OUTER)  B : 2 / C : 100 pcs.
	O17496FU 44333-S0A-003 CRV (1996) Drive Shaft Boot (FR, OUTER)  B : 2 / C : 100 pcs.
	O17206UZ 44333-SEL-T01 CIVIC (2006) (1.8 cc) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O17008IZ 44315-SDF-T01 ACCORD (2008) (3.5 cc), CRV (2007) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	O17008UZ 44333-SDF-T01 ACCORD (2008) (3.5 cc), CRV (2007) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
O172120IZ 44315-TR0-J91 CIVIC (2012) (1.8 cc) Drive Shaft Boot (INNER, M/T)  B : 2 / C : 100 pcs.	O172120UZ 44333-TS6-H91, 44018-TR0-J90 CIVIC (2012) (1.8 M/T), (2.0 A/T) Drive Shaft Boot (OUTER, M/T)  B : 2 / C : 100 pcs.
	O17212UZ 44333-TF0-003, 44018-TF6-N13 CIVIC (2012) (1.8 cc) Drive Shaft Boot (OUTER, A/T)  B : 2 / C : 100 pcs.
O17304AIZ 44017-T9A-T01 CITY, JAZZ (2009-2014), MOBILIO (2014) Drive Shaft Boot (INNER, A/T)  B : 2 / C : 100 pcs.	O17304AUZ 44018-T9A-T01 CITY, JAZZ (2009-2014), MOBILIO (2014) Drive Shaft Boot (OUTER, A/T)  B : 2 / C : 100 pcs.
O17304IZ 44017-T9A-T91 CITY JAZZ (2009-2014) Drive Shaft Boot (INNER, M/T)  B : 2 / C : 100 pcs.	O17304UZ 44018-T9A-T91 CITY JAZZ (2009-2014) Drive Shaft Boot (OUTER, M/T)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O17407E 42315-SWE-003, 42017-SWE-000 CRV (2007) G3, (2013) G4 Drive Shaft Boot (RE, INNER, OUTER) B : 2 / C : 100 pcs. 	
O17414IZ 44315-S2H-003, 44017-T2A-010 CRV (2014) Drive Shaft Boot (INNER) B : 2 / C : 100 pcs. 	O17414UZ 44333-TL1-E01 CRV (2014) Drive Shaft Boot (FR, OUTER) B : 2 / C : 100 pcs. 
O17515IZ 44017-T7W-A01, T7W-305, TSA-K50 HR-V (2015) G1, BR-V (2016) Drive Shaft Boot (LH, RH INNER) B : 2 / C : 100 pcs. 	O17515UZ 44018-T7W-A02, T7W-315, TE7-K51 HR-V (2015) G1, BR-V (2016) Drive Shaft Boot (LH, RH OUTER) B : 2 / C : 100 pcs. 
O172165IZ 44017-TBC-306, A50 CIVIC (2016) (1.5 cc LH, RH), (1.8 cc RH) Drive Shaft Boot (LH, RH INNER) B : 2 / C : 100 pcs. 	O172165UZ 44018-TED-305, T00 CIVIC (2016) (1.5 cc) Drive Shaft Boot (LH, RH OUTER) B : 2 / C : 100 pcs. 
O172168ILZ 44017-TEX-306 CIVIC (2016) (1.8 cc) Drive Shaft Boot (LH, INNER) B : 2 / C : 100 pcs. 	O172168UZ 44018-TEA-305, T00 CIVIC (2016) (1.8 cc) Drive Shaft Boot (LH, RH OUTER) B : 2 / C : 100 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

HONDA

0180869 53534-SE0-A52 ACCORD (1986-1989) Steering Gear Boot (POWER)  B : 2 / C : 50 pcs.	0180903 53534-SD4-000 ACCORD (1990-1993) Steering Gear Boot (POWER)  B : 2 / C : 50 pcs.
018094L 53534-SV4-003 ACCORD (1994-1996), CRV (1996) G1 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	018094R 53534-SV4-N01 ACCORD (1994-1996) Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
0180980 53534-S84-A01, SDA-A01 ACCORD (1998) Steering Gear Boot  B : 2 / C : 50 pcs.	0182880 53534-SA5-951 CIVIC (1988-1990) Steering Gear Boot (POWER)  B : 2 / C : 50 pcs.
018008Z 53534-TA0-A02 ACCORD (2008) Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	
0182925 53534-SR3-N52 CIVIC (1992), CRV (1996) Steering Gear Boot (LH, RH POWER)  B : 2 / C : 50 pcs.	018296Z 53534-SR3-N62 CIVIC (1996) Steering Gear Boot (POWER)  B : 2 / C : 50 pcs.
018301L 53537-SH3-J00 CITY Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	018301LP 53534-ST0-013 CITY Steering Gear Boot (POWER, LH)  B : 2 / C : 50 pcs.
018301R 53537-SH3-000, 53537-SX8-T01 CITY (SX8), CIVIC (1988) Steering Gear Boot (RH, M/T)  B : 2 / C : 50 pcs.	018201S 06537-S5A-H01 CIVIC (2001) Steering Gear Boot (SMALL)  B : 2 / C : 50 pcs.
018303L 53534-SEL-003 CITY (2003) Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	018303R 53535-SEL-003 CITY (2003) Steering Gear Boot (RH)  B : 2 / C : 50 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O18206LZ 53535-SNA-A01 CIVIC (2006) Steering Gear Boot (LH) B : 2 / C : 50 pcs. 	O18206RZ 53534-SNA-A01 CIVIC (2006) Steering Gear Boot (RH) B : 2 / C : 50 pcs. 
O184020 53536-S9A-003 CRV (2002) Steering Gear Boot B : 2 / C : 50 pcs. 	O182120Z 53429-TR0-A02 CIVIC (2012) Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 
O18314LR 53429-T5E-003 CITY (2014), JAZZ (2015) Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	
O18407LR 53534-SMA-003 CRV (2007) Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	O18515LR 53429-T7S-T01 HR-V (2015)G1, (2021)G2 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 
O19212EPL 52466-TR0-A00 CIVIC (2012) Coil spring rubber (UP, RE, LH) B : 4 / C : 64 pcs. 	O19212EPR 52461-TR0-A00 CIVIC (2012) Coil spring rubber (UP, RE, RH) B : 4 / C : 64 pcs. 
O19212EWL 52476-TR0-A01 CIVIC (2012) Coil spring rubber (LOW, RE, LH) B : 4 / C : 64 pcs. 	O19212EWR 52471-TR0-A01 CIVIC (2012) Coil spring rubber (LOW, RE, RH) B : 4 / C : 64 pcs. 
O19212F0 51608-SNA-000 CRV (2007,2013,2017) Shock ABS Mounting Cap (FR) B : 12 / C : 240 pcs. 	O19212FW 51684-TR0-E01 CIVIC (2012), HR-V (2015) Coil spring rubber (LOW, FR) B : 6 / C : 96 pcs. 
O19417WE 52355-TLA-A52-2, 52748-TLA-A50 CRV (2017) Coil Spring Rubber (LOW, RE) B : 4 / C : 64 pcs. 	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

021086E 52315-SE0-000 ACCORD (1986-1989) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021086F 51316-SE0-000 ACCORD (1986-1989) Stabilizer Shaft Rubber (FR) B : 20 / C : 480 pcs. 
021090E 52315-SJ4-000 ACCORD (1990) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021090F 51306-SM4-010 ACCORD (1990) Stabilizer Shaft Rubber (FR) B : 12 / C : 192 pcs. 
021094E 52315-SA3-900 ACCORD (1994-1998) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021094F 51306-SV4-000 ACCORD (1994) Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 
021098E 52306-S84-A01 ACCORD (1998) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021098F 51306-S84-A01 ACCORD (1998) Stabilizer Shaft Rubber (FR) B : 10 / C : 240 pcs. 
021286E 52315-SB0-000 CIVIC (1986-1991) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021286F 51316-SH3-J00 CIVIC (1986-1991) Stabilizer Shaft Rubber (FR) B : 20 / C : 480 pcs. 
021292E 52315-SR3-000 CIVIC (1992) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021292F 51306-SR3-010 CIVIC (1992) Stabilizer Shaft Rubber (FR) B : 10 / C : 240 pcs. 
021296E 52315-S04-N00 CIVIC (1996) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	021296F 51306-S04-003 CIVIC (1996) Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 
021201E 52306-S5A-003 CIVIC (2001) Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs. 	021201F 51306-S5A-003 CIVIC (2001) Stabilizer Shaft Rubber (FR) B : 10 / C : 160 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O21301F 51306-SX8-T00 CITY Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs. 	O2140E 52315-S10-023 CRV (1996) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 
O21303E 52315-SEL-000 CITY (2003) Stabilizer Shaft Rubber (RE) B : 12 / C : 288 pcs. 	O21303F 51306-SEL-T01 CITY (2003) Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs. 
O21402E 52306-S9A-005, SWA-A01 CRV (2002) G2, (2007) G3 Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	O21402F 51306-S7B-014 CRV (2002) Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 
O2141E 52315-S10-A01 CRV (2001) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	O2141F 51306-S04-N01 CRV Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 
O21003E 52306-SDA-A01 ACCORD (2003) Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs. 	O21003F 51306-SDA-A03 ACCORD (2003) Stabilizer Shaft Rubber (FR) B : 6 / C : 96 pcs. 
O21203F 51306-S5A-A11 CIVIC (2003) Stabilizer Shaft Rubber (FR) B : 10 / C : 160 pcs. 	O21M014F 51306-TE7-K02 MOBILIO (2014) Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 
O21206E 52306-SNG-J01, 52306-SNC-J01 CIVIC (2006) FD, G8 (2012) FB, G9 Stabilizer Shaft Rubber (RE) B : 24 / C : 576 pcs. 	O21206F 51306-SNA-A02 CIVIC (2006) Stabilizer Shaft Rubber (FR) B : 8 / C : 128 pcs. 
O21019F0 NEW 51300-TVA-A02-0 ACCORD (2019) Stabilizer Shaft Rubber (FR) B : 8 / C : 128 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O21008E 52306-TA0-A02, 52306-T0A-A01 ACCORD (2008) (2.0, 2.4 cc), CRV (2013) G4 Stabilizer Shaft Rubber (RE)  B : 8 / C : 128 pcs.	O21008F 51306-TA0-A01 ACCORD (2008) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
O21009E 52306-TA1-A02 ACCORD (2008) (3.5 cc) Stabilizer Shaft Rubber (RE)  B : 8 / C : 128 pcs.	O21204F 51306-S5A-801 CIVIC (2004) Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
O21205F 51306-S5G-801 CIVIC (2005) (2.0 cc) Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.	O21304F 51306-TM0-003, 51306-TM6-M00 CITY (2009-2016), JAZZ Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
O21305F 51306-TF0-003, 51306-SWA-A01 JAZZ (2009) GE, G2, CRV (2007) G3, (2013) G4 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	O21303F0 51306-SAA-J01 JAZZ (2004) Stabilizer Shaft Rubber (FR)  B : 14 / C : 336 pcs.
O213050 51306-TJ0-M01 FIT (2009-2016) Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	O21202F 51306-S5J-003 CIVIC SEDAN 5 DOOR Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.
O21202F0 51306-S5J-801 CIVIC SEDAN 5 DOOR Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	O21202F1 51306-SNJ-P00 CIVIC SEDAN 5 DOOR Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.
O21008FL 51307-TL0-G01 ACCORD (2008-2013) Stabilizer Shaft Rubber (FR, LH)  B : 6 / C : 96 pcs.	O21008FR 51306-TL0-G01 ACCORD (2008-2013) Stabilizer Shaft Rubber (FR, RH)  B : 6 / C : 96 pcs.
O21501F 51306-S2H-003 HR-V (1999-2003) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	O21013F 51306-T2A-A01 ACCORD (2013) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.






PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O21314FL 51307-T9C-T01 CITY (2014), JAZZ (2015) Stabilizer Shaft Rubber (FR, LH) B : 8 / C : 192 pcs. 	O21314FR 51306-T9C-T01 CITY (2014), JAZZ (2015) Stabilizer Shaft Rubber (FR, RH) B : 8 / C : 192 pcs. 
O21316F 51306-TSA-K01 BR-V (2016) Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 	O21SW10F 51306-SZW-J01 STEP WAGON, SPADA (2010) Stabilizer Shaft Rubber (FR) B : 6 / C : 144 pcs. 
O21013E 52306-TE0-A01 ACCORD (2013) Stabilizer Shaft Rubber (RE) B : 6 / C : 96 pcs. 	O21212F 51306-TR0-A11, 51307-TR0-A11 CIVIC (2012) Stabilizer Shaft Rubber (FR,LH,RH) B : 8 / C : 192 pcs. 
O21216E 52300-TEA-T01-0 CIVIC (2016) Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs. 	O21216F 51300-TEA-T01-0 CIVIC (2016) Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 
O21515FL 51307-T7A-004 HR-V (2015) Stabilizer Shaft Rubber (FR, LH) B : 8 / C : 192 pcs. 	O21515FR 51306-T7A-004 HR-V (2015) Stabilizer Shaft Rubber (FR, RH) B : 8 / C : 192 pcs. 
O21608F 51306-SYY-003 FREED Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 	O21BR12F 51306-T4T-T02, 51306-TG1-T01 BRIO AMAZE Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 
O21705F 51306-SED-004 ODYSSY (2005) Stabilizer Shaft Rubber (FR) B : 6 / C : 96 pcs. 	O21795F 51306-SX0-003 ODYSSY (1995) Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 
O21417E 52306-TMJ-T51 CRV (2017) Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs. 	O21417F 51300-TMJ-T52-0 CRV (2017) Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O220880 52316-SA5-000 CIVIC (1988), ACCORD (1988-1998) Stabilizer Shaft Grommet  B : 30 / C : 1,950 pcs.	O22090 90112-SM4-020 ACCORD (1990) Stabilizer Shaft Grommet  B : 50 / C : 1,200 pcs.
O220920 52314-SH3-000 CIVIC (1988-1992) Stabilizer Shaft Bush (RE)  B : 10 / C : 240 pcs.	
O23086IY 51380-SE0-003 ACCORD (1986-1989) Strut Bar Rubber (INNER)  B : 14 / C : 336 pcs.	O23086UY 51390-SE0-003, 51390-SE0-033 ACCORD (1986-1989) Strut Bar Rubber (OUTER)  B : 10 / C : 240 pcs.
O23090BY 51391-SM4-013, 51391-S84-A01 ACCORD (1990, 1994, 1998-2002) Strut Bar Rubber (BIG)  B : 12 / C : 192 pcs.	O23090SY 51381-SM4-013 ACCORD (1990) Strut Bar Rubber (SMALL)  B : 12 / C : 192 pcs.
O23286Y 51395-SH3-003 CIVIC (1986-1992) Strut Bar Rubber  B : 16 / C : 384 pcs.	
O23090Z 51391-SM4-013-S ACCORD (1990, 1994, 1998-2002) Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	O23286Z 51395-SH3-003-S CIVIC (1986-1992) Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
O23086Z 51390-SE0-003-S ACCORD (1986-1989) Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O24086P0 51458-SB0-000 ACCORD (1986-1989) Upper Arm Bushing  B : 20 / C : 360 pcs.	O24086P 51455-SB0-003 ACCORD (1986-1989) Upper Arm Bushing  B : 10 / C : 180 pcs.
O24088WB 51810-SE0-003 ACCORD (1988) Lower Arm Bushing (BIG)  B : 8 / C : 144 pcs.	O24090P 51450-SM4-023, 51460-SV4-000 ACCORD (1990, 1994, 1998) Upper Arm Bushing  B : 10 / C : 180 pcs.
O24090WB 51810-SM4-004, SV4-003, SDA-A01 ACCORD (1990, 1994-1998) Lower Arm Bushing (BIG)  B : 10 / C : 180 pcs.	O24090WS 51393-SM4-013 ACCORD (1990) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
O24098P 51460-S86-K00, 51460-S86-K01 ACCORD (1998) Upper Arm Bushing  B : 8 / C : 144 pcs.	O24094WS 51393-SL5-013, 51393-SV1-A01 ACCORD (1994-1998) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
O24286WB 51810-SH3-004 CIVIC (1986-1991, 1992) Lower Arm Bushing (BIG)  B : 10 / C : 180 pcs.	O24286WS 51393-SH3-003, 51393-692-014 CIVIC (1986-1991), ACCORD (1988) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
O24286P 51455-SH3-005 CIVIC (1986-1991) Upper Arm Bushing  B : 10 / C : 180 pcs.	O24292P 51455-SR3-004 CIVIC (1992) Upper Arm Bushing  B : 10 / C : 180 pcs.
O24292WB 51391-SR3-0040, 51395-SR3-N02 CIVIC (1992) Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	O24292WLS 51392-SR3-024 CIVIC (1992) Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
O24296L 51360-S04-G00M CIVIC (1996) Lower Arm Bushing  B : 8 / C : 144 pcs.	O24296PL 51460-S04-023, 51460-S10-020 CIVIC (1996), CRV (1996) Upper Arm Bushing  B : 10 / C : 180 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O24296WB 51391-S04-005 CIVIC (1996), CRV Lower Arm Bushing (BIG)  B : 4 / C : 64 pcs.	O24296WLS 51360-S04-G00S CIVIC (1996), CRV Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
O24201WB 51391-S5A-024, 51391-S7A-005 CIVIC (2001, 2002) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	O24201WS 51392-S5A-004 CIVIC (2001) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
O24206WB 51391-SNA-903 CIVIC (2006) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	O24206WS 51392-SNA-903, TR0-305 CIVIC (2006, 2012) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
O24301WI 51360-SX8-T02 CITY Lower Arm Bushing (INNER, BIG)  B : 6 / C : 108 pcs.	O24301WU 51360-SX8-T01 CITY Lower Arm Bushing (OUTER, SMALL)  B : 8 / C : 144 pcs.
O24003WB 51391-SDA-A03 ACCORD (2003) Lower Arm Bushing (BIG)  B : 4 / C : 64 pcs.	O24003WS 51393-SDA-A02 ACCORD (2003) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
O24003P0 51460-SDA-A01 ACCORD (2003) Upper Arm Bushing  B : 10 / C : 180 pcs.	
O24302WB 51391-SEL-T01 CITY (2003), JAZZ Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	O24302WS 51392-SEL-T01 CITY (2003), JAZZ Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
O24304WB 51360-TG0-T02B, TG1-T02-1 CITY (2008) G3, JAZZ (2009) GE, G2, BRIO, AMAZE (2011) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	O24304WS 51360-TG0-T02S, TG1-T02-2 CITY (2008) G3, JAZZ (2009) GE, G2, BRIO, AMAZE (2011) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

024407WB 51350-SWA-E01B CRV (2007) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	024407WS 51350-SWA-E01S CRV (2007) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
024008WB 51391-TA0-A01 ACCORD (2008) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	
024013WB 51391-T2A-A03 ACCORD (2013) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	024013WS 51392-T2A-A02 ACCORD (2013) Lower Arm Bushing (SMALL)  B : 2 / C : 36 pcs.
024212WB 51391-TR0-305 CIVIC (2012) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	
024314WB 51391-T5A-J01 CITY (2014), JAZZ (2015) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	024314WS 51392-T5A-J01, 51360-T7A-H11S CITY (2014), JAZZ (2015), HR-V (2015) Lower Arm Bushing (LH, SMALL)  B : 8 / C : 144 pcs.
024608WB 51391-SYY-010 FREED Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	024608WS 51360-TSA-K11-2, 51392-SYY-010 FREED, BR-V (2016) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
024515WB 51360-T7A-H11B HR-V (2015) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	
024316WB 51360-TSA-K11-1 BR-V (2016) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O24414WB 51360-T0A-E02B CRV (2014) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	O24414WS 51360-T0A-E02S CRV (2014) Lower Arm Bushing (SMALL)  B : 2 / C : 32 pcs.
O24SW10WB 51360-SZW-003-1 STEP WAGON, SPADA (2010) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	O24SW10WS 51360-SZW-003-2 STEP WAGON, SPADA (2010) Lower Arm Bushing (SMALL)  B : 4 / C : 64 pcs.
O24216WB 51360-TEA-T01-1, T10-1 CIVIC (2016) (1.5,1.8 cc) Lower Arm Bushing (BIG)  B : 2 / C : 24 pcs.	O24216WS 51360-TEA-T01-2, T10-2 CIVIC (2016) (1.5,1.8 cc) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
O24417WB 51360-TMJ-T01-1 CRV (2017) Lower Arm Bushing (BIG)  B : 2 / C : 24 pcs.	O24417WS 51360-TMJ-T01-2 CRV (2017) Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O25088B 52384-SE0-G02 ACCORD (1988) Suspension Bush (BIG)  B : 4 / C : 72 pcs.	O25088S 52365-SE0-003 ACCORD (1988) Suspension Bush  B : 10 / C : 180 pcs.
O25089B 52384-SE0-023 ACCORD (1989) Suspension Bush (BIG)  B : 4 / C : 72 pcs.	O25090 52393-SM4-004 ACCORD (1990-1998) Suspension Bush  B : 8 / C : 144 pcs.
O25090G 52366-SM4-005, 52368-SM4-005 ACCORD (1990, 1994, 1998) Suspension Bush  B : 10 / C : 180 pcs.	O25090S 52365-SM4-004,005, 52367-SM4-005 ACCORD (1990, 1994, 1996, 1998, 2003) Suspension Bush  B : 10 / C : 180 pcs.
O25090SS 52371-SM4-010S, 52343-SM4-00A ACCORD (1990, 1994) Suspension Bush (SMALL)  B : 10 / C : 180 pcs.	O25094B 52371-SM4-010B ACCORD (1990, 1994) Suspension Bush (BIG)  B : 2 / C : 36 pcs.
O250980 52360-S86-K01, 52360-SDA-A00 ACCORD (1998, 2003) Suspension Bush  B : 10 / C : 180 pcs.	O25098S 52390-S84-A01, SDA-A01, 52350-SDA-A00 ACCORD (1998, 2003) Suspension Bush (SMALL)  B : 8 / C : 144 pcs.
O25098B 1) 52380-S84-A01 ACCORD (1998, 2003) Suspension Bush (BIG)  B : 8 / C : 144 pcs.	<u>Substitute Number</u> 2) 52370-SDA-A50 3) 52370-S86-K50 4) 52375-S86-K50 5) 52380-S86-K01 6) 52375-SDA-A50 7) 52375-SDE-T50 8) 52380-SDA-A00 9) 52380-SDE-T00
O250081 52345-TA0-A00-1 ACCORD (2008, 2013) Suspension Bush (RE, BIG)  B : 6 / C : 108 pcs.	O250082 52345-TA0-A00-2 ACCORD (2008, 2013) Suspension Bush (RE, SMALL)  B : 6 / C : 108 pcs.
O25019550 NEW 52355-TVE-H02-0 ACCORD (2019) Suspension Bush (RE)  B : 8 / C : 144 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O252010 52365-S5A-024, 52365-S9A-004 CIVIC (2001) ES G7, CRV (2002) G2 Suspension Bush (RE, SMALL) B : 6 / C : 108 pcs.	O252011 52366-S5A-024, 52365-S6M-004 CIVIC (2001) ES G7, CRV (2002) G2, STREAM (2000) Suspension Bush (RE, BIG) B : 6 / C : 108 pcs.
O252012 52395-S5A-004 CIVIC (2001) ES G7, CRV (2002) G2, (2007) G3, STREAM (2000) Suspension Bush B : 8 / C : 144 pcs.	O252013 52364-S5A-004 CIVIC (2001) ES G7, CRV (2002) G2, STREAM (2000) Suspension Bush B : 8 / C : 144 pcs.
O252014 52390-S5H-000, 52390-S5H-980 CIVIC (2001) Suspension Bush B : 4 / C : 72 pcs.	O252015 52370-S5A-030, 52371-S5A-030 CIVIC (2001) ES G7, CRV (2002) G2 Suspension Bush B : 4 / C : 72 pcs.
O252880 52395-SH3-004 CIVIC (1988, 1992, 1996), CRV (1996) G1 Suspension Bush (RE) B : 10 / C : 180 pcs.	O25288B 52365-SH3-014 CIVIC (1988-1992) Suspension Bush (BIG) B : 10 / C : 180 pcs.
O25288BX 52371-SH3-G70 CIVIC (1988) Suspension Bush (BIG) B : 2 / C : 32 pcs.	O25288S 52343-SK7-003, 52343-SH3-004 CIVIC (1988,1992, 1996), CRV (1996) G1 Suspension Bush (RE) B : 10 / C : 180 pcs.
O25292B 52370-SH3-G70, 52385-S21-003 CIVIC (1992), CRV (1996) G1 Suspension Bush (RE) B : 2 / C : 32 pcs.	O25288SX 52393- SH3-004, SR3-004, SK7-004 CIVIC (1988-1992), CRV (1996) G1 Suspension Bush (RE) B : 8 / C : 144 pcs.
O25296L 52350-S04-000L, 52365-S04-014 CIVIC (1996), CRV (1996) G1 Suspension Bush (RE) B : 10 / C : 180 pcs.	O25296S 52350-S04-000S, 52622-SH3-003 CIVIC (1996) Suspension Bush B : 10 / C : 180 pcs.
O25298B 52385-SK7-N02 CIVIC (1998) Suspension Bush B : 2 / C : 32 pcs.	O2540211 50711-S9A-000 CRV (2002) Suspension Bush B : 4 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O253010 52370-SX8-T00 CITY Suspension Bush  B : 8 / C : 144 pcs.	O25301S 52350-SX8-T00, 52360-SX8-T00 CITY Suspension Bush  B : 10 / C : 180 pcs.
O25206B 52400-SNA-900B CIVIC (2006) Suspension Bush (BIG)  B : 4 / C : 72 pcs.	O25206S 52400-SNA-900S CIVIC (2006) Suspension Bush (SMALL)  B : 8 / C : 144 pcs.
O25302E 52384-SAE-T00, 52385-SEL-000 CITY (2003), JAZZ Suspension Bush (RE)  B : 4 / C : 64 pcs.	O25203E 52390-S5H-810 CIVIC (2003) Suspension Bush (RE)  B : 4 / C : 64 pcs.
O250080 52215-TC0-T00M ACCORD (2008) G8, (2013) G9 Suspension Bush (RE MEDIUM)  B : 8 / C : 144 pcs.	O25008B 52215-TC0-T00B ACCORD (2008) G8, (2013) G9 Suspension Bush (RE BIG)  B : 6 / C : 108 pcs.
O25008P 52520-TA0-A02 ACCORD (2008) Suspension Bush  B : 6 / C : 108 pcs.	O25008S 52215-TC0-T00S ACCORD (2008) G8, (2013) G9 Suspension Bush (RE SMALL)  B : 10 / C : 180 pcs.
O252030 52365-S5A-802 CIVIC (2003) Suspension Bush  B : 6 / C : 108 pcs.	
O254070E 52371-SWA-J01S CRV (2007-2011) Suspension Bush (RE)  B : 6 / C : 108 pcs.	O25407E 52215-SWE-T00S CRV (2007-2011) Suspension Bush  B : 8 / C : 144 pcs.
O254070B 52215-SWE-T00B CRV (2007-2011) Suspension Bush  B : 6 / C : 108 pcs.	O25SW10E0 42100-SLJ-030-0 STEPWAGON (2005-2009) RG1 Suspension Bush (RE)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O2521201E 52510-TS4-T01S, 52510-TS4-T51S CIVIC (2012) (1.8 cc, 2.0 cc) Suspension Bush (LH, RH)  B : 8 / C : 144 pcs.	O2521202E 52371-TR7-A03S, TS4-T02S, SNL-T03S CIVIC (2006) (FD), (2012) (FB) (1.8, 2.0 cc) Suspension Bush (RE, SMALL)  B : 8 / C : 144 pcs.
O252120B 52215-TR0-A50B, SNA-A50B CIVIC (2006, 2012) Suspension Bush (RE, BIG)  B : 6 / C : 108 pcs.	O252120S 52215-TR0-A50S, SNA-A50S CIVIC (2006, 2012) Suspension Bush (RE, SMAIL)  B : 6 / C : 108 pcs.
O25304E 42100-TM0-T02 CITY (2009-2012) Suspension Bush  B : 2 / C : 32 pcs.	O25407B 52371-SWA-J01B CRV (2007-2011) Suspension Bush  B : 1 / C : 18 pcs.
O2501301E 52355-TA0-J00, 52350-TA0-A00 ACCORD (2008) G8, (2013) G9 Suspension Bush (RE)  B : 8 / C : 144 pcs.	O25013E 52370-T2A-A00 ACCORD (2013-2015) Suspension Bush  B : 8 / C : 144 pcs.
O2521200 52371-TR7-A03B, TS4-T02B, SNL-T03B CIVIC (2006) (FD), (2012) (FB) (1.8, 2.0 cc) Suspension Bush (RE, BIG)  B : 1 / C : 18 pcs.	O2521201B 52510-TS4-T01B, 52510-TS4-T51B CIVIC (2012) (1.8 cc, 2.0 cc) Suspension Bush  B : 4 / C : 72 pcs.
O25013P 52520-T2A-A00 ACCORD (2013) Suspension Bush  B : 4 / C : 72 pcs.	O2541751 52355-TLA-A52-1 CRV (2017) Suspension Bush (RE)  B : 8 / C : 144 pcs.
O2521610 52510-TEA-T00-0 CIVIC (2016) Suspension Bush (RE, UPPER)  B : 8 / C : 144 pcs.	O2521650 52355-TEA-T00-0 CIVIC (2016) Suspension Bush (RE)  B : 8 / C : 144 pcs.
O2521671 52370-TEA-T00-1 CIVIC (2016) Suspension Bush (RE, LOWER)  B : 8 / C : 144 pcs.	O2521672 52370-TEA-T00-2 CIVIC (2016) Suspension Bush (RE, LOWER)  B : 8 / C : 144 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O260031 50361-SDB-A02 ACCORD (2003) Subframe Rubber (RE, RE)  B : 6 / C : 96 pcs.	O260032 50371-SDB-A02 ACCORD (2003) Subframe Rubber (FR, RE)  B : 6 / C : 96 pcs.
O260033 50271-SDA-A01 ACCORD (2003) Subframe Rubber (FR, RE)  B : 10 / C : 160 pcs.	O260034 50261-SDA-A02 ACCORD (2003) Subframe Rubber (FR, FR)  B : 10 / C : 160 pcs.
O26008261 50261-TA0-A01 ACCORD (2008, 2013) Subframe Rubber (FR/FR, FR/RE)  B : 8 / C : 128 pcs.	NEW
O2640213 50713-SH9-010 CRV (2002) Suspension Rubber (RE)  B : 6 / C : 96 pcs.	O26084 51303-SA5-014 CIVIC, ACCORD Bushing Side  B : 100 / C : 1,600 pcs.
O26003E 52622-SDA-A01 ACCORD (2003) Shock Absorber Bush (RE)  B : 8 / C : 144 pcs.	O262060E 52622-SNA-A01 CIVIC (2006-2014) Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.
O26086B 50836-689-000 ACCORD (1986) Shock Absorber Bush (BIG)  B : 8 / C : 144 pcs.	O26090E 52622-SM4-003 ACCORD (1990-1996) Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.
O26098E 52622-S84-A01 ACCORD (1998) Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.	O26201E 52622-S5A-004 CIVIC (2001) Shock Absorber Bush  B : 10 / C : 180 pcs.
O26402E 52622-S7A-014, 52622-S7A-A04 CRV (2002) Shock Absorber Bush (RE)  B : 6 / C : 108 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O26303E 52611-T5L-T01-0 CITY 03, 06, 14 JAZZ 09, 15 BRIO 11, FREED 10, MOBILIO 14, AMAZE 12, BR-V 16, HR-V 15 Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.	<u>Substitute Number</u> 52622-SAA-005, TG0-T01 52610-SEL-T22-1, TG1-T02-1, SZY-003-1, TRD-K01-1, T4T-T01-1, TSE-T02-1
O26286S 50836-634-000 CIVIC (1986) Shock Absorber Bush (SMALL)  B : 8 / C : 144 pcs.	O26292E 52622-SR3-003 CIVIC (1988-1992) Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.
O26216E 52611-TEA-T02-0, 52611-TED-T02-0 CIVIC (2016) (1.5 cc), (1.8 cc) Shock Absorber Bush (RE)  B : 8 / C : 144 pcs.	O26417E 52611-TMJ-T51-0 CRV (2017) Shock Absorber Bush (RE)  B : 8 / C : 144 pcs.
O26320E0 NEW 52611-T00-T11-0 CITY (2020) Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.	
O26013E0 53685-T2A-A21 ACCORD (2013) Grommet Steering Bush (RE)  B : 10 / C : 180 pcs.	O26311L 53685-TG1-T01 BRIO AMAZE Grommet Steering Bush (LH)  B : 10 / C : 180 pcs.
O26013FL 53685-T2A-A11 ACCORD (2013) Grommet Steering Bush (FR, LH)  B : 10 / C : 180 pcs.	O26013FR 53685-T2A-A01 ACCORD (2013) Grommet Steering Bush (FR, RH)  B : 10 / C : 180 pcs.
O26311E 53686-TG1-T01 BRIO AMAZE (2011) Grommet Steering Bush (RE)  B : 10 / C : 180 pcs.	O26311R 53684-TG1-T01 BRIO AMAZE (2011) Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
O26515FR 53684-T7S-T01 HR-V (2015) Grommet Steering Bush (FR, RH)  B : 10 / C : 180 pcs.	O26515FL 53686-T7S-T01 HR-V (2015) Grommet Steering Bush (FR, LH)  B : 10 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O26414EL 53684-T0A-A01 CRV (2014) Grommet Steering Bush (RE, LH)  B : 8 / C : 144 pcs.	O26414FLR 53686-T0A-A01 CRV (2014) Grommet Steering Bush (FR, LH, RH)  B : 8 / C : 144 pcs.
O263040 53684-TF0-003 JAZZ (2009) (10.4) Grommet Steering Bush  B : 10 / C : 180 pcs.	O26304L 53685-TF0-003 JAZZ (2009) Grommet Steering Bush (LH)  B : 10 / C : 180 pcs.
O26414ER 53685-T0A-A01 CRV (2014) Grommet Steering Bush (RE, RH)  B : 8 / C : 144 pcs.	O26098R 53685-S84-A01, SDA-A01 ACCORD (1998) Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
O26206R 53685-SMG-E01 CIVIC (2006) Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.	O26303R 53685-SCC-003 CITY (2003) Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
O26515RE 53685-T7S-T01 HR-V (2015) Grommet Steering Bush (RE)  B : 10 / C : 180 pcs.	O26008E0 53685-TA0-A01 ACCORD (2008) Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
O26206R0 53685-SNA-A01 CIVIC (2006) HPS Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.	O26304E0 53686-TF0-003 CITY (2008), JAZZ (2009), BR-V (2016) Grommet Steering Bush (RE)  B : 10 / C : 180 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O27090 90112-SM4-020-S ACCORD (1990) Stabilizer Link  B : 10 / C : 120 pcs.	O27286 90112-SE0-000 CIVIC (1986-1991) Stabilizer Link  B : 10 / C : 120 pcs.
O27300 90112-SX8-000 CITY, ACCORD (1988) Stabilizer Link  B : 10 / C : 120 pcs.	
O27098EL 52325-S84-A01 ACCORD (1998) Link Assy (RE, LH)  B : 2 / C : 54 pcs.	O27098ER 52320-S84-A01 ACCORD (1998) Link Assy (RE, RH)  B : 2 / C : 54 pcs.
O27098FL 51321-S84-A01 ACCORD (1998) Link Assy (FR, LH)  B : 2 / C : 90 pcs.	O27098FR 51320-S84-A01 ACCORD (1998) Link Assy (FR, RH)  B : 2 / C : 90 pcs.
O27201EL 52321-S5A-013, 52321-S7A-003 CIVIC (2001), STREAM Link Assy (RE, LH)  B : 2 / C : 90 pcs.	O27201ER 52320-S5A-013, 52320-S7A-003 CIVIC (2001), STREAM Link Assy (RE, RH)  B : 2 / C : 90 pcs.
O27201FL 51321-S5A-003 CIVIC (2001) ES G7, CRV (2002) G2, STREAM (2000) Link Assy (FR, LH)  B : 2 / C : 90 pcs.	O27201FR 51320-S5A-003 CIVIC (2001) ES G7, CRV (2002) G2, STREAM (2000) Link Assy (FR, RH)  B : 2 / C : 90 pcs.
O27296 51320-S04-003 CIVIC (1996), CRV Link Assy (FR)  B : 2 / C : 90 pcs.	
O27296EL 52321-S04-003 CIVIC (1996, 2000) Link Assy (RE, LH)  B : 2 / C : 54 pcs.	O27296ER 52320-S04-003 CIVIC (1996, 2000) Link Assy (RE, RH)  B : 2 / C : 54 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O27300E 52320-S3N-013 ODYSSEY (2000) Link Assy (RE) B : 2 / C : 54 pcs. 	O27301E 52325-SX8-T30 CITY (1996-2002) Link Assy (RE) B : 2 / C : 90 pcs. 
O27303FL 51321-SEL-T01 CITY (2003) Link Assy (FR, LH) B : 2 / C : 32 pcs. 	O27303FR 51320-SEL-T01 CITY (2003) Link Assy (FR, RH) B : 2 / C : 32 pcs. 
O27402EL 52321-S9A-003 CRV (2002) Link Assy (RE, LH) B : 2 / C : 90 pcs. 	O27402ER 52320-S9A-003 CRV (2002) Link Assy (RE, RH) B : 2 / C : 90 pcs. 
O2741EL 52321-S10-003 CRV (1996) Link Assy (RE, LH) B : 2 / C : 54 pcs. 	O2741ER 52320-S10-003 CRV (1996) Link Assy (RE, RH) B : 2 / C : 54 pcs. 
O27003FL 51321-SDA-A05 ACCORD (2003) Link Assy (FR, LH) B : 2 / C : 90 pcs. 	O27003FR 51320-SDA-A05 ACCORD (2003) Link Assy (FR, RH) B : 2 / C : 90 pcs. 
O27008FL 51325-TA0-A01 ACCORD (2008) Link Assy (FR, LH) B : 2 / C : 90 pcs. 	O27008FR 51320-TA0-A01 ACCORD (2008) Link Assy (FR, RH) B : 2 / C : 90 pcs. 
O27008EL 52325-TA0-A01 ACCORD (2008) Link Assy (RE, LH) B : 2 / C : 54 pcs. 	O27008ER 52320-TA0-A01 ACCORD (2008) Link Assy (RE, RH) B : 2 / C : 54 pcs. 
O27IN00F 51320-ST7-003 INTEGRA Link Assy (FR) B : 2 / C : 108 pcs. 	O27LE00F 51320-SP0-003 LEGEND Link Assy (FR) B : 2 / C : 108 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O27205FL 51321-SAE-T01 CITY (2006), JAZZ Link Assy (FR, LH) B : 2 / C : 36 pcs. 	O27205FR 51320-SAE-T01 CITY (2006), JAZZ Link Assy (FR, RH) B : 2 / C : 36 pcs. 
O27304F 51320-TG0-T01, TG2-T01 CITY (2008) G3 (2009), JAZZ (2009) GE, BR-V (2016), MOBILIO Link Assy (FR, LH, RH) B : 2 / C : 36 pcs. 	
O27206FL 51321-SNA-A02 CIVIC (2006) Link Assy (FR, LH) B : 2 / C : 90 pcs. 	O27206FR 51320-SNA-A02 CIVIC (2006) Link Assy (FR, RH) B : 2 / C : 90 pcs. 
O27206EL 52321-SNL-T01 CIVIC (2006) Link Assy (RE, LH) B : 2 / C : 90 pcs. 	O27206ER 52320-SNL-T01 CIVIC (2006) Link Assy (RE, RH) B : 2 / C : 90 pcs. 
O27212EL 52321-SNA-A01 CIVIC (2012) Link Assy (RE, LH) B : 2 / C : 90 pcs. 	O27212ER 52320-SNA-A01 CIVIC (2012) Link Assy (RE, RH) B : 2 / C : 90 pcs. 
O27407EL 52321-SWA-A01 CRV (2007-2011) Link Assy (RE, LH) B : 2 / C : 90 pcs. 	O27407ER 52320-SWA-A01 CRV (2007-2011) Link Assy (RE, RH) B : 2 / C : 90 pcs. 
O27407F0 51320-STK-A01 CRV (2007) Link Assy (FR, LH, RH) B : 2 / C : 36 pcs. 	O27414F0 51320-T0N-T01 CRV (2014) Link Assy (FR) B : 2 / C : 36 pcs. 
O27SW10FL 51321-SZW-003 STEP WAGON, SPADA (2010) Link Assy (FR, LH) B : 2 / C : 36 pcs. 	O27SW10FR 51320-SZW-003 STEP WAGON, SPADA (2010) Link Assy (FR, RH) B : 2 / C : 36 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O27038FL 51321-SEA-E01 ACCORD (2003, 2008) Link Assy (FR, LH) B : 2 / C : 90 pcs.	O27038FR 51320-SEA-E01 ACCORD (2003, 2008) Link Assy (FR, RH) B : 2 / C : 90 pcs.
O27300F 51320-S0X-A02 ODYSSEY (2000-2004) Link Assy (FR, LH, RH) B : 2 / C : 36 pcs.	O27301F 51320-SHJ-A02 ODYSSEY (2005-2010) Link Assy (FR, LH, RH) B : 2 / C : 36 pcs.
O27013FL 51325-T2A-A01 ACCROD (2013) Link Assy (FR, LH) B : 2 / C : 36 pcs.	O27013FR 51320-T2A-A01 ACCROD (2013) Link Assy (FR, RH) B : 2 / C : 36 pcs.
O27212FL 51321-TR0-A01 CIVIC (2012) Link Assy (FR, LH) B : 2 / C : 36 pcs.	O27212FR 51320-TR0-A01 CIVIC (2012) Link Assy (FR, RH) B : 2 / C : 36 pcs.
O27306FL 51325-T5A-003 CITY (2014), JAZZ (2015) Link Assy (FR, LH) B : 2 / C : 32 pcs.	O27306FR 51320-T5A-003 CITY (2014), JAZZ (2015) Link Assy (FR, RH) B : 2 / C : 32 pcs.
O27608F 51320-SYY-003 HONDA FREED Link Assy (FR) B : 2 / C : 36 pcs.	
O27515FL 51325-T7A-003 HR-V (2015) Link Assy (FR, LH) B : 2 / C : 36 pcs.	O27515FR 51320-T7A-003 HR-V (2015) Link Assy (FR, RH) B : 2 / C : 36 pcs.
O27320FL 51325-T00-T01 CITY (2020) Link Assy (FR, LH) B : 2 / C : 32 pcs.	O27320FR 51320-T00-T01 CITY (2020) Link Assy (FR, RH) B : 2 / C : 32 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

* RBI Center Bearing is assembled with Japanese Bearing

O29402T 40100-S9A-J01, 40100-S9A-E01 CRV (2002) Center Bearing  B : 1 / C : 20 pcs.	O29496G 40520-S10-003 CRV (1996) Center Bearing  B : 1 / C : 20 pcs.
O30080 45216-SE0-911 ACCORD (1986-1989) Cylinder Piston  B : 1 / C : 60 pcs.	O30090 45216-SM4-003 ACCORD (1990-1992) Cylinder Piston  B : 1 / C : 60 pcs.
O30094 45216-SM4-A01 ACCORD (1994), CRV (1996) Cylinder Piston  B : 1 / C : 60 pcs.	O302010 45216-S5H-T01, 45216-SR3-V01 CIVIC (1996, 2001, 2006), CITY (2020), iAAZ (2014) V-TEC Cylinder Piston  B : 1 / C : 60 pcs.
O30288 45216-SC2-003, 45216-SEL-T01 CIVIC (1988-1990), CITY (2003) Cylinder Piston  B : 1 / C : 60 pcs.	O30290 45216-SR3-003 CIVIC (1992) Cylinder Piston  B : 1 / C : 60 pcs.
O30402F 45216-S9A-A01, 45216-TEA-T01 CRV (2002), CIVIC (2017) Cylinder Piston (FR)  B : 1 / C : 60 pcs.	O30402E 43215-S7A-003 CRV (2002-2011) Cylinder Piston  B : 1 / C : 60 pcs.
O30013F 45216-T2G-A01 ACCORD (2013)G9, HR-V (2021)G2 Cylinder Piston (FR)  B : 1 / C : 60 pcs.	O30013E 43215-TW0-W01 ACCORD (2013) Cylinder Piston  B : 1 / C : 120 pcs.
O304070 45216-SHJ-A01 CRV (2007-2011) Cylinder Piston  B : 1 / C : 60 pcs.	
O3129200 18215-671-000 CIVIC (1992-2000) Exhaust Pipe Support  B : 10 / C : 160 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

HONDA

O38088L 53436-SE0-950 ACCORD (1988) Grommet Steering Rack (LH)  B : 8 / C : 128 pcs.	O38088R 53435-SE0-950 ACCORD (1988) Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.
O38090Z 53436-SM4-000-S ACCORD (1990-1993) Grommet Steering Rack  B : 4 / C : 96 pcs.	O38094Z 53436-SV4-000-S, 53685-SV4-A00-S ACCORD (1994) Grommet Steering Rack  B : 4 / C : 96 pcs.
O38098L 53436-S84-A01, SDA-A01 ACCORD (1998) Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	
O38286Z 53436-SH3-000-S CIVIC (1986-1991) Grommet Steering Rack  B : 4 / C : 96 pcs.	O38288PZ 53436-SH3-950-S CIVIC (1988-1992) Grommet Steering Rack (POWER)  B : 4 / C : 96 pcs.
O38296PZ 53436-S04-J51-S CIVIC (1996) Grommet Steering Rack (POWER)  B : 4 / C : 96 pcs.	
O38301PZ 53436-SX8-T50-S CITY Grommet Steering Rack (POWER)  B : 4 / C : 96 pcs.	O38301Z 53436-SX8-T00-S, 53685-SH3-000-S CITY Grommet Steering Rack  B : 4 / C : 96 pcs.
O38303L 53436-SEL-003 CITY (2003) Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	
O38401Z 53436-S10-010-S CRV (1996) Grommet Steering Rack  B : 4 / C : 96 pcs.	O38402Z 53436-S9A-000-S CRV (2002) Grommet Steering Rack  B : 4 / C : 96 pcs.

**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

HONDA

O38206L 53436-SNB-J01 CIVIC (2006) (EPS) Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	O38206L0 53436-SNA-A01 CIVIC (2006) (HPS) Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.
O38008L 53436-TA0-A01 ACCORD (2008) Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	
O41402E 50721-S5C-003 CRV (2002) Rubber Differential Mount (RE)  B : 2 / C : 24 pcs.	

