



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M0902B MB007161 A156 Front Engine Bushing (FR, BIG)  B : 10 / C : 120 pcs.	
M0902S MB007156 A156 Front Engine Bushing (FR, SMALL)  B : 10 / C : 120 pcs.	
M0902R MB007183, MB007184 A156 Front Engine Bushing (RH)  B : 6 / C : 72 pcs.	
M0902E MB007162 A156 Front Engine Bushing (RE)  B : 6 / C : 72 pcs.	
M0906L MB436537 E33 Front Engine Bushing (LH)  B : 2 / C : 24 pcs.	
M0906R MB436553 E33 Front Engine Bushing (RH)  B : 2 / C : 24 pcs.	
M0907EA MB911267 E54, E55 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	M0907EAZ MB911267-IN E54, E55 Insulator Engine (RE, A/T)  B : 1 / C : 12 pcs.
M0907EM MB844290 E54, E55 Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	M0907EMZ MB844290-IN E54, E55 Insulator Engine (RE, M/T)  B : 1 / C : 12 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M0907FA MB844276 E54, E55 Front Engine Bushing (FR, A/T)  B : 4 / C : 48 pcs.	M0907FAZ MB844276-IN E54, E55 Insulator Engine (FR, A/T)  B : 2 / C : 24 pcs.
M0907FM MB844274 E54, E55 Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	M0907FMZ MB844274-IN E54, E55 Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
M0907LA MB844258 E54, E55 Front Engine Bushing (LH, A/T)  B : 2 / C : 24 pcs.	M0907LAZ MB844258-IN E54, E55 Insulator Engine (LH, A/T)  B : 1 / C : 12 pcs.
M0907LM MR171324, MB844255 E54, E55 Front Engine Bushing (LH, M/T)  B : 2 / C : 24 pcs.	
M0907RA MB844536 E54, E55 Front Engine Bushing (RH, A/T)  B : 2 / C : 24 pcs.	M0907RAZ MB910201-IN E54, E55 Insulator Engine (RH, A/T)  B : 1 / C : 12 pcs.
M0907RM MB844267 E54, E55 Front Engine Bushing (RH, M/T)  B : 2 / C : 24 pcs.	M0907RMZ MB844267-IN E54, E55 Insulator Engine (RH, M/T)  B : 1 / C : 8 pcs.
M0923E MB309269 C11, C12 Front Engine Bushing (RE)  B : 6 / C : 72 pcs.	
M0923F MB309519 C11, C12 Front Engine Bushing (FR)  B : 6 / C : 72 pcs.	M0923FZ MB309512-IN C11, C12 Insulator Engine (FR)  B : 2 / C : 24 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M0923L MB303046 C11 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	
M0923R MB309366 C11 Front Engine Bushing (RH)  B : 4 / C : 48 pcs.	
	M09240Z MB309998-IN C12 III, CHAMP Insulator Engine (FR)  B : 4 / C : 48 pcs.
M0924L MB436020 C12 Front Engine Bushing (LH)  B : 2 / C : 24 pcs.	M0924LZ MB309985-IN C12 Insulator Engine (LH)  B : 1 / C : 8 pcs.
M0924R MB436410 C12 Front Engine Bushing (RH)  B : 2 / C : 24 pcs.	
M0926LR MB871602, MB949145 CB1, CB2 Front Engine Bushing (LH, RH)  B : 2 / C : 24 pcs.	M09264LZ MB691231-IN CB4 (1.6 cc) Insulator Engine (LH)  B : 1 / C : 12 pcs.
M0926LR MB871602, MB949145 CB1, CB2 Front Engine Bushing (LH, RH)  B : 2 / C : 24 pcs.	M0926RAZ MB691253-IN CB1, CB2 Insulator Engine (RH, A/T)  B : 1 / C : 12 pcs.
M0926LR MB871602, MB949145 CB1, CB2 Front Engine Bushing (LH, RH)  B : 2 / C : 24 pcs.	M0926RMZ MB691251-IN, MR103177-IN CB1, CB2 Insulator Engine (RH, M/T)  B : 1 / C : 12 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M0926EA MB870262 CB1, CB2 Front Engine Bushing (RE, A/T)	 B : 4 / C : 48 pcs.	M0926EAZ MB691238-IN CB1, CB2 Insulator Engine (RE, A/T)	 B : 2 / C : 24 pcs.
M0926EM MB891564 CB1, CB2 Front Engine Bushing (RE, M/T)	 B : 4 / C : 48 pcs.	M0926EMZ MB870012-IN CB1, CB2 Insulator Engine (RE, M/T)	 B : 2 / C : 24 pcs.
M0926FA MB691236 CB1, CB2 Front Engine Bushing (FR, A/T)	 B : 4 / C : 48 pcs.	M0926FAZ MB691236-IN CB1, CB2 Insulator Engine (FR, A/T)	 B : 2 / C : 24 pcs.
M0926FM MB891563 CB1, CB2 Front Engine Bushing (FR, M/T)	 B : 4 / C : 48 pcs.	M0926FMZ MB691235-IN CB1, CB2 Insulator Engine (FR, M/T)	 B : 2 / C : 24 pcs.
M0928FA MB309486 CK2, CK5 Front Engine Bushing (FR, A/T)	 B : 4 / C : 48 pcs.	M0928FAZ MR333578-IN, MR197541-IN CK2, CK5, CS3 Insulator Engine (FR, A/T)	 B : 2 / C : 24 pcs.
M0928FM MR197519 CK2, CK5 Front Engine Bushing (FR, M/T)	 B : 4 / C : 48 pcs.	M0928FMZ MR333577-IN, MR197537-IN CK2, CK5 Insulator Engine (FR, M/T)	 B : 2 / C : 24 pcs.
M0928LR MR244836, MR244886 CK2, CK5 Front Engine Bushing (LH, RH)	 B : 2 / C : 24 pcs.		
M0929EA MR223674 CK5 (1999) Front Engine Bushing (RE, A/T)	 B : 4 / C : 48 pcs.	M0929EAZ MR223674-IN CK5 (1999) Insulator Engine (RE, A/T)	 B : 2 / C : 24 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M0929EM MR297257 CK5 (1999) Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	M0929EMZ MR297256-IN CK5 (1999) Insulator Engine (RE, M/T)  B : 2 / C : 24 pcs.
M09CS3EA0 MR554541 CEDIA CS3, CS5 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	M09CS3EAZ MR554541-IN CEDIA CS3, CS5 Insulator Engine (RE, A/T)  B : 1 / C : 8 pcs.
M09CS3EM0 MR519400 CEDIA CS3 Front Engine Bushing (RE, M/T)  B : 4 / C : 48 pcs.	M09CS3EMZ MR519400-IN CS3, CS5 Insulator Engine (RE, M/T)  B : 1 / C : 8 pcs.
M09CS3FM0 MR554244 CS3 Front Engine Bushing (FR, M/T)  B : 4 / C : 48 pcs.	M09CS3FMZ MR554244-IN CS3 Insulator Engine (FR, M/T)  B : 2 / C : 24 pcs.
M09CS3LM0 MR403861 CEDIA CS3 Front Engine Bushing (LH, A/T, M/T)  B : 2 / C : 24 pcs.	M09CS3LMZ MR491557-IN CS3 Insulator Engine (LH, M/T)  B : 1 / C : 8 pcs.
M09CS3LM0 MR403861 CEDIA CS3 Front Engine Bushing (LH, A/T, M/T)  B : 2 / C : 24 pcs.	M09CS3LAZ MR403670-IN CEDIA CS3 Insulator Engine (LH, A/T)  B : 1 / C : 12 pcs.
M09CS5LA0 MR491527 CEDIA CS5 Front Engine Bushing (LH, A/T)  B : 2 / C : 24 pcs.	M09CS5LAZ MR491555-IN CEDIA CS5 Insulator Engine (LH, A/T)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M09NA4F MR594383 SPACE WAGON NA4 Front Engine Bushing (FR)  B : 4 / C : 48 pcs.	M09NA4E MR594385 SPACE WAGON NA4 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.
M09NA4L MN103097 SPACE WAGON NA4 Front Engine Bushing (LH)  B : 2 / C : 24 pcs.	
M09CY30F MN184058 LANCER EX CY3, CY4 Front Engine Bushing (FR)  B : 4 / C : 48 pcs.	M09CY3FZ MN184355-IN LANCER EX CY3, CY4 Insulator Engine (FR)  B : 2 / C : 24 pcs.
M09CY30E MN184060 LANCER EX CY3, CY4 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.	M09CY30LZ MN101574-IN LANCER EX, CY3, CY4 Insulator Engine (LH)  B : 1 / C : 12 pcs.
M09CS5LA0 MR491527 CEDIA CS5 Front Engine Bushing (LH, A/T)  B : 2 / C : 24 pcs.	M09CY30RZ MN101441-IN LANCER EX, CY3, CY4 Insulator Engine (RH)  B : 1 / C : 8 pcs.
M09A03F0 1092A096S, 1092A127S MIRAGE ATTRAGE A03, A13 Front Engine Bushing (FR M/T, A/T)  B : 8 / C : 192 pcs.	
M09A03FA 1092A127B MIRAGE, ATTRAGE A03, A13 Front Engine Bushing (FR, A/T)  B : 6 / C : 72 pcs.	M09A03FAZ 1092A127-IN MIRAGE, ATTRAGE A03, A13 Insulator Engine (FR, A/T)  B : 2 / C : 12 pcs.
M09A03FM 1092A096B MIRAGE, ATTRAGE A03, A13 Front Engine Bushing (FR, M/T)  B : 6 / C : 72 pcs.	M09A03FMZ 1092A096-IN MIRAGE, ATTRAGE A03, A13 Insulator Engine (FR, M/T)  B : 2 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M10010 MB006759 A121, L200 B Front Engine Mounting B : 2 / C : 24 pcs.		M10220 MA152605 A72 Front Engine Mounting B : 2 / C : 24 pcs.	
M1042L MB006605, MB436578 L200, K14, K64 (2.5 cc) Front Engine Mounting (LH) B : 2 / C : 24 pcs.		M1042R MB007023, MR151342 L200D, GTO, K64 (2.5 cc) Front Engine Mounting (RH) B : 2 / C : 24 pcs.	
M10440 MR151375 STRADA K64 (2.8 cc) Front Engine Mounting B : 2 / C : 24 pcs.		M10C010 ME011832, ME011836 CANTER, FE111-444 Front Engine Mounting B : 2 / C : 24 pcs.	
M1062L MB436833 L300, P15V Front Engine Mounting (LH) B : 1 / C : 12 pcs.		M1062R MB436832 L300, P15V Front Engine Mounting (RH) B : 1 / C : 12 pcs.	
M10T0204 MR995005, MR992670, 1093A035 TRITON (2WD), (4WD) (2.4 cc) Front Engine Mounting B : 2 / C : 24 pcs.			
M10V450 MR132720, MR132721 PAJERO V45, V46 Front Engine Mounting (FR) B : 1 / C : 12 pcs.			





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

mitsubishi

M11010 MB006602 A121, A123, GTO Rear Engine Mounting B : 1 / C : 15 pcs. 	M11020 MB180256 A156 Rear Engine Mounting B : 2 / C : 24 pcs. 
M11210 MA152606 A53 Rear Engine Mounting B : 2 / C : 24 pcs. 	
M11230 MB307175 C11, C12 Rear Engine Mounting B : 2 / C : 24 pcs. 	M11420 MB436365, MR992703 L200, K14, TRITON (2WD) Rear Engine Mounting (A/T) B : 1 / C : 15 pcs. 
M11440 MR133061, MR995006 STRADA (2500), K64, TRITON (2WD) Rear Engine Mounting (M/T) B : 1 / C : 15 pcs. 	M11441 MR133062, MR992706 STRADA (2800), K67, TRITON (B) Rear Engine Mounting (M/T) B : 1 / C : 15 pcs. 
M114X01B MR133073 STRADA, K77 (4WD) Rear Engine Mounting (BIG) B : 1 / C : 8 pcs. 	M114X01S MR353470 STRADA, K77 (4WD) Rear Engine Mounting (SMALL) B : 4 / C : 48 pcs. 
M1162Y MB436036, MB436041 L300, P15V Rear Engine Bushing B : 4 / C : 48 pcs. 	M11L047S MB260676 PAJERO L047 Rear Engine Mounting B : 6 / C : 72 pcs. 
M11T04A MR992714 TRITON (4WD) (3.2 cc) Rear Engine Mounting (A/T) B : 1 / C : 6 pcs. 	M11T040 MR992713 TRITON (4WD) (2.5 cc) Rear Engine Mounting (A/T) B : 1 / C : 6 pcs. 
M11T04MS 3204A005 TRITON (4WD) (2.5 cc) Rear Engine Mounting (SMALL, M/T) B : 4 / C : 48 pcs. 	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

M1303F MB109866 A161 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	
M1312EB MB338618 E12, E15, E33, E54 Shock Absorber Rubber (RE, BIG)  B : 16 / C : 320 pcs.	M1312ES MB242358 E12, E15, E33, E54 Shock Absorber Rubber (RE, SMALL)  B : 20 / C : 400 pcs.
M1312F MB303384 E12, E15 Shock Absorber Mounting (FR)  B : 2 / C : 40 pcs.	M1322F MB002163 A72 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.
M1323F MB303066 C11 Shock Absorber Rubber (FR)  B : 2 / C : 32 pcs.	M1324F MB430356 C12 III Shock Absorber Rubber (FR)  B : 2 / C : 32 pcs.
M1326EB MR130230 CB1, CB2 Shock Absorber Rubber (RE, BIG)  B : 8 / C : 160 pcs.	M1326ES MR130231 CB1, CB2 Shock Absorber Rubber (RE, SMALL)  B : 8 / C : 160 pcs.
M1326F MB808306 CB1, CB2, CB4 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	M1328F MR131420 CK2, CK5 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.
M13CS3F MR455018 CK5, CS3, CS5 (1999) Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	M1306F MB518670 E33 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.
M13T04P MR992329 TRITON (4WD) Shock Absorber Rubber (UPPER)  B : 12 / C : 240 pcs.	M13T04W MR992330V TRITON (4WD) Shock Absorber Rubber (LOWER)  B : 12 / C : 240 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

M13NA4F MR594347 SPACE WAGON NA4 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	M13CS901F MR554860 CEDIA CS9 Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.
M13CY30F MN101372 LANCER EX (2007), CY3, CY4, XPANDER (2018) Shock Absorber Mounting (FR)  B : 1 / C : 20 pcs.	
M13NA4EB MR594439 SPACE WAGON NA4 Shock Absorber Rubber (RE, BIG)  B : 8 / C : 160 pcs.	M13NA4ES MR594438 SPACE WAGON NA4 Shock Absorber Rubber (RE, SMALL)  B : 16 / C : 320 pcs.
M13CS3EB MR554370, MR594613 LANCER CEDIA CS3, CS5, CS9, LANCER EX (2007), CY3, CY4 Shock Absorber Rubber (RE, BIG)  B : 12 / C : 240 pcs.	M13CS3ES MR554369, MR594612 LANCER CEDIA CS3, CS5, CS9, LANCER EX (2007), CY3, CY4 Shock Absorber Rubber (RE, SMALL)  B : 16 / C : 320 pcs.
M13A03F 4060A445 MIRAGE, ATTRAGE A03, A13 Shock Absorber Rubber (FR)  B : 6 / C : 120 pcs.	M13A03E 4162A193 MIRAGE, ATTRAGE A03, A13 Shock Absorber Rubber (RE)  B : 10 / C : 200 pcs.
M13A030E 4162A194 MIRAGE, ATTRAGE A03, A13 Shock Absorber Rubber (RE)  B : 10 / C : 200 pcs.	
M13V73UF MR374546 PAJERO V73, V75, V78 Shock Absorber Rubber (FR)  B : 8 / C : 160 pcs.	M13V73WF MR374547 PAJERO V73, V75, V78 Shock Absorber Rubber (FR)  B : 8 / C : 160 pcs.
M13XP18EP 4162A441 XPANDER (2018) NC1W Shock Absorber Rubber (RE, UPPER)  B : 10 / C : 200 pcs.	M13XP18EW 4162A442 XPANDER (2018) NC1W Shock Absorber Rubber (RE, LOWER)  B : 10 / C : 200 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M1401B MA150599 A121 Shock Absorber Bound (FR, BIG Diameter) B : 10 / C : 120 pcs. 	M1422S MA150598 A72 Shock Absorber Bound (FR, SMALL Diameter) B : 10 / C : 120 pcs. 
M1402F MB303069 C12, CB1, CB2 Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 	
M1406E MB338684 E12, E33, CB1, CB2 Shock Absorber Bumper (RE) B : 6 / C : 72 pcs. 	M1406F MB349347 E12, E15, E33, E54 Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 
M14NA4E 4060A047 SPACE WAGON NA4, XPANDER (2018) 300 NC1W Shock Absorber Bumper (RE) B : 8 / C : 96 pcs. 	M14CS90F MR961189 CEDIA CS9 Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 
M14PG4E MR418018 PAJERO SPORT Shock Absorber Bumper (RE) B : 2 / C : 24 pcs. 	
M14XP18F1 4055A048 XPANDER (2018) NC1W Shock Absorber Bumper (FR) B : 6 / C : 72 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M14CS3EC MR510002 CS3, CS5, CS9 Shock Dust Cover (RE) B : 2 / C : 32 pcs. 	M14CS3F0 MR455020 CS3, CS5 Shock Dust Cover (FR) B : 2 / C : 32 pcs. 
M14NA4F MR272833, 4060A532 SPACE WAGON NA4, LANCER EX, CY3, CY4 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	M14T040F MR992325 TRITON (4WD) Shock Dust Cover (FR) B : 4 / C : 80 pcs. 
M14A030F 4055A038 MIRAGE, ATTRAGE A03, A13 Shock Dust Cover (FR) B : 4 / C : 80 pcs. 	M14A030E 4155A027 MIRAGE, ATTRAGE A03, A13 Shock Dust Cover (RE) B : 2 / C : 44 pcs. 
M14V75F MR554120 PAJERO V73, V75, V78 Shock Dust Cover (FR) B : 2 / C : 32 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M1702IZ MB176164 A156 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1702UZ MB176162 A156 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1706IZ MB526977 E33 (8V) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1706UZ MB620168 E33 (8V) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1707IZ MB526907 E33 (16V), CS9 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1707UZ MB526905 E33 (16V) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1708IZ MB937998 E55 (16V) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1708UZ MR222684 E55 (16V) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1709IZ MB937307 E54 (24V) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1709UZ MR222635 E54, E55 (24V) Drive Shaft Boot (OUTER)  B : 1 / C : 50 pcs.
M1711IZ MB176861 E11, E12 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1711UZ MB297351 E11, E12 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1715IZ MB620054 E15 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1715UZ MB620053 E15 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1723E MB110423 C12 Drive Shaft Boot (RE)  B : 4 / C : 64 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M1723IZ MB297454 C11, C12 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1723UZ MB175869 C11, C12 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1725IZ MB298546 C13 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1725UZ MB176195 C13 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1726IZ MB620876 CB1, CB2, CB4 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1726UZ MB837211 CB1, CB2, CB4 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1727IZ MB886676 PAJERO, STRADA, K77 (4WD) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1727UZ MB896069 PAJERO Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
	M174X01UZ MR232240 STRADA, K77 (4WD) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M1728IZ MR195707 CK1, CK2, CK3, CK5 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M1728UZ MR196053 CK1, CK2, CK3, CK5 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M17CS3IZ MR276444 CS3, CS5 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M17CS3UZ MR276442 LANCER CEDIA CS3, CS5, CS9 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M17T04IZ MR528709 TRITON (4WD) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M17T04UZ 3815A180V TRITON (4WD) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M17NA4IZ MN110516 SPACE WAGON NA4 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	
M17K57IZ MR350589 G-WAGON (2.8 cc) K57 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M17K57UZ MR350588 G-WAGON (2.8 cc) K57 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M17CY3IZ 3817A135 LANCER EX, CY3, CY4 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M17CY3UZ 3817A134 LANCER EX, CY3, CY4 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
M17A03IZ 3817A208 MIRAGE, ATTRAGE A03, A13 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	M17A03AUZ 3817A209 MIRAGE A03, ATTRAGE A13 Drive Shaft Boot (OUTER, A/T)  B : 2 / C : 100 pcs.
M17A03UMZ 3817A210 MIRAGE A03, ATTRAGE A13 Drive Shaft Boot (OUTER, M/T)  B : 2 / C : 100 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M18020Z MB122136 A156 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	M18A030Z 4410A549 MIRAGE ATTRAGE A03, A13 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
M1811LZ MB266165 E11, E12 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	M1811RZ MB266166 E11, E12 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
M1823LZ MB347364 C11, C12 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	M1823RZ MB347365 C11, C12 Steering Gear Boot (RH)  B : 2 / C : 50 pcs.
M1826LZ MB532531 CB1, CB2 Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	M1826RPZ MB501711 CB1, CB2, E12, E33 Steering Gear Boot (RH, POWER)  B : 2 / C : 50 pcs.
M18CS30Z MR491361 CEDIA CS3, CS5, CS9 Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.	M18T02LRZ 4410A179 TRITON (2WD) Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
M18NA4Z MN103262 SPACE WAGON NA4 Steering Gear Boot  B : 2 / C : 50 pcs.	M18T04Z 4410A180 TRITON Steering Gear Boot (LH, RH)  B : 2 / C : 50 pcs.
M18V73LZ MR510271 PAJERO V73-V78 (1998-2007) Steering Gear Boot (LH)  B : 2 / C : 50 pcs.	M18V73RZ MR510272 PAJERO V73-V78 (1998-2007) Steering Gear Boot (RH)  B : 2 / C : 50 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M19T020 MR992443 TRITON (2WD) Coil Spring Rubber  B : 4 / C : 64 pcs.	M19T040 MR992324 TRITON (4WD) Coil Spring Rubber  B : 4 / C : 64 pcs.
M2022B MA180631 A72 Spring Shackle Rubber (BIG)  B : 8 / C : 192 pcs.	M2022G MA471176 A72 Spring Shackle Rubber (LONG)  B : 36 / C : 864 pcs.
M2022T MA126004 A72 Spring Shackle Rubber (SHORT)  B : 36 / C : 864 pcs.	
M2041B MB111203 L200 Spring Shackle Rubber (BIG)  B : 16 / C : 384 pcs.	M2041G MB584531, MT111071 L200, K14, K64, K77, TRITON (2005,2015) Spring Shackle Rubber (LONG)  B : 10 / C : 240 pcs.
M2041T MB584530, MT362394 L200, K14, K64, K77 Spring Shackle Rubber (SHORT)  B : 16 / C : 384 pcs.	
M20TT15ET 4152A020 TRITON (2015) Spring Shackle Rubber (RE SHORT)  B : 20 / C : 480 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M21010 MB175639 A121 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	
M2102B MB176757 A156 Stabilizer Shaft Rubber (FR, BIG)  B : 16 / C : 384 pcs.	M2102S MB176279 A156 Stabilizer Shaft Rubber (FR, SMALL)  B : 20 / C : 480 pcs.
M21030 MB175638 A161 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	M21040 MB175640 A173 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.
M21061 MB573207 E33 (8V) Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.	M21062 MB573054 E33 (16V) Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.
M2107E MR297504 E54, E55 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	M2107F MR297500 E54, E55 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.
M21120 MB303541 E12 Stabilizer Shaft Rubber  B : 30 / C : 720 pcs.	M21210 MA150612 A53 Stabilizer Shaft Rubber (SMALL Diameter)  B : 16 / C : 384 pcs.
M21220 MA150610 A72 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	M2123F MB349530 C11, C12 Stabilizer Shaft Rubber  B : 24 / C : 576 pcs.
M2126E MB809357 CB1, CB2 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	M2126F MB844456 CB1, CB2 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.






PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2128E MR197475 CK2, CK5 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	M2128F MR171441 CK2, CK5 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.
M2129F MR403082 CK5 (1999) Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	
M21410 MB109557 L200 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	M21440 MB111240 STRADA, K64, K67 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.
M21450 MR151326 K77 (4WD) Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.	M21620 MB430968 L300 P15V Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.
M2163040 MB573810 DELICA, P25W Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	
M2163041 MR151285 DELICA Stabilizer Shaft Rubber  B : 6 / C : 96 pcs.	M2163042 MR150095 DELICA Stabilizer Shaft Rubber  B : 6 / C : 96 pcs.
M21CS3F00 MR403645 CS3 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	M21CS5F00 MR491192 CS5 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
M21L0470 MB176442 PAJERO L047 Stabilizer Shaft Rubber  B : 16 / C : 384 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M21N31F MB633239 RVR, N28W, N31 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	M21V45F MR150094 PAJERO V45 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
M21NA4E MN103392 NA4 Stabilizer Shaft Rubber (RE)  B : 10 / C : 240 pcs.	M21NA4F MR594335 NA4 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
M21T04F MR992317 TRITON (4WD) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	M21TT15F 4056A219 TRITON, PAJERO SPORT (2015) (2WD, 4WD) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
M21CS901E MR589637 CEDIA CS9 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	M21V450 MR150091 PAJERO V45 Stabilizer Shaft Rubber  B : 6 / C : 96 pcs.
M21V73E MR418547 PAJERO V73 (2001-2007) Stabilizer Shaft Rubber (RE)  B : 6 / C : 96 pcs.	M21V73F MR374520 PAJERO V73 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
M21PG4E MB338594 PAJERO SPORT Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	M21PG15^E 4156A113 PAJERO SPORT (2015) Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
M21CY3F 4056A049, 4056A078 LANCER EX (2007), CY3, CY4, XPANDER (2018) Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.	M21CY3E MN101395 LANCER EX, CY3 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
M21DJ10F MR589438 DJ1, DJ3 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.	M21DJ5F MN101323 DJ5, DK2, DK4 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M21EA11F MR244115, MR589815, MR589816 EA1, EA2, EA3, EA6, EA7, EA8, D52 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	M21EA11E MR223536, MR272717, MR589402 EA1, EA2, EA3, EA6, D52, D53, DJ1 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.
M21EA21F MR244116 EA2, EA3, EA4, EA5, EA6, EA8, D53 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	M21EA40E MN101148, MR297629 EA4, EA5, DJ1, DJ3, DK2 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.
M21EA50F MR272646 EA5 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.	M21L141F MB573784 L141G, L144G, V23C, V23W, V24C, V24V, V24W, V24WG, V34V Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
M21CY4E 4156A004 LANCER EX, CY4 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	M21N11E MB871062 N11, N13, N28, N23, N84 Stabilizer Shaft Rubber (RE)  B : 24 / C : 576 pcs.
M21N84F MR316227 N84 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.	M21PD40E MR267685 PD4W, PD6W, PD8W, PEXW, PF6W, PF8W Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.
M21CA30F MB844455 CA3A, CB3A, CB6A, DE3A, H31A, H36A, H57A Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	
M21CK40F MR197005 CK4 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	M21CP90F MR491144 CN9, CP9 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
M21CU20E MR403775 CU2, CU4, CU5, CQ1, CQ2, CQ5, CR5, CR6 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	M21CU20F MR554095, MR554820 CU2, CU4, CS1, CS3, CS5, CT9 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M21CJ40F MR369084 CJ4, CK4, CM5 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs.		M21CJ40E MR197002, MR197003 CJ4, DE2, DE3, CE9 Stabilizer Shaft Rubber (RE) B : 20 / C : 480 pcs.	
M21CW50F 4056A079 CW5, CW6, GA#, CV5 Stabilizer Shaft Rubber (FR) B : 6 / C : 144 pcs.		M21CW50E 4156A028 CW5, CW6 Stabilizer Shaft Rubber (RE) B : 6 / C : 144 pcs.	
M22450 MR150767 K77 (4WD) Stabilizer Grommet Rubber B : 12 / C : 288 pcs.			





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M23011 MB109789 A121 Strut Bar Rubber  B : 12 / C : 288 pcs.	M23012 MB109788 A121 Strut Bar Rubber  B : 12 / C : 288 pcs.
M2302Y MB176740 A156 Strut Bar Rubber  B : 12 / C : 288 pcs.	M23041 MB175617 A173 Strut Bar Rubber  B : 12 / C : 192 pcs.
M23042 MB175618 A173 Strut Bar Rubber  B : 12 / C : 192 pcs.	M23221 MB001766 A72 Strut Bar Rubber  B : 12 / C : 288 pcs.
M23222 MB001765 A72 Strut Bar Rubber  B : 12 / C : 288 pcs.	M23431 MB176371 K14 Strut Bar Rubber  B : 10 / C : 240 pcs.
M23432 MB176372 K14 Strut Bar Rubber  B : 10 / C : 240 pcs.	M23611 MB430158, MB527387 L300, P15V Strut Bar Rubber  B : 12 / C : 192 pcs.
M23T020 4016A001 TRITON (2WD) Strut Bar Rubber  B : 12 / C : 192 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2301Z MB109815-S A121 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	M2302Z MB109460-S A156 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
M2304Z MB175619-S A173, K64 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	M2322Z MB001698-S A72, L200B Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
M2343Z MB176373-S, MR234247-S K14, K64, K67 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.	M2361Z MB175543-S L300, L031 Strut Bar Rubber (SET)  B : 1 / C : 65 pcs.
M23T020Z 4016A001-S TRITON (2WD) Strut Bar Rubber (SET)  B : 1 / C : 50 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2403W MB175762 A156 Lower Arm Bushing  B : 10 / C : 180 pcs.	M2404W MB109786 A161, A173 Lower Arm Bushing  B : 8 / C : 144 pcs.
M2406W MB518220 E33 Lower Arm Bushing  B : 4 / C : 72 pcs.	M2407P0 MB891518 E54, E55 (ULTIMA) Upper Arm Bushing  B : 10 / C : 180 pcs.
M2407WB MR296319, MR162582 E54, E55 (ULTIMA) Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	M2407WG MB808556, MB162580 E54, E55 (ULTIMA) Lower Arm Bushing (LONG)  B : 10 / C : 180 pcs.
M2407WT MR296296, MR162581 E54, E55 (ULTIMA) Lower Arm Bushing (SHORT)  B : 8 / C : 144 pcs.	
M2412B MB303680 E12 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	M2412S MB430311 E12, E15, E33, E185 Lower Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
M2415L MB518094 E15 Lower Arm Bushing (LH)  B : 4 / C : 72 pcs.	M2415R MB518095 E15 Lower Arm Bushing (RH)  B : 4 / C : 72 pcs.
M2421W MB001620 A53, 16L Lower Arm Bushing  B : 10 / C : 180 pcs.	M2422W MB001621 A72, A121 Lower Arm Bushing  B : 20 / C : 480 pcs.
M2423L MB518392 C11, C12 Lower Arm Bushing (LH)  B : 4 / C : 72 pcs.	M2423R MB518393 C11, C12 Lower Arm Bushing (RH)  B : 4 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2424S MB303787 C12 Lower Arm Bushing (SMALL Diameter) B : 10 / C : 180 pcs.	M2425S MB430385 C12 III Lower Arm Bushing (BIG Diameter) B : 8 / C : 144 pcs.
M2426L MB808909 CB1, CB2, CK2, CK5 Lower Arm Bushing (LH) B : 4 / C : 72 pcs.	M2426R MB808910 CB1, CB2, CK2, CK5 Lower Arm Bushing (RH) B : 4 / C : 72 pcs.
M2426S MR130983 CB1, CB2, CK2, CK5 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs.	
M2441W MB109529 L200 Lower Arm Bushing B : 16 / C : 384 pcs.	M2443W MB109528 K14 Lower Arm Bushing B : 6 / C : 108 pcs.
M2444P MB430462 STRADA, K14, K64 Upper Arm Bushing B : 8 / C : 144 pcs.	M2444W MR132039 STRADA, K64 Lower Arm Bushing B : 4 / C : 72 pcs.
M2445P MR124880, MB633820 STRADA K77 (4WD), PAJERO V43, V45 Upper Arm Bushing B : 6 / C : 108 pcs.	
M2445WB MB109662 PAJERO L042, L047 Lower Arm Bushing (BIG) B : 6 / C : 108 pcs.	M2445WS MB109684 STRADA K77 (4WD), PAJERO V6, V43, V45 Lower Arm Bushing (SMALL) B : 8 / C : 144 pcs.
M2461W MB109936 L300, L031 Lower Arm Bushing (SMALL) B : 6 / C : 108 pcs.	M24621P00 MB430201 L300, P15V, HI2404 Upper Arm Bushing (SMALL) B : 8 / C : 144 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2462PB MB430200 L300, P15V, HI2405 Upper Arm Bushing (BIG)	 B : 4 / C : 72 pcs.	M2462W MR319537, MB430145 L300, P15V, HI2401 Lower Arm Bushing	 B : 4 / C : 72 pcs.
M24CS3WB MR403441 CEDIA CS3, CS5, CS9 Lower Arm Bushing (BIG)	 B : 4 / C : 72 pcs.	M24CS3WS MR403440 CEDIA CS3, CS5, CS9 Lower Arm Bushing (SMALL)	 B : 8 / C : 144 pcs.
M24CS3WT MR403441T CS3, CS5 CEDIA Lower Arm Bushing	 B : 4 / C : 72 pcs.	M24K77W MB633870 STRADA K77 (4WD), PAJERO V6, V43, V45 Lower Arm Bushing (BIG)	 B : 4 / C : 72 pcs.
M24N31WL MB633003 N31, N33 SPACE WAGON Lower Arm Bushing (LH)	 B : 4 / C : 64 pcs.	M24N31WR MB633004 N31, N33 SPACE WAGON Lower Arm Bushing (RH)	 B : 4 / C : 64 pcs.
M24N31WS MB633002 N31, N33 SPACE WAGON Lower Arm Bushing (SMALL)	 B : 8 / C : 144 pcs.		
M24NA4WB MR594320 NA4 SPACE WAGON Lower Arm Bushing (BIG)	 B : 4 / C : 72 pcs.	M24NA4WS MR594325 NA4 SPACE WAGON Lower Arm Bushing (SMALL)	 B : 8 / C : 144 pcs.
M24T02P 4010A017 TRITON (2WD) Upper Arm Bushing	 B : 6 / C : 108 pcs.	M24T02W MR992410 TRITON (2WD) Lower Arm Bushing	 B : 4 / C : 72 pcs.
M24T04P 4010A013 TRITON (4WD) Upper Arm Bushing	 B : 6 / C : 108 pcs.	M24T04W MR992256 TRITON (4WD) Lower Arm Bushing	 B : 4 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M24V75P MR519398 PAJERO V75 (3.5 cc) Upper Arm Bushing  B : 6 / C : 108 pcs.	
M24V75WB MR510417B PAJERO V75 (3.5 cc) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	M24V75WS MR510417S PAJERO V75 (3.5 cc) Lower Arm Bushing (SMALL)  B : 4 / C : 72 pcs.
M24CY30W MN125871 LANCER EX (2007), CY3, CY4, XPANDER (2018) Lower Arm Bushing  B : 8 / C : 144 pcs.	M24CY3WB MN184133, 4013A426 LANCER EX (2007), CY3, CY4, XPANDER (2018) Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.
M24A03WB 4013A311 MIRAGE, ATTRAGE A03, A13 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	M24A03WS 4013A312 MIRAGE, ATTRAGE A03, A13 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
M24FB70P MK335060 CANTER FB70 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	
M24N94WB MR316074 SPACE WAGON N94 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M25011 MB003019 A121 Suspension Bush  B : 8 / C : 144 pcs.	M25012 MB002979 A121 Suspension Bush  B : 6 / C : 108 pcs.
M25013 MB002990 A121 Suspension Bush  B : 4 / C : 72 pcs.	M25031 MB111173 A161 Suspension Bush  B : 8 / C : 144 pcs.
M25032 MB111040 A161 Suspension Bush  B : 4 / C : 72 pcs.	
M25041 MB110815 A173 Suspension Bush  B : 8 / C : 144 pcs.	M25042 MB110808 A173 Suspension Bush  B : 8 / C : 144 pcs.
M25043 MB110720 A173 Suspension Bush  B : 6 / C : 108 pcs.	M25044 MB002998 A173, A121, A161 Suspension Bush  B : 10 / C : 180 pcs.
M2506EB MB515500 E33 Suspension Bush (BIG)  B : 4 / C : 72 pcs.	M2506ES MB584084 E33 Suspension Bush (SMALL)  B : 10 / C : 180 pcs.
M2507EB MB864736 E54, E55 Suspension Bush (BIG, RE)  B : 6 / C : 108 pcs.	M2507E0 MB809170 E54, E55 Suspension Bush (RE)  B : 8 / C : 144 pcs.
M2507ES MR223673, MB864964, MR102013 E54, E55, CB, CK Suspension Bush (SMALL)  B : 10 / C : 180 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2512EB MB242367 E12, E15 Suspension Bush (BIG) B : 4 / C : 72 pcs.		M2512ES MB242332 E12, E15 Suspension Bush (SMALL) B : 6 / C : 108 pcs.	
M2512FB MB303626 E12, E15, E33 Suspension Bush (FR, BIG) B : 6 / C : 108 pcs.		M2512FS MB303628 E12, E15, E33 Suspension Bush (FR, SMALL) B : 6 / C : 108 pcs.	
M2526EB MB809262, MR102063 CB1, CB2, CK2, CK5 Suspension Bush (RE, BIG) B : 4 / C : 64 pcs.		M2526ES MR102012 CB1, CB2 Suspension Bush (SMALL) B : 10 / C : 180 pcs.	
M2528B MR102014 CB1, CB2, CK2, CK5 Suspension Bush B : 8 / C : 144 pcs.		M25290 MR403464 CK2, CK5, CS3, CS5 Suspension Bush B : 10 / C : 180 pcs.	
M25450 MR374327, MB430694 STRADA, K77 (4WD) Suspension Bush (FR) B : 4 / C : 72 pcs.			
M25630 MB951444 L400 Suspension Bush B : 4 / C : 72 pcs.		M25631 MB951445 L400 Suspension Bush B : 6 / C : 108 pcs.	
M2563040 MR112710 DELICA, PD#PF (4WD) Suspension Bush B : 6 / C : 108 pcs.		M2563041 MR112711 DELICA, PD#PF (4WD) Suspension Bush B : 4 / C : 72 pcs.	
M2563042 MB430960 DELICA, P25W (4WD) Suspension Bush B : 6 / C : 108 pcs.		M2563043 MB633070 DELICA, P25W (4WD) Suspension Bush B : 6 / C : 108 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M25CS30B MR519127 CEDIA CS3, CS5 Suspension Bush (BIG)  B : 2 / C : 32 pcs.	M25CS301 MR491911, MN100110, MN100086S CEDIA CS3, CS5, CS9 Suspension Bush  B : 10 / C : 180 pcs.
M25CS302 MR403485 CEDIA CS3, CS5 Suspension Bush  B : 10 / C : 180 pcs.	
M25N2100 MB515563 N21, N41W, N43W SPACE WAGON Suspension Bush  B : 8 / C : 144 pcs.	
M25V43E MB631492 PAJERO V43, V45 Suspension Bush  B : 4 / C : 72 pcs.	M25V45E MR112891 PAJERO V45 Suspension Bush  B : 4 / C : 72 pcs.
M25V75E MR510418 PAJERO V75 Suspension Bush (RE)  B : 2 / C : 32 pcs.	M25K57E MR267949, MB922857 G-WAGON K57, PAJERO V43V Suspension Bush  B : 4 / C : 72 pcs.
M25CS901G MN100086B CEDIA CS9 Suspension Bush (BIG, LONG)  B : 8 / C : 144 pcs.	M25CS901S MN100109S CEDIA CS9 Suspension Bush (SMALL)  B : 8 / C : 144 pcs.
M25CS901T MN100109B CEDIA CS9 Suspension Bush (BIG, SHORT)  B : 8 / C : 144 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M25V73E MR374575 PAJERO V73 Suspension Bush  B : 4 / C : 72 pcs.	M25V750E MR374672 PAJERO V75 (3.5 cc) Suspension Bush  B : 6 / C : 108 pcs.
M25V730 MR554076 PAJERO V73 Suspension Bush  B : 4 / C : 72 pcs.	M25V730E MR374574 PAJERO V43W, V75W, V76W Suspension Bush  B : 4 / C : 72 pcs.
M25V731 MR418671 PAJERO V73-V78 Suspension Bush  B : 4 / C : 72 pcs.	M25CY30E 4120A125 LANCER EX, CY3, CY4 Suspension Bush  B : 2 / C : 32 pcs.
M25PG40 MR210731 PAJERO SPORT Suspension Bush  B : 4 / C : 72 pcs.	M25PG4E 4113A085 PAJERO SPORT Suspension Bush  B : 4 / C : 72 pcs.
M25T04F MR992363, MN125147-0 TRITON, PAJERO SPORT (2005, 2015) (4WD) Suspension Bush (FR)  B : 4 / C : 72 pcs.	M25T04FZ MN125147-IN TRITON, PAJERO SPORT (2005, 2015) (4WD) Suspension Bush (FR)  B : 2 / C : 24 pcs.
M25V43FZ MB951304-IN PAJERO V43W (3.0 cc) Suspension Bush (FR)  B : 1 / C : 18 pcs.	
M25NA4183 4100A018-3, MR594429 SPACE WAGON NA4 Suspension Bush (RE)  B : 2 / C : 36 pcs.	M25NA4ES0 MN103487-0 SPACE WAGON NA4 Suspension Bush (RE)  B : 6 / C : 108 pcs.
M25NA4182 4100A018-2, MR594430 SPACE WAGON NA4 Suspension Bush (RE)  B : 2 / C : 36 pcs.	M25XP18E0 4120A266-0 XPANDER (2018) NC1W Suspension Bush (RE)  B : 2 / C : 32 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2644F MR418960 K64, K67, K77 STRADA Spring Shackle Bush (FR)  B : 10 / C : 160 pcs.	M2643F MB515925 L200, K14 Spring Shackle Bush (FR)  B : 10 / C : 160 pcs.
M26A030E 4162A199, 4162A256 MIRAGE, ATTRAGE A03, A13 Shock Absorber Bushing  B : 10 / C : 180 pcs.	M26V73F MR992126 PAJERO V73, V75, V78 Shock Absorber Bushing  B : 8 / C : 144 pcs.
M26120 MB303650 E12, E15, E33, E54 Suspension Bush  B : 20 / C : 480 pcs.	
M2623FB MB349419 C11 Suspension Bush (FR, BIG)  B : 20 / C : 480 pcs.	M2623FS MB176667 C11 Suspension Bush (FR, SMALL)  B : 20 / C : 480 pcs.
M2623RB MB515143 C11 Suspension Bush (RE, BIG)  B : 8 / C : 128 pcs.	M2623RS MB515142 C11 Suspension Bush (RE, SMALL)  B : 8 / C : 128 pcs.
M2626E MB891463 CB1, CB4, CK2 Shock Absorber Bush (RE)  B : 8 / C : 144 pcs.	M26V454 MB584166 PAJERO V43, V45, PAJERO SPORT (2005-2015) Bushing Sway (RE)  B : 8 / C : 144 pcs.
M2626FB MB844446 CB1, CB2 Suspension Rubber (FR, BIG)  B : 20 / C : 480 pcs.	M2626FS MB844445 CB1, CB2 Suspension Rubber (FR, SMALL)  B : 20 / C : 480 pcs.
M26N31FB MB808747 N31 SPACE WAGON Suspension Rubber (FR, BIG)  B : 20 / C : 480 pcs.	M26N31FS MB808748 N31 SPACE WAGON Suspension Rubber (FR, SMALL)  B : 20 / C : 480 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M26V43E MB809388 PAJERO (1992-1998), V43 Suspension Rubber  B : 12 / C : 192 pcs.	
M26T020 MR992435 TRITON (2WD) Shock Absorber Bush  B : 10 / C : 180 pcs.	M26T040 MR992320 TRITON, PAJERO (2005, 2015) (4WD) Shock Absorber Bush (FR)  B : 10 / C : 180 pcs.
M26CS301 MR403503 CS3, CS9 Grommet Steering Bush  B : 10 / C : 180 pcs.	M26T0204 4410A166 TRITON (2WD), (4WD) Grommet Steering Bush (RH)  B : 10 / C : 180 pcs.
M26A030 4410A355 MIRAGE, ATTRAGE A03, A13 Grommet Steering Bush (LH, RH)  B : 10 / C : 180 pcs.	M26NA4LR 4410A102 SPACE WAGON NA4 Grommet Steering Bush (LH, RH)  B : 10 / C : 180 pcs.
M26XP18EW 4162A409-0 XPANDER (2018) NC1W Shock Absorber Bush (RE)  B : 6 / C : 108 pcs.	NEW M26PG05E1 4162A364-1, 4162A413-1 PAJERO SPORT (2005,2015) Shock Absorber Bush (RE, LOW)  B : 8 / C : 144 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2707E MB892982 E54, E55 Link Assy (RE) B : 2 / C : 108 pcs. 	M2707F MB892981 E54, E55 Link Assy (FR) B : 2 / C : 54 pcs. 
M2726E MB809354 CB1, CB2, CB4 Link Assy (RE) B : 2 / C : 108 pcs. 	
M27N31FL MB672370 N31, N33 SPACE WAGON Link Assy (FR, LH) B : 2 / C : 90 pcs. 	M27N31FR MB808076 N31, N33 SPACE WAGON Link Assy (FR, RH) B : 2 / C : 90 pcs. 
M27NA4FL MR594339 SPACE WAGON NA4 Link Assy (FR, LH) B : 2 / C : 32 pcs. 	M27NA4FR MR594340 SPACE WAGON NA4 Link Assy (FR, RH) B : 2 / C : 32 pcs. 
M27T04FL MR992309, 4056A192 TRITON (4WD) Link Assy (FR, LH) B : 2 / C : 90 pcs. 	M27T04FR MR992310, 4056A193 TRITON (4WD) Link Assy (FR, RH) B : 2 / C : 90 pcs. 
M27V73FL MR374521 PAJERO V73 Link Assy (FR, LH) B : 2 / C : 90 pcs. 	M27V73FR MR374522 PAJERO V73 Link Assy (FR, RH) B : 2 / C : 90 pcs. 
M27V73EL MR418052 PAJERO V73 Link Assy (RE, LH) B : 2 / C : 54 pcs. 	M27V73ER MR418053 PAJERO V73 Link Assy (RE, RH) B : 2 / C : 54 pcs. 
M27CS9E 4056A037 LANCER CEDIA (2004), CS9 Link Assy (RE) B : 2 / C : 90 pcs. 	M27V45F MB633926 PAJERO V45 (1995-1999) (3.5 cc) Link Assy (FR) B : 2 / C : 108 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M27CY3E MN184194 LANCER EX CY3, CY4 Link Assy (RE)  B : 2 / C : 90 pcs.	M27CY3F MN101368 LANCER EX (2007), CY3, CY4, XPANDER (2018) Link Assy (FR)  B : 2 / C : 32 pcs.
M27CS3F 4056A040 CS3, 9 CU2W, CR5W Link Assy (FR)  B : 2 / C : 108 pcs.	M27CY3EL 4156A014 CY2, CY3, 4A, D5 CV5 Link Assy (RE, LH)  B : 2 / C : 90 pcs.
M27DJ00E MR589336 DJA1A, DJA3, DK2A, DK4A, D71W Link Assy (RE, LH, RH)  B : 2 / C : 108 pcs.	M27E38F0 4056A039, MB584467 E38A, 39A F11A, FA12A Link Assy (FR, LH, RH)  B : 2 / C : 108 pcs.
M27EA3FL MR297333 EA3A, EA8A Link Assy (FR, LH)  B : 2 / C : 32 pcs.	M27EA3FR MR333763 EA3A, EA8A Link Assy (FR, RH)  B : 2 / C : 32 pcs.
M27EA3E 4056A019 EA3A, 8A, F11, 12A, S22A, 27A Link Assy (RE)  B : 2 / C : 90 pcs.	
M27N50FL 4056A034 N50 Link Assy (FR, LH)  B : 2 / C : 40 pcs.	M27N50FR 4056A035 N50 Link Assy (FR, RH)  B : 2 / C : 40 pcs.
M27PA30F MR132707, MR267873 PA3W, PA4W, PD4W, PD5W, P02T, P05T, P13T, P15T, P25T Link Assy (FR, LH, RH)  B : 2 / C : 90 pcs.	M27PA30E MB185476, MR112394, MR267875 PA3W, PA4W, PD4W, PD5W, PD6W, PD8W, L041G, L149G, P23W, P25V Link Assy (FR, RH)  B : 2 / C : 108 pcs.
M27PD40F MR150705, MR267874 PD4W, PD5W, PD6W, PD8W Link Assy (FR, LH, RH)  B : 2 / C : 90 pcs.	M27DA1F0 MR272116 DA1 Link Assy (FR, LH, RH)  B : 2 / C : 40 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M27TT15FL 4056A198 TRITON, PAJERO SPORT (2015) (2WD,4WD) Link Assy (FR, LH) B : 2 / C : 54 pcs. 	M27TT15FR 4056A199 TRITON, PAJERO SPORT (2015) (2WD,4WD) Link Assy (FR, RH) B : 2 / C : 54 pcs. 
M27H76E0 MR510319, MR554830 PAJERO IO H76W Link Assy (RE) B : 2 / C : 40 pcs. NEW 	
M27V45FL MR267876 PAJERO V45W Link Assy (FR, LH) B : 2 / C : 90 pcs. NEW 	M27V45FR MR267877 PAJERO V45W Link Assy (FR, RH) B : 2 / C : 90 pcs. NEW 
M27210 MB001626 A53 Stabilizer Link B : 10 / C : 120 pcs. 	M27220 MB241429, 4056A053 A172, A173, NA4 Stabilizer Link B : 10 / C : 120 pcs. 
M27230 MB241974 C11, CB1-2, CK2, CS9, A13 Stabilizer Link (FR) B : 10 / C : 120 pcs. 	M27410 MB527168 L200, E12, K14 Stabilizer Link B : 10 / C : 120 pcs. 
M27440 MB598097 STRADA, K64 Stabilizer Link B : 10 / C : 120 pcs. 	M2728E MB860011 CK2, CK5 Stabilizer Link (RE) B : 10 / C : 120 pcs. 
M27PG4E 4056A138 PAJERO SPORT Stabilizer Link (RE) B : 10 / C : 120 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M2841E MB111253 L200, K14, K64 Bumper Bound (RE)  B : 2 / C : 24 pcs.	M2841P MB185502 L200, K64 Upper Bumper Bound  B : 10 / C : 120 pcs.
M2841L MB185995 L200, K14, K64 Lower Bumper Bound (LH)  B : 2 / C : 24 pcs.	M2841R MB185996 L200, K14, K64 Lower Bumper Bound (RH)  B : 2 / C : 24 pcs.
M28T02E MR319973 TRITON (2WD) Bumper Bound (RE)  B : 2 / C : 24 pcs.	M28T04E MR992642 TRITON (4WD) Bumper Bound (RE)  B : 2 / C : 24 pcs.
M28T02P 4055A006T TRITON (2WD) Upper Bumper Bound  B : 10 / C : 120 pcs.	
M28T02L 4055A009 TRITON (2WD) Lower Bumper Bound (LH)  B : 2 / C : 24 pcs.	M28T02R 4055A010 TRITON (2WD) Lower Bumper Bound (RH)  B : 2 / C : 24 pcs.
M28T04W 4055A008T TRITON (4WD) Lower Bumper Bound  B : 6 / C : 72 pcs.	M28T04P 4055A007T TRITON (4WD) Upper Bumper Bound  B : 10 / C : 120 pcs.
M28L047W MB831096 PAJERO L047 Lower Bumper Bound  B : 6 / C : 72 pcs.	M28PG4E0 MB584148 PAJERO SPORT Bumper Bound (RE)  B : 6 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

* RBI Center Bearing is assembled with Japanese Bearing

M29430 MB154080 L200 D, K14 Center Bearing B : 1 / C : 20 pcs.		M29440 MB154199 STRADA, K64, K67 Center Bearing B : 1 / C : 20 pcs.	
M29450 MR223119 STRADA, K77 (4WD) Center Bearing B : 1 / C : 20 pcs.		M29T0204 MR580647 TRITON (2WD), (4WD) Center Bearing B : 1 / C : 24 pcs.	
M29CK00 MN171430 G-WAGON (2.8 cc) K57 Center Bearing B : 1 / C : 20 pcs.			





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M30060 MB699692 E33, E54, K64 Cylinder Piston  B : 1 / C : 60 pcs.	M30220 MA169978 A72, A121, A156 Cylinder Piston  B : 1 / C : 60 pcs.
M30230 MB134805 C11, A173, A161 Cylinder Piston  B : 1 / C : 60 pcs.	M30241 MB699169 C12 III, CK5 Cylinder Piston  B : 1 / C : 60 pcs.
M30242 MB238726 C12 II, E12, E15 Cylinder Piston  B : 1 / C : 60 pcs.	M30260 MB699475 CB1, CB2, CK2 Cylinder Piston  B : 1 / C : 60 pcs.
M30410 MB082338 L200 Cylinder Piston  B : 1 / C : 60 pcs.	M30430 MB500779 L200 D, K14 Cylinder Piston  B : 1 / C : 60 pcs.
M3044400 MR955109 STRADA GRANDIS (4WD) Cylinder Piston  B : 1 / C : 60 pcs.	M304500 MB857837 STRADA (4WD) Cylinder Piston (FR)  B : 1 / C : 60 pcs.
M30NA4F MR527609 SPACE WAGON NA4 Cylinder Piston (FR)  B : 1 / C : 60 pcs.	M30T001 MR527545 TRITON Cylinder Piston  B : 1 / C : 60 pcs.
M30CS3E MB857613 CS3, CS5 Cylinder Piston (RE)  B : 1 / C : 120 pcs.	M30CY30F 4605A221 LANCER EX, CY3, CY4 Cylinder Piston (FR)  B : 1 / C : 60 pcs.
M30A030 MR493152 MIRAGE, ATTRAGE Cylinder Piston (FR)  B : 1 / C : 60 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

MITSUBISHI

M31270 MB252113 PAJERO Exhaust Pipe Support B : 6 / C : 72 pcs. 	
M3823L MB288983 C11 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 	M3823R MB266705, MR197377 C11, CB1, CB2, CK2 Grommet Steering Rack (RH) B : 6 / C : 96 pcs. 
M3826L MB910968 CB1, CB2 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 	M38CS3L MR491363 CS3, CS5, CS9 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 
M38T020 4410A184 TRITON (2WD) Grommet Steering Rack B : 6 / C : 96 pcs. 	M38T040 4410A185 TRITON (4WD) Grommet Steering Rack B : 6 / C : 96 pcs. 
M40K5730 MB275630 K57 Rubber Body Mounting B : 6 / C : 96 pcs. 	M40V430 MB675984 PAJERO V43 Rubber Body Mounting B : 2 / C : 32 pcs. 

