



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N0906E 11321-51E01 U12 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.	N0906EZ 11320-51E01-IN U12 Insulator Engine (RE)  B : 2 / C : 24 pcs.
N0906F 11271-51E01 U12 Front Engine Bushing (FR)  B : 6 / C : 72 pcs.	N0906FZ 11270-51E01-IN U12 Insulator Engine (FR)  B : 2 / C : 24 pcs.
N0906L 11221-51E01 U12 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	N0906LMZ 11220-51E00-IN U12 (1.8 cc) Insulator Engine (LH, M/T)  B : 1 / C : 8 pcs.
N0906R 11211-51E01 U12 Front Engine Bushing (RH)  B : 4 / C : 48 pcs.	
N0906LA 11221-51E21 U12 (1.8 cc, 2.0 cc) Front Engine Bushing (LH, A/T)  B : 4 / C : 48 pcs.	N0906LAZ 11220-51E21-IN U12 (1.8 cc, 2.0 cc) Insulator Engine (LH, A/T)  B : 1 / C : 9 pcs.
N09062EA 11321-51E21 U12 (2.0 cc) Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	N09062EAZ 11320-51E21-IN U12 (2.0 cc) Insulator Engine (RE, A/T)  B : 2 / C : 24 pcs.
N0906L 11221-51E01 U12 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	N09062LMZ 11220-51E11-IN U12 (2.0 cc) Insulator Engine (LH, M/T)  B : 1 / C : 8 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N0908E 11321-40U00 A32, U13 Front Engine Bushing (RE)  B : 2 / C : 24 pcs.	N0908EZ 11320-40U01-IN A32, U13 Insulator Engine (RE)  B : 1 / C : 9 pcs.
N0908F 11271-40U00 A32, U13 Front Engine Bushing (FR)  B : 2 / C : 24 pcs.	N0908FZ 11270-40U02-IN A32, U13 Insulator Engine (FR)  B : 1 / C : 8 pcs.
N0908L 11220-31U00, 11221-40U02, 4M410 A32, A33, U13 Front Engine Bushing (LH)  B : 2 / C : 24 pcs.	
N0908R 11210-31U12, 11211-31U10 A32, U13 Front Engine Bushing (RH)  B : 2 / C : 24 pcs.	N0908RZ 11210-31U12-IN, 11211-31U12-IN A32, U13 Insulator Engine (RH)  B : 1 / C : 12 pcs.
N0927L 11220-01A00 B11 Front Engine Bushing (LH)  B : 4 / C : 48 pcs.	N0927LZ 11220-01A00-IN B11 Insulator Engine (LH)  B : 1 / C : 6 pcs.
N0930B 11351-02B01 B13 Front Engine Bushing (FR, BIG)  B : 5 / C : 120 pcs.	N0930FZ 11350-50Y00-IN, 41B00-IN B13, B14 Insulator Engine (FR)  B : 4 / C : 48 pcs.
N0930S 11350-02B01 B13 Front Engine Bushing (FR, SMALL)  B : 6 / C : 144 pcs.	N0930FZ 11350-50Y00-IN, 41B00-IN B13, B14 Insulator Engine (FR)  B : 4 / C : 48 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N0930L 11211-50Y05, 50Y00 B13 Front Engine Bushing (LH, RH)  B : 4 / C : 48 pcs.	N0930RZ 11211-50Y00-IN, 11210-0M000-IN B13, B14 Insulator Engine (RH, M/T)  B : 2 / C : 24 pcs.
N0930E 11321-59Y00 B13 Front Engine Bushing (RE)  B : 4 / C : 48 pcs.	N0930EMZ 11320-0M002-IN, 59Y00-IN, 50Y00-IN B13, B14 Insulator Engine (RE, M/T)  B : 2 / C : 24 pcs.
N0931E 11320-50Y11, 11321-50Y10 B14 Front Engine Bushing (RE, A/T)  B : 4 / C : 48 pcs.	N0931EAZ 11320-50Y11-IN B14 Insulator Engine (RE, A/T)  B : 2 / C : 24 pcs.
N0931L 11220-0M600, 11211-0M005 B14 Front Engine Bushing (LH, M/T)  B : 4 / C : 48 pcs.	N0931LMZ 11211-0M005-IN, 11220-0M600-IN B14 Insulator Engine (LH, M/T)  B : 1 / C : 9 pcs.
N0931LA 11220-0M010, 11211-50Y11 B14 Front Engine Bushing (LH, A/T)  B : 4 / C : 48 pcs.	N0931LAZ 11220-0M010-IN B14 Insulator Engine (LH, A/T)  B : 1 / C : 12 pcs.
N0931R 11210-0M600 B14 Front Engine Bushing (RH, A/T)  B : 4 / C : 48 pcs.	N0931RAZ 11210-0M600-IN B14 Insulator Engine (RH, A/T)  B : 2 / C : 24 pcs.
N0932E 11321-4M400, 11320-4M400 NEO, N16 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	N0932EZ 11320-4M400-IN NEO, N16 Insulator Engine (RE, A/T, M/T)  B : 2 / C : 24 pcs.
N0932F 11271-4M400 NEO, N16 Front Engine Bushing (FR, A/T, M/T)  B : 4 / C : 48 pcs.	N0932FZ 11270-4M400-IN NEO, N16 Insulator Engine (FR, A/T, M/T)  B : 1 / C : 15 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N0908L 11220-31U00, 11221-40U02 A32, U13 Front Engine Bushing (LH)  B : 2 / C : 24 pcs.	N0932LAZ 11220-4M412-IN NEO, N16 Insulator Engine (LH, A/T)  B : 1 / C : 12 pcs.
N0932LM 11221-4M400 NEO, N16 Front Engine Bushing (LH, M/T)  B : 2 / C : 24 pcs.	
	N0932RZ 11211-6N000-IN, 11210-6N000-IN NEO, N16 Insulator Engine (RH, A/T, M/T)  B : 1 / C : 12 pcs.
N09P11E0 11321-2J211 PRIMERA P11 Front Engine Bushing (RE, A/T, M/T)  B : 4 / C : 48 pcs.	N09P11EZ 11320-2J210-IN PRIMERA P11 Insulator Engine (RE, A/T, M/T)  B : 2 / C : 24 pcs.
N09P11F0 11271-2J211 PRIMERA P11 Front Engine Bushing (FR, A/T, M/T)  B : 4 / C : 48 pcs.	N09P11FZ 11270-2J210-IN PRIMERA P11 Insulator Engine (FR, A/T, M/T)  B : 2 / C : 24 pcs.
N09P11L0 11221-2J015 PRIMERA P11 Front Engine Bushing (LH, A/T, M/T)  B : 2 / C : 24 pcs.	N09P11LZ 11220-2J011-IN PRIMERA P11 Insulator Engine (LH, A/T, M/T)  B : 1 / C : 12 pcs.
N09P11R0 11210-4M810 PRIMERA P11 Front Engine Bushing (RH, A/T, M/T)  B : 2 / C : 24 pcs.	N09P11RZ 11210-4M810-IN PRIMERA P11 Insulator Engine (RH, A/T, M/T)  B : 1 / C : 12 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N09J30F0 11271-85E10 MURANO J30 Front Engine Bushing (FR, A/T, M/T) B : 4 / C : 48 pcs. 	
N09J30LM 11221-85E00 MURANO J30 Front Engine Bushing (LH, M/T) B : 4 / C : 48 pcs. 	
N09J30LA 11221-85E10 MURANO J30 Front Engine Bushing (LH, A/T) B : 4 / C : 48 pcs. 	
N09J30RM 11341-85E10 MURANO J30 Front Engine Bushing (RH, M/T) B : 4 / C : 48 pcs. 	
N09J30EA 11321-85E10 MURANO J30 Front Engine Bushing (RE, A/T) B : 4 / C : 48 pcs. 	
N09J30EM 11321-85E00 MURANO J30 Front Engine Bushing (RE, M/T) B : 4 / C : 48 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N09J31FA 11271-8J100 TEANA J31 Front Engine Bushing (FR) B : 2 / C : 24 pcs. 	N09J31FAZ 11270-8J10A-IN TEANA J31 Insulator Engine (FR) B : 1 / C : 9 pcs. 
N09J31R0 11210-CA000, 11210-CN00A TEANA J31 Front Engine Bushing (RH) B : 2 / C : 24 pcs. 	N09J31RZ 11210-CN00A-IN TEANA J31 QR20 Insulator Engine (RH) B : 2 / C : 12 pcs. 
N09J31L0 11220-9Y106 TEANA J31 Front Engine Bushing (LH) B : 2 / C : 24 pcs. 	N09J31LZ 11220-9Y106-IN TEANA J31 Insulator Engine (LH) B : 1 / C : 12 pcs. 
N09A33FE 11270-2Y011, 11320-2Y000 A33 Front Engine Bushing (FR, RE) B : 2 / C : 24 pcs. 	
N09T30F 11271-8H300 X-TRAIL T30 Front Engine Bushing (FR) B : 4 / C : 48 pcs. 	N09T30FZ 11271-8H310-IN X-TRAIL T30 Insulator Engine (FR) B : 2 / C : 24 pcs. 
N09T30R 11210-8H30E X-TRAIL T30 Front Engine Bushing (RH) B : 2 / C : 24 pcs. 	N09T30RZ 11210-8H30E-IN T30 QC25DE Insulator Engine (RH) B : 1 / C : 8 pcs. 
	N09TI10Z 11350-ED800-IN TIIDA C11, LATIO SC11 Insulator Engine B : 2 / C : 24 pcs. 
	N09K13FMZ 11360-1HC0A-IN MARCH (2010) K13, ALMERA (2011) N17 Insulator Engine (FR, A/T, M/T) B : 1 / C : 12 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

		N10070 11220-71L00 A31 Front Engine Mounting B : 2 / C : 24 pcs.	
N10240 11223-H1000 B110 Front Engine Mounting B : 4 / C : 48 pcs.		N10250 11223-H9100 B310 Front Engine Mounting B : 4 / C : 48 pcs.	
N1027G 11360-01A04 FF, B11 Front Engine Mounting (RE, LONG) B : 2 / C : 24 pcs.		N1027T 11350-01A04 FF, B11 Front Engine Mounting (FR, SHORT) B : 2 / C : 24 pcs.	
N1032R 11211-6N000, 11210-6N000 NEO, N16 Front Engine Mounting (RH, A/T, M/T) B : 2 / C : 24 pcs.			
N10430 11220-B8000 620, 720B Front Engine Mounting (RH) B : 2 / C : 24 pcs.			
		N1045R 11220-G7000 720D, SD22 Front Engine Mounting (RH) B : 2 / C : 24 pcs.	
N10E25L 11220-VW201 E25 Front Engine Mounting (LH). B : 1 / C : 12 pcs.		N10E25R 11210-VW201 E25 Front Engine Mounting (RH) B : 1 / C : 12 pcs.	
		N10NR40 11220-EB70C NAVARA D40T Front Engine Mounting B : 2 / C : 24 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N1048L 11220-35G00 BIG-M Front Engine Mounting (LH) B : 2 / C : 24 pcs. 	N1048R 11210-43G00 BIG-M, TD25 Front Engine Mounting (RH) B : 2 / C : 24 pcs. 
N10492L0 11220-9S010 BIG-M, D22 (ZD30E) Front Engine Mounting (LH) B : 2 / C : 24 pcs. 	N10492R0 11210-9S010 BIG-M, D22 (ZD30E) Front Engine Mounting (RH) B : 2 / C : 24 pcs. 
N10630 11220-27G00 E24 Front Engine Mounting B : 2 / C : 24 pcs. 	N10820 11220-Y4400 260C, E23, LD20 Front Engine Mounting B : 2 / C : 24 pcs. 
N10CB00 11327-76001 CARBON Front Engine Mounting B : 4 / C : 48 pcs. 	
N1047R 11210-18G01 TD25, NA20, D21 (1986-1995) (2WD) Front Engine Mounting (RH) B : 2 / C : 24 pcs. 	N10TY60 11220-10J07 Y60 Front Engine Mounting (FR) B : 2 / C : 24 pcs. 
N10TI10LA 11220-ED000 TIIDA C11, LATIO SC11 (1.6, 1.8 cc) Front Engine Mounting (LH, A/T) B : 2 / C : 24 pcs. 	N10TI10LM 11220-ED50A TIIDA C11, LATIO SC11 (1.6) Front Engine Mounting (LH, M/T) B : 2 / C : 24 pcs. 
N10TI10E 11360-ED000 TIIDA C11, LATIO SC11, LIVINA L11N (1.6, 1.8 cc) Front Engine Mounting (RE) B : 1 / C : 12 pcs. 	
N10K13FA 11360-1KA0A, 11360-1KA0B SYLPHY B17, PULSAR C12, JUKE F15 Front Engine Mounting (FR, A/T) B : 1 / C : 12 pcs. 	N10K13LA 11220-1HC0C MARCH K13 Front Engine Mounting (LH, A/T) B : 2 / C : 24 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N11070 11320-71L03 A31 (12V) Rear Engine Mounting  B : 2 / C : 24 pcs.	N11071 11320-85L00B A31 (24V) Rear Engine Mounting  B : 2 / C : 24 pcs.
N11230 11320-U2010 160J Rear Engine Mounting  B : 2 / C : 24 pcs.	N11240 11321-H1000 B110 Rear Engine Mounting  B : 4 / C : 48 pcs.
N11250 11320-W5000 B310 Rear Engine Mounting  B : 2 / C : 24 pcs.	N1127E 11320-01A02 B11 Rear Engine Mounting  B : 2 / C : 24 pcs.
	N11480 11320-01G00 BIG-M Rear Engine Mounting  B : 2 / C : 24 pcs.
N1149X 11320-31G05 BIG-M, D22 (4WD) Rear Engine Mounting  B : 1 / C : 12 pcs.	N11630 11320-R8060 E23, E24 Rear Engine Mounting  B : 1 / C : 12 pcs.
N11820 11320-P0100 260C Rear Engine Mounting  B : 2 / C : 24 pcs.	N11NR40 11320-JR70A, 11320-JR70B NAVARA D40T (4WD) Rear Engine Mounting  B : 1 / C : 12 pcs.
N11E25EB 11321-VW000 E25 Rear Engine Bushing (RE, BIG)  B : 2 / C : 24 pcs.	
N11NR20A 11320-JS21A NAVARA D40T (2WD) Rear Engine Mounting (A/T)  B : 1 / C : 8 pcs.	N11NR20M 11320-JS11A NAVARA D40T (2WD) Rear Engine Mounting (M/T)  B : 1 / C : 8 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

N13050 54320-05E01 U11 Shock Absorber Mounting B : 1 / C : 20 pcs.		N13060 54320-51E00 U12 Shock Absorber Mounting B : 1 / C : 20 pcs.	
N13070 54320-72L01 A31 (12V) Shock Absorber Mounting B : 1 / C : 20 pcs.		N13071 54320-35F00 A31 (24V) Shock Absorber Mounting (FR) B : 1 / C : 20 pcs.	
N1308F 54320-40U20 A32 Shock Absorber Mounting (FR) B : 2 / C : 40 pcs.		N13240 54320-H1000 B110 Shock Absorber Mounting B : 1 / C : 20 pcs.	
N13250 54320-N8200 B310, PA10 Shock Absorber Mounting B : 1 / C : 20 pcs.		N13260 54320-50A00 B12 Shock Absorber Mounting (FR) B : 8 / C : 160 pcs.	
N13270 54321-01A01 B11 Shock Absorber Mounting (FR, RE) B : 8 / C : 160 pcs.		N13A35F0 54320-JA00A ALTIMA (2008-UP), MAXIMA (2009-UP) Shock Absorber Mounting (FR) B : 1 / C : 16 pcs.	
N1330F 54320-50Y12 B13, B14, NV Shock Absorber Mounting (FR) B : 2 / C : 40 pcs.		N1330E 55320-50Y12 B13 Shock Absorber Mounting (RE) B : 2 / C : 40 pcs.	
N13N16F00 54320-4M400 NEO, N16 Shock Absorber Mounting (FR) B : 2 / C : 40 pcs.		N13A33F 54320-4Y000, 9Y000, CN001 A33 Shock Absorber Mounting (FR) B : 2 / C : 40 pcs.	
N13K13F0 54320-1HA0B, 1HJ0A MARCH K13, K13Z, K13K, N17Z Shock Absorber Mounting (FR) B : 2 / C : 40 pcs.		N13NA40F 56115-EB70A, 54034-EB70A NAVARA D40 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

* RBI Shock Absorber Mounting is assembled with Japanese Bearing

N13080F 54320-0E001,0E00A U13 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	N13NA20F 56217-EB70A NAVARA Shock Absorber Rubber (FR) B : 12 / C : 2 40 pcs. 
N13J32F 54320-JN01A TEANA J32 Shock Absorber Mounting (FR) B : 1 / C : 20 pcs. 	N13T32F0 54320-4CL0B X-TRAIL T32 Shock Absorber Mounting (LH, RH) B : 1 / C : 20 pcs. 
N13TI11FL 54321-1FE0A, ED001 TIIDA C11, LATIO SC11, LIVINA L11N Shock Absorber Mounting (FR, LH) B : 1 / C : 20 pcs. 	N13TI11FR 54320-1FE0A, ED001 TIIDA C11, LATIO SC11, LIVINA L11N Shock Absorber Mounting (FR, RH) B : 1 / C : 20 pcs. 
N13L33EZ 55322-3TS0A TEANA L33 Shock Absorber Mounting (RE) B : 1 / C : 20 pcs. 	N13L33F0 54320-3TU0A TEANA L33 Shock Absorber Rubber (FR, LH, RH) B : 1 / C : 20 pcs. 
N13T31FL 54321-JG01C X-TRAIL T31 Shock Absorber Mounting (FR, LH) B : 1 / C : 20 pcs. 	N13T31FR 54320-JG01C X-TRAIL T31 Shock Absorber Mounting (FR, RH) B : 1 / C : 20 pcs. 
N13B17FL 54321-1KA0B SYLPHY B17 (2013-2018), JUKE F15 (2011-2017), LEAF (2011-2019) Shock Absorber Mounting (FR, LH) B : 1 / C : 20 pcs. 	N13B17FR 54320-1KA0B SYLPHY B17 (2013-2018), JUKE F15 (2011-2017), LEAF (2011-2019) Shock Absorber Mounting (FR, RH) B : 1 / C : 20 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N13TI10E 56217-AX000, 56217-EE50A TIIDA C11, LATIO SC11, SYLPHY B17, PULSAR C12, LIVINA L11N Shock Absorber Rubber (RE)  B : 20 / C : 400 pcs.	N13070E 56218-72L11 A31 Shock Absorber Rubber (RE)  B : 12 / C : 240 pcs.
N1308PS 56217-61L10 A32, B14 Shock Absorber Rubber (UP, SMALL)  B : 20 / C : 400 pcs.	N1308WB 56218-61L10 A32, B14 Shock Absorber Rubber (LOW, BIG)  B : 12 / C : 240 pcs.
N13K130E 56217-1HJ0A MARCH K13 Shock Absorber Rubber (RE)  B : 20 / C : 400 pcs.	N13Y62F0 56217-1LA0A PATROL Y62 (2013) Shock Absorber Rubber  B : 10 / C : 200 pcs.
N13L33EP 56217-3Z600 TEANA L33 Shock Absorber Rubber (UP, RE)  B : 20 / C : 400 pcs.	N13L33EW 56218-3Z600 TEANA L33 Shock Absorber Rubber (LOW, RE)  B : 12 / C : 240 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N1426F 55240-D0100 FX (STANZA) Shock Absorber Bumper  B : 6 / C : 72 pcs.	N14R50E 55240-0W010 R50, JR50 Shock Absorber Bumper (RE)  B : 2 / C : 24 pcs.
N14T32F0 54050-4CL0B X-TRAIL T32 Shock Absorber Bumper (FR)  B : 4 / C : 48 pcs.	N14T32E0 55240-JG000 X-TRAIL T32 Shock Absorber Bumper (RE)  B : 6 / C : 72 pcs.
N1430E000 55240-50Y00 B13 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	N1430F000 54052-50Y00 B13 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
N1431E 55240-0M015 B14, A32 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	N1431F 54052-0M011 B14 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
N1432FZ 54052-4M400-S NEO, N16 Shock Dust Cover (FR, SET)  B : 2 / C : 40 pcs.	N14N16E00 55240-8M600 NEO, N16 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.
N14P11F0 54050-2J200 PRIMERA P11 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.	N14A32F0 54050-31U02 MAXIMA, A32 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
N14A33E00 55240-2Y000 A33 Shock Dust Cover (RE)  B : 2 / C : 40 pcs.	N14A33F00 54050-2Y0B1 A33 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.
N14D23F0 E6110-4JC2A-2, 4JE6A-2, 4JE7A-2 NAVARA NP300 D23T (2WD), (4WD), D/C Shock Dust Cover (FR)  B : 2 / C : 32 pcs.	N14E26F0 E6110-3XG0A-2 NV350 E26 Shock Dust Cover (FR)  B : 2 / C : 40 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N14PF01F 54050-0W002 PATHFINDER Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	
N14TI10F 54050-EE500 TIIDA C11, LATIO SC11, LIVINA L11N Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	N14TI10E 55240-EE50A TIIDA C11, LATIO SC11 Shock Dust Cover (RE) B : 2 / C : 44 pcs. 
N14J31F 54050-9Y000 TEANA J31 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	N14J31E 55240-9Y000 TEANA J31 Shock Dust Cover (RE) B : 2 / C : 32 pcs. 
N14J32F 54050-JP00A, JN00A TEANA J32, L33 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	N14J32E 55240-9N00A TEANA J32 Shock Dust Cover (RE) B : 2 / C : 40 pcs. 
N1408F 54050-38U00, 38UB2 A32 Shock Dust Cover (SHORT) B : 2 / C : 40 pcs. 	N14L33E 55240-3TS0A TEANA L33 Shock Dust Cover (RE) B : 2 / C : 40 pcs. 
N14K13F 54050-1HJ0A MARCH K13 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	N14K13E 55240-1HJ0A, 55240-1HJ0B MARCH K13 Shock Dust Cover (RE) B : 2 / C : 44 pcs. 
N14SP12F 54050-3DA0A SYLPHY B17 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	N14B17E 55240-3DA0A, 1KA0A SYLPHY B17, PULSAR C12, JUKE F15 Shock Dust Cover (RE) B : 2 / C : 44 pcs. 
N14JU10F 54050-3NF0A JUKE F15 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 	N14N18F 54050-3VU0B ALMERA (2021) N18 Shock Dust Cover (FR) B : 2 / C : 40 pcs. 

NEW



PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N1705IZ 39741-10E25 U11, U12 (1.8 cc, 2.0 cc TURBO) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N1705UZ 39241-10E25 U11, U12 (1.8 cc, 2.0 cc TURBO) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N17070E 39741-04F25 A31 (12V) Drive Shaft Boot (RE)  B : 2 / C : 100 pcs.	N17071E 39741-05U27 A31 (24V) Drive Shaft Boot (RE)  B : 2 / C : 100 pcs.
N1708I 39741-55E85 A32, PRESEA R11 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N1708U 39241-10E88 A32, CEFIRO Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N1726IZ 39741-D0101 T11, FX Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N1726UZ 39241-D0101 T11, FX Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N1727LZ 39741-01A01 B11, FF (1.3 cc) Drive Shaft Boot (INNER, LH)  B : 2 / C : 100 pcs.	N1727RZ 39741-01A00 B11, FF (1.3 cc) Drive Shaft Boot (INNER, RH)  B : 2 / C : 100 pcs.
N1727UZ 39241-01A01 B11, FF (1.3 cc, 1.5 cc) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.	
N1728LZ 39741-11A01 B11, FF (1.5 cc) Drive Shaft Boot (INNER, LH)  B : 2 / C : 100 pcs.	N1728RZ 39741-11A00 B11, FF (1.5 cc) Drive Shaft Boot (INNER, RH)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N1729IZ 39741-02A01 B12 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N1729UZ 39241-50A00 B12 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N1730IZ 39741-01E25 B13, U11, NV Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N1730UZ 39241-01E25 B13, U11, NV Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N1731IZ 39741-02A90 B14, NEO N16 (1.5 cc) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N1731UZ 39241-50A92 B14, NEO N16 (1.5 cc) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N17P11IZ 39741-0M326 PRIMERA (P11) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17P11UZ 39241-0M326 PRIMERA (P11) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
	N17R11U 39241-0M626 PRESEA (R11) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N17R20I 39741-0F000 BIG-M (D21), FRONTIER (D22), TERRANO (R20) (4WD) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17R20U 39241-0F000 BIG-M (D21), FRONTIER (D22), TERRANO (R20) (4WD) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
	N17A33UZ 39241-5V125 A33 Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N17NR23I C97DA-EB70B NAVARA NP300 D23T Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17D23UZ C9B41-EA000 NAVARA NP300 D23T Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N17TI10IA C9741-EE70A TIIDA C11, LATIO SC11 (1.6 cc) Drive Shaft Boot (INNER, A/T)  B : 2 / C : 100 pcs.	N17TI10IM C9741-EE70B TIIDA C11, LATIO SC11 (1.6 cc) Drive Shaft Boot (INNER, M/T)  B : 2 / C : 100 pcs.
N17T32IZ C9741-4BA0A, C9G41-4BA0K X-TRAIL T32 Drive Shaft Boot (INNER, LH, RH)  B : 2 / C : 100 pcs.	N17T32UZ C92DA-JE32J, C9B41-JE32J X-TRAIL T32 Drive Shaft Boot (OUTER, LH, RH)  B : 2 / C : 100 pcs.
N17TI11IZ C9741-EE76A TIIDA C11, LATIO SC11 (1.8 cc) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17TI11UZ C9241-EE76A, EW60K, 39241-EW60K TIIDA C11, TIIDA LATIO SC11 (1.8 cc), SYLPHY B17, PULSAR C12 (1.8 cc), (1.6 cc TURBO) Drive Shaft Boot (OUTER A/T)  B : 2 / C : 100 pcs.
N17NR40IZ 39741-EA027 NAVARA D40T (4WD) Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17NR40UZ 39241-EA027 NAVARA D40T (4WD) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N17J31IZ 39741-6N225 TEANA J31, X-TRAIL T30 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17J31UZ 39241-9Y028 TEANA J31 (2.0 cc), (2.3 cc) Drive Shaft Boot (OUTER)  B : 2 / C : 100 pcs.
N17J31RZ 39741-8H525 J31, T30 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17TI10UZ C9241-EE70A, C9B41-CG000 TIIDA C11, TIIDA LATIO SC11 (1.6 cc), SYLPHY B17, PULSAR C12 (1.6 cc) Drive Shaft Boot (OUTER A/T)  B : 2 / C : 100 pcs.
N17K13IZ C9741-1HC1A MARCH K13 Drive Shaft Boot (INNER, M/T, A/T)  B : 2 / C : 100 pcs.	N17K13UZ C9241-1HC1B MARCH K13 Drive Shaft Boot (OUTER, M/T, A/T)  B : 2 / C : 100 pcs.
N17J32IZ 39741-AV927, AV928 TEANA J32 Drive Shaft Boot (INNER)  B : 2 / C : 100 pcs.	N17J32UZ 39241-9Y085, 9Y086, C924A-9Y015 TEANA (2009) J32, SYLPHY B17, PULSAR C12 (1.6 cc) Drive Shaft Boot (OUTER M/T)  B : 2 / C : 100 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N1804L 48204-W1000 910, B11, B12, T11 Steering Gear Boot (LH) B : 2 / C : 50 pcs. 	N1804R 48203-W1000 910, T11, FX Steering Gear Boot (RH) B : 2 / C : 50 pcs. 
N1804P 48204-D0301 T11, FX Steering Gear Boot (POWER) B : 2 / C : 50 pcs. 	N1805PZ 48203-10V00 U12, A31 Steering Gear Boot (POWER) B : 2 / C : 50 pcs. 
N1805LPZ 48204-05F00 U11, B12 Steering Gear Boot (POWER, LH) B : 2 / C : 50 pcs. 	N1805RPZ 48203-05F26 U11, B12 Steering Gear Boot (POWER, RH) B : 2 / C : 50 pcs. 
N1827PZ 48204-53A00 B11 Steering Gear Boot (POWER) B : 2 / C : 50 pcs. 	N1827R 48203-11A00 B11 (FF) Steering Gear Boot (RH) B : 2 / C : 50 pcs. 
N1829LZ 48204-01F00 B12 Steering Gear Boot (LH) B : 2 / C : 50 pcs. 	N1829P 48203-D0301 U11, B12 Steering Gear Boot (POWER) B : 2 / C : 50 pcs. 
N1829R 48203-01F00 B12 Steering Gear Boot (RH) B : 2 / C : 50 pcs. 	N1830LPZ 48204-53Y25 B13 Steering Gear Boot (POWER, LH) B : 2 / C : 50 pcs. 
N1830LZ 48204-50Y00 B13, B14 Steering Gear Boot (LH, M/T) B : 2 / C : 50 pcs. 	N1830RPZ 48203-53Y25 B13 Steering Gear Boot (POWER, RH) B : 2 / C : 50 pcs. 
N1830RZ 48203-50Y00 B13, B14 Steering Gear Boot (RH, M/T) B : 2 / C : 50 pcs. 	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N1831LZ 48203-41B27 B14 Steering Gear Boot (POWER, LH) B : 2 / C : 50 pcs. 	N1831RZ 48203-0E025 B14 Steering Gear Boot (POWER, RH) B : 2 / C : 50 pcs. 
N18630 48203-27N26 E24 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	
N1832L 48204-4M525 NEO, N16 Steering Gear Boot (LH) B : 2 / C : 50 pcs. 	N1832R 48203-4M525 NEO, N16 Steering Gear Boot (RH) B : 2 / C : 50 pcs. 
N18E250 48204-VW025 E25 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	N18PF01 48203-0W025 PATHFINDER Steering Gear Boot B : 2 / C : 50 pcs. 
N18A33LZ 48204-5Y025 A33, TEANA J31, J32 Steering Gear Boot (LH) B : 2 / C : 50 pcs. 	N18A33RZ 48203-AL525 A33, TEANA J31 Steering Gear Boot (RH) B : 2 / C : 50 pcs. 
N18TI10Z 48203-3U025 TIIDA C11, LATIO SC11, LIVINA L11N Steering Gear Boot B : 2 / C : 50 pcs. 	N18NR40Z 48203-EB70A, D8203-EB70A NAVARA D40T Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 
N18K130Z D8203-1HJ0A MARCH K13 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 	N18B17LR D8203-3RA1A SYLPHY B17, PULSAR C12 Steering Gear Boot B : 2 / C : 50 pcs. 
N18J32R 48203-VG026 TEANA J32 Steering Gear Boot (RH) B : 2 / C : 50 pcs. 	N18L33LR D8B03-3GJ0C TEANA L33 Steering Gear Boot (LH, RH) B : 2 / C : 50 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N19B1300 12376-53Y00 B13 Seal Rocker Cover  B : 12 / C : 288 pcs.	N19T32EP 55034-EN101 X-TRAIL T31, T32 (2013) Coil Spring Rubber (RE, UPPER)  B : 4 / C : 64 pcs.
N19Y61E 56219-VB000 PATROL Y61 (1997-2013) Shock Absorber Rubber (RE)  B : 28 / C : 672 pcs.	N19Y61F 56119-01J00 PATROL Y61 (1997-2013) Shock Absorber Rubber (FR)  B : 28 / C : 672 pcs.
N20241 55045-18000 B110 Spring Shackle Rubber (BIG)  B : 16 / C : 384 pcs.	N20242 55045-H1000 B110 Spring Shackle Rubber (SMALL)  B : 20 / C : 480 pcs.
N2024G 55046-H1000 B110 Spring Shackle Rubber (LONG)  B : 30 / C : 720 pcs.	N2024T 55047-H1000 B110 Spring Shackle Rubber (SHORT)  B : 36 / C : 864 pcs.
N2042G 55046-20400 521 Spring Shackle Rubber (LONG)  B : 10 / C : 240 pcs.	N2042T 55047-20400 521 Spring Shackle Rubber (SHORT)  B : 20 / C : 480 pcs.
N2044E 55046-01W10 720 Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.	N2044F 55045-01W10 720 Spring Shackle Rubber (FR)  B : 12 / C : 288 pcs.
N2048E 55046-01G00 BIG-M Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.	N2048F 55045-10W00 BIG-M Spring Shackle Rubber (FR)  B : 12 / C : 288 pcs.
N2061E 55046-B8400 URWAN, E20 Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.	N20040F 55045-G2500 910 Spring Shackle Rubber (FR)  B : 10 / C : 240 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N20620 55046-R8000 E23, E24 Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.	
N20C22F2 55046-G2500 C22 (2WD) Spring Shackle Rubber (FR)  B : 24 / C : 576 pcs.	
N20E25EG 55046-VW000 E25 Spring Shackle Rubber (RE, LONG)  B : 12 / C : 288 pcs.	N20E25ET 55047-VW000 E25 Spring Shackle Rubber (RE, SHOT)  B : 10 / C : 240 pcs.
N20H40F 55046-S9000 ATLAS H40 Spring Shackle Rubber (FR)  B : 16 / C : 384 pcs.	N20H41F 55046-0T000 ATLAS H41 Spring Shackle Rubber (FR)  B : 10 / C : 160 pcs.
N20NR40ET 55047-EB70C NAVARA (2007) D40 (2WD, 4WD) Spring Shackle Rubber (RE, SHORT)  B : 16 / C : 384 pcs.	N20NR40EG 55046-EB70C NAVARA (2007) D40 (2WD, 4WD) Spring Shackle Rubber (RE, LONG)  B : 12 / C : 192 pcs.
N20W40E 55046-S9400 CIVILIAN W40 (1982-1999) Spring Shackle Rubber (RE)  B : 8 / C : 192 pcs.	N20NR23E 55046-4JA1A NAVARA (2014) NP300 D23 (2WD, 4WD) Spring Shackle Rubber (RE)  B : 20 / C : 480 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN



N21020 54617-27500 510 Stabilizer Shaft Rubber  B : 20 / C : 320 pcs.	
N21030 54613-28500 810 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.	N21040 54613-A0100 910 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.
N2105F 54613-D4400 U11 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	N21060 54612-51E00 U12 Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
N2106E 56243-51E00 U12 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	N21070 54613-35F13 A31 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.
N2107E 54613-71L10 A31 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	N21080 54613-0E000 A32 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.
N2108F 54613-0E015 A32, U13 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	
N21230 54617-U0200 160J, 510 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.	N21240 54617-H1001 B110 Stabilizer Shaft Rubber  B : 24 / C : 576 pcs.
N21250 54617-H5000 B310, 120Y Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.	N21270 54613-03A00 B11 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2129E 55149-50A00 B12 Stabilizer Shaft Rubber (RE)  B : 12 / C : 192 pcs.	N2129F 54612-58700 B12 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
N2130E 56243-60Y10 B13 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.	N2130F 54612-58Y10 B13 Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
N2131F 54612-60Y00 B14 Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.	N21B15E 56243-65Y00 B15 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.
N21440 54613-14900 720, 620 Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.	N2132F 54613-8M620 NEO, N16 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.
N21480 54613-W1410 BIG-M Stabilizer Shaft Rubber  B : 24 / C : 576 pcs.	N2149XF 54613-32G00 BIG-M (4WD) Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.
N2149F 54613-0P005 D22 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	N21810 54613-66000 240C, 260C Stabilizer Shaft Rubber  B : 20 / C : 480 pcs.
N2163F 54613-05N00 E24 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	N21E25F0 54613-27N10 E25 Stabilizer Shaft Rubber  B : 6 / C : 144 pcs.
N21TI10F 54613-EE500 TIIDA C11, LATIIO SC11, LIVINA L11N Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	N21E25F 54613-VW009 E25 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN


N21P11F 56243-30R10,92J00 PRIMERA P11 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	
N21PF010 54613-88G00 PATHFINDER Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.	N21PF014 54613-4P007 PATHFINDER Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.
N21C23F 54613-1C404 SERENA C23 Stabilizer Shaft Rubber  B : 10 / C : 240 pcs.	N21A33F 54613-2Y002 A33 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
N21H035 54613-5L609 LAUREL H035 Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.	N21U13E 56243-0E015 BLUE BIRD U13 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.
N21NR20F 54613-EB71B NAVARA D40T (2WD) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	N21C32F 54613-51S00 LAUREL C32 Stabilizer Shaft Rubber (FR)  B : 12 / C : 192 pcs.
N21NR40F 54613-EB71A NAVARA D40T (4WD) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	N21A331F 54613-2Y003 MAXIMA, CEFIRO (1999-2004) Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
N21490F 54613-2S600 D22 (4WD) Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	N21J30E 56243-85E00 J30 Stabilizer Shaft Rubber (RE)  B : 20 / C : 480 pcs.
N21J31E 54613-9Y016, 9Y0B6 J31, J31Z Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N21K11F00 54613-47B02 K11 Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.	N21K11F03 54613-4F100 K11E Stabilizer Shaft Rubber (FR)  B : 10 / C : 240 pcs.
N21L31E 54613-8J021 L31 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	N21L310 54613-8J002 L31 Stabilizer Shaft Rubber  B : 10 / C : 240 pcs.
N21L32E 56243-JA100 L32, CL32 Stabilizer Shaft Rubber (RE)  B : 8 / C : 128 pcs.	N21L33E 56243-3TS0A TEANA L33 Stabilizer Shaft Rubber (RE)  B : 6 / C : 96 pcs.
N21E24F 54613-G9600 E24, 160 Stabilizer Shaft Rubber (FR)  B : 20 / C : 480 pcs.	N21NR21F 54613-EB70A NAVARA D40T Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.
N21T30F 54613-AU718, 8H318 T30, P12 Stabilizer Shaft Rubber (FR)  B : 6 / 144 pcs.	N21T30E 54613-AU717 T30, P12 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.
N21T31E 54613-JG17C T31 Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.	N21T310 54613-JG02A T31 Stabilizer Shaft Rubber  B : 8 / C : 128 pcs.
N21TY61F 54613-1Y415 Y61 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	
N21WD21F 54613-42G00 WD21 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	N21QQ08E 54613-JD17A QASHQAI J10, JJ10E Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N21Y600F 54613-01J11 Y61 Stabilizer Shaft Rubber (FR)  B : 24 / C : 576 pcs.	
N21Y60F 54613-04F02 Y60 Stabilizer Shaft Rubber (FR)  B : 16 / C : 384 pcs.	N21Y60E 54613-06J10 Y60 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
N21Y61F 54613-VC223 Y61 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	N21Y61E 54613-VB010, 56243-VC220 Y61 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.
N21Y610F 54613-VB002 Y61 Stabilizer Shaft Rubber (FR)  B : 24 / C : 576 pcs.	N21Y61F0 54613-VC020 PATROL Y61 (1997-2013) Stabilizer shaft rubber (FR)  B : 12 / C : 288 pcs.
N21Y62F 54613-1LB0C PATROL Y62 (2013) Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	
N21P12E0 54613-AU102 P12 Stabilizer Shaft Rubber (RE)  B : 16 / C : 384 pcs.	N21Z500E 54613-CA000 Z50 Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.
N21Z50E 54613-CC48A Z50 Stabilizer Shaft Rubber (RE)  B : 8 / C : 192 pcs.	N21Z51E 56243-1AA0A Z51, A35 Stabilizer Shaft Rubber (RE)  B : 8 / C : 128 pcs.
N21C23F0 54613-1C406 C23 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.	N21C23F1 54613-1C421 C23 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N21P12F0 54613-AU004 P12, P12E Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 	N21P12F1 54613-AU715 P12 Stabilizer Shaft Rubber (FR) B : 6 / C : 144 pcs. 
N21P12F2 54613-BA000, BA001 P12E Stabilizer Shaft Rubber (FR) B : 12 / C : 288 pcs. 	
N21R51F 54613-ZL10A, 54613-ZT00A R51, R51M, D40, D40M Stabilizer Shaft Rubber (FR) B : 6 / C : 96 pcs. 	N21R51E 54613-EA520 R51, R51M Stabilizer Shaft Rubber (RE) B : 6 / C : 96 pcs. 
N21TA60F 54613-ZV50A TA60 Stabilizer Shaft Rubber (FR) B : 6 / C : 96 pcs. 	
N21B150F 54613-4M720 B15 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs. 	N21B151F 54613-4M718 B15 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs. 
N21B152F 54613-4M722 B15, B15X Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs. 	N21K11F01 54613-2U601 K11 Stabilizer Shaft Rubber (FR) B : 8 / C : 192 pcs. 
N21P100E 56243-4J519, 65J15 P10, U14, WP11 Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs. 	N21P101E 56243-8E800, 65J00 P10, U14 Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs. 
N21P10F 56243-32R10 P10 Stabilizer Shaft Rubber (FR) B : 16 / C : 384 pcs. 	N21P10E 56243-35R10 P10, P10E Stabilizer Shaft Rubber (RE) B : 16 / C : 384 pcs. 






PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N21WD21E 54613-7F001, 01N00, 41G00 WD21, R20, E24, VE24 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	N21WD21F0 54613-43G00 WD21 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
N21L320 54613-JA00A, JA00B, JA10A L32, CL32 Stabilizer Shaft Rubber  B : 8 / C : 128 pcs.	N21Y340 54613-AG112 Y34 Stabilizer Shaft Rubber  B : 12 / C : 288 pcs.
N21R20E 54613-0F001 R20 Stabilizer Shaft Rubber (RE)  B : 12 / C : 288 pcs.	N21N170F 54613-1HA0A ALMERA N17 Stabilizer Shaft Rubber (FR)  B : 12 / C : 288 pcs.
N21J31F 54613-9Y002 TEANA J31 Stabilizer Shaft Rubber (FR)  B : 8 / C : 192 pcs.	N21JU10F 54613-JD04A JUKE F15 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.
N21SP12F 54613-3RA0A, 54613-3RA0C SYLPHY B17, PULSAR C12 (1.6, 1.8 cc) Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	
N21J32E 56243-ZN40A, JA00A, 1AD0A L32, Z51, J32 Stabilizer Shaft Rubber (RE)  B : 8 / C : 128 pcs.	N21J32F 54613-JN20AF TEANA J32 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.
N21L33F 54613-3TA1A TEANA L33 Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.	N21T32F0 54613-3UB0A X-TRAIL T32 Stabilizer Shaft Rubber (FR)  B : 6 / C : 144 pcs.
N21E26F 54613-3XA0A NV350 E26 Stabilizer Shaft Rubber (FR)  B : 6 / C : 96 pcs.	N21QQ08F 54613-JD03A QASHQAI J10, JJ10E Stabilizer Shaft Rubber (FR)  B : 8 / C : 128 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N22240 56125-18100 B110, B310 Stabilizer Shaft Grommet  B : 100 / C : 2,400 pcs.	
N2302Y 54476-21000 510, 160J Strut Bar Rubber  B : 14 / C : 224 pcs.	N2304Y 54476-W1010 910 Strut Bar Rubber  B : 12 / C : 288 pcs.
N2324Y 54476-W5000 B110, B310 Strut Bar Rubber  B : 28 / C : 672 pcs.	N2343Y 54481-18000 620, B10 Strut Bar Rubber  B : 28 / C : 672 pcs.
N2344Y 54476-F0200 720 Strut Bar Rubber  B : 8 / C : 192 pcs.	N2348Y 54476-01G00 BIG-M, E24 Strut Bar Rubber  B : 12 / C : 192 pcs.
N23GC220 54477-G8010 GC22 (1986-1993) VANETTE Strut Bar Rubber (WITH EDGE)  B : 10 / C : 240 pcs.	N23GC221 54476-G8010 GC22 (1986-1993) VANETTE Strut Bar Rubber (WITH OUT EDGE)  B : 12 / C : 288 pcs.
N23Y60Y 54476-01J00 Y60, Y61 Strut Bar Rubber  B : 6 / C : 144 pcs.	N23Y61Y 54476-VC001 PATROL Y61 (1997-2013) Strut Bar Rubber  B : 6 / C : 144 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2302Z 54476-21000-S 510, 160 J Strut Bar Rubber (SET) B : 1 / C : 65 pcs. 	N2304Z 54476-W1010-S 910 Strut Bar Rubber (SET) B : 1 / C : 65 pcs. 
N2324Z 54476-W5000-S B110, B310, 120Y Strut Bar Rubber (SET) B : 1 / C : 65 pcs. 	N2343Z 54481-18000-S 620, B10 Strut Bar Rubber (SET) B : 1 / C : 65 pcs. 
N2344Z 54476-F0200-S 720 Strut Bar Rubber (SET) B : 1 / C : 65 pcs. 	N2348Z 54476-01G00-S BIG-M, E24 Strut Bar Rubber (SET) B : 1 / C : 65 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2402W 54535-22008 510 Lower Arm Bushing B : 10 / C : 180 pcs. 	N24030 54535-U3400 810 Lower Arm Bushing B : 8 / C : 144 pcs. 
N2404W 54535-W1010 910, A31 Lower Arm Bushing B : 6 / C : 108 pcs. 	
N2406WB 54596-01E01 U12, U11 Lower Arm Bushing (BIG) B : 4 / C : 72 pcs. 	N2406WS 54590-01E00 U12, U11 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs. 
N2423W 54535-A0801 160J Lower Arm Bushing B : 10 / C : 180 pcs. 	N2424W 54131-H1000 B110, B310 Lower Arm Bushing B : 12 / C : 216 pcs. 
N2426WB 54476-D0100 FX, T11 Lower Arm Bushing (INNER, BIG) B : 4 / C : 72 pcs. 	N2426WS 54535-D0101 FX, T11 Lower Arm Bushing (OUTER, SMALL) B : 10 / C : 180 pcs. 
N2427WB 54505-01A10 FF, B11 Lower Arm Bushing (INNER, BIG) B : 8 / C : 144 pcs. 	N2427WS 54504-01A00 FF, B11 Lower Arm Bushing (OUTER, SMALL) B : 10 / C : 180 pcs. 
N2428WB 54570-50A10 B12 Lower Arm Bushing (BIG) B : 4 / C : 72 pcs. 	N2428WS 54560-50A00 B12, B13 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs. 
N2430WB 54570-69Y10 B13, U13, A32 Lower Arm Bushing (BIG Diameter) B : 4 / C : 64 pcs. 	N2430WS 54501-52Y10 B13 Lower Arm Bushing (SMALL Diameter) B : 4 / C : 64 pcs. 





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2431WB 54570-0M010 B14 Lower Arm Bushing (BIG) B : 4 / C : 64 pcs.		N2431WS 54560-50Y10 B14 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs.	
N2432WB 54570-4M410 NEO, N16 Lower Arm Bushing (BIG) B : 8 / C : 144 pcs.		N2432WS 55044-4M410 NEO, N16 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs.	
N2443P 54519-08700 620, 520 Upper Arm Bushing B : 18 / C : 1170 pcs.		N2444P 54506-B9500 720, BIG-M, E24 Upper Arm Bushing B : 8 / C : 144 pcs.	
N2444W 54423-B9500 720 Lower Arm Bushing B : 8 / C : 144 pcs.		N2448W 54560-01G00 BIG-M, E24 Lower Arm Bushing B : 6 / C : 108 pcs.	
N2449P 54542-2S610 D22 (4WD) Upper Arm Bushing B : 8 / C : 144 pcs.		N2449W 54560-2S600 D22 (4WD) Lower Arm Bushing B : 8 / C : 144 pcs.	
N24A32WB 54570-85E20 MAXIMA J30, A32 Lower Arm Bushing B : 4 / C : 64 pcs.			
N24A33WB 54570-2Y411 A33, MAXIMA Lower Arm Bushing (BIG) B : 4 / C : 72 pcs.		N24A33WS 54560-2Y020 A33 Lower Arm Bushing (SMALL) B : 10 / C : 180 pcs.	
N24CABP 54542-21T10 CABSTAR (1992) Upper Arm Bushing B : 6 / C : 108 pcs.		N24CABW 54560-2T800 CABSTAR (1992) Lower Arm Bushing B : 6 / C : 108 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N24C23W0 55040-5C010 SERENA C23 Lower Arm Bushing	 B : 8 / C : 144 pcs.	N24C23W1 55040-5C040 SERENA C23 Lower Arm Bushing	 B : 8 / C : 144 pcs.
N24P11W0 54570-2J500 PRIMERA P11 Lower Arm Bushing (BIG)	 B : 6 / C : 108 pcs.		
N24P11WRZ 54505-2J511-IN PRIMERA P11 Lower Arm Bushing (RH Bracket)	 B : 2 / C : 32 pcs.	N24P11WLZ 54506-2J511-IN PRIMERA P11 Lower Arm Bushing (LH Bracket)	 B : 2 / C : 32 pcs.
N24PF01B 54570-52F10, 0W001 PATHFINDER, LAUREL A31 Lower Arm Bushing (BIG)	 B : 4 / C : 72 pcs.	N24PF01S 54590-0W001, 20N10 PATHFINDER, VENNETTE Lower Arm Bushing (SMALL)	 B : 6 / C : 108 pcs.
N24J31WB 54570-CA000 TEANA J31 Lower Arm Bushing (BIG)	 B : 4 / C : 64 pcs.	N24J310Z 54570-CA000-IN TEANA J31 Lower Arm Bushing (BIG, LH, RH Bracket)	 B : 2 / C : 24 pcs.
N24J31WS 54560-CA000 TEANA J31 Lower Arm Bushing (SMALL)	 B : 8 / C : 144 pcs.	N24TY61W 54560-01J00, VC000 Y60, Y61 Lower Arm Bushing	 B : 4 / C : 72 pcs.
N24C20P 54450-G0300 C20 Upper Arm Bushing	 B : 10 / C : 180 pcs.	N24C20W 54460-G0300 C20 Lower Arm Bushing	 B : 6 / C : 108 pcs.
N24E25WB 54560-VW010, 3XA1A, 54501-3XA0A-1 E25, E26, NV350 Lower Arm Bushing (BIG)	 B : 4 / C : 72 pcs.	N24E25WS 54560-VW000, 54501-3XA0A-2 E25, E26, NV350 Lower Arm Bushing (SMALL)	 B : 6 / C : 108 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N24E25P0 54542-VW000, 54525-3XA1A-0 E25, E26, NV350 Upper Arm Bushing  B : 6 / C : 108 pcs.	N24P10WB 54570-86J00 PREMIRA P10 Lower Arm Bushing (BIG)  B : 4 / C : 64 pcs.
N24F23W 54560-22T10 ATLAS F23 Lower Arm Bushing  B : 6 / C : 108 pcs.	N24H410 54045-0T000 ATLAS H41 Cover Bush  B : 10 / C : 180 pcs.
N24V00WB 54570-20N10 VANNETTE, SERENA Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	
N24F31W 54570-0M020 FB14 Lower Arm Bushing  B : 4 / C : 64 pcs.	N24NR20W 54560-EB70A, 4JA0A, 54501-4JA0A-0 NAVARA D40T, NP300, D23T (2WD), (4WD) Lower Arm Bushing  B : 6 / C : 108 pcs.
N24P10PB 54541-90J05, 01U67 PREMIRA P10 Upper Arm Bushing (BIG)  B : 8 / C : 144 pcs.	N24P10PS 54545-90J00, 50J05 PREMIRA P10 Upper Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
N24P11P 54545-33P11 PRIMERA P11 (1996) Upper Arm Bushing  B : 8 / C : 144 pcs.	N24TI10PS 54525-AX002S, 54524-AX001S TIIDA C11, LATIO SC11, PULSAR C12, LIVINA L11N Upper Arm Bushing (SMALL)  B : 10 / C : 180 pcs.
N24TI11WB 54570-EE500 TIIDA C11, LATIO SC11, LIVINA L11N Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	N24TI10WS 54560-EE530, 3ST0A TIIDA C11, LATIO SC11, SYLPHY B17, PULSAR C12, LIVINA L11N Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
N24NR20P 54542-EB70A NAVARA D40T (2WD), (4WD) Upper Arm Bushing  B : 6 / C : 108 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N24K13WB 54570-1HJ0A, 54500-1HJ0A-2, 54501-1HJ0A-2, 5EK0C-2 MARCH (2010) K13, ALMERA (2011) N17, (2020) N18, KICK (2020) P15, NOTE E12 Lower Arm Bushing (BIG)  B : 6 / C : 108 pcs.	N24K13WS 54560-1HJ0A, 54500-1HJ0A-1, 54501-1HJ0A-1, 5EK0C-1 MARCH (2010) K13, ALMERA (2011) N17, (2020) N18, KICK (2020) P15, NOTE E12 Lower Arm Bushing (SMALL)  B : 8 / C : 144 pcs.
N24J32WB 54570-1AA1A TEANA J32 Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	N24J32WS 54560-JP00B TEANA J32 Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
N24T30WB 54570-8H300 X-TRAIL T30 Lower Arm Bushing (BIG)  B : 2 / C : 36 pcs.	N24T30WS 54560-8H300 X-TRAIL T30 Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.
N24T31WB 54570-EN002 X-TRAIL T31, T32, JUKE F15 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	N24T30WBZ 54570-8H300-IN X-TRAIL T30 Lower Arm Bushing (BRACKET)  B : 2 / C : 24 pcs.
N24TI11PB 54525-AX002B TIIDA C11, LATIO SC11, SYLPHY B17, PULSAR C12, LIVINA L11N Upper Arm Bushing (BIG)  B : 10 / C : 180 pcs.	
N24JU10WS 54560-1KA0A JUKE F15 Lower Arm Bushing (SMALL)  B : 6 / C : 108 pcs.	N24T31WS 54560-EN001 X-TRAIL T31, T32 Lower Arm Bushing (SMALL)  B : 6 / C : 96 pcs.
N24TI11PR 54524-AX001B TIIDA C11, LATIO SC11, SYLPHY B17, PULSAR C12, LIVINA L11N Upper Arm Bushing (RH, BIG)  B : 10 / C : 180 pcs.	
N24B17WB 54570-3DA2A PULSAR C12, SYLPHY B17 Lower Arm Bushing (BIG)  B : 4 / C : 72 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N24L33WB 54570-3JA0A TEANA L33 Lower Arm Bushing (BIG) B : 2 / C : 32 pcs.		N24L33WS 54560-3JA0A TEANA L33 Lower Arm Bushing (SMALL) B : 6 / C : 108 pcs.	
N24Y62P 54542-1LB0A PATROL Y62 Upper Arm Bushing B : 4 / C : 72 pcs.		N24Y62W 54560-1LB0A PATROL Y62 Lower Arm Bushing B : 4 / C : 72 pcs.	
N24D23P0 54525-4JA0A-0, 54542-4JA0A NAVARA NP300 D23T Upper Arm Bushing B : 6 / C : 108 pcs.			





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N25040 55045-Q0103 910 Suspension Bush B : 6 / C : 108 pcs. 	
N2504E 55120-W0500 910 Suspension Bush B : 6 / C : 108 pcs. 	N2504Z 55120-W0500-IN 910 Suspension Bush (Bracket) B : 1 / C : 10 pcs. 
N25050 56234-01E01 U11 Suspension Bush B : 8 / C : 144 pcs. 	N2506S 55152-51E00, 55157-50A10 U12 Suspension Bush (SMALL) B : 8 / C : 144 pcs. 
N25070E 55501-60U25 A31 Suspension Bush (RE) B : 10 / C : 180 pcs. 	N25071 55157-0P000, 33P01 A31 Suspension Bush B : 10 / C : 180 pcs. 
N25072 55152-35F00 A31 Suspension Bush B : 10 / C : 180 pcs. 	N25073T 55442-35F02 A31 Suspension Bush (SHORT) B : 2 / C : 36 pcs. 
N25074G 55440-35F02 A31 Suspension Bush (LONG) B : 2 / C : 36 pcs. 	N25250 55045-W5001 B310, PA10 Suspension Bush B : 6 / C : 108 pcs. 
N25260 55045-D0101 FX, B13, T11 Suspension Bush (BIG) B : 6 / C : 108 pcs. 	N25270 55045-01A05 B11 Suspension Bush B : 4 / C : 72 pcs. 
N2530S 55152-50A10 B13 Suspension Bush (SMALL) B : 10 / C : 180 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N25310 55045-0M000, 2J000 B14, A32, P11, NEO Suspension Bush B : 4 / C : 72 pcs. 	N25311 55157-0M011 B14, A32, NEO Suspension Bush B : 10 / C : 180 pcs. 
N25312 55135-0M000 B14, A32, P11 Suspension Bush B : 6 / C : 108 pcs. 	N25313 55157-0M001 B14, A32, NEO Suspension Bush B : 10 / C : 180 pcs. 
N25314 55136-0M000 B14, A32 Suspension Bush B : 10 / C : 180 pcs. 	N2532E 55135-8M610 NEO N16 Suspension Bush B : 6 / C : 108 pcs. 
N25A3335 55135-2Y000 A33 Suspension Bush B : 4 / C : 72 pcs. 	N25A3336 55136-2Y610 A33 Suspension Bush B : 8 / C : 144 pcs. 
N25A3345 55045-2Y002 A33 Suspension Bush B : 2 / C : 32 pcs. 	N25A3355 55157-2Y010 A33 Suspension Bush B : 10 / C : 180 pcs. 
N25A3357 55157-2Y000 A33 Suspension Bush B : 10 / C : 180 pcs. 	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N25J31A10 551A1-9Y000-0 TEANA J31 Suspension Bush (RE)  B : 10 / C : 180 pcs.	N25J31B00 55158-CA010, 551B0-9Y000-0 TEANA J31 Suspension Bush (RE)  B : 8 / C : 144 pcs.
N25J32B00 551B0-JA000-0 TEANA J32 Suspension Bush (RE)  B : 8 / C : 144 pcs.	N25J329F1 55157-AR000, JK00A, 56219-JN00A, 43019-JN00AF-1 TEANA J31, J32 Suspension Bush (RE)  B : 8 / C : 144 pcs.
N25J329F2 43019-JN00AF-2, 55148-AL500 TEANA J31, J32 Suspension Bush (RE)  B : 10 / C : 180 pcs.	N25J329F3 43019-JN00AF-3, 55152-7Y000 TEANA J32 Suspension Bush (RE)  B : 10 / C : 180 pcs.
N25J32A00 551A0-JN00AF-0 TEANA J32 Suspension Bush (RE)  B : 10 / C : 180 pcs.	N25J3220 55502-JN00AF-0 TEANA J32 Suspension Bush (RE)  B : 8 / C : 144 pcs.
N25JU10E0 55045-1KA0B, 55501-1KA1A-0 UKE F15 (2021) Suspension Bush (RE)  B : 2 / C : 36 pcs.	N25K130E 55045-1HJ0A MARCH K13 Suspension Bush  B : 2 / C : 36 pcs.
N25L339A2 43019-3TS0A-2 TEANA L33 Suspension Bush (RE)  B : 10 / C : 180 pcs.	N25L339A3 43019-3TS0A-3 TEANA L33 Suspension Bush (RE)  B : 10 / C : 180 pcs.
N25L33B0 551B1-3TS0B-0 TEANA L33 Suspension Bush (RE)  B : 10 / C : 180 pcs.	N25L33350 55120-3TS0A-0, 55135-3TA0A TEANA L33 Suspension Bush (RE)  B : 10 / C : 180 pcs.
N25L331B2 551A1-3TS0B-2 TEANA L33 Suspension Bush (RE)  B : 8 / C : 144 pcs.	N25L339A1 43019-3TS0A-1, 56219-3TS0A TEANA L33 Suspension Bush  B : 8 / C : 144 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N25NVB 55045-60R00, 90R00 NISSAN (NV) Suspension Bush (BIG) B : 6 / C : 108 pcs.		N25NVS 55136-70N00 NISSAN (NV) Suspension Bush (SMALL) B : 10 / C : 180 pcs.	
N25NR4F 54721-EA300 NAVARA D40T, NP300 D23T Cushion Differential Mount (FR) B : 4 / C : 72 pcs.			
N25P1136 55136-0M011 PRIMERA P11 Suspension Bush B : 10 / C : 180 pcs.		N25P1157 55157-2J210 PRIMERA P11 Suspension Bush B : 10 / C : 180 pcs.	
N25P115E 55157-2J200 PRIMERA P11 Suspension Bush B : 10 / C : 180 pcs.			
N25R5000 55046-0W001 TERRANO R50 Suspension Bush B : 6 / C : 108 pcs.		N25R50W0 55045-0W023 TERRANO R50 Suspension Bush B : 6 / C : 108 pcs.	
N25R50E 55135-0W000 R50, JR50, WD21 Suspension Bush B : 6 / C : 108 pcs.			
N25T32ELZ 55619-JY00B-IN X-TRAIL T32 Suspension Bush (RE, LH) B : 2 / C : 24 pcs.		N25T32ERZ 55618-JY00B-IN X-TRAIL T32 Suspension Bush (RE, RH) B : 2 / C : 24 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N25T3211W 55045-EN100, 55111-JG00B-0 X-TRAIL T32 Suspension Bush (Lower, RE)  B : 8 / C : 144 pcs.	N25T3221P 55121-JD00B-0 X-TRAIL T32 Suspension Bush (Upper, RE)  B : 8 / C : 144 pcs.
N25T32180 55618-JY00B-0, 55619-JY00B-0 X-TRAIL T32 Suspension Bush (RE, RH, LH)  B : 10 / C : 180 pcs.	
N25T32FG 54400-4CB0B-1, 54400-1KA0A-1 X-TRAIL (2014) T32, JUKE F15 Suspension Bush (FR, LONG)  B : 4 / C : 64 pcs.	N25T32FT 54400-4CB0B-2, 54400-1KA0A-2 X-TRAIL (2014) T32, JUKE F15 Suspension Bush (FR, SHORT)  B : 4 / C : 72 pcs.
N25T31E 55618-JD00A T31 Suspension Bush  B : 10 / C : 180 pcs.	
N25TI10E 55045-EE500 TIIDA C11, LATIO SC11 Suspension Bush (RE)  B : 2 / C : 36 pcs.	N25TI100 54467-AX001 TIIDA C11, TIIDA LATIO SC11, LIVINA L11N Suspension Bush (FR)  B : 6 / C : 108 pcs.
N25TY61B 55135-01J01 TY61, Y60, Y61 Suspension Bush  B : 6 / C : 108 pcs.	N25TY61E 55135-01J10 TY61, Y60, Y61 Suspension Bush (RE)  B : 6 / C : 108 pcs.
N25Y301 55045-V0102 CREDRIC Y30 Suspension Bush  B : 4 / C : 72 pcs.	
N25Y62EP 55045-1LB0A, 55501-1LB0A-0 PATROL Y62 Suspension Bush (UP RE LH, RH)  B : 4 / C : 72 pcs.	N25Y62EW 551A0-1LB0B-0 PATROL Y62 Suspension Bush (LOW RE LH, RH)  B : 4 / C : 72 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2629B 55193-50A00 B12 Suspension Rubber (BIG)  B : 16 / C : 384 pcs.	N2629S 55148-50A00 B12 Suspension Rubber (SMALL)  B : 20 / C : 480 pcs.
N2607WE 56210-72L27 A31 Shock Absorber Bush (Lower, RE)  B : 8 / C : 144 pcs.	
N2630F0 11248-50Y05 B13 Suspension Rubber  B : 20 / C : 1300 pcs.	N2632F0 11248-4M410 NEO, N16 Suspension Rubber  B : 20 / C : 1000 pcs.
N26NR01F E6110-EB71A, EB71B, 4JE6A-1, 4JE7A-1, 4JC2A-1 NP300 D23T, (2WD), (4WD), D/C, NAVARA D40T Shock Absorber Bush (FR)  B : 8 / C : 144 pcs.	
N26JU10E E6210-1TT4A JUKE F15 Shock Absorber Bush (RE)  B : 10 / C : 180 pcs.	
N2643E 55046-07200 620 Spring Shackle Bush (RE)  B : 20 / C : 480 pcs.	N2643F 55045-B5000 620 Spring Shackle Bush (FR)  B : 8 / C : 128 pcs.
N26610 55046-B8460 E20 Spring Shackle Bush  B : 20 / C : 480 pcs.	N26621 55045-01N00 E23, E24 Spring Shackle Bush (FR)  B : 10 / C : 160 pcs.
N26070 54476-35F20 A31 Strut Bar Bush  B : 4 / C : 72 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N26E25FR 55045-VW000 E25 Spring Shackle Bush (FR)	 B : 6 / C : 108 pcs.	N26Y60E 55045-06J00 Y60 Spring Shackle Bush	 B : 6 / C : 108 pcs.
N26NR40F 55045-EB71A NAVARA D40T (4WD) Spring Shackle Bush (FR)	 B : 6 / C : 108 pcs.	N2641X0F 55045-31G00 D21, D22, D22S (4WD) Spring Shackle Bush (FR)	 B : 6 / C : 108 pcs.
N26W40F 55045-S9000 CIVILIAN W40 (1982-1999), ATRAS, CONDOR (1981-1992) Spring Shackle Bush (FR)	 B : 6 / C : 108 pcs.		
N26E26RH 54444-3XA0A NV350 E26 Grommet Steering Bush (RH)	 B : 10 / C : 180 pcs.		
N26E26E0 55047-3XA0A NV350 E26 Spring Shackle Bush (RE)	 B : 6 / C : 108 pcs.	N26E26F E6110-3XG0A-1 NV350 E26 Shock Absorber Bush (FR)	 B : 10 / C : 180 pcs.
N26E26EW 56218-3XA0A NV350 E26 Shock Absorber Bush (RE)	 B : 6 / C : 108 pcs.		
N2632R 54444-4M400 NEO, N16 Grommet Steering Bush (RH)	 B : 10 / C : 180 pcs.	N26NR20R 54444-EB70B NAVARA D40 (2WD), (4WD) Grommet Steering Bush (RH)	 B : 10 / C : 180 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2707F 54618-56S11 A31 Link Assy (FR) B : 2 / C : 108 pcs. 	N2708F 54618-0E000 A32, U13 Link Assy (FR) B : 2 / C : 108 pcs. 
N2729E 54618-58Y10 B12, B13 Link Assy (RE) B : 2 / C : 54 pcs. 	N2729F 54618-50Y00 B12, B13, B14, U12 Link Assy (FR) B : 2 / C : 108 pcs. 
N27A33FL 54668-2Y000 A33 Link Assy (FR, LH) B : 2 / C : 54 pcs. 	N27A33FR 54618-2Y000 A33 Link Assy (FR, RH) B : 2 / C : 54 pcs. 
N27E25FL 54667-VW000 E25 Link Assy (FR, LH) B : 2 / C : 108 pcs. 	N27E25FR 54617-VW000 E25 Link Assy (FR, RH) B : 2 / C : 108 pcs. 
N27P10F 54618-50J60 P10 Link Assy (FR) B : 2 / C : 54 pcs. 	<u>Substitute Number</u> - 54618-50J10, 54618-50J11 - 54618-50J20, 54618-50J21
N27PF01E 56260-0W001 PATHFINDER (1996) Link Assy (RE) B : 2 / C : 40 pcs. 	N27PF01F 54618-0W001 PATHFINDER (1996) Link Assy (FR) B : 2 / C : 40 pcs. 
N27R20F 54618-0F000 R20 Link Assy (FR) B : 2 / C : 108 pcs. 	N2732F 54618-4M400 NEO N16 Link Assy (FR) B : 2 / C : 108 pcs. 
N27T30E 56261-50J00 T30 Link Assy (RE) B : 2 / C : 54 pcs. 	N27TY61E 56260-01J10 TY61, Y60, Y61 Link Assy (RE) B : 2 / C : 54 pcs. 



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N27GA0FR 54668-9C002 GURGO, VENETTE Link Assy (FR, RH) B : 2 / C : 54 pcs. 	N27VE0FR 54618-9C002 VENETTE Link Assy (FR, RH) B : 2 / C : 54 pcs. 
N27J31ER 54618-CA010 TEANA (2005) J31 (2.0, 2.3, 3.5 cc) Link Assy (RE, RH) B : 2 / C : 90 pcs. 	N27J31EL 54668-CA010 TEANA (2005) J31 (2.0, 2.3, 3.5 cc) Link Assy (RE, LH) B : 2 / C : 90 pcs. 
N27J31FR 54618-CN011 TEANA J31 Link Assy (FR, RH) B : 1 / C : 16 pcs. 	N27J31FL 54668-CN011 TEANA J31 Link Assy (FR, LH) B : 1 / C : 16 pcs. 
N27J32ER 54618-9W200 TEANA (2005) J31 (3.5 cc) Link Assy (RE, RH) B : 2 / C : 54 pcs. 	N27J32EL 54668-9W200 TEANA (2005) J31 (3.5 cc) Link Assy (RE, LH) B : 2 / C : 54 pcs. 
N27IN0F 54618-60U05, D5015 INFINITY Q45 (1990-1996), G50 Link Assy (FR) B : 2 / C : 108 pcs. 	
N27080 56261-0E000 U13 Link Assy B : 2 / C : 90 pcs. 	
N27NR01FR 54618-EB71A NAVARA (2007), D40 (2WD, 4WD) Link Assy (FR, RH) B : 2 / C : 90 pcs. 	N27NR01FL 54668-EB71A NAVARA (2007), D40 (2WD, 4WD) Link Assy (FR, LH) B : 2 / C : 90 pcs. 
N27TI10F 54618-ED00A, JX00A TIIDA C11, LATIO SC11 Link Assy (FR) B : 2 / C : 40 pcs. 	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N27J30FR 54618-CA000 MURANO J30 Link Assy (FR, RH) B : 2 / C : 36 pcs.	N27J30FL 54668-CA000 MURANO J30 Link Assy (FR, LH) B : 2 / C : 36 pcs.
N27T30FR 54618-8H300 X-TRAIL T30 Link Assy (FR, RH) B : 2 / C : 54 pcs.	N27T30FL 54668-8H300 X-TRAIL T30 Link Assy (FR, LH) B : 2 / C : 54 pcs.
N27Y61E 56260-VC310 PATROL GR11, Y61 Link Assy (RE) B : 2 / C : 40 pcs.	N27Y61E0 56260-VC300 PATROL Y61 (1997-2013) Link Assy (RE) B : 2 / C : 54 pcs.
N27AR0F 54618-7S000 ARMADA (2005-2008) Link Assy (FR) B : 2 / C : 54 pcs.	N27AR0E1 56261-7S011 ARMADA (2005-2008) Link Assy (RE) B : 2 / C : 54 pcs.
N27J32FR 54618-1AA0A T31, J32, Z51 Link Assy (FR, RH) B : 2 / C : 36 pcs.	N27J32FL 54668-1AA0A T31, J32, Z51 Link Assy (FR, LH) B : 2 / C : 36 pcs.
N27J320ER 56261-1AD0A J32, Z51 Link Assy (RE, RH) B : 2 / C : 54 pcs.	N27J320EL 56261-1AD0B J32, Z51 Link Assy (RE, LH) B : 2 / C : 54 pcs.
N27NR4F0 54618-EB70A NAVARA (2007) D40, (2014) NP300 D23 (2WD) Link Assy (FR LH, RH) B : 2 / C : 54 pcs.	N27TA60ER 56261-7S001 TA60 Link Assy (RE, RH) B : 2 / C : 54 pcs.
N27T31FL 54668-JD00A T31 Link Assy (FR, LH) B : 2 / C : 36 pcs.	N27T31FR 54618-JD00A T31 Link Assy (FR, RH) B : 2 / C : 36 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N27V42FL 54668-CK000 V42 Link Assy (FR, LH) B : 2 / C : 36 pcs.	N27V42FR 54618-CK000 V42 Link Assy (FR, RH) B : 2 / C : 36 pcs.
N27V42E 56261-CK000 V42 Link Assy (RE) B : 2 / C : 90 pcs.	N27B15E 56260-60Y60 B15, N15, 16, G10, RNB14 Link Assy (RE) B : 2 / C : 90 pcs.
N27E51FL 54667-WL010 E51 Link Assy (FR, LH) B : 2 / C : 40 pcs.	N27E51FR 54617-WL010 E51 Link Assy (FR, RH) B : 2 / C : 40 pcs.
N27JU3FL 54668-AD000 JU30, U30 Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27JU3FR 54618-AD000 JU30, U30 Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27L32FL 54668-JA000 L32, CL32 Link Assy (FR, LH) B : 2 / C : 36 pcs.	N27L32FR 54618-JA000 L32, CL32 Link Assy (FR, RH) B : 2 / C : 36 pcs.
N27L32E 56261-8J000, 56E10 L32, A34, M11 Link Assy (RE) B : 2 / C : 90 pcs.	
N27L32EL 56261-JA005 A35, L32, CL32 Link Assy (RE, LH) B : 2 / C : 90 pcs.	N27L32ER 56261-JA000 A35, L32, CL32 Link Assy (RE, RH) B : 2 / C : 90 pcs.
N27N30F 54618-5V000 N30 Link Assy (FR, LH, RH) B : 2 / C : 108 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N27R51FL 56261-7S000 R51 Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27R51FR 56261-7S010 R51 Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27Y34FL 54668-AG001 Y34 Link Assy (FR, LH) B : 2 / C : 40 pcs.	N27Y34FR 54618-AG001 Y34 Link Assy (FR, RH) B : 2 / C : 40 pcs.
N27Y61F 54618-VC300 Y61 Link Assy (FR) B : 2 / C : 54 pcs.	N27Y61F0 54618-VB000 Y61 Link Assy (FR, LH, RH) B : 2 / C : 54 pcs.
N27J30EL 56260-85E15 J30 Link Assy (RE, LH) B : 2 / C : 24 pcs.	N27J30ER 56260-51E15 J30 Link Assy (RE, RH) B : 2 / C : 54 pcs.
N27V10FL 54668-4U000 V10M Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27V10FR 54618-4U000 V10M Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27V36FL 54668-JK52C V36, J50 Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27V36FR 54618-JK52C V36, J50 Link Assy (FR, RH) B : 2 / C : 40 pcs.
N27C24EL 54668-4N010 C24 Link Assy (RE, LH) B : 2 / C : 54 pcs.	N27C24ER 54618-4N010 C24 Link Assy (RE, RH) B : 2 / C : 54 pcs.
N27C23F0 54618-0C010, 0C011 C23, C23M, W30 Link Assy (FR) B : 2 / C : 40 pcs.	



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

NISSAN

N27FX35F 54617-CG000 FX35, FX45, S50 Link Assy (FR, LH, RH)  B : 2 / C : 36 pcs.	N27M12F 54618-WF101 M12, W11, VW11, NW11 (4WD) Link Assy (FR, LH, RH)  B : 2 / C : 108 pcs.
N27P12FL 54668-BA30A P12, W12 Link Assy (FR, LH)  B : 2 / C : 90 pcs.	N27P12FR 54618-BA30A P12, W12 Link Assy (FR, RH)  B : 2 / C : 90 pcs.
N27P12EL 56261-AV611 P12, W12 Link Assy (RE, LH)  B : 2 / C : 90 pcs.	N27V35EL 54668-EG02A V35, V36, AM35, M35, Y50, J50 Link Assy (RE, LH)  B : 2 / C : 54 pcs.
N27V35FL 54668-AL502 V35, AM35, M35 Link Assy (FR, LH)  B : 2 / C : 54 pcs.	N27V35FR 54618-AL502 V35, AM35, M35 Link Assy (FR, RH)  B : 2 / C : 54 pcs.
N27V36EL 54668-EG02B V35, V36, AM35, M35, Y50, J50 Link Assy (RE, LH)  B : 2 / C : 54 pcs.	N27V36ER 54618-EG02A V35, V36, AM35, M35, V50, J50 Link Assy (RE, RH)  B : 2 / C : 54 pcs.
N27Z510EL 56261-1AA0B Z51 Link Assy (RE, LH)  B : 2 / C : 54 pcs.	N27Z510ER 56261-1AA0A Z51 Link Assy (RE, RH)  B : 2 / C : 54 pcs.
N27A31F0 54618-05U00 A31, C34, C35, R32 (4WD) Link Assy (FR)  B : 2 / C : 90 pcs.	
N27M110E 56260-30R00 M11 Link Assy (RE, LH, RH)  B : 2 / C : 70 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N27A35FL 54668-9N00A A35 Link Assy (FR, LH) B : 2 / C : 32 pcs.	N27A35FR 54618-9N00A A35 Link Assy (FR, RH) B : 2 / C : 32 pcs.
N27C24FL 54668-4N001 C24 Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27C24FR 54618-4N001 C24 Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27E51EL 54668-WL01A E51 Link Assy (RE, LH) B : 2 / C : 24 pcs.	N27E51ER 54618-WL01A E51 Link Assy (RE, RH) B : 2 / C : 24 pcs.
N27JU3E0 55061-5V201 JU30, U30, W30, N30, C23, C23M Link Assy (RE, LH, RH) B : 2 / C : 54 pcs.	
N27R510FL 54668-EA010 R51M Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27R510FR 54618-EA010 R51M Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27R51EL 56261-EA510 R51, R51M Link Assy (RE, LH) B : 2 / C : 54 pcs.	N27R51ER 56261-EA500 R51, R51M Link Assy (RE, RH) B : 2 / C : 54 pcs.
N27B17F 54618-CY00A SYLPHY B17, PULSAR C12, JUKE F15 Link Assy (FR) B : 2 / C : 32 pcs.	N27N170F 54618-JX00AF MARCH (2010) K13, ALMERA (2011) N17, (2020) N18, LIVINA L11N Link Assy (FR) B : 2 / C : 40 pcs.
N27T32FL 54668-1AA0E X-TRAIL T32 Link Assy (FR, LH) B : 2 / C : 36 pcs.	N27T32FR 54618-1AA0E X-TRAIL T32 Link Assy (FR, RH) B : 2 / C : 36 pcs.



**PACLOS CO., LTD. - RBI AUTHORIZED DEALER**

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,

KLONGTOEI, BANGKOK 10110 THAILAND

TEL: (66) 2 392 1148

E-MAIL: rbiautoparts@gmail.com

NISSAN

N27D23FL 54668-4JA0A NAVARA (2014) NP300, D23 (2WD, 4WD) Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27D23FR 54618-4JA0A NAVARA (2014) NP300, D23 (2WD, 4WD) Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27E26FL 56261-1LB0A NV350, E26 Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27E26FR 56261-1LB1A NV350, E26 Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27L33EL 56261-3TS0B TEANA L33 Link Assy (RE, LH) B : 2 / C : 90 pcs.	N27L33ER 56261-3TS0A TEANA L33 Link Assy (RE, RH) B : 2 / C : 90 pcs.
N27L33FL 54668-3TS0A TEANA L33 Link Assy (FR, LH) B : 2 / C : 32 pcs.	N27L33FR 54618-3TS0A TEANA L33 Link Assy (FR, RH) B : 2 / C : 32 pcs.
N27Y62FL 54668-1LB0A PATROL Y62 (2013) Link Assy (FR, LH) B : 2 / C : 54 pcs.	N27Y62FR 54618-1LB0A PATROL Y62 (2013) Link Assy (FR, RH) B : 2 / C : 54 pcs.
N27040 54618-U7400K 910 Stabilizer Link B : 10 / C : 120 pcs.	N27240 54618-W5000K B110, B310, PA10 Stabilizer Link B : 10 / C : 120 pcs.
N27270 54618-01A00K B11 Stabilizer Link B : 10 / C : 120 pcs.	N27430 54616-B5000K 620 Stabilizer Link B : 10 / C : 120 pcs.
N27440 54616-B9700K 720 Stabilizer Link B : 10 / C : 120 pcs.	N27480 54618-01G00K BIG-M Stabilizer Link B : 10 / C : 120 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N2843P 54053-04301 620 Upper Bumper Bound  B : 20 / C : 480 pcs.	N2844E 55240-01W10 720, 620 Bumper Bound (RE)  B : 2 / C : 24 pcs.
N2844P 54053-B9500 720 Upper Bumper Bound  B : 20 / C : 480 pcs.	N2844W 54050-B9510 720 Lower Bumper Bound  B : 6 / C : 72 pcs.
N2848E 55240-15G00 BIG-M Bumper Bound (RE)  B : 2 / C : 24 pcs.	N2848P 54053-50W00 BIG-M Upper Bumper Bound  B : 20 / C : 480 pcs.
N2848W 54050-01G00 BIG-M Lower Bumper Bound  B : 6 / C : 72 pcs.	N28E25E 55240-VW001 E25 Bumper Bound (RE)  B : 2 / C : 24 pcs.
N2863E 55240-R8001 E23, E24 Bumper Bound (RE)  B : 2 / C : 24 pcs.	N2863W 54050-01N00 E23, E24 Lower Bumper Bound  B : 2 / C : 24 pcs.
N28NR20E 55240-EB70A NAVARA D40T (2WD) Bumper Bound (RE)  B : 2 / C : 24 pcs.	N28NR40W 54050-EB70A NAVARA D40T (4WD) Lower Bumper Bound  B : 6 / C : 72 pcs.
N28NR4EP 55236-EB71A NAVARA D40T (4WD) Upper Bumper Bound (RE)  B : 4 / C : 48 pcs.	N28NR4EW 55240-EB71A NAVARA D40T (4WD) Lower Bumper Bound (RE)  B : 4 / C : 48 pcs.
N28D23W0 54050-4JA0A NP300, D23T Lower Bumper Bound  B : 4 / C : 48 pcs.	N28E26W0 54050-3XR0A NV350, E26 Lower Bumper Bound  B : 4 / C : 48 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

* RBI Center Bearing is assembled with Japanese Bearing

N28E26E0 55240-3XA0A NV350 E26 Bumper Bound (RE)  B : 2 / C : 24 pcs.	
N29070 37521-85L26 A31 Center Bearing  B : 1 / C : 24 pcs.	
N2943K 37521-B5025 620 Center Bearing (THICK)  B : 1 / C : 24 pcs.	N2943N 37521-B5026 620 Center Bearing (THIN)  B : 1 / C : 24 pcs.
N2944K 37521-01W26 720 Center Bearing (THICK)  B : 1 / C : 24 pcs.	N2944N 37521-01W25 720 Center Bearing (THIN)  B : 1 / C : 24 pcs.
N2948K 37521-W1026 BIG-M Center Bearing (THICK)  B : 1 / C : 24 pcs.	N2948N 37521-W1025 BIG-M, D21, D22 (2WD) Center Bearing (THIN)  B : 1 / C : 24 pcs.
N2941X4 37521-56G25 BIG-M, D21 (4WD) Center Bearing  B : 1 / C : 24 pcs.	





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N30061 41121-11L01 U12 (1.8 cc) Cylinder Piston  B : 1 / C : 60 pcs.	N30062 41121-71E00 U12 (2.0 cc) Cylinder Piston  B : 1 / C : 60 pcs.
N30260 41121-D0100 FX, T11 Cylinder Piston  B : 1 / C : 60 pcs.	N30270 41121-01A01 B11, B13 Cylinder Piston  B : 1 / C : 60 pcs.
N30310 41121-40F00 B14, NEO N16, TIIDA C11, LATIO SC11, LIVINA L11N Cylinder Piston  B : 1 / C : 60 pcs.	
N30460 41121-09W10 720, PRO, SD23 Cylinder Piston  B : 1 / C : 75 pcs.	N30480 41121-V0300 BIG-M, E23 Cylinder Piston  B : 1 / C : 75 pcs.
N30490 41121-05A10 NV Cylinder Piston  B : 1 / C : 60 pcs.	N30630 41121-09G02 E24 Cylinder Piston  B : 1 / C : 60 pcs.
N30A3200C 41121-1E000 A32, A33 (3.0 cc) Cylinder Piston  B : 1 / C : 60 pcs.	N30E25F 41121-VW001 E25 Cylinder Piston  B : 1 / C : 60 pcs.
N30NR10F 41121-VK100 NAVARA Cylinder Piston  B : 1 / C : 60 pcs.	N30JU10F 41121-9W000 JUKE F15, TEANA J32 Cylinder Piston  B : 1 / C : 60 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N3806L 48377-56E00 U12 Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	N3806R 48376-51E00 U12 Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.
N3807L 54445-71L00 A31 Grommet Steering Rack (LH)  B : 8 / C : 128 pcs.	N3807R 54444-61U00 A31 Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.
N3808L 54445-31U00 A32 Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	N3808R 54444-31U01 A32 Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.
N3827L 54445-11A10 B11 Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	N3827R 54444-11A11 B11 Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.
N3830L 54445-51J00 B13 Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	N3830R 54444-50Y10 B13 Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.
N3831L 54445-52Y00 B14, B13, NV Grommet Steering Rack (LH, POWER)  B : 8 / C : 128 pcs.	N3831R 54444-50Y11 B14, B13, NV Grommet Steering Rack (RH, POWER)  B : 8 / C : 128 pcs.
N3832L 54445-4M400 NEO, N16 Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	
N3863L 54445-25C00 E24 Grommet Steering Rack (LH)  B : 6 / C : 96 pcs.	N3863R 54444-G5110 E24 Grommet Steering Rack (RH)  B : 6 / C : 96 pcs.





PACLOS CO., LTD. - RBI AUTHORIZED DEALER

ADDRESS: 4980 RAMA 4 RD., PHRA KHANONG,
KLONGTOEI, BANGKOK 10110 THAILAND
TEL: (66) 2 392 1148
E-MAIL: rbiautoparts@gmail.com

NISSAN

N38PF01L 54445-0W000 PATHFINDER Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 	N38PF01R 54444-0W000 PATHFINDER Grommet Steering Rack (RH) B : 6 / C : 96 pcs. 
N38A33L 54445-5Y500 A33 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 	
N38NR200 54445-EB70B NAVARA (2WD), (4WD) Grommet Steering Rack B : 6 / C : 96 pcs. 	
N38E26LH 54445-3XA0A NV350 E26 Grommet Steering Rack (LH) B : 6 / C : 96 pcs. 	

