

**HYUNDAI**

<p><b>H094LM</b></p> <p>21812-28250</p> <p>TIBURON</p> <p>Front Engine Bushing (LH, M/T)</p>		<p><b>H09A00R</b></p> <p>21834-22030</p> <p>ACCENT</p> <p>Front Engine Bushing (RH)</p>	
<p><b>H09A00E</b></p> <p>21850-22702</p> <p>ACCENT (1996)</p> <p>Front Engine Bushing (RE)</p>		<p><b>H09A97E</b></p> <p>21851-24700</p> <p>ACCENT (1997), EXCEL, SCOUPE</p> <p>Front Engine Bushing (RE)</p>	
<p><b>H09A97FA</b></p> <p>21911-22400, 21911-28500</p> <p>ACCENT (1997), ELANTRA (1997)</p> <p>Front Engine Bushing (FR, A/T)</p>		<p><b>H09A97FM</b></p> <p>21911-22001, 23000, 28000</p> <p>ACCENT (1997), TIBURON</p> <p>Front Engine Bushing (FR, M/T)</p>	
<p><b>H09E92EA</b></p> <p>21931-28500</p> <p>ELANTRA (1992) (1.8 cc)</p> <p>Front Engine Bushing (RE, A/T)</p>		<p><b>H09E92EM</b></p> <p>21931-29000</p> <p>ELANTRA (1992, 1996), TIBURON</p> <p>Front Engine Bushing (RE, M/T)</p>	
<p><b>H09E92FA</b></p> <p>21910-28500</p> <p>ELANTRA (1992, 1994), SCOUPE</p> <p>Front Engine Bushing (FR, A/T)</p>		<p><b>H09E92L0</b></p> <p>21812-28200</p> <p>ELANTRA (1992, 1994) (1.6 cc, 1.8 cc)</p> <p>Front Engine Bushing (LH)</p>	
<p><b>H09E94FA</b></p> <p>21641-33410</p> <p>ELANTRA (1992, 1994) (1.8 cc)</p> <p>Front Engine Bushing (FR)</p>		<p><b>H09E9600</b></p> <p>21812-29150</p> <p>ELANTRA (1992, 1996), TIBURON</p> <p>Front Engine Bushing</p>	
<p><b>H09S92EA</b></p> <p>21631-33410</p> <p>SONATA (1992)</p> <p>Front Engine Bushing (RE, A/T)</p>		<p><b>H09S92EM</b></p> <p>21631-36000</p> <p>SONATA (1992)</p> <p>Front Engine Bushing (RE, M/T)</p>	
<p><b>H09S94EA</b></p> <p>21931-34100</p> <p>SONATA (1994)</p> <p>Front Engine Bushing (RE, A/T)</p>		<p><b>H09S94FA</b></p> <p>21911-34500</p> <p>SONATA (1994)</p> <p>Front Engine Bushing (FR, A/T)</p>	



# RUBBER INTERTRADE CO., LTD.






Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p><b>H09S94L0</b> 21852-33070 SONATA (1992, 1994) Front Engine Bushing (LH)</p>		<p>B : 2 / C : 24 pcs.</p>	<p><b>H09S94L1</b> 21812-34600 SONATA (1994) 16V Front Engine Bushing (LH)</p>		<p>B : 2 / C : 24 pcs.</p>
<p><b>H09S97EA</b> 21931-35500 SONATA (1997) Front Engine Bushing (RE, A/T)</p>		<p>B : 4 / C : 48 pcs.</p>	<p><b>H09S97EM</b> 21931-35000 SONATA (1997) Front Engine Bushing (RE, M/T)</p>		<p>B : 4 / C : 48 pcs.</p>
<p><b>H09S97FA</b> 21911-34401, 21911-34411 SONATA (1997) Front Engine Bushing (FR, A/T)</p>		<p>B : 4 / C : 48 pcs.</p>	<p><b>H09S97FM</b> 21911-35010 SONATA (1997) Front Engine Bushing (FR, M/T)</p>		<p>B : 4 / C : 48 pcs.</p>
<p><b>H09S97L0</b> 21812-35140 SONATA (1997) Front Engine Bushing (LH, M/T, A/T)</p>		<p>B : 2 / C : 24 pcs.</p>			
<p><b>H09X00L0</b> 21818-24000, 21834-24700 EXCEL, SCOUPE Front Engine Bushing (LH)</p>		<p>B : 2 / C : 24 pcs.</p>	<p><b>H09X92E0</b> 21851-24000 EXCEL, SCOUPE Front Engine Bushing (RE, M/T)</p>		<p>B : 4 / C : 48 pcs.</p>
<p><b>H09X92FA</b> 21840-24710 EXCEL Front Engine Bushing (FR, A/T)</p>		<p>B : 4 / C : 48 pcs.</p>	<p><b>H09X92FM</b> 21846-24000 EXCEL Front Engine Bushing (FR, M/T)</p>		<p>B : 4 / C : 48 pcs.</p>



**HYUNDAI**

<p>H11A94R0 21834-22130 ACCENT Rear Engine Bushing (RH, M/T, A/T)</p>	 <p>B : 2 / C : 24 pcs.</p>
<p>H11E92E0 21832-28700 ELANTRA (1992, 1994, 1996) Rear Engine Bushing (RE, A/T)</p>	<p>H11E92EA 21832-28200 ELANTRA (1992, 1994, 1996) Rear Engine Bushing (RE, A/T)</p>  <p>B : 2 / C : 24 pcs.</p>
<p>H11S920A 21872-33070 SONATA (1992) 16V Rear Engine Bushing (A/T)</p>	<p>H11S920M 21860-33070 SONATA (1992) 16V Rear Engine Bushing (M/T)</p>  <p>B : 4 / C : 48 pcs.</p>
<p>H11S94E0 21832-34600 SONATA (1994) Rear Engine Bushing (RE, A/T, M/T)</p>	 <p>B : 4 / C : 48 pcs.</p>
<p>H11X92EA 21834-24800 EXCEL, SCOUPE Rear Engine Bushing (RE, A/T)</p>	<p>H11X92EM 21834-24000 EXCEL, SCOUPE Rear Engine Bushing (RE, M/T)</p>  <p>B : 2 / C : 24 pcs.</p>



**HYUNDAI**

\* RBI Shock Absorber Mounting is assembled with Japanese Bearing





<p><b>H13A00F</b> 54610-22000 ACCENT Shock Absorber Mounting (FR)</p>		<p>B : 1 / C : 20 pcs.</p>	<p><b>H13E92F</b> 54610-28000 ELANTRA (1992-1994) Shock Absorber Mounting (FR)</p>		<p>B : 1 / C : 20 pcs.</p>
<p><b>H13E96F0</b> 54610-29000 ELANTRA (1996) Shock Absorber Mounting (FR)</p>		<p>B : 1 / C : 20 pcs.</p>			
<p><b>H13S94F</b> 54610-34010 SONATA (1994-1997) Shock Absorber Mounting (FR)</p>		<p>B : 1 / C : 20 pcs.</p>	<p><b>H13X92F</b> 54610-24001 EXCEL, SCOUPE Shock Absorber Mounting (FR)</p>		<p>B : 1 / C : 20 pcs.</p>
<p><b>H13S92F</b> 54610-36002 SONATA (1992) Shock Absorber Mounting (FR)</p>		<p>B : 1 / C : 20 pcs.</p>			
<p><b>H13E96EL</b> 55310-29000 ELANTRA (1996) Shock Absorber Mounting (RE, LH)</p>		<p>B : 1 / C : 20 pcs.</p>	<p><b>H13E96ER</b> 55320-29000 ELANTRA (1996) Shock Absorber Mounting (RE, RH)</p>		<p>B : 1 / C : 20 pcs.</p>
<p><b>H13H10F</b> 54610-4H000 HYUNDAI H1 Shock Absorber Mounting (FR, LH, RH)</p>		<p>B : 1 / C : 20 pcs.</p>			
<p><b>H14H10F</b> 54626-4H000 HYUNDAI H1 Shock Absorber Bumper (FR)</p>		<p>B : 6 / C : 72 pcs.</p>	<p><b>H14H100F</b> 54625-4H000 HYUNDAI H1 Shock Dust Cover (FR)</p>		<p>B : 2 / C : 40 pcs.</p>



# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p><b>H17S201Z</b> 49506-3KA10 SONATA (2007) Drive Shaft Boot (INNER)</p>  <p>B : 2 / C : 100 pcs.</p>	<p><b>H17S201UZ</b> 49509-3KA10 SONATA (2007) Drive Shaft Boot (OUTER)</p>  <p>B : 2 / C : 100 pcs.</p>
<p><b>H18S201Z</b> 57740-3K000 SONATA (2007) Steering Gear Boot</p>  <p>B : 2 / C : 50 pcs.</p>	
<p><b>H19SX00</b> 56315-2K000 HYUNDAI SONATA, ELANTRA, VELOSTER, SANTA FE, AZERA, KIA FORTE SOUL, OPTIMA Flexible steering coupling</p>  <p>B : 30 / C : 1950 pcs.</p>	



# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p><b>H21A00E</b> 55513-22010 ACCENT Stabilizer Shaft Rubber (RE)</p>  <p>B : 20 / C : 480 pcs.</p>	<p><b>H21A00F</b> 54813-22200 ACCENT Stabilizer Shaft Rubber (FR)</p>  <p>B : 20 / C : 480 pcs.</p>
<p><b>H21E92F</b> 54813-28001 ELANTRA (1992, 1994) Stabilizer Shaft Rubber (FR)</p>  <p>B : 20 / C : 480 pcs.</p>	
<p><b>H21E96E</b> 55513-29100 ELANTRA (1996) Stabilizer Shaft Rubber (RE)</p>  <p>B : 12 / C : 288 pcs.</p>	<p><b>H21E96F</b> 54813-29100 ELANTRA (1996) Stabilizer Shaft Rubber (FR)</p>  <p>B : 10 / C : 240 pcs.</p>
<p><b>H21S92F</b> 54813-33022 SONATA (1992) Stabilizer Shaft Rubber (FR)</p>  <p>B : 20 / C : 480 pcs.</p>	
<p><b>H21S94E</b> 55577-34000 SONATA (1994, 1997) Stabilizer Shaft Rubber (RE)</p>  <p>B : 20 / C : 480 pcs.</p>	<p><b>H21S94F</b> 54813-34000 SONATA (1994, 1997) Stabilizer Shaft Rubber (FR)</p>  <p>B : 16 / C : 384 pcs.</p>
<p><b>H21X00F</b> 54813-24010 EXCEL, SCOUPE Stabilizer Shaft Rubber (FR)</p>  <p>B : 20 / C : 480 pcs.</p>	<p><b>H21H100</b> 54813-4A600 HYUNDAI H1 Stabilizer Shaft Rubber (FR)</p>  <p>B : 8 / C : 128 pcs.</p>
<p><b>H21H10F</b> 54813-3K100 HYUNDAI H1 Stabilizer Shaft Rubber (FR)</p>  <p>B : 6 / C : 144 pcs.</p>	<p><b>H21H10E</b> 55513-4H100 HYUNDAI H1 Stabilizer Shaft Rubber (RE)</p>  <p>B : 6 / C : 144 pcs.</p>
<p><b>H23H100</b> 54751-4B002 H100 Strut Bar Rubber</p>  <p>B : 12 / C : 192 pcs.</p>	



# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p><b>H24A00WS</b> 54551-22000 ACCENT Lower Arm Bushing (SMALL)</p>	 B : 10 / C : 180 pcs.		
<p><b>H24A0WL</b> 54555-22102 ACCENT Lower Arm Bushing (LH)</p>	 B : 4 / C : 72 pcs.	<p><b>H24A0WR</b> 54556-22102 ACCENT Lower Arm Bushing (RH)</p>	 B : 4 / C : 72 pcs.
<p><b>H24E92WS</b> 54551-28000 ELANTRA (1992, 1994) Lower Arm Bushing (SMALL)</p>	 B : 10 / C : 180 pcs.		
<p><b>H24E92WL</b> 54555-28001 ELANTRA (1992) Lower Arm Bushing (BIG, LH)</p>	 B : 4 / C : 72 pcs.	<p><b>H24E92WR</b> 54556-28001 ELANTRA (1992) Lower Arm Bushing (BIG, RH)</p>	 B : 4 / C : 72 pcs.
<p><b>H24E94WL</b> 54555-28071 ELANTRA (1994) Lower Arm Bushing (BIG, LH)</p>	 B : 4 / C : 72 pcs.	<p><b>H24E94WR</b> 54556-28071 ELANTRA (1994) Lower Arm Bushing (BIG, RH)</p>	 B : 4 / C : 72 pcs.
<p><b>H24E95WL</b> 54555-28070 ELANTRA (1995) Lower Arm Bushing (BIG, LH)</p>	 B : 4 / C : 64 pcs.	<p><b>H24E95WR</b> 54556-28070 ELANTRA (1995) Lower Arm Bushing (BIG, RH)</p>	 B : 4 / C : 64 pcs.
<p><b>H24E96WB</b> 54583-29000, 54584-29000 ELANTRA (1996) Lower Arm Bushing (BIG LH, RH)</p>	 B : 6 / C : 108 pcs.	<p><b>H24E96WS</b> 54551-29000 ELANTRA (1996) Lower Arm Bushing (SMALL)</p>	 B : 8 / C : 144 pcs.
<p><b>H24S92WS</b> 54551-36000 SONATA (1992) Lower Arm Bushing (SMALL)</p>	 B : 8 / C : 144 pcs.		



# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p>H24S94W0</p> <p>55116-37000</p> <p>SONATA (1994, 1997)</p> <p>Lower Arm Bushing</p>	<p>H24S94WS</p> <p>54551-37000</p> <p>SONATA (1994, 1997)</p> <p>Lower Arm Bushing (SMALL)</p>
<p>H24S95WB</p> <p>54580, 54581-35000B</p> <p>SONATA (1995, 1997)</p> <p>Lower Arm Bushing (BIG)</p>	<p>H24S95WS</p> <p>54580, 54581-35000S</p> <p>SONATA (1995, 1997)</p> <p>Lower Arm Bushing (SMALL)</p>
<p>H24X92W</p> <p>54551-24001</p> <p>EXCEL, SCOUPE</p> <p>Lower Arm Bushing</p>	
<p>H24M00W</p> <p>54551-25000</p> <p>MATRIX</p> <p>Low Arm Bushing</p>	<p>H24M01W</p> <p>54584-17000</p> <p>MATRIX</p> <p>Low Arm Bushing</p>
<p>H24T00WS</p> <p>54551-3A000</p> <p>TRAJET</p> <p>Low Arm Bushing (SMALL)</p>	
<p>H24H10WB</p> <p>54584-4H000</p> <p>HYUDAI H1</p> <p>Low Arm Bushing (BIG)</p>	<p>H24H10WS</p> <p>54551-4H000</p> <p>HYUDAI H1</p> <p>Low Arm Bushing (SMALL).</p>
<p>H24S201W</p> <p>54551-3K000, 3L000</p> <p>SONATA (2005-2010), GRANDEUR (2005)</p> <p>Low Arm Bushing</p>	<p>H24S202W</p> <p>54552-3K600, 54552-3K000</p> <p>SONATA (2005-2010), GRANDEUR (2005)</p> <p>Low Arm Bushing (SMALL)</p>
<p>H24S20WB</p> <p>54584-3F600</p> <p>SONATA (2007)</p> <p>Low Arm Bushing</p>	





# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p><b>H24A050WS</b></p> <p><b>54551-2H000</b></p> <p>ACCENT (2005), ELANTRA (2010), SOLARIS (2010), TUCSON (2004-2010), VELOSTER (2011), VERNA</p> <p><b>Low Arm Bushing</b></p>	<p><b>H24A051WS</b></p> <p><b>54584-2H000</b></p> <p>ACCENT (2005), ELANTRA (2010), SOLARIS (2010), TUCSON (2004-2010), VELOSTER (2011), VERNA</p> <p><b>Low Arm Bushing</b></p>
<p><b>H24A05WB</b></p> <p><b>54584-3X000</b></p> <p>ACCENT (2005), ELANTRA (2010), SOLARIS (2010), TUCSON (2004-2010), VELOSTER (2011), VERNA (2007)</p> <p><b>Low Arm Bushing</b></p>	<p><b>H24A05WS</b></p> <p><b>54551-1J000</b></p> <p>ACCENT (2005-2011), ELANTRA (2012)</p> <p><b>Low Arm Bushing</b></p>
<p><b>H24S205WS</b></p> <p><b>54443-3K000</b></p> <p>SONATA (2005-2010), GRANDEUR (2005), AZERA (2006)</p> <p><b>Low Arm Bushing</b></p>	<p><b>H24S900W</b></p> <p><b>54584-3K000</b></p> <p>SONATA (1990-2010), ELANTRA (2000-2006), ENTOURAGE (2006), COUPE (2001), CM10 (2009)</p> <p><b>Low Arm Bushing</b></p>



**HYUNDAI**

<p>H25E9201 54551-28310 ELANTRA (1992, 1994) Suspension Bush</p>	 B : 4 / C : 72 pcs.	<p>H25S9401 55543-37000 SONATA (1994) Suspension Bush</p>	 B : 4 / C : 72 pcs.
<p>H25S9402 55543-35000 SONATA (1994, 1997) Suspension Bush</p>	 B : 4 / C : 64 pcs.	<p>H25A00E 54555-25000 ACCENT Y2K Suspension Bush</p>	 B : 6 / C : 108 pcs.
<p>H25T00E 54555-3A100 TRAJET Suspension Bush</p>	 B : 4 / C : 72 pcs.		
<p>H25H100 55630-4H000 HYUNDAI H1 Suspension Bush</p>	 B : 6 / C : 108 pcs.	<p>H25H101 55217-4H000 HYUNDAI H1 Suspension Bush</p>	 B : 4 / C : 72 pcs.
<p>H25H102 55270-4H100 HYUNDAI H1 Suspension Bush</p>	 B : 4 / C : 72 pcs.	<p>H25H103 55225-4H100 HYUNDAI H1 Suspension Bush</p>	 B : 4 / C : 72 pcs.
<p>H25H10E 55620-4H000 HYUNDAI H1 Suspension Bush</p>	 B : 8 / C : 144 pcs.	<p>H25H104 55216-4H100 HYUDAI H1 Suspension Bush</p>	 B : 2 / C : 36 pcs.



# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI





<p>H27E920F</p> <p>54830-37020</p> <p>ELANTRA (1992, 1994)</p> <p>Link Assy (FR)</p>	<p>B : 2 / C : 108 pcs.</p>
<p>H27E960F</p> <p>54830-29500</p> <p>ELANTRA (1996)</p> <p>Link Assy (FR)</p>	<p>H27E960E</p> <p>55530-29500</p> <p>ELANTRA (1996)</p> <p>Link Assy (RE)</p> <p>B : 2 / C : 54 pcs.</p>
<p>H27S920F</p> <p>54830-36101</p> <p>SONATA (1992)</p> <p>Link Assy (FR)</p>	<p>B : 2 / C : 108 pcs.</p>
<p>H27S940F</p> <p>54830-2D000</p> <p>SONATA (1994)</p> <p>Link Assy (FR)</p>	<p>H27S940E</p> <p>55580-37030</p> <p>SONATA (1994)</p> <p>Link Assy (RE)</p> <p>B : 2 / C : 90 pcs.</p>
<p>H27H1EL</p> <p>55530-4H000</p> <p>HYUNDAI H1</p> <p>Link Assy (RE, LH)</p>	<p>H27H1ER</p> <p>55540-4H000</p> <p>HYUNDAI H1</p> <p>Link Assy (RE, RH)</p> <p>B : 2 / C : 54 pcs.</p>
<p>H27H1FL</p> <p>54830-4H000</p> <p>HYUNDAI H1</p> <p>Link Assy (FR, LH)</p>	<p>H27H1FR</p> <p>54840-4H000</p> <p>HYUNDAI H1</p> <p>Link Assy (FR, RH)</p> <p>B : 2 / C : 32 pcs.</p>
<p>H27S20F</p> <p>54830-3K010, 54830-3K010</p> <p>SONATA (2007)</p> <p>Link Assy (FR)</p>	<p>H27S20E</p> <p>55530-3K002</p> <p>SONATA (2007)</p> <p>Link Assy (RE)</p> <p>B : 2 / C : 108 pcs.</p>



# RUBBER INTERTRADE CO., LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded parts

## HYUNDAI

<p><b>H27A011F</b></p> <p>54830-0U000</p> <p>ACCENT (2011), BLUESA (2011), SOLARIS (2010), VELOSTER (2011)</p> <p>Link Assy (FR)</p>  <p>B : 2 / C : 32 pcs.</p>	<p><b>H27T04F0</b></p> <p>54830-2E000</p> <p>HYUNDAI TUCSON (2004-2010)</p> <p>Link Assy (FR)</p>  <p>B : 2 / C : 40 pcs.</p>
<p><b>H27V20FL</b></p> <p>54830-2B000</p> <p>CM10 (2009), IX55 (2008), SANTA'FE (2006), VERACRUZ (2006)</p> <p>Link Assy (FR, LH)</p>  <p>B : 2 / C : 36 pcs.</p>	<p><b>H27V20FR</b></p> <p>54840-2B000</p> <p>CM10 (2009), IX55 (2008), SANTA'FE (2006), VERACRUZ (2006)</p> <p>Link Assy (FR, RH)</p>  <p>B : 2 / C : 36 pcs.</p>
<p><b>H38H10L</b></p> <p>57789-4H000</p> <p>HYUNDAI H1</p> <p>Grommet Steering Rack (LH)</p>  <p><b>NEW</b></p> <p>B : 6 / C : 96 pcs.</p>	